

# ADMIRAL ... AKAI

| MFG. P/N         | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N     | PRB NO. |
|------------------|---------|----------------|---------|----------------|---------|----------------|---------|--------------|---------|
| <b>ADMIRAL</b>   |         | 221-1157       | SCX9.5  | 82-309-247-01  | SCY4.0  | S1-921-090-040 | SCX5.5  | MB328754     | FRZ11.0 |
| 2012411          | 0A7.4   | 221-1205       | 087.2   | 82-310-208-01  | FRM8.0  | S1-921-090-240 | SCX7.0  | MB328929     | SCY9.0  |
| 2012A110         | 0A4.6   | 2214302        | SCX2.6  | 82-318-207-01  | SCY6.7  | S8-059-070-100 | FRQ11.2 | MB329228     | SCY7.0  |
| 2012A112         | FRM7.5  | 221-53020      | SCX8.6  | 82-319-227-01  | FRM7.5  | S8-059-071-000 | FRQ11.2 | MB331350     | SCB14.0 |
| 2012A113         | 0A5.8   | 221-5443       | SCX8.6  | 82-332-052-010 | 089.4   | S8-059-150-060 | SCQ6.5  | MB331351     | FRX22.4 |
| 20124114         | FRM11.5 | 221-5444       | SCX8.6  | 82-358-234-21  | 0A7.4   | S8-063-110-090 | SCA10.5 | MB336021     | SCX5.1  |
| 20124116         | 0A5.4   | 221-55480      | SCX8.6  | 82-361-272-11  | 0A6.1   | S8-063-150-060 | SCQ5.7  | MB336026     | FRM9.0  |
| 20124118         | OB10.9  | 221-6245       | 0411.7  | 82-371-343-01  | SCY4.2  |                |         | M6336588     | SCY8.0  |
| 20124119         | FRM12.1 | 221-9142       | SCQ6.7  | 82-372-226-01  | SCX9.2  | <b>AKA/</b>    |         | MB344041     | FRX11.2 |
| 2012A12          | 0A8.5   | 221-9153       | 0410.1  | 82-380-393-01  | SCY7.0  | 10RF014        | FR15.9  | MB344042     | SCX5.1  |
| 2012A123         | SCX8.9  | 221-9213       | 0410.1  | 82-380-399-01  | SCX5.1  | 1720036        | OB14.0  | MB344088     | SCX4.3  |
| 2012A124         | FRY10.7 | 221-92130      | 0A7.0   | 82-380-440-01  | SCX2.4  | 172003B        | 0A7.4   | MB359875     | FRM10.5 |
| 2012A125         | 0A9.4   | 222-2133       | 0410.9  | 82-380-441-01  | SCY10.5 | 1740011        | FR14.1  | MB359886     | FR5.9   |
| 2012A126         | FRW12.0 | 222-3286       | 087.2   | 82-385-253-01  | SCY6.5  | 408N           | FRZ13.2 | M6360532     | FRW10.6 |
| 20124128         | FRM11.2 | 222-32880      | 0410.1  | 82-385-313-01  | SCX8.0  | 418408         | 0A6.6   | MB365332     | 044.0   |
| 20124129         | FRM11.0 | 224-4020       | 0A6.6   | 82-385-314-01  | SCX4.3  | 43069          | 0814.0  | MB365408     | FRW10.6 |
| 20124130         | SCX10.7 | 224-6206       | 0810.1  | 62-387-262-01  | FRX12.7 | 43070          | FRM12.1 | MB366287     | SCX4.6  |
| 2012A132         | FRY10.7 | 224-62060      | OB10.9  | 82-392-319-01  | FRY10.7 | 6246           | 0814.0  | MB369663     | 0410.1  |
| 2012A14          | SCX8.6  | 224-6234       | SCX11.8 | 82-3974314-01  | SCY6.5  | 6313           | FRZ13.2 | MB369753     | 0A7.4   |
| 2012A15          | SCX4.0  | 224-6243       | 0411.7  | 82-397-325-01  | SCY4.6  | 66600300       | SCB12.5 | MB373080     | SCA9.6  |
| 2012A16          | SCB8.1  | 224-62430      | 0814.0  | 82-409-217-01  | OSC10.2 | 66600700       | SCB11.3 | MB373096     | SCB2.8  |
| 20124169         | 0A4.2   | 224-6245       | 0411.7  | 82-409-296-01  | 0A5.0   | 66600701       | OB10.9  | MB373386     | SCX2.9  |
| 2012A17          | 0A5.0   | 224-8190       | FF13.2  | 82-416-220-11  | SCX9.2  | 820036         | 0813.2  | MB387101     | SCQ11.1 |
| 2012A18          | 0814.0  | 224-9149       | 0A7.0   | 82-418-211-01  | 0A9.4   | 84001P         | FR13.4  | MB387235     | SCQ8.2  |
| 2012A19          | FR5.9   | 224-9193       | 0A6.6   | 82-422-237-01  | 0A9.4   | BLB353110      | VA054   | MB387246     | SCQ11.1 |
| 317110           | 0A8.5   | 224-91930      | 0A13.2  | 82-439-342-01  | SCY3.5  | ED373101       | VCR33   | MB394852     | SCB6.9  |
| 406A20           | FR2.0   | 224-9220       | 0413.2  | 82-445-250-01  | SCY7.0  | ED3731011      | VCR33   | MB407542     | FRM10.2 |
| 406A312          | FR2.0   | 224-9255       | FF13.2  | 82-446-204-01  | SCY4.4  | EDF015         | FRM14.7 | MB407575     | FRM10.2 |
| 700AI200406      | 114105  | 224-9323       | FRM14.0 | 82-446-205-01  | SCY6.0  | EG011097USA    | V752    | MB415743     | SCY11.7 |
| 70041685171      | IW11    | 225-0170       | SCX2.4  | 82-458-293-11  | FR12.5  | ES359700       | VCR21   | MB422267     | SCX7.0  |
| 7004816191       | OB10.9  | 225-80930      | 0410.1  | 82-461-318-01  | SCY5.2  | ET353635       | VCR14   | MB422268     | SCX7.0  |
| 700A816201       | FRM11.2 | 225-8127       | SCX4.3  | 82-462-204-01  | SCQ6.5  | ET359700       | VCR21   | M8422278     | SCX7.0  |
| 7004816273       | FRM11.2 | 225-81270      | 0A4.2   | 82-470-226-01  | SCY10.5 | ET361463       | VCR13   | MB422627     | SCA5.4  |
| 700A816474       | FRM11.5 | 225-8190       | SCQ10.0 | 82-481-264-01  | FRM9.6  | ET361490       | VCR20   | MB437703     | FR14.0  |
| 700A816580       | FRQ11.2 | 226-03300      | SCX7.0  | 82-481-265-01  | SCY4.4  | ET706766       | VCR10   | MB454184     | SCY4.2  |
| 700A816676       | FRQ11.2 | 226-03310      | SCY4.2  | 82-481-266-01  | SCY6.0  | EX318308       | VCR21   | MB454217     | SCB11.3 |
| 7500153439       | FRM11.5 | 233-20520      | 0A8.5   | 82-493-232-01  | SCX8.4  | LCS507         | FR14.1  | MB456660     | SCA13.2 |
| 7500153441       | FRM11.5 | 233-22100      | 0410.9  | 82-530-210-01  | SCY4.6  | MC0048         | 0A7.4   | MB456895     | SCQ4.8  |
| 7500153447       | FRM11.2 | 233-22106      | 0410.9  | 82-533-219-01  | SCY6.0  | M9053          | FR13.4  | M8456917     | SCY7.0  |
| 7500153484       | FRM11.5 | 233-23430      | OB14.0  | 82-535-236-01  | SCY6.7  | MB02556        | FRW10.7 | MB468292     | 0A4.2   |
|                  |         | 234-11620      | 048.5   | 82-538-210-01  | SCY7.0  | MB18087        | FRW10.7 | MB527556     | SCX11.8 |
|                  |         | 234-12450      | SCB12.5 | 82-540-339-01  | SCQ5.6  | MB222333       | FRQ14.5 | M6533068     | SCQ11.1 |
| <b>ADVENT</b>    |         | 234-1250       | SCB12.5 | 82-541-268-01  | SCY4.2  | MB230286       | SCX9.2  | MB541012     | FRZ14.5 |
| 95000045         | SCQ6.0  | 234-21160      | SCX13.6 | 82-548-205-01  | SCY6.5  | MB238768       | FRM14.7 | MB542283     | SCX8.6  |
| 95000048         | ST.815  | 234-63900      | SCY4.2  | 82-561-209-01  | FRX9.7  | MB253574       | FRM7.0  | M8566583     | SCA3.2  |
| 95000052         | SCA7.5  | 236-29900      | 0A7.0   | 82-564-244-01  | SCX4.0  | MB253866       | SCY4.2  | MB566684     | FR18.2  |
| <b>AIREQUIPT</b> |         | 240-23190      | 0A9.4   | 82-585-287-01  | FRY10.0 | MB256590       | FR13.4  | MB576123     | SCA5.6  |
| 2370             | 085.8   | 414-428-00     | SCX8.9  | 82-585-336-01  | SCX7.4  | MB256601       | FR13.4  | MB577012     | SCX3.5  |
| 3795             | 0A4.6   | 80-VW1-217-010 | SCQ4.8  | 82-585-378-01  | SCQ5.6  | MB282093       | FRX11.2 | MB580138     | 0A9.0   |
| 4056             | 0A5.4   | 80-ZM2-240-010 | SCY9.2  | 82-585-451-01  | FRX10.5 | MB296458       | SCY8.2  | MB595701     | SCY7.0  |
| 51208            | 085.8   | 80-ZM6-227-110 | SCQ5.3  | 82-587-209-01  | SCY6.7  | MB302211       | SCY8.6  | MB595743     | SCY7.0  |
| 81829            | 0A5.4   | 81-507-247-010 | FRW8.5  | 82-639-298-01  | SCY8.6  | MB302316       | FRM11.0 | MB613258     | SCY9.0  |
| 81833            | 0A4.6   | 81415-210-01   | SCY3.2  | 82-641-214-01  | SCY4.2  | MB302866       | FRX25.0 | MB613260     | SCA4.5  |
| CA1303           | OB11.7  | 81-ZG1-232-010 | SCA4.0  | 82-647-305-01  | SCY5.2  | MB304807       | SCQ4.8  | MB613271     | FRQ13.6 |
| CA803            | 0A3.8   | 81-ZG1-233-010 | SCQ2.0  | 82-ZM1-260-010 | SCX8.0  | MB309185       | FRX11.7 | MB625566     | SCQ11.1 |
|                  |         | 81-ZM7-202-110 | SCQ10.0 | 82-ZM1-261-010 | SCX5.1  | M6309197       | SCY4.6  | MB629548     | SCX11.8 |
| <b>AIRLINE</b>   |         | 81-ZM7-203     | SCX10.5 | 83-CT2-210-010 | SCQ5.7  | MB310715       | FRX10.5 | MB629561     | SCX7.4  |
| 36MW75           | 0A8.2   | 81-ZM7-203-110 | SCX10.5 | 84-185-202-01  | FRX25.0 | MB310716       | SCY7.0  | MB630404     | SCY6.0  |
| 39MW202          | SCX8.6  | 62-150-29401   | SCX2.6  | 85-258-093-11  | OSC10.2 | MB313387       | FRM9.7  | MB669036     | FRM10.5 |
| 40904            | FF12.6  | 82-150-339-01  | SCQ5.6  | 86-524-471-010 | SCX8.4  | MB313389       | SCY4.6  | MB690390     | SCX8.9  |
| 4310015          | FR12.0  | 82-157-211-01  | SCY1.5  | 86-567-221-019 | SCY9.0  | MB313845       | SCA8.9  | MB699118     | FRZ12.1 |
| 432014           | OC9.0   | 82-161-294-01  | FRM9.2  | 86-567-268-010 | SCY7.0  | MB31388        | SCX7.4  | MB702556     | FRW10.7 |
| 432015           | OC11.2  | 82-162-227-01  | SCY7.0  | 86-567-269-010 | SCY3.2  | MB31389        | SCX4.3  | MB702582     | SCX8.9  |
| 432016           | 0A9.4   | 82-170-230-01  | FRM9.7  | 86-574-221-010 | FRW9.2  | MB314317       | FRY10.4 | MB705171     | FRM8.0  |
| 6668122          | 0A8.2   | 82-173-252-01  | SCY5.2  | 86-574-222-010 | FRW8.5  | MB315653       | SCY10.5 | MB706365     | SCY7.0  |
| 6668154          | FF12.6  | 82-173-254-01  | FRW10.1 | 86-575-238-010 | FRM8.0  | MB316029       | 0410.9  | MB706392     | FRW8.0  |
| 80MW337          | 0410.9  | 82-176-207-01  | FRW10.7 | 86-575-302-110 | SCX8.0  | MB317387       | SCQ6.7  | MB706393     | SCX5.1  |
| 80MW88           | 0814.0  | 82-179-256-01  | SCQ6.0  | 93-053-307-010 | SCQ3.0  | MB317388       | SCY3.5  | MB710131     | SCY5.7  |
| 85454            | 008.2   | 82-180-223-01  | FRX9.4  | 93-653-387-000 | SCQ3.2  | MB317776       | SCX7.4  | MB713472     | SCA8.9  |
| 85456            | OB12.4  | 82-258-093-11  | OSC10.2 | 93-853-387-000 | SCQ3.0  | MB317779       | SCY8.6  | MB713473     | FR10.8  |
| 854908           | 0A9.4   | 82-277-334-11  | SCX7.0  | S1-003-650-100 | SCX3.2  | MB317794       | SCA8.1  | MB713475     | SCB6.6  |
| 899A3            | FF12.4  | 82-282-247-01  | SCY4.2  | S1-003-650-400 | SCX14.5 | MB317795       | SCA10.5 | M8720876     | FRW10.7 |
| A908             | 0A8.2   | 82-282-286-01  | 0A4.0   | S1-003-650-800 | SCX3.2  | MB317796       | SCQ4.8  | MB94852      | SCB6.9  |
| TD999            | FF12.6  | 82-282-298-01  | SCX7.0  | S1-005-250-300 | SCX15.0 | MB318077       | FRM9.2  | M1317796     | ST1.243 |
| 70171            | OC12.8  | 82-283-272-11  | SCX10.7 | S1-821-070-110 | SCX4.3  | MB318081       | FRW10.7 | M1317906     | ST1.243 |
| TR1548           | 006.1   | 82-283-311-01  | 0816.4  | S1-821-120-210 | SCY7.3  | MB318087       | FRW10.7 | M1327773     | VA050   |
|                  |         | 82-283-378-01  | SCY7.0  | S1-821-120-220 | SCX7.0  | MB321389       | FRX13.1 | M361964      | VA054   |
|                  |         | 82-292-276-01  | SCX7.0  | S1-821-121-420 | SCX9.5  | MB321391       | SCY5.2  | M1713481     | ST.599  |
|                  |         | 82-292-278-01  | 0A4.2   | S1-821-121-730 | SCY5.7  | MB321392       | SCY8.6  | M1713481     | VA90    |
|                  |         | 82-297-325-01  | SCX7.0  | S1-877-090-130 | SCY4.4  | MB323681       | FR8.2   | M1713492     | ST.927  |
|                  |         | 82-297-326-01  | SCY4.6  | S1-888-070-070 | SCX5.5  | MB324611       | SCX9.2  | MP357547     | VPR21   |
|                  |         | 82-302-318-01  | SCY4.0  | S1-888-090-300 | SCX11.8 | MB326474       | FR11.9  | MP361543     | VPR22   |
|                  |         | 82-303-310-01  | FRW8.5  | S1-908-050-080 | SCY4.6  | MB327330       | 0A14.8  | MP3615438    | VPR22   |
|                  |         | 82-303-385-01  | SCX3.2  | S1-921-070-030 | SCY4.2  | MB328323       | FRW8.0  | MP706871     | VPR7    |
|                  |         | 82-304-247-01  | SCY6.7  | S1-921-070-110 | SCX4.3  | MB328324       | SCY8.0  | MPV200441204 | VPR12   |

\* = Replacement Belt

= Kit May Not Include Tires

▲ Part of the Assy

Mfg. # to PRB#

# AKAI ... AUTOMATIC RADIO

| MFG. P/N               | PRB NO. | MFG. P/N    | PRB NO. | MFG. PIN     | PRB NO. | MFG. P/N            | PRB NQ. | MFG. P/N               | PRB NO. |
|------------------------|---------|-------------|---------|--------------|---------|---------------------|---------|------------------------|---------|
| MRM108                 | FRQ14.5 | 431-015     | 0011.2  | 785-3251     | STC.823 | 45                  | 004.6   | TT39                   | 0814.0  |
| MRM2Q7                 | SCX9.2  | 431-02101   | QC16.0  | 785-3257     | STC.742 | 46                  | OC2.5   | TT41                   | 0A10.1  |
| MZ366960               | ST1.118 | 431-5001    | ST1.41  | 785-3295     | SQX2.6  | 54                  | WP15    | TT77112                | 0A5.8   |
| MZ366960               | VA055   | 431-5002    | ST.536  | 785-3295-01  | SCX8.6  | 55                  | WP16    | TT77116                | FRM11.7 |
| RCCMO24                | 0A10.1  | 431-5002-10 | OB10.9  | 785-4011     | FRM12.1 | B07099              | FR7.4   | TT77A112               | FRM7.0  |
| RCCM623                | SCX2.9  | 431-5003-10 | OSC18.5 | 785-5111     | STO.742 | B07156              | 085.8   | TT77A120               | FRM11.0 |
| RCCM636                | 0A4.0   | 431-5004    | OSC22.8 | 785-5115     | STC.823 |                     |         |                        |         |
| SD035A                 | FR13.4  | 431-5004-30 | OS022.8 | 785-5195     | SCQ6.5  | <b>ARGUS</b>        |         | <b>AUDIO VOX</b>       |         |
| SXF011                 | FR13.4  | 432-0010    | 0012.8  | 785-5195-01  | 0A6.6   | 00198               | 064.6   | 004042010              | SCY8.6  |
| SXM110                 | 0A14.8  | 432-0014    | 009.0   | 785-5253     | SCX2.6  | 07228               | 006.1   | 13301503               | FRM8.0  |
|                        |         | 432-0015    | 0011.2  | 785-5254-01  | SCX2.4  | 340115              | 088.8   | 1975 Series            | 0A4.2   |
| <b>ALLIED</b>          |         | 432-0016    | 0A9.4   | 785-5293-01  | SCX2.4  | 340154              | SCB8.1  | 20810104               | FRY10.7 |
| 21-V7000               | FRM9.7  | 432-010     | 0013.2  | 791-0152     | SCX9.5  | 39124               | OB10.9  | 23                     | FRM10.5 |
| 34-141-121             | SCX8.0  | 432-015     | 009.0   | 791-0353     | SCX7.0  | 42001               | Q06.6   | 234462                 | FRX9.0  |
| 34-595-007             | SCQ6.5  | 432-016     | 0A10.1  | 791-0353-01  | STC.742 | 42173               | QB6.6   | 25810172               | FRM9.7  |
| 34-840-17              | SCX10.7 | 528-80326   | STC.823 | 791-0354-01  | ST.536  | 42196               | GT9.1   | 25810183               | FRM9.7  |
| \$4-863-001            | SCQ6.5  | 62-34       | 0503.8  | 791-0423     | SCX10.7 | 42200               | WP20    | 26810173               | FRY10.7 |
|                        |         | 62-45       | FR12.5  | 791-0423-01  | 0A10.9  | 423500              | 007.0   | 27810172               | FRM9.7  |
| <b>ALP/NE</b>          |         | 62-46       | 0914.0  | 791-0521     | SCX2.6  | 54521               | 084.6   | 28810182               | FRM11.0 |
| 25755480               | FRW6.5  | 704-6050-02 | ST3.63  | 791-0535     | SCQ10.0 | 551121              | 0810.9  | 28810202               | FRM10.5 |
| 25755599               | S003.6  | 725-0013    | SCX9.5  | 791-0535-01  | 0A9.4   | 55204               | 084.6   | 29810202               | FRY10.7 |
| 25759015               | SCY4.6  | 731-0001    | ST1.41  | 791-0625-01  | ST.536  | 55521               | 084.6   | 37510183               | SCX7.0  |
| 25759027               | SCQ3.2  | 731-0001-01 | ST1.31  | 791-0647     | SCX8.9  | 58310               | WP17    | 37510184               | SCY4.6  |
| 42A10380W01            | SCX11.8 | 731-0002    | ST.536  | 791-0667     | SCX4.3  | 58314               | 056.6   | 370220402              | SCX4.0  |
| 42A22098W01            | SCX2.6  | 731-0002-01 | ST1.31  | 791-0667-01  | SCX4.3  | 58329               | 085.6   | 38510183               | SCX7.4  |
| 42A4Q969F01            | SCX16.0 | 731-0013    | 0A9.4   | 791-0674-01  | SCX8.9  | 755800              | 0C16.0  | 38510184               | SCY4.6  |
| 42A43653U01            | SCX9.5  | 731-0013-01 | 0A9.0   | 791-0675     | SQX2.6  | 755900              | WP19    | 38510232               | 0A4.2   |
| 42A60221F01            | SCX3.2  | 731-002-01  | ST.536  | 791-0675-01  | SCX5.1  | 776100              | 002.7   | 380350404              | FRM8.0  |
| 42A70551F01            | SCY6.3  | 731-004-10  | FRM12.1 | 791-1139-01  | SCX8.0  | 776200              | 0012.4  | 404151                 | FRM11.2 |
| 42A81427F02            | SCX3.5  | 731-004-20  | FRM12.1 | 791-1153-01  | SCQ10.0 | 901300              | WP18    | 538083                 | FRM9.7  |
| 42L340367T01           | SCX14.7 | 731-6006-01 | 05014.9 | 791-1448     | SCX8.0  | 903200              | QB6.6   | 58001                  | FRM12.1 |
| 42E02738S01            | S006.7  | 731-6008    | OSC21.2 | 791-1448-01  | 0A7.0   | 904132              | 006.1   | 58810192               | FRM11.0 |
| 42E05368S01            | SCX5.5  | 731-6008-01 | OSC21.2 | 791-1449-01  | SCQ10.0 | 904154              | 058.8   | 74202                  | FRY10.7 |
| 42E05383801            | FRW9.6  | 731-6009    | OSE14.9 | 791-1474     | OB14.0  |                     |         | 770120402              | SCX4.0  |
| 42E05491501            | SCY6.3  | 731-6013    | SCA9.2  | 791-1474-001 | 0014.0  |                     |         | 78E350404              | FRM8.0  |
| 4A40969F01             | SCX16.0 | 731-6013-01 | 0A9.4   | 791-1824-01  | SCX8.9  | 200-2210-79         | 0010.5  | 79FQDXM                | FRM8.0  |
| 5500E014               | SCX14.7 | 785-0674    | SCX8.6  | 791-1999     | SC811.3 | 200-2336-40         | SC512.5 | 801RST                 | FRM11.2 |
| 602007400              | SCQ10.0 | 785-0675    | SCX2.6  | 791-2115-01  | FRM12.1 | 200-2336-55         | 0A10.9  | 80324                  | SCX4.0  |
| 95755600               | FRW7.7  | 785-1129    | SCX12.2 | 791-2708-01  | SCX7.0  | 200-626-.83         | 0A9.4   | A5038                  | FRM11.2 |
| 95759205               | SCY1.5  | 785-1130    | SCX4.3  |              |         | 200-6422-22         | 0A9.4   | Q10                    | FRM12.1 |
| FF11M11                | SCX7.4  | 785-1131    | SCX8.4  | <b>AMPRO</b> |         | 200-6431-85         | FRM12.1 | 012                    | FRM12.1 |
| FF11N11                | SCY6.0  | 785-1132    | SCX2.6  | 15020        | WP01    | 200-6441-35         | SCX8.6  | 013                    | FRM11.2 |
| FF15E12                | FRW9.1  | 785-1284    | STC.742 | 15029        | WP02    | 200-6613-24         | SCX8.6  | 015                    | FRM11.5 |
| FF16M11                | FRW8.5  | 785-1284-01 | ST.536  | 15044        | WP07    | 200-6615-68         | SCX8.6  | 04                     | FRM12.1 |
| FP17513                | SCX8.6  | 785-1285    | STC.823 | 1509         | WP14    | 201-0088-92         | FRM11.5 | 05                     | FRW9.7  |
| FP25214                | SCX14.7 | 785-1485    | SCX4.6  | 1510         | WP13    | 201-0957-78         | FRM11.5 | 06                     | FRM11.5 |
| FP26511                | SCX9.5  | 785-1485-01 | SCX13.6 | 16212        | 003.7   | 201-0977-67         | SCQ10.0 | 09                     | SCA8.9  |
| FP43011                | SCX3.5  | 785-1489    | STC.638 | 16223        | 004.4   | 201-3019-33         | FRM11.0 |                        |         |
| FP46211                | FRW8.0  | 785-1489-01 | SCX4.6  | 16512        | WP09    | 201-5000-296        | SCX8.9  |                        |         |
| FP46311                | SCX4.9  | 785-1605    | STC.742 | 1661         | OSC10.2 | 201-5540-110        | SCX8.9  |                        |         |
|                        |         | 785-1978    | SCX8.0  | 16912        | 0010.5  | 201-6636-140        | SCQ6.0  | <b>AUDISCAN</b>        | OB7.7   |
| <b>AMERICAN MOTORS</b> |         | 785-1978-01 | SCX8.0  | 1738         | WP10    | 206-615-68          | SCX8.6  | 2010                   | OB7.7   |
| 26810-173              | FRM10.5 | 785-2064    | STC.742 | 17946        | WP03    | 66682-122           | 0A8.5   | 2100002001             | 0A13.2  |
| 36327-04               | FRB.4   | 785-2064-01 | STO.823 | 17947        | WP04    | 66682-144           | 0013.2  | 2100002003             | 0A12.4  |
| 38510-183              | SCX7.4  | 785-2071    | 510.823 | 17948        | WP05    | 66682-154           | FF12.6  | 2100003001             | 087.0   |
| 38510-184              | SCX438  | 785-2087    | SCQ10.0 | 17997        | WP06    |                     |         | 2205                   | 004.4   |
| 42-42683801            | FRM12.1 | 785-2087-01 | SCQ10.0 | 73603        | 003.1   |                     |         | <b>AUTOMATE</b>        | OB12.4  |
| 42-42683B04            | FR8.4   | 785-2088    | SCY8.6  | 73604        | 082.5   | <b>A TC</b>         |         | 321600000              | OB12.4  |
| MAT75-CXP              | SCX7.4  | 785-2088-01 | SCX8.6  | 75601        | 0013.2  | HW307               | SCX8.4  |                        |         |
| MAT75-TPX/A            | FRM10.5 | 785-2146-01 | ST.536  | 75614        | 0020.3  |                     |         | <b>AUTOMATIC RADIO</b> |         |
| PAC75-CXP              | SCX7.4  | 785-2154    | STC.823 | 75615        | OB11.7  |                     |         | 067-00157              | OB14.0  |
| PAC75-TPXA             | FRM10.5 | 785-2444-01 | STC.823 | 75616        | 0018.0  | <b>AUDIOTRONICS</b> |         | 067-11152              | 0012.4  |
|                        |         | 785-2493-01 | SCX8.9  | 75647        | OSC18.5 | 0560020             | SCX8.0  | 100 Series             | FRY10.7 |
| <b>AMPEX</b>           |         | 785-2494-01 | SCX13.6 |              |         | 0560030             | SCY4.6  | 135A-13042             | STC.742 |
| 265-2726               | SCX8.9  | 785-2495-01 | SCX4.9  | <b>ANSCO</b> |         | 0704                | SCQ5.6  | 135A-13147             | FRM11.0 |
| 30123                  | SOQ10.0 | 785-2496-01 | SCQ8.2  | 25310        | WP17    | 0821                | SCA10.5 | 258-40172              | FRM9.7  |
| 30137                  | SCX8.0  | 785-2538    | STC.742 | 411803       | OSC22.8 | 102449              | 0613.2  | 278-40172              | FRX9.0  |
| 30138                  | SCY8.6  | 785-2540    | ST.750  | 411817       | 002.3   | 141526401           | SCY5.2  | 285-910403             | SCA8.9  |
| 31-0001                | 009.0   | 785-2575-01 | ST.536  | 411818       | ST.365  | 141526402           | 0A4.6   | 52A-13345              | FRM11.7 |
| 31-00011               | QC8.5   | 785-2579-01 | ST.536  | 42200        | WP20    | 1420704             | SCY5.2  | 55A-5043               | FRM12.1 |
| 31-0002                | 0011.2  | 785-2676    | STC.823 | 438564       | FRF7.6  | 182264402           | FRM11.7 | 55D-5043               | FRM11.5 |
| 31-0003                | 0A9.4   | 785-2677-01 | ST.536  | 438825       | 003.1   | 182826401           | SOQ11.1 | 588-90225              | FRM11.0 |
| 31-00031               | 0A10.1  | 785-2678    | SCQ5.6  | 438827       | FRF7.6  | 186920401           | 0A6.1   | 602-004200             | SCA8.9  |
| 31-0008                | 0012.8  | 785-2678-01 | ST.536  | 438828       | 003.8   | 186926401           | 0A5.8   | 67-10178               | FRM11.5 |
| 31-0015                | FR12.0  | 785-2726    | SCX2.4  | 438853       | OSC22.8 | 188626401           | FR7.7   | 67-157                 | OB14.0  |
| 31-00151               | FR12.0  | 785-2708-01 | SCX8.9  | 438863       | ST.365  | 268.4               | OB10.1  | 67A-05116              | FRM12.1 |
| 31-0021                | 009.0   | 785-2740    | SCX4.3  | 438865       | OSC22.8 | 268.5               | 0A10.9  | 67A-10049              | FRM12.1 |
| 31-0022                | 0011.7  | 785-2746    | SCX9.5  | 438867       | 002.3   | 268.6               | 0011.2  | 67A-10178              | FR12.5  |
| 431-0003-10            | 009.8   | 785-2916    | SCQ11.1 | 449607       | 0A6.6   | 304826401           | SCQ5.6  | 67A-10338              | FRM11.5 |
| 431-0005-10            | FRM12.1 | 785-2916-01 | SCX10.7 | 449805       | 006.6   | 77120               | FRM11.7 | 67A-10493              | FRY10.7 |
| 431-0052-2             | 0014.8  | 785-2917-01 | SCQ5.6  | 449806       | 0011.7  | A200149             | 0A10.1  | 67A-10674              | .0A13.2 |
| 431-0057-1             | FR12.0  | 785-3239    | STO.823 | 449807       | 005.0   | HW307               | SCX8.6  | 67A-10846              | OB12.4  |
| 431-0057-10            | FR12.0  | 785-3240    | STC.742 | 449808       | 006.6   | HW327               | SCQ6.5  | 67A-10909              | FR13.4  |
| 431-0065-01            | FRX15.9 | 785-3240-01 | ST.536  | 449811       | 0A6.6   | T77A58              | 0A4.6   | 67A-10959              | 0612.4  |
| 431-014                | 009.0   | 785-3245    | SCX2.4  | 449873806    | 0025.0  | TT112               | OX5.9   | 67A-11143              | SCX7.4  |
|                        |         |             |         |              |         | TT116               | SCA10.5 | 67A-11148              | SCQ6.0  |

= Part of the Assy

\*\*= Kit May Not Include Tires

^ = Part of the Assy

# AUTOMATIC RADIO ... CLARION

| MFG. P/N                 | PRB NO. | MFG. P/N                 | PRB NO.  | MFG. P/N              | PRB NO.    | MFG. P/N        | PRB NO. | MFG. P/N              | PRB NO. |
|--------------------------|---------|--------------------------|----------|-----------------------|------------|-----------------|---------|-----------------------|---------|
| 67A-11250                | SCB8.1  | 2732046                  | SCQ6.7   | 71315                 | SCX12.2    | <b>BOMAN</b>    |         | <b>CAPEHART</b>       |         |
| 67A-11423                | SCX14.7 | 2732047                  | SCX8.6   | 71316                 | SCX4.9     | 11164701        | FRM9.6  | 1891003               | SCQ6.0  |
| 67A-11430                | SCX8.9  | 2732048                  | FRX1.1.0 | 71317                 | 71318      | 1332063         | SCX7.4  | 2001800077            | SCX10.7 |
| 67A-11516                | FRM9.7  |                          |          | 71318                 | SCX2.4     | 1332064         | SCX4.0  | 2027093012            | SCX8.9  |
| 67A-12175                | FRM12.1 | <b>BASF</b>              |          | 71319                 | 0A9.4      | 165005          | FRW9.2  | 2971301               | SCQ6.0  |
| 67A-12321                | FRM11.0 | 19400641                 | SCA8.9   | 71320                 | SCX13.6    | 165018          | SCX4.0  | 5610902               | FRY10.7 |
| 67A-12427                | FRM13.3 | 22580830                 | 009.8    | 71321                 | SCX4.3     | 165019          | SCX4.0  | 7100631               | 007.0   |
| 67A-12596                | OB11.7  | 22732790                 | SCX8.9   | 71323                 | 0A8.2      | 165021          | SCX4.0  | 7100632               | OB12.4  |
| 67A-1275                 | FRM12.1 |                          |          | 71882                 | SCQ8.8     | 165022          | SCX7.4  | 8891201               | SCX8.9  |
| 67A-12954                | FRM11.7 | <b>BELK STORES</b>       |          | 73013                 | SCX8.6     | 165032          | SCX7.0  |                       |         |
| 67A-13041                | SCX3.5  | 103101                   | SCX5.1   | 7572                  | WP36       | 165033          | SCX7.0  | <b>CARTAPE</b>        |         |
| 67A-13064                | SCQ5.6  | 106773                   | FRM9.6   | 770437                | SCX8.6     | 165040          | FRW8.8  | 1500083               | 069.0   |
| 67A-13345                | FRM12.1 | 773357                   | SCQ10.0  | 770438                | SCX4.0     | 232023          | SCA8.9  | 1500205               | 009.8   |
| 67A-13346                | FRM12.1 |                          |          | 772065                | 0A6.6      | 233061          | FRM10.5 | 233060                | FRY10.7 |
| 67A-13507                | SCX3.5  | <b>BELL &amp; HOWELL</b> |          | 772066                | 0A10.9     | 26010001        | SCX9.2  | 233061                | FRM10.5 |
| 67A-13585                | FRM11.7 | 011791                   | STC1.14  | 772067                | 0013.2     | 26010002        | SCX4.0  | 23462990              | 0A7.0   |
| 67A-13732                | FRM12.1 | 015226                   | ST1.48   | 772068                | SCX2.6     | 34235704        | FRW8.8  | 23463900              | 0A5.4   |
| 67A-13870                | FRM11.5 | 10089                    | WP40D    | 772069                | 0A6.1      | 34331701        | SCX7.0  | 23582340              | 0A7.0   |
| 67A-14030                | FRM11.7 | 102187                   | SCX4.0   | 772096                | 0A6.1      | 34331703        | SCX7.0  | 23582350              | 0A3.1   |
| 67A-14147                | SCX8.9  | 102188                   | SCX5.1   | 773614                | 773614     | 34891701        | SCX7.0  | 43550054              | FR8.8   |
| 67A-14856                | FRM11.5 | 102189                   | SCX9.2   | 773796                | 773796     | 538083          | FRM10.5 | 8000054               | FRM11.7 |
| 67A-14978                | FRM11.2 | 102190                   | SCX3.5   | 773878                | 773878     | 9201304         | SCX7.0  | 9300063               | SCX8.0  |
| 67A-15116                | FRM9.7  | 102772                   | SCX8.9   | 774306                | 774306     | MA3019          | SCX4.0  | 9300064               | SCX4.0  |
| 67A-1516                 | FRM12.1 | 103069                   | SCX14.7  | 775079                | 775079     | MA3021          | SCX7.4  |                       |         |
| 67A-15254                | SCY2.2  | 103086                   | SCX4.9   | 800129                | 800129     | MR5             | FRW9.2  |                       |         |
| 67A-15272                | SCX7.0  | 103087                   | SCX8.9   | 80054                 | 80054      |                 |         | <b>CHANNEL MASTER</b> |         |
| 67A-15288                | SCX8.0  | 103087                   | SCX8.9   | 800544                | 800544     |                 |         | 1089                  | FRM10.2 |
| 67A-157                  | OB14.0  | 103089                   | 0A4.2    | 86630                 | 86630      |                 |         | 117239                | 0A10.9  |
| 67A-15765                | FRM11.0 | 103371                   | SCX8.9   | 86827                 | 86827      | A102442         | SCA14.1 | 1244                  | FRM11.0 |
| 67A-15916                | OB12.4  | 103406                   | SCX8.6   | 86850                 | 86850      | A109586         | FRM13.3 | 1391                  | SCQ10.0 |
| 67A-15955                | FR12.5  | 103537                   | SCX4.0   | 87093                 | 87093      | A110684         | FRM15.2 | 1407                  | SCA8.9  |
| 67A-16194                | FRY10.7 | 104625                   | SCQ10.0  | 9487                  | 9487       | A114446         | FRM15.2 | 2111202               | SCX4.9  |
| 67A-16279                | 0A8.5   | 10552                    | WP32     | 9488                  | 9488       | A200149         | 0A10.9  | 21V7022               | FRX9.7  |
| 67A-16410                | FRM9.7  | 10578                    | WP32A    | 9888                  | 9888       |                 |         | 6717                  | OB9.4   |
| 67A-16698                | FRY10.7 | 106151                   | SCX9.2   | QDB0058               | QDB0058    |                 |         | 8700035               | SCX8.9  |
| 67A-16732                | FRM11.5 | 106364                   | FRM12.1  | QDB0107               | QDB0107    | <b>BUICK</b>    |         | 870037                | SCX8.9  |
| 67A-16942                | SCB8.1  | 107181                   | SCX8.9   | QDB0108               | QDB0108    | 7931636         | SCB16.6 | A261                  | FRM10.2 |
| 67A-16943                | SCX7.0  | 11002                    | WP33A    | M60109                | M60109     |                 |         | C256                  | SCX4.9  |
| 67A-16992                | SCX3.5  | 11035                    | WP33     | QDB0110               | QDB0110    | <b>CADILLAC</b> |         | C257                  | SCA10.5 |
| 67A-17229                | FRM10.5 | 12228                    | WP23     | QDB0111               | QDB0111    | 385183          | SCX7.4  | D521400019            | FRW9.7  |
| 67A-17335                | FRM9.7  | 12497                    | WP35A    | QDB0113               | QDB0113    | 385184          | SCX4.3  | F594                  | OB16.4  |
| 67A-17464                | FRY10.7 | 12830                    | WP25     | QDB0114               | QDB0114    | 385232          | 0A4.2   | J839                  | FRM10.2 |
| 67A-18374                | FRY10.7 | 1412464900300            | 0A8.5    | R448041               | R448041    |                 |         | K252                  | SCX11.8 |
| 67A-18614                | FRM11.0 | 1412562T03200            | SCY9.2   | R448192               | R448192    | <b>CALIFONE</b> |         | K253                  | SCX7.4  |
| 67A-18760                | FRY10.7 | 16707                    | WP34     | X62826                | X62826     | 1725-81111      | 0A10.9  | K254                  | SCX4.3  |
| 67A-18810                | FRM9.7  | 19624                    | 008.2    | X62828                | X62828     | 3-363           | GR.475  | K859                  | 0A9.4   |
| 67A-19447                | FRM12.1 | 20071882                 | SCX8.6   |                       |            | 30-107-4        | MS17    | R490                  | SCX8.0  |
| 67A-19497                | FRM13.3 | 21898                    | WP24     | <b>BELL SOUND SYS</b> |            | 60-144-61       | OB9.4   |                       |         |
| 67A-19671                | SCX4.3  | 2265                     | SCQ10.0  | 10                    | 10         | 62-144-69       | OB13.2  | <b>CHEVROLET</b>      |         |
| 67A-19752                | SCA11.1 | 22660                    | WP26     | 17                    | 17         | 62-178          | SCA14.1 | 7304589               | OB12.4  |
| 67A-19819                | FR8.8   | 24047                    | FF6.2    | 22019                 | 22019      | 62-209-5        | SCA12.0 | 7312439               | SCA12.0 |
| 67A-19933                | FRM9.7  | 26011                    | 0C12.1   | 42007                 | 42007      | 62-209-6        | 0A7.0   |                       |         |
| 67A-20184                | SCX7.0  | 26019                    | 0012.1   |                       |            | 62-209-7        | SCX12.2 |                       |         |
| 67A-20185                | SCY4.6  | 26056                    | 009.0    | <b>BELSONA</b>        |            | 62-235          | SCY7.0  | <b>CHRYSLER</b>       |         |
| 67A-20269                | FRM11.2 | 26058                    | WP40     | 638858                | 638858     | 62-236          | SCY8.2  | 310410405403          | SCX8.6  |
| 67A-20515                | SCX8.9  | 27313                    | STC1.14  | 948037                | 948037     | 63-0069         | 0A10.9  | 4222459               | SCY16.3 |
| 67A-20516                | SCY4.6  | 27947                    | WP27     |                       |            | 662-0014-07     | FRX9.0  | 4242561002            | FRM11.7 |
| 67A-20725                | OB10.9  | 28728                    | WP32B    | <b>BEL TEK</b>        |            | 662-0014-20     | SCX9.5  | 424683801             | FRM11.7 |
| 67A-20873                | FRX9.0  | 29451                    | 007.4    | 34840017              | 34840017   | 662-0018-02     | SCX8.6  | 42A40969F01           | SCX16.0 |
| 67A-20963                | SCX8.6  | 31023                    | GT13.7   | 34863001              | 34863001   | 662-0018-02     | SCX8.6  |                       |         |
| 67A-20966                | SCY4.2  | 31341                    | FR8.9    |                       |            | 662-10          | SCX8.6  | <b>CIPHER</b>         |         |
| 67A-21192                | SCB8.1  | 31687                    | VT13.3   | <b>BIC</b>            |            | 662-10-1        | SCX8.9  | 20310                 | 0012.4  |
| 67A-21193                | SCX7.0  | 3233                     | WP41     | 3713001               | 3713001    | 662-11-14       | SCX4.6  | 26014                 | 0A12.4  |
| 67A-21380                | SCB24.2 | 32858                    | OSC10.2  | 3713004               | 3713004    | 662-11-4        | SCX9.2  | 531010                | 0A11.7  |
| 67A-21450                | SCX9.2  | 33979                    | 0012.4   | A7                    | A7         | 662-11-5        | SCX4.3  | 6733301               | 0013.2  |
| 704-0031                 | SCX8.9  | 34988                    | WP33     | <b>BIGSTON</b>        |            | 662-12-1        | SCA8.9  | 770069                | 0A11.7  |
| 704-0032                 | SCY4.2  | 36057                    | ST.719   | 12510044              | 12510044   | 662-12-16       | SCX8.6  |                       |         |
| 704-0520                 | FRX9.0  | 37885                    | 009.8    | 12510199              | 12510199   | 662-12-3        | STC.742 | <b>CLARION</b>        |         |
| 740-520                  | FR8.8   | 40948                    | FR7.5    |                       |            | 662-14          | 0X5.9   | 10036501              | SCX3.5  |
| 79-47                    | FRM10.5 | 42885                    | OB10.1   | <b>BLA UPUNKT</b>     |            | 662-14-1        | SCX3.2  | 10036504              | SCY14.7 |
| 833-632120               | FRM12.1 | 42954                    | OSC10.2  | CR17140580            | CR17140580 | 662-14-2        | SCY5.2  | 602000200             | 0A13.2  |
| 833-63230                | FR13.4  | 43888                    | FR8.9    | CR17140590            | CR17140590 | 662-14-20       | FRX9.5  | 602000500             | FRM12.1 |
| 833-7947                 | FRY10.7 | 44459                    | FR12.6   | CR47140010            | CR47140010 | 662-14-7        | FRX9.0  | 602000600             | FR12.5  |
|                          |         | 44780                    | OSC10.2  | CR47140020            | CR47140020 | 663-0086-00     | SCX9.2  | 6020012               | SCB28.2 |
| <b>AZUSA</b>             |         | 45684                    | ST.720   |                       |            | 663-37          | 0A12.4  | 6020013               | SCQ6.5  |
| 5610902                  | FRM10.5 | 46128                    | SCX7.4   | <b>BOLEX</b>          |            | 663-81          | 0A10.9  | 6020014               | SCQ6.5  |
| GB077080T9               | FRM9.2  | 4668                     | WP35     | 2593                  | 2593       | 663-86          | SCX9.2  | 602001401             | SCX7.0  |
|                          |         | 4875                     | WP32A    | 3233                  | 3233       | 663-87          | SCX7.0  | 602001500             | SCX9.5  |
|                          |         | 4877                     | WP35     | 3700990               | 3700990    | 663-88          | SCQ2.5  | 602001600             | SCX2.9  |
| <b>BANG &amp; OLDFEN</b> |         | 5265                     | WP36A    | 37930                 | 37930      | 709252          | FRX9.7  | 602001700             | SCX3.2  |
| 2732018                  | FRX35.1 | 611332                   | WP28     | 3956                  | 3956       | 88-0111-00      | SCX8.9  | 602001900             | FRM10.2 |
| 2732027                  | 0A10.1  | 611333                   | WP29     | 750072                | 750072     | BE1             | OB11.7  | 602002100             | FRM11.7 |
| 2732030                  | FRX35.1 | 705742                   | 0010.1   | BP5243                | BP5243     | 8E11            | OB12.4  | 602002200             | FRW9.2  |
| 2732033                  | 0A6.1   | 705762                   | 0010.1   |                       |            | BE13            | 0014.0  | 602002601             | SCX9.2  |
| 2732042                  | FRM12.7 | 709679                   | FR12.6   |                       |            | BE14            | OB13.2  | 602002602             | SCX9.2  |
| 2732044                  | SCQ6.7  | 71314                    | SCA7.5   |                       |            | BE15            | 0014.0  | 602002700             | FRM10.2 |

\* = Replacement Belt

= Kit May Not Include Tires

= Part of the Assy

**CLARION ... CRAIG**

| MFG. P/N             | PRB NO.   | MFG. P/N          | PRB NO. | MFG. P/N     | PRB NO.  | MFG. P/N | PRB NO.  | MFG. P/N     | PRB NO.  |
|----------------------|-----------|-------------------|---------|--------------|----------|----------|----------|--------------|----------|
| 602002001            | SQX9.5    | <b>CONCERTONE</b> |         | 0080084      | SCX8.9   | 2405306  | SCX8.6   | 350956       | SCX4.3   |
| 602003200            | SCA10.0   | 06-0008           | OM 0.1  | QDB0097      | OA5.8    | 2408200  | OC9.0    | 3510170      | SCX9.2   |
| 602003400            | SCX14.7   | 06-9009           | OB13.2  | 0080100      | FRM13.3  | 2408202  | SOAI2.5  | 351079       | SCQ10.0  |
| 602004000            | SC06.7    | 06-0015           | QA6.1   | QQB0114      | SCX4.0   | 2422     | SCX8.6   | 3511116      | SCQ6.5   |
| 602004100            | \$0)(13.6 | 08-0017           | Q812.4  | QDB0117      | \$QX9.2  | 2505411  | SCX5.1   | 3511117      | SCQ10.7  |
| 602004200            | SCA8.9    | 06-0036           | OA9.0   | QDB0118      | SCX14.7  | 2602185  | SQX9.2   | 3515052      | SCX3.5   |
| 602004201            | SCA8.9    | Q6-Q038           | OA7.0   | 0069120      | 0013.2   | 2602301  | QA8.2    | 3515053      | SCX7.4   |
| 602004300            | SCX3.5    | 06-0038-0         | 087.6   | 0050123      | SCX9.2   | 2603084  | SCX8.6   | 3516068      | SCX3.5   |
| 602004900            | SCX13.6   | 2110              | SCX9.5  | QD80126      | SCX8.9   | 2605042  | SCX4.3   | 3516075      | SCX7.4   |
| 602005000            | SCX14.0   | 27-136            | OB10.1  | 0DB0128      | OA8.2    | 2605047  | SCX4.3   | 44248        | SCX11.8  |
| 602405100            | SQY7.0    | 27-142            | OA10.1  | 0080133      | SQX9.2   | 2606136  | OQ9.8    | 4GP25NA      | FRM15.2  |
| 602005300            | SCY4.0    | 400-157           | WBO5    | QDB0134      | FRM13.3  | 2606155  | SCX5.1   | 4MM641       | FRM14.0  |
| 602005402            | SCX14.0   | 400-159           | OA10.9  | QD60141      | FRM9.6   | 2606159  | SCX4.3   | 8133166      | SCX4.3   |
| 602005500            | SCX8.0    | 4001-106          | OC10.9  | 0080142      | OA5.4    | 2607185  | OC9.8    | 91012401     | FR15.2   |
| 602005602            | SCY6.3    | 4001-121          | SC812.5 | QDB0143      | SCY7.0   | 2607190  | SCX5.1   | AI ON28612B  | SCX13.6  |
| 602005900            | SCY8.0    | 700-013           | 0810.1  | QDB1077      | SC B24.2 | 2613218  | SCX4.3   | A1 ON286060  | FRM12.1  |
| 602005901            | SCY8.0    | 700-013.3         | FR17.0  | QQBA0001     | QA5.8    | 2613234  | SQQ6.5   | Ai ON28606B  | FRM12.1  |
| 602006200            | SCX7.4    | 700-014           | OA9.4   | QPBK0001     | OB7.0    | 2613235  | SCX4.3   | A1 ON286(18A | FRM12.7  |
| 602006300            | SCX9.5    | 700-022           | OA9.4   | Q05K0003     | SCX8.6   | 2614122  | SCX8.6   | Ai ON28616A  | SCX9.2   |
| 602006501            | SCX8.4    | 7000B             | 0810.1  | QDBOB1       | SCX8.9   | 2614129  | SCX3.5   | A1 ON28617A  | OA4.0    |
| 602006800            | SCX15.0   | 810-063.0         | OC12.8  | QDBOB5       | FRM12.7  | 2614265  | SCX3.5   | A1 ON286200  | FRW8.5   |
| 602906900            | SQX3.2    | 810-063.1         | 007.0   | QDBT0008     | SCQ11.1  | 2615159  | SCX8.6   | C501/2       | QO14.4   |
| 602007000            | SCX14.0   | 810-063.2         | 006.1   | QDBT0009     | OA4.0    | 2615165  | SCY2.9   | CNT008       | FRW7.7   |
| 602007100            | SCX3.2    | 810-110           | 0A11.7  | QD8T0010     | OA4.0    | 2616036  | SCQ6.5   | CNT013       | OA3.1    |
| 602007102            | SCX3.2    | <b>CONCORD</b>    |         | 0130K0001    | SCX8.4   | 2616185  | SCA8.9   | CNT036       | OA8.2    |
| 602007590            | SCX2.6    | 605701            | 0810.1  | 000K0003     | ST.750   | 2618185  | SCX7.0   | CNT066       | FRM6.1   |
| 602007800            | SCX16.0   | 7014              | OA9.4   | Q00K0005     | SCX4.9   | 2620102  | QA5.8    | K34930A      | FRM9.0   |
| 602007900            | SCX15.5   | 830276            | OC9.8   | Qp0K0006     | SCX2.6   | 2621068  | SCX8.6   | GU45715      | OSO4.7   |
| 602007901            | SCX3.5    | 830288            | OC10.5  | ODQK0026     | SCX2.4   | 2622971  | OA6.1    | H221209      | FRW8.5   |
| 602008000            | SCX3.5    | 83063             | QC9.0   | REF109       | OB7.0    | 2622072  | FRW8.5   | 11261208     | SCX8.0   |
| 602008200            | SCX15.2   | 83074             | OA9.4   | REF142       | 0013.2   | 2625105  | SCX4.3   | H261209      | FRW10.7  |
| 602009101            | SCX15.0   | 83097             | 0611.7  | R EF30       | FR12.5   | 2626095  | SCX7.4   | H341298      | FRY10.7  |
| 602009102            | SCX15.0   | 90740020          | FRM11.5 | REF31        | SCX8.9   | 2629095  | FRM9.6   | H424208      | SCX8.0   |
| 602009202            | SCX2.9    | 90740520          | FR12.5  | REF55        | OB7.0    | 2630440  | SCA8.9   | H424209      | FRW8.5   |
| 602009203            | SQX2.6    | 90749920          | FR12.5  | REF80        | SCX8.9   | 2633069  | SCX8.6   | H460208      | FRW7.0   |
| 602009204            | SCX2.6    | 9401206           | SCX8.6  | REF95        | SCX8.9   | 2634051  | SCX9.2   | H460209      | SCX7.4   |
| 602009700            | SCX15.2   | M1024             | QB10.9  | REF96        | SCX8.9   | 2634052  | SCX7.4   | H461208      | SCX8.9   |
| 602009701            | SCX15.2   | M1 02C            | OA9.4   | RQ2245       | OB7.0    | 2703204  | SCAI2.5  | H461209      | SCY6.0   |
| 602009802            | SCX2.9    | M1073             | 089.0   | RQ2365       | OA4.0    | 2704176  | SV5.1    | H464208      | FRWI 0.1 |
| 602010300            | SCX15.2   | M108              | QB12.4  | R04205       | OA4.0    | 2704204  | SCAI2.5  | J100208      | SCX9.2   |
| 602010310            | \$CX15.2  | M109              | 0810.1  | RS2465       | OA4.0    | 2705437  | OA8.2    | J101208      | \$CY4.6  |
| 602010801            | SQX14.0   | M1092             | SCQ11.1 | VPV8         | FR14.5   | 2706115  | SCY5.2   | J103208      | SCY3.5   |
| 60205402             | SCX14.0   | M1139             | SCX2.6  | <b>CRAIG</b> |          | 2706130  | \$OX8.6  | J103209      | SCX7.0   |
| 658010328            | SCX7.4    | M150              | OA5.8   | 002600101    | FR8.8    | 2708151  | OA8.2    | J105208      | FRM9.6   |
| 658010329            | \$CY4.2   | M342              | FR8.8   | 0026030084   | SCX8.9   | 2708169  | SCX8.9   | J105209      | SQY5.2   |
| 658010430            | \$CX8.0   | M403              | QA10.9  | 00260600155  | \$OX14.7 | 2709296  | SCX14.7  | J3143083     | FRW9.1   |
| 658010434            | \$CY4.0   | M404              | OA7.4   | 0026060159   | SCX4.3   | 2712033  | QX5.5    | J424208      | SCX8.0   |
| 658912964            | SCX9.2    | M569              | VR20.3  | 002606159    | SCX4.3   | 2801022  | SQX11.8  | J425208      | SC011.1  |
| 658013876            | SQX16.0   | M61               | SC011.1 | 002606179    | SCX4.9   | 2801043  | SCX4.3   | J425209      | SCY7.6   |
| <b>CODE-A -PHONE</b> |           | M656              | OA8.2   | 0026067019   | SCX14.7  | 3102943  | FRM15.2  | J500208      | SCY4.2   |
| 3001751              | STC1.55   | M77               | OA12.4  | 0026070110   | SCX14.7  | 3128177  | SCA10.0  | J551209      | SCY5.2   |
| 3002178              | ST2.36    | M786              | OA10.1  | 0026070179   | SCX4.3   | 3134059  | FRM10.2  | J580206      | SCX8.9   |
| 3002191              | STC1.77X  | M796              | SCX9.2  | 0026070185   | OC9.8    | 3135049  | FRW8.5   | J580209      | SCX3.2   |
| 3002348              | ST2.30    | M80               | OC12.4  | 0026070190   | SCX14.7  | 3136033  | FRW8.5   | J580210      | SCY5.2   |
| 3002386              | ST1.86    | M819              | 089.4   | 0026080222   | OA8.5    | 3137041  | FRM8.0   | J580211      | SCY3.5   |
| 3002437              | ST.937    | M887              | OB10.1  | 0026080224   | SCX14.7  | 3137046  | FRY8.4   | K349012      | FR15.9   |
| J00017               | OA14.8    | M891              | SCQ11.1 | 0026080234   | SCX4.3   | 3143083  | FRW8.5   | KRA36052     | SCX8.9   |
| J00018               | OB5.0     | M892              | OA4.6   | 0026090415   | SCX4.3   | 3145015  | FRW10.1  | MC9300       | SCX3.5   |
| J00019               | 088.0     | M9                | FRM9.6  | 0026090738   | SCX4.0   | 3147033  | FRM9.7   | N281013      | FRM12.1  |
| J00065               | SCA8.6    | M92               | OC9.8   | 0026110075   | OA8.5    | 3148059  | FRY10.0  | N28604       | FRM12.7  |
| 40080                | ST.937    | M93               | OA10.9  | 0026120313   | OA9.4    | 3149066  | FRMii .7 | N286040      | FRM12.1  |
| J09081               | ST2.66    | M943              | OA1i .7 | 0026130218   | SCX4.3   | 3205     | FRM12.7  | N28606       | FRM12.1  |
| J09083               | SCX6.2    | M98               | OA14.0  | 0026140122   | SCX8.9   | 3209064  | FRM10.5  | N286066      | FRM12.1  |
| J09085               | OA6.6     | MD4081            | OB7.0   | 0026150159   | SCX8.6   | 3210     | FRM11.5  | N28608       | FRM12.7  |
| J00094               | SQQ6.5    | MD4081 H          | OC9.8   | 0026150165   | SCX4.0   | 3210080  | FRM11.5  | N286080      | FRM12.7  |
| J00095               | SCA5.4    | MD4150            | 0810.9  | 0026180159   | SCX4.3   | 3211103  | FRM10.5  | N28610       | OA5.4    |
| J09114               | SCX7.4    | MD4579            | OB7.0   | 0026180185   | SCX7.0   | 3211116  | FRM12.1  | N28611       | OA8.2    |
| J09147               | SCQ6.7    | MD4599            | SCA8.9  | 0026200101   | FRW8.5   | 3212157  | FRM11.2  | N28616       | SQX9.2   |
| J90195               | SCY6.5    | MD4788            | SCQ6.5  | 0026220070   | FR8.8    | 3215063  | FRM10.2  | N28617       | OA4.2    |
| J00196               | SCY6.7    | MD5150            | OC9.8   | 0027080151   | OA4.6    | 3216085  | FRM9.2   | N28620       | FRM13.3  |
| P00881               | ST1.86    | QDB0001           | SCX8.6  | 0031340059   | FRM10.2  | 3303373  | FRM12.1  | PN041        | SCX4.9   |
| P00995               | ST.937    | QDB0002           | SCQ11.1 | 2101003      | SCX11.8  | 3303375  | FRM11.0  | PN060A       | SCX4.6   |
| <b>COLUMBIA</b>      |           | QDB0009           | OA4.6   | 2102002      | FR8.8    | 3304109  | FRY10.7  | PN219        | OC9.0    |
| 40021                | OA13.2    | 0080017.1         | FF15.0  | 2102003      | FR8.8    | 3305190  | FRM10.5  | PN230        | FR15.2   |
| 49087                | OC10.5    | QQB0023           | OA8.2   | 21020318     | SCQ11.1  | 3307039  | FR12.5   | PN247        | FRM9.7   |
| 792162               | SCB12.5   | 0080024           | OB10.9  | 2107318      | SCX5.1   | 3401     | FRY10.7  | PN248        | OB19.9   |
| 80023                | SCB12.5   | QQB0025           | OB7.6   | 2107319      | SCX7.0   | 340131   | FRY-10.7 | PN280        | FRM9.0   |
| 808166               | SCB12.5   | QDB0034           | OB10.9  | 2201         | SCX8.6   | 3402     | FRY10.7  | PN408        | SCX9.5   |
| 89818                | 0514.0    | QDB0050           | SCQ11.1 | 2401360      | SCX8.6   | 3402307  | SCX8.6   | R448010      | OC14.0   |
|                      |           | QDB0055           | OA9.4   | 2401361      | SCA8.9   | 3403     | FRY10.7  | R448036      | FRW12.6  |
|                      |           | 90B0058           | SCQ11.1 | 2402250      | OA7.0    | 3403119  | FRY10.7  | R448042      | SCX13.6  |
|                      |           | QQB0065           | FRM12.7 | 2402288      | SCA8.9   | 3404     | FRY10.7  | R448046      | SCX8.0   |
|                      |           | QDB0083           | OA9.4   | 2402306      | SCX8.6   | 3434     | FRQ11.2  | R448048      | SCX4.3   |
|                      |           |                   |         | 2402307      | SCX8.6   | 3506223  | SCQ11.1  | R448054      | FR16.9   |
|                      |           |                   |         | 2405250      | OA7.0    | 3506224  | SCX4.3   | R448059      | SCX9.5   |

Mfg # to PRB #

= Part of the Assy

\*\*\* = Kit May Not Include Tires

= Part of the Assy

# CRAIG ... ECG

| MFG. P/N         | PRB NO. | MFG. P/N             | PRB NO. | MFG. P/N          | PRB NO.  | MFG. P/N        | PRB NO.  | MFG. P/N   | PRB NO.  |
|------------------|---------|----------------------|---------|-------------------|----------|-----------------|----------|------------|----------|
| R448091          | SCX11.8 | R831111              | SCX4.3  | DEJUR             |          | 143016          | SCQ5.6   | 8TR8340    | 0A4.6    |
| R448166          | SCX4.9  | R911005              | 0A5.4   | 08440081          | 004.0    | 143017          | SCX4.3   | 8TR8355    | FRM9.7   |
| R448192          | SCX8.9  | R911006A             | 0A7.0   | 1044135           | 008.5    | 143503          | SCY9.0   | <b>ECG</b> |          |
| R448214          | SCX4.3  | R945014              | 0A9.4   | 104448            | 05D7.1   | 143521          | ST.999   | CR1000B    | FRW12.6  |
| R448408          | SCX4.3  | R958320              | SCX4.3  | 24457             | WP46     | 143522          | ST.585   | CR1001B    | FRW12.6  |
| R44841           | SCX4.9  | R958323              | 0A6.1   | 81004453          | 0012.8   | 144048          | SCX4.9   | CR1002B    | FRW12.6  |
| R65101           | SCX2.6  | R958337              | SCX8.6  | 8100453           | 0012.8   | 145022          | STC.975  | CR1003B    | FRW12.6  |
| R651015          | STC.742 | <b>CURTIS MATHES</b> |         | <b>DELCO</b>      |          | 145337          | STC.975  | CR1004B    | FR11.9   |
| R655009          | SCX8.6  | 018494028            | 0A7.0   | 1222760           | 0A13.2   | 154411          | FRM7.0   | CR1005B    | FR11.9   |
| S180080          | FRM9.2  | 018494034            | SCX4.3  | 1223664           | SCA12.5  | 178090          | SCA3.2   | CR1006B    | FRW12.0  |
| S604208          | FRX9.4  | 144259.              | SCA3.0  | 1223674           | SCX13.6  | 651270          | SCX5.1   | CR1007B    | FRW12.0  |
| S609208          | FRW9.7  | 144260               | SCX8.6  | 1224370           | SCX7.4   | 651277          | SCX8.9   | CR1008B    | FRW12.0  |
| S680065          | FRM10.2 | 144263               | ST1.160 | 1224554           | SCX8.4   | 651290          | SCX4.0   | CR1009B    | FRW12.0  |
| T100039          | SCX10.7 | 144267               | SCQ9.8  | 1224876           | SCX8.9   | 877519          | FRM8.0   | CR1010B    | V752     |
| T180058          | SCX8.9  | 146967               | FRW12.6 | 1226135           | SCX9.2   | <b>DOKORDER</b> |          | CR1011B    | FRW12.0  |
| T601090          | SCQ6.5  | 146968               | FRW12.6 | 1226670           | SCX9.5 & | 96300030        | OB17.2   | CR1012B    | FRW12.6  |
| T608209          | SCX8.9  | 146969               | FRW12.6 |                   | SCX4.9   | T25755171       | SCX4.0   | CR1013B    | FRW12.6  |
| T612208          | SCX7.4  | 147756               | SCX2.9* | 1227785           | SCX9.5   | T25755267       | SCY8.6   | CR1014B    | FRW12.6  |
| T617208          | SCX10.5 | 147916               | SCB14.0 | 124499            | 0A10.1   | <b>DORO</b>     |          | CR102      | V758     |
| T617209          | SCX3.5  | AUK9000E             | FRY2.9  | 16002827          | SCX12.2  | T45216001       | SCQ6.0   | CR103      | V760     |
| T622208          | SCX9.2  | AV00073              | SCA10.0 | 16005603          | SCA10.5  | T45625001       | SCX8.6   | CR104      | V755     |
| T631208          | SCQ11.1 | AV00075              | SCA10.0 | 16019626          | SCX9.2   | <b>DUAL</b>     |          | CR105      | V753     |
| T639209          | FRX9.7  | EW02X0953            | ST1.165 | 16025182          | SCX7.0   | 226258          | SCX7.4   | CR1051B    | SCX8.6   |
| T640208          | SCX10.5 | VDV0020              | SCA13.2 | 160288540         | SCX7.0   | 226259          | 0X5.5    | CRi 052B   | OX5.5    |
| T681208          | SCX7.4  | VDV0072              | SCB14.0 | 16116746          | SCX7.0   | 226259          | FRA19.6  | CR1053B    | SCX3.2   |
| T684208          | SCA9.2  | VDV0074              | SCA3.0  | 7298842           | SCX7.0   | 234435          | 0X5.9    | 0R1054E3   | SCX2.9   |
| T687208          | SCX14.7 | VDV00741             | SCA3.0  | 7304589-          | SCA14.1  | 235134          | SCA10.5  | CP1055B    | SCX4.9   |
| T688208          | SCX9.2  | VDV0075              | SCX8.6  | 7312439           | SCA12.0  | 235135          | SCA12.0  | CR1056B    | SCY3.2   |
| T688209          | SCA6.7  | VDV0076              | OX5.5   | 7931636           | SCB16.6  | 235471          | SC06.7   | CR1057B    | SCY8.6   |
| T740208          | SCY9.0  | VDV0092              | SCQ9.8  | 7933447           | SCA8.6   | 240253          | FRY10.0  | CR10588    | SCY3.2   |
| T740209          | SCX4.3  | VDV0094              | FRW12.6 | <b>DENON</b>      |          | 242338          | SCX7.4   | CR106      | V754     |
| W120208          | FRW8.0  | VDV0101              | SCX3.2* | 4230043008        | SCQ2.2   | 246084.         | SCX5.1   | CR1060B    | SCX8.0   |
| W150208          | SCX7.4  | V0V0120              | SCC12.1 | 4230044007        | SCQ4.0   | 247689          | FRA19.6  | CR1061 B   | SCX4.0   |
| W360208          | SCX8.6  | VDV0121              | FR11.9  | 4230044023        | SCQ4.0   | 260928          | FRM9.0   | CR1062B    | SCX3.5   |
| <b>CRANWOOD</b>  |         | VDV0122              | SCA4.5  | 4230044036        | SCX2.6   | 261921          | FRX16.3  | CR1063B    | SCY7.5   |
| 171131032        | FRM11.5 | VDV0123              | SCA13.2 | 4230044036        | SCY3.2   | 269539          | FRW9.2   | CR1064B    | SCY4.2   |
| 171131040        | FR8.8   | VDV0124              | SCY6.3  | 4230044049        | SC04.0   | 270378          | FRW9.1   | CR1065E3   | SCY4.2   |
| <b>CRESCENT</b>  |         | VI:A/0127            | SCX8.6  | 4230047004        | SCB4.2   | 279582          | FRW19.5  | CR1066B    | SCY7.5   |
| 3935             | W03     | VDV0130              | SCX3.5  | 4230047004        | SCB4.2   | 7100631         | FRY25.0  | CR1067B    | SCY5.0   |
| <b>CRESTWOOD</b> |         | VDV0216              | SCQ6.5  | 4230048002        | SCQ4.3   | 7100632         | 007.0    | CR1068E3   | SCY3.5   |
| 904048           | 009.8   | VDV0217              | SCX8.6  | 4230050004        | SCA5.6   | PU48967B        | OB12.4   | CR1069B    | SCQ6.5   |
| 904049           | 008.5   | VDV0218              | SCY3.2  | 4230056011        | SCQ4.6   | PU48967B        | ST1.113  | CR107      | V759     |
| <b>CROWN</b>     |         | VDVS0012             | FRW12.6 | 4230057007        | SCQ3.2   | <b>DUKANE</b>   |          | CR108      | V757     |
| CTR320           | 0A6.1   | VDVS0013             | SCB14.0 | 4230058006        | SCQ3.0   | 15203           | 008.5    | CR109      | V761     |
| CTR5000          | OB10.9  | VDVS0018             | FR11.9  | 4230061006        | SCB3.8   | 15208           | FR2.0    | CR110      | V763     |
| CTR5050          | OB10.9  | VDVS0019             | SCC12.1 | 4238027000        | SCQ3.2   | 15210           | 0A9.0    | CR11018    | SCA3.0   |
| CTR5400          | OB9.4   | VDVS0020             | SCA13.2 | 4238033007        | FRX5.1   | 15211           | 008.5    | CR1102E3   | SCA3.0   |
| CTR6550          | 0A10.9  | VDVS0022             | SCB14.0 | 4240043008        | SCQ2.2   | 15212           | 0A4.0    | CRii 03B   | SCA13.2  |
| CTR9100          | SCX2.4  | VDVS0023             | SCY7.5  | 5334411501        | SCX15.5  | 15213           | 008.5    | CR11104    | SCB12.5  |
| CTR9650          | SCX2.4  | VDVS0024             | SCY4.2  | 9300636007        | SCX16.0  | 15216           | 0A9.0    | CR1106B    | SCA3.0   |
| CTR9650F         | 0A6.1   | VOVS0029             | FRW12.0 | 9300637006        | SCX4.0   | 15219           | 0A10.1   | CR1107B    | SCA4.5   |
| CTVV5950         | OB10.9  | VDVS0032             | SCY7.5  | 9300728009        | SCX14.5  | 15221           | 03017.7  | CR111      | V762     |
| CVA5001          | OB9.4   | VDVS0033             | SCY5.0  | 9400019003        | SCX15.2  | 15222           | 0014.0   | CR1112     | V764     |
| CVA5002          | 0A10.9  | VDVS0034             | SCY4.0  | 9400158003        | SCX15.2  | 15223           | 0010.1   | CR11151B   | SCB10.5  |
| D701032A         | 0A8.5   | VDVS0122             | SCA4.5  | 9400413502        | SCX15.5  | 15228           | 0A9.0    | CR1152B    | FRX6.7   |
| D801020          | 0A6.1   | VXP0174              | ST1.160 | 9450001303        | SCX15.2  | 15231           | 0011.2   | CR1153B    | SC B9.5  |
| D801021          | 0A4.0   | VXP0174              | VA23    | 9470006703        | SCX15.5  | 15232           | 0010.i   | CRii 54B   | SCB6.9   |
| 0904304          | 0A8.5   | VXP0213              | ST.752  | 9500001005        | SCX3.5   | 15234           | 0B7.7    | CR1155B    | SCQ6.5   |
| D904331          | 087.0   | VXP0213              | VA200   | 9J141071          | SCY7.5   | 15237           | 0010.5   | CR1201 B   | SCC12.1  |
| KL903            | ST.536  | VXP0329              | ST1.330 | 9J180372          | FRW9.1   | 15243           | 0B7.7    | CR1202E3   | SCB14.0  |
| M510015F30       | 0A7.4   | VXP0329              | VA20    | 9J191471          | SCY9.0   | 15247           | 0B6.4    | CR1251B    | SCB14.0  |
| R301239A         | WB02    | VXP0331              | ST1.230 | 9JT415697         | SCY3.5   | 15255           | 0B5.6    | CR1252B    | SCA9.6   |
| R5012051         | FF11.0  | VA25                 | VA25    | 9JT415698         | FRX10.5  | 15258           | 0B8.5    | CR1253B    | SCB14.0  |
| R633026A         | OB10.1  | VXP0344              | ST1.330 | 9JT416307         | SCY4.6   | 59462           | OSA4.5   | CR1254E3   | SCA9.6   |
| R633028          | FF11.0  | VXP0344              | VA26    | 9JT416764         | SCY4.4   | 5948042         | SCX8.4   | CR1351B    | SCA14.1  |
| R651010          | SCX2.6  | VXPS0054             | ST1.370 | 9JT416861         | SCY4.4   | 62019           | FR11.8   | CR1401 K   | VKT18**  |
| R651015          | STC.742 | VXPS0054             | VA28    | S334411501        | SCX15.5  | 62040           | OSA4.5   | CR1403K    | VKT137** |
| R651027          | 0A8.2   | VX20076              | VB6     | <b>DICTAPHONE</b> |          | 62141           | .0SA4.5  | CR1404K    | VKT85**  |
| R655009          | SCX8.6  | VXZS0005             | VB1     | 122501            | 0A9.0    | 65009           | 0A4.0    | CR1406K    | VKT88**  |
| R7001316         | SCX8.6  | <b>DAEWOO</b>        |         | 124499            | 0A10.1   | 65019           | FRM7.5   | CR1407K    | VKT165** |
| R7001317         | OB7.0   | 97S446500            | VPR17   | 132384            | FRM9.2   | 7009            | OX5.9    | CR1451 K   | VKT113** |
| R7001335         | SCX8.6  | 97S5500600           | SCA4.5  | 136138            | ST.999   | 75032           | SCX8.6   | CR1480K    | VKT161** |
| R701.032A        | 0A8.5   | 9785501400           | SCA9.2  | 142265            | ST.585   | 8030            | STC1.057 | CR1462K    | VKT160** |
| R744023A         | 0A6.1   | 97SA2705200          | VA450   | 142295            | SCX4.3   | 8042            | SCX8.4   | CR1463K    | VKT147** |
| R751043          | 009.8   | 97SA387600           | ST.675  | 142296            | SCQ5.6   | 84141           | SCQ10.0  | CR1551W    | VCR2     |
| R751045          | 0A10.9  | 97SA387600           | VA451   | 142297            | SCQ10.0  | <b>E.R.C.</b>   |          | CR1552W    | VCR1     |
| R754053          | SCX12.2 | 97SA395800           | ST1.156 | 142298            | SCX9.5   | 8TR200          | FRM12.1  | CR1553W    | VCR7     |
| R754054          | 0A7.4   | 97SA395800           | VA450   | 142299            | SCX3.5   | 8TR350          | FRM11.5  | CR1555W    | VCR26    |
| R811003          | SCX14.7 | 97SA396200           | VCR33   | 142300            | SCX8.0   | 8TR500          | FRM12.1  | CR1556W    | VCR40    |
| R831047          | SCX6.2  | 97SA446500           | VPR16   | 142573000         | STC.780  | 8TR600          | FRX11.0  | CR1557W    | VCR3     |
|                  |         | 97SA507200           | ST1.156 | 142797000         | 0A5.0    | 8TR750          | FRX11.0  | CR1558W    | VCR33    |
|                  |         | 97SA507200           | VA450   | 142836            | 0A4.6    |                 |          | CR1601M    | VPR1     |
|                  |         |                      |         |                   |          |                 |          | CR1602M    | VPR2     |

= Replacement Belt

\*\* = Kit May Not Include Tires

^ = Part of the Assy

# ECG ... ESQUIRE

| MFG. P/N          | PRB NO. | MFG. P/N             | PRB NO. | MFG. P/N            | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N       | PRB NO. |
|-------------------|---------|----------------------|---------|---------------------|---------|----------------|---------|----------------|---------|
| CR1603M           | VPR7    | <b>ELECTRA</b>       |         | W39                 | VA53    | <b>ELGIN</b>   |         | 641B101020     | ST.927  |
| CR1604M           | VPR4    | 10580403             | FRM11.5 | W4                  | VA61    | V41745         | SCX8.6  | 6530205        | VCR33   |
| CR1605M           | VPR8    | 12230202             | S0010.0 | W40                 | VA14    |                |         | 657010A        | VCR7    |
| 0R1606M           | VPR9    | 8TR200               | FRM12.1 | W41                 | VA15    | <b>EL MO</b>   |         | 70114347       | VCR21   |
| CR1607M           | VPR10   | \$TR300              | FRM12.1 | W43                 | VA90    | 4P48887        | 0010.5  | 70115406       | VCR33   |
| CR1608M           | VPR3    | 8TR350               | FRM12.1 | W44                 | VA91    | EEP6707B       | 0012.4  | 70326530       | ST1.211 |
| CR1609M           | VPR11   | 8TR500               | FRM12.1 | W45                 | VA18    |                |         | 70326530       | VA30    |
| CR1610M           | VPR5    |                      |         | W47                 | VA204   | <b>EMERSON</b> |         | 70326538       | 811.211 |
| CR1612M           | VPR13   | <b>ELECTRO SOUND</b> |         | W48                 | VA207   | 0000100020     | VCR20   | 70326538       | VA30    |
| CR1613            | VPR6    | T10                  | ST.985  | W49                 | VA202   | 0000100020     | V0R20   | 70342123       | SCQ3.6  |
| CR1651M           | ST1.350 | T11                  | ST1.243 | W5                  | VA01    | 0002300140     | VCR15   | 7504003        | SCX5.1  |
| CR1652M           | ST1.165 | T13                  | ST1.350 | W50                 | VA41    | 0002000010     | VCR7    | 789JRA0001     | SCA3.2  |
| CR1653M           | ST1.014 | T14                  | ST1.211 | W51                 | VA54    | 0002000020     | VCR9    | 789JRA0002     | SCA3.2  |
| CR1654M           | ST1.211 | T15                  | ST1.370 | W52                 | VA104   | 000000040      | VCR26   | 8244           | SCX11.8 |
| CR1901M           | VA60    | T16                  | ST.47Q  | W53                 | VA55    | 001000300      | VCR33   | 850A200004     | VA501   |
| CR1902M           | VA22    | T17                  | ST8.50  | W54                 | VA47    | 0010100300     | VCR33   | 850A200005     | VA551   |
| CR1903M           | VA40    | T18                  | ST1.211 | W55                 | VA105   | 0021121050     | VCR33   | 850A200021     | VA552   |
| CR1904M           | VA61    | T19                  | ST.685  | W56                 | VA49    | 0021G25010     | VCR33   | 850A200026     | VA553   |
| CR1905M           | VA21    | T2                   | ST1.160 | W57                 | VA505   | 002G00020      | VCR9    | 850A200027     | VA552   |
| CR1906M           | VA20    | T20                  | ST1.420 | W59                 | VA46    | 0150100001     | V763    | 850A20004      | VA501   |
| CR1907M           | VA01    | T21                  | ST1.118 | W6                  | VA10    | 0150100006     | V763    | 850A200020     | VA553   |
| CR1908M           | VA26    | T22                  | ST1.205 | W60                 | VA054   | 0150100007     | V758    | 850A400018     | VPR16   |
| CR1910M           | VA70    | T23                  | ST1.113 | W61                 | VA98    | 0150700002     | V760    | 850A400041     | VPR16   |
| CR1911M           | VA25    | T24                  | ST.970  | W62                 | VA96    | 10851203       | SCX8.0  | 850A400073     | VPR18   |
| CR1915M           | VA12    | T25                  | ST.925  | W63                 | VA97    | 10851204       | OB15.6  | 850A600039     | VA554   |
| CR1916M           | VA10    | T26                  | ST1.016 | W64                 | VA450   | 117V           | OA8.2   | 850P300005     | SCA4.2  |
| CR1918M           | VA101   | T27                  | 81.599  | W65                 | VA150   | 18210705       | SCY4.2  | 850P400041     | VPR17   |
| CR1920M           | VA207   | T28                  | ST1.130 | W66                 | VA215   | 18211211       | SCX5.5  | 850P600022     | FRW9.7  |
| CR1921M           | VA41    | T29                  | ST1.152 | W68                 | VA551   | 182112142      | SCY5.7  | 850P600055     | SCY2.9  |
| CR1922M           | VB2     | 3                    | ST1.165 | W69                 | VA501   | 182112161      | SCX5.5  | 850P600063     | SCY5.2  |
| CR1924M           | VB1     | 130                  | ST1.211 | W7                  | VA12    | 182112173      | SCY5.7  | 850P600124     | 8088.4  |
| CR1925M           | VA203   | 131                  | ST1.113 | W70                 | VA217   | 18211221       | SCX7.0  | 850P600125     | \$C52.5 |
| CR1927M           | VA02    | 132                  | ST.948  | W71                 | VA758   | 18770908       | SCY4.2  | 850P600170     | SCQ4.0  |
| 0R1928M           | VA204   | 133                  | ST1.46  | W8                  | VA11    | 19210703       | SCY4.2  | 850P600277     | SCA8.9  |
| CR1930M           | VA03    | 134                  | ST1.014 | W9                  | VA13    | 19210924       | SCY7.0  | 850P600315     | SCA3.2  |
| CR1931M           | VA202   | 135                  | ST1.130 | PR1                 | VPR1    | 21611          | SCX5.5  | 850P600316     | SCA8.9  |
| CR1932M           | VA28    | T37                  | ST1.182 | PR10                | VPR10   | 264P307010     | VCR33   | 850P600317     | SCA3.5  |
| CR1933M           | VA27    | T38                  | ST1.165 | PR11                | VPR7    | 321218A        | VA502   | 850P600325     | SCA8.9  |
| CR1934M           | VA04    | T39                  | ST1.152 | PR12                | VPR18   | 434035A        | VPR16   | 850P600326     | SCA3.5  |
| CR1935M           | VA200   | T4                   | ST1.330 | PR13                | VPR19   | 4340350        | VPR16   | 850P700005     | SCX5.5  |
| CR1937M           | VA42    | T40                  | ST1.165 | PR14                | VPR20   | 4340370        | VPR16   | 850P700020     | SCX7.0  |
| CR1938M           | VA44    | T41                  | ST.689  | PR15                | VPR11   | 452024A        | SCQ5.7  | 850P700023     | SCX4.9  |
| CR1939M           | VA63    | T42                  | ST.927  | PR16                | VPR21   | 452024A        | SC810.0 | 850P900080     | ST1.350 |
| CR1941M           | VA07    | T44                  | ST.977  | PR17                | VPR13   | 452030A        | SCA8.9  | 850P900080     | VA60    |
| CR1942M           | VA08    | T45                  | ST1.208 | PR18                | VPR2    | 45223A         | SCA5.4  | 851A600039     | VA554   |
| CR1943M           | VA18    | T47                  | ST.463  | PR19                | VPR14   | 511191A        | VCR33   | 85900001       | FRM9.7  |
| CR1944M           | VA13    | T50                  | ST1.243 | PR2                 | VPR2    | 511217A        | VCR7    | 85900003       | SCA8.9  |
| CR1945M           | VA80    | T51                  | ST.515  | PR20                | VPR8    | 511352A        | VCR6    | 880601         | SCY4.2  |
| CR1946M           | VA67    | T52                  | ST1.156 | PR21                | VPR6    | 511392A        | VCR6    | 918589         | OA8.5   |
| CR1947M           | VA53    | T53                  | ST1.165 | PR3                 | VPR3    | 511393A        | VCR6    | 928B29101      | VCR9 &  |
| CR1948M           | VA30    | T6                   | ST.752  | PR4                 | VPR4    | 513191A        | VCR33   |                | VCR33   |
| CR1949M           | VA100   | T7                   | ST1.230 | PR5                 | VPR5    | 521003201      | SCY8.2  | 9288291010     | VCR9 &  |
| CR195QM           | VA45    | T8                   | ST1.330 | PR6                 | VPR6    | 521003401      | SCY9.2  |                | VCR33   |
| CR1951M           | VA09    | T9                   | ST.685  | PR7                 | VPR17   | 521004001      | SCA8.9  | 928030601      | VCR9 &  |
| CR1953M           | VA46.,  | W1                   | VA40    | PR8                 | VPR9    | 5210040010     | SCA8.9  |                | VCR33   |
| CR1956M           | VA06    | W10                  | VA02    | PR9                 | VPR16   | 521004101      | FR10.8  | 962538         | W02     |
| CR1959M           | VA201   | W11                  | VA03    | VBK10               | VKT58   | 5210041010     | FR10.8  | 981590         | 0.45.4  |
| CR1962M           | VA23    | W12                  | VA04    | VBK101              | VKT113  | 521004201      | SC B6.6 | 983439         | OA7.4   |
| CR1963M           | VA105   | W13                  | VA101   | VBK102              | VKT160  | 5210042010     | SC B6.6 | 983440         | OA8.2   |
| CR1971M           | VA90    | W14                  | VA07    | VBK103              | VKT170  | 5210046010     | SCA7.1  | 986507         | FRX6.6  |
| CR1975M           | VA51    | W15                  | VA42    | VBK104              | VKT159  | 521004901      | SCA7.1  | 986508         | OA4.6   |
| QR1978M           | VA101   | W16                  | VA44    | VBK106              | VKT147  | 5210049010     | SCB3.8  | A810070        | SC04.0  |
| CR1980M           | VA49    | W18                  | VA27    | VBK105              | VKT162  | 521005001      | SCB3.8  | ET361490       | VCR20   |
| <b>EDL</b>        |         | W19                  | VA23    | VBK106              | VKT163  | 5210050010     | FRM10.5 | MDF33VA3409    | V758    |
| 752859            | SCX2.4  | W2                   | VA22    | VBK107              | VKT157  | 521005501      | FRM10.5 | MDF8VA3422     | V760    |
| 752989            | STC.742 | W20                  | VA28    | VBK38               | VKT19   | 5210055010     | SCB9.5  | T.B1548        | 006.1   |
| 753139            | SCX8.4  | W21                  | VA23    | VBK41               | VKT19   | 5210053010     | SCB9.5  | 181614         | OB11.7  |
| <b>EIKI/IA VA</b> |         | W22                  | VA25    | VBK42               | VKT84   | 522801701      | ST.850  | TB2387         | OA8.5   |
| 86266             | 009.0   | W23                  | VA26    | VBK44               | VKT88   | 5228017010     | VA96    | TB2921         | OB14.0  |
| 8691              | WP83    | W24                  | VA20    | VBK45               | VKT88   | 5228017010     | ST.850  | 183199         | OB10.9  |
| EX15109           | WP81    | W25                  | VA70    | VBK50               | VKT18   | 522801801      | VA97    | TB4000         | OA10.1  |
| EX15129           | 007.0   | W26                  | VA63    | VBK65               | VKT105  | 522005501      | VPR3    | TB4101         | 0011.7  |
| EX3/5204          | 0011.7  | W27                  | VA30    | <b>ELECTROBRAND</b> | VKT60   | 522005502      | VPR3    | 10171          | OC13.2  |
| 5146              | WP80    | W28                  | VA08    | 6514                | FRM9.7  | 522005503      | VPR3    | 10242          | 008.5   |
| ST19041           | WP80    | W29                  | VA09    | 6531                | FRM11.5 | 5220055030     | VPR3    | 10243          | OA12.4  |
| X113161           | 009.0   | W3                   | VA60    | 6533                | FRM11.5 | 5220055030     | ST.599  | 10401          | 0013.2  |
| X119041           | WP80    | W30                  | VA80    | 6703                | FRM9.7  | 522P00201      | VA90    | V15            | SCY5.2  |
| <b>ELAC</b>       |         | W31                  | VA45    | 6704                | FRM9.7  | 522P002010     | ST.599  | <b>ESQUIRE</b> |         |
| (4501422A)        | SCX4.9  | W32                  | VA100   | 6704                | FRM9.7  | 524B00301      | FR8.8   | 12020901       | FRX9.7  |
|                   |         | W33                  | VA92    | 6712                | FRM10.5 | 5246003010     | FR8.8   | 1891003        | SCY6.5  |
|                   |         | W34                  | VA93    | 7634                | SCX10.7 | 56000343       | SCX5.1  | 2111202        | SCQ5.6  |
|                   |         | W35                  | VA94    | 7705                | SCQ10.0 | 56000410       | FRM11.2 | 21V7017        | FRW8.5  |
|                   |         | W36                  | VA95    | 7707                | SCA8.9  | 641B101010     | ST.927  | 21V7080        | FRX10.5 |
|                   |         | W37                  | VA51    |                     |         | 641810102      | ST.927  | 21V7387        | SCY6.5  |
|                   |         | W38                  | VA52    |                     |         |                |         |                |         |

= Part of the Assy

= Kit May Not Include Tires

= Part of the Assy

# ESQUIRE ... GC WALSCO

| MGF. P/N             | PRB NO. | MGF. P/N         | PRB NO. | MGF. P/N | PRB NO.  | MGF. P/N | PRB NO. | MGF. P/N | PRB NO. |
|----------------------|---------|------------------|---------|----------|----------|----------|---------|----------|---------|
| 5610902              | FRM10.5 | <b>GC-WALSCO</b> |         | 1424-26  | FRM14.0  | 1425-57  | SCX4.0  | 1427-21  | SCA3.2  |
| 8891202              | SCX8.9  | 1401-66          | SCB14.0 | 1424-27  | FR15.9   | 1425-58  | SCQ6.5  | 1427-22  | SCB3.2  |
| J391171              | FRM10.5 | 1408-15          | VKT18** | 1424-28  | FRW7.7   | 1425-59  | SCA10.5 | 1427-23  | SCA3.2  |
| <b>FAIRCHILD</b>     |         | 1408-20          | VKT19** | 1424-29  | FRX9.0   | 1425-60  | SCQ11.1 | 1427-24  | SCY3.5  |
| 20187                | FRY13.4 | 1408-23          | VKT59** | 1424-30  | FRX9.7   | 1425-61  | SCB12.1 | 1427-25  | SCX4.0  |
| 2234801              | SCX9.5  | 1408-24          | VKT19** | 1424-31  | FRZ12.1  | 1425-62  | SCA13.2 | 1427-26  | SCX4.0  |
| 2234803              | SCX2.6  | 1408-26          | VKT84** | 1424-32  | FRW7.0   | 1425-63  | SCA13.2 | 1427-27  | SCA4.0  |
| 24025                | FRM14.7 | 1409-04          | FF15.0  | 1424-33  | FR7.8    | 1425-64  | SCB14.0 | 1427-28  | SCA4.2  |
| 7021                 | FRM14.7 | 1409-14          | FF15.0  | 1424-34  | FRX9.7   | 1425-65  | SCA8.6  | 1427-29  | SCY4.2  |
| 7115596              | FRX7.5  | 1410-04          | 007.4   | 1424-35  | FR16.9   | 1425-66  | SCX3.2  | 1427-30  | SCY4.4  |
| 7115602              | SCA14.1 | 1410-05          | 087.6   | 1424-36  | FRX22.4  | 1425-67  | SCB12.5 | 1427-31  | SCX4.3  |
| 7115605              | OB8.0   | 1410-06          | 006.1   | 1424-37  | FRX25.0  | 1426-01  | FRM8.0  | 1427-32  | SCY4.6  |
| 7115608              | 0A3.8   | 1410-07          | 007.4   | 1424-38  | FRW8.0   | 1426-02  | FR8.9   | 1427-33  | SCQ4.8  |
| 7115611              | SCA12.5 | 1410-08          | 008.5   | 1424-39  | FRW12.0  | 1426-03  | FRW9.0  | 1427-34  | SCY4.8  |
| 8000273              | OC9.0   | 1410-09          | SCX9.5  | 1424-41  | FRX35.1  | 1426-07  | FR23.6  | 1427-35  | SCY5.2  |
| 9000296              | 0010.1  | 1410-10          | 0010.5  | 1424-42  | FRQ13.6  | 1426-08  | FRW7.0  | 1427-37  | SCY5.1  |
| 9014101              | OB12.4  | 1410-12          | OB11.7  | 1424-43  | FR18.2   | 1426-09  | FRM7.5  | 1427-40  | SCY5.7  |
| 9014103              | OB16.4  | 1410-14          | 0014.4  | 1424-44  | FR19.6   | 1426-10  | FRW9.7  | 1427-41  | SCA5.4  |
| 9014104              | OB11.7  | 1410-18          | 0018.0  | 1424-45  | FRX35.1  | 1426-11  | FRW9.7  | 1427-42  | SCA6.1  |
| 9014105              | OB13.2  | 1410-20          | SCX8.4  | 1424-47  | FRW12.6  | 1426-15  | FRW20.7 | 1427-43  | SCA6.1  |
| 9014106              | 0A13.2  | 1410-50          | 0010.9  | 1424-48  | FRQ18.2  | 1426-20  | FRX2.9  | 1427-44  | SCQ6.0  |
| 9014107              | 068.4   | 1410-51          | 0A10.9  | 1424-49  | FR5.9    | 1426-22  | FRX4.3  | 1427-45  | SCY6.7  |
| 9014108              | 0A4.6   | 1410-52          | 005.8   | 1424-50  | FR8.8    | 1426-23  | FRX4.7  | 1427-46  | SCB6.7  |
| 9014109              | OB13.2  | 1410-53          | OSD6.7  | 1424-51  | FRW9.7   | 1426-24  | FRX5.7  | 1427-47  | SCA6.7  |
| 9014110              | OB10.9  | 1410-54          | OB14.0  | 1424-52  | FRX15.2  | 1426-25  | FRX5.7  | 1427-48  | SCB6.9  |
| 9014111              | 0A10.9  | 1410-56          | 0013.6  | 1424-53  | FRX15.2  | 1426-26  | FR5.9   | 1427-49  | SCY7.0  |
| 91381                | SCQ2.5  | 1410-57          | 009.0   | 1424-54  | FRY17.2  | 1426-27  | FRM6.1  | 1427-50  | SCX7.0  |
| 91411                | OB12.4  | 1410-58          | OB9.4   | 1424-55  | FR17.2   | 1426-29  | FRX6.7  | 1427-51  | SCA6.7  |
| A22801               | FRM14.7 | 1410-59          | 0011.2  | 1424-56  | FR19.6   | 1426-30  | FR6.9   | 1427-53  | SCB7.0  |
| A9065                | 005.0   | 1410-61          | 0A12.4  | 1424-57  | FRX23.6  | 1426-31  | FR6.9   | 1427-54  | SCX7.4  |
| A9874                | FRX19.6 | 1410-63          | 0A8.5   | 1424-58  | FR23.6   | 1426-32  | FRM7.0  | 1427-55  | SCA7.5  |
|                      |         | 1410-64          | SCX7.4  | 1424-59  | FRZ12.1  | 1426-33  | FRW7.0  | 1427-56  | SCX7.4  |
| <b>FISHER</b>        |         | 1410-65          | OB14.0  | 1424-60  | FR11.9   | 1426-34  | FRM7.5  | 1427-57  | SCX8.0  |
| (See Sanyo/Fisher)   |         | 1410-67          | OB10.1  | 1425-02  | SCX2.4   | 1426-35  | FRZ7.5  | 1427-58  | SCB8.1  |
| <b>FORD MERCURY</b>  |         | 1410-68          | 0A6.6   | 1425-03  | SCX12.2  | 1426-36  | FRX7.8  | 1427-59  | SCY8.2  |
| 19A168AA             | 0A13.2  | 1410-71          | OX5.9   | 1425-04  | SCO5.6   | 1426-37  | FRM8.0  | 1427-60  | SCB8.4  |
| 26810173             | FRM10.5 | 1410-72          | 0A6.1   | 1425-06  | SCY5.0   | 1426-39  | FR8.4   | 1427-61  | SCA8.6  |
| 38510183             | SCX7.4  | 1410-73          | OSC10.2 | 1425-07  | SCX8.6   | 1426-40  | FR9.0   | 1427-62  | SCB8.6  |
| 38510184             | SCX4.3  | 1410-74          | 0015.6  | 1425-08  | SCX4.6   | 1426-41  | FRW9.1  | 1427-63  | SCA8.9  |
| 38510232             | 0A4.2   | 1410-75          | OB16.4  | 1425-10  | SCX8.0   | 1426-42  | FRX9.4  | 1427-64  | SCX8.9  |
| 4240151F03           | FRM12.1 | 1410-76          | OSC18.5 | 1425-11  | SCB21.2  | 1426-43  | FR9.4   | 1427-67  | SCB9.5  |
| 726049522            | 0A13.2  | 1410-77          | OSC22.8 | 1425-12  | SCQ10.0  | 1426-44  | FRX9.5  | 1427-68  | SCX9.5  |
| 726049553            | SCX15.0 | 1410-78          | OSC22.8 | 1425-13  | STC.742  | 1426-45  | FR9.4   | 1427-69  | SCQ10.0 |
| 766049522            | 0A13.2  | 1410-79          | 0A5.4   | 1425-14  | SCA12.0  | 1426-46  | FRY10.0 | 1427-70  | SCA10.5 |
|                      |         | 1410-80          | 0A13.2  | 1425-15  | SC B24.2 | 1426-47  | FRW10.1 | 1427-71  | SCX10.7 |
|                      |         | 1410-81          | 0A3.1   | 1425-16  | SCB16.6  | 1426-48  | FRW10.1 | 1427-73  | SCB11.3 |
|                      |         | 1410-82          | 0A4.0   | 1425-17  | SCB18.1  | 1426-49  | FRM10.2 | 1427-74  | SCY11.7 |
| <b>FUNAI</b>         |         | 1410-83          | 0A4.6   | 1425-18  | SCA14.1  | 1426-50  | FRW10.1 | 1427-75  | SCX11.8 |
| 1810632US            | V766    | 1410-84          | 0A5.0   | 1425-19  | SCB28.2  | 1426-51  | FRW10.1 | 1427-76  | SCX11.8 |
| 181225BUS            | V767    | 1410-85          | SCX4.9  | 1425-20  | SCA12.5  | 1426-52  | FRX10.4 | 1427-77  | SCX11.8 |
| 62D805909302         | VA757   | 1410-86          | 0A7.0   | 1425-21  | SCX13.6  | 1426-54  | FRX10.5 | 1427-78  | SCB12.1 |
| 80000922             | VPR4    | 1410-87          | SCX9.2  | 1425-22  | SCX4.3   | 1426-56  | FRY10.7 | 1427-79  | SCC12.1 |
| 800012304            | VA350   | 1410-88          | 0A9.0   | 1425-23  | SCX8.6   | 1426-57  | FRW10.7 | 1427-80  | SCX12.2 |
| 800012305            | VA755   | 1410-89          | 0A9.4   | 1425-24  | SCQ11.1  | 1426-58  | FRM11.0 | 1427-81  | SCB12.1 |
| 800012309            | VA35    | 1410-90          | 0A10.1  | 1425-25  | SCX2.4   | 1426-59  | FRY11.5 | 1427-82  | SCY12.7 |
| 80001607             | FR8.2   | 1410-91          | 0A10.9  | 1425-26  | SCX4.0   | 1426-60  | FRX11.5 | 1427-83  | SCB12.5 |
| 80001608             | SCB10.0 | 1410-92          | 0013.6  | 1425-27  | SCQ6.5   | 1426-61  | FR11.5  | 1427-84  | SCX12.2 |
| 80002139             | FR3.6   | 1410-94          | 0A4.6   | 1425-28  | SCX8.9   | 1426-62  | FR11.5  | 1427-86  | SCX13.6 |
| 80591506             | SCA6.7  | 1410-95          | 0A6.6   | 1425-29  | SCX3.5   | 1426-63  | FR11.9  | 1427-87  | SCA14.1 |
|                      |         | 1410-96          | SCQ6.7  | 1425-30  | SCO5.6   | 1426-64  | FRW12.0 | 1427-88  | SCX14.7 |
| <b>GAF</b>           |         | 1410-98          | OB17.2  | 1425-31  | S006.7   | 1426-65  | FR12.0  | 1427-89  | SCX15.0 |
| (See Ansco)          |         | 1410-99          | OX5.9   | 1425-32  | SCX7.4   | 1426-66  | FRZ12.1 | 1427-90  | SCX16.0 |
| <b>GAMBLE-SKOGMO</b> |         | 1412-04          | 008.2   | 1425-33  | SCX9.5   | 1426-67  | FRX13.1 | 1427-91  | SCB18.1 |
| 2402250              | 0A7.0   | 1412-14          | 0A14.0  | 1425-34  | SCX10.5  | 1426-68  | FRZ13.2 | 1427-92  | SCB21.2 |
| 2402307              | SCX8.6  | 1414(Pair)       | FR2.9   | 1425-35  | SCX11.8  | 1426-72  | FR16.9  | 1427-94  | SCA14.1 |
| 46M046               | FRM11.0 | 1415(Pair)       | FR2.0   | 1425-36  | SCX14.7  | 1426-73  | FRX17.2 | 1427-96  | SCY7.5  |
| 46M048               | FRM9.7  | 1416             | FR8.8   | 1425-37  | SCA3.0   | 1426-75  | FRY19.6 | 1427-97  | SCA14.1 |
| 46M050               | FRM9.7  | 1424-00          | FR9.0   | 1425-38  | SCA8.9   | 1426-76  | FR19.6  | 1428-02  | 002.7   |
|                      |         | 1424-01          | FR12.0  | 1425-39  | SCA14.1  | 1426-78  | FR21.5  | 1428-04  | ST1.41  |
|                      |         | 1424-03          | FR15.9  | 1425-40  | SCB6.0   | 1426-80  | FRX21.6 | 1428-05  | ST.536  |
|                      |         | 1424-06          | FR12.5  | 1425-41  | SCB6.0   | 1426-81  | FRX23.6 | 1428-07  | STC.742 |
|                      |         | 1424-12          | FR13.4  | 1425-42  | SCX13.6  | 1427-02  | SCA3.0  | 1441-01  | FRX20.7 |
|                      |         | 1424-13          | FRM8.0  | 1425-43  | SCC15.7  | 1427-03  | SCX2.9  | 1447-03  | IW09    |
|                      |         | 1424-14          | FRM9.0  | 1425-44  | FR19.6   | 1427-04  | SCX4.6  | 1472-01  | IW03    |
|                      |         | 1424-15          | FRM9.7  | 1425-45  | SCA9.6   | 1427-06  | SCA7.5  | 1474-00  | 009.8   |
|                      |         | 1424-16          | FRM11.0 | 1425-46  | SCA3.2   | 1427-08  | SCA9.6  | 1476-00  | FR2.9   |
|                      |         | 1424-17          | FRM11.2 | 1425-47  | SCB14.0  | 1427-09  | SCA10.5 | 1489-100 | VA60    |
|                      |         | 1424-18          | FRM11.5 | 1425-48  | SCY8.6   | 1427-10  | SCX8.0  | 1489-101 | VA22    |
|                      |         | 1424-19          | FRM12.1 | 1425-49  | SCX5.1   | 1427-11  | SCA8.6  | 1489-102 | VA40    |
|                      |         | 1424-20          | FRM13.3 | 1425-50  | SCA4.5   | 1427-14  | SCX1.9  | 1489-103 | VA61    |
|                      |         | 1424-21          | FRM10.5 | 1425-52  | SCY6.0   | 1427-15  | SCX1.9  | 1489-104 | VA21    |
|                      |         | 1424-22          | FRM6.1  | 1425-53  | SCA7.5   | 1427-16  | SCA2.3  | 1489-105 | VA20    |
|                      |         | 1424-23          | FRW8.5  | 1425-54  | SCY8.6   | 1427-18  | SCA2.3  | 1489-106 | VA01    |
|                      |         | 1424-24          | FRX12.5 | 1425-55  | SCB16.6  | 1427-19  | SCY2.9  | 1489-107 | VA26    |
|                      |         | 1424-25          |         | 1425-56  | SCX4.0   | 1427-20  | SCX2.9  | 1489-109 | VA70    |

\* = Replacement Belt

11

= Kit May Not Include Tires

= Part of the Assy

Mfg.# to PRB#



# GC WALSCO ... HITACHI

| MFG. P/N                | PRB NO.        | MFG. P/N       | PRB NO. | MFG. P/N             | PRB NO. | MFG. P/N               | PRB NO. | MFG. P/N | PRB NO. |
|-------------------------|----------------|----------------|---------|----------------------|---------|------------------------|---------|----------|---------|
| 1489-110                | VA25           | 452018A        | SCY3.2  | 1261                 | SCX9.5  | C3568/01527332         | SCX5.1  | 538093   | VCR33   |
| 1489-113                | VA101          | 452019A        | FRW12.6 | 300523               | SCA8.6  | C3616/01527354         | FRV101  | 5380931  | VCR33   |
| 1489-114                | VA23           | 452020A        | \$QX3.5 | 5027262              | OC7.4   | FP46211                | FRW8.0  | 5380933  | VCR33   |
| 1489-115                | VA42           | 452023A        | \$QQ5.7 | 505                  | 1W14A   | FP46311                | SCX5.1  | 5381041  | VCR7    |
| 1489-116                | VA20           | 452024A        | SCB10.0 | 7881001              | OB9.4   |                        |         | 5381681  | VCR6    |
| 1489-119                | VA23           | 452025A        | SCQ5.7  | 7881002              | OS D6.7 | <b>HEWLETT PACKARD</b> |         | 5381682  | VCR5    |
| 1489-120                | VA41           | 452028A        | SCA13.2 | 7881009              | OC20.3  | 15000274               | OB9A    | 5381611  | VCR23   |
| 1489-121                | VA04           | 452029A        | SCY5.7  | 7881703              | OC9.8   |                        |         | 5587752  | V768    |
| 1489-122                | VA03           | 4520296        | SCY5.7  | 7881704              | 0A12.4  | <b>HITACHI</b>         |         | 5587753  | V772    |
| 1489-126                | VA10           | 452030A        | SCA8.9  | 7881705              | 039.4   | 0056207000             | SCO5.6  | 5587753  | V774    |
| 1489-127                | VA101          | 452030B        | SCA8.9  | 7681706              | OC11.7  | 0056211000             | SCX8.0  | 5589001  | V772    |
| 1489-131                | VA02           | 452045A        | SCA8.9  | 7881707              | 009.8   | 0948343                | 0A8.2   | 5569241  | V772    |
| 1496-05                 | 1W05           | 452046A        | SC85.7  | 7881708              | 0A12.4  | 0971123                | 0A11.7  | 5589332  | V772    |
| 1499-15                 | 0010.9         | 452047A        | SCA6.6  | 7881710              | 0512.4  | 0971126                | 0814.0  | 5721942  | ICP-N20 |
| 1489-18                 | OB12.4         | 45230A         | SCA8.6  | 7881712              | OC9.8   | 0971189                | 0A9.0   | 5968193  | VCR25   |
| 1499-19                 | 0A8.2          | 511139A        | VCR33   | 7881713              | OB12.4  | 0971193                | 0A6.1   | 60409914 | SCC12.6 |
| 1499-20                 | OB9.0          | 511140A        | VCR33   | 7881715              | OB10.9  | 0971235                | 0A14.0  | 6210233  | 0A10.9  |
| 1499-21                 | SCB28.2        | 511217A        | VCR7    | 7881717              | OB12.4  | 0971236                | 0A9.0   | 6310232  | 0A10.9  |
| 1499-24                 | FRX12.5        | 511392A        | VCR6    | 7881718              | 007.0   | 0971246                | 0A4.0   | 6350001  | SC812.5 |
| 1499-29                 | FR14.1         | 511393A        | VCR6    | 7881719              | 006.1   | 0971247                | 0A4.0   | 6350011  | SCX4.0  |
| 1499-30                 | OBTO           | 513194A        | VCR7    | 7881720              | 009.0   | 11007045               | SCA4.0  | 6350021  | SCX7.0  |
| 1499-31                 | OB13.2         | 5920018        | V762    | 7881721              | 0A10.9  | 157053                 | SCQ5.3  | 6350051  | 0A4.6   |
| 1499-33                 | 0812.4         | 5920058        | V763    | 7881722              | OB7.0   | 163879                 | SQA3.2  | 6350141  | SCX8.6  |
| 1499-72                 | 1W11           | 592010A        | V768    | 7881724              | QA8.2   | 163895                 | FRZ11.0 | 6350212  | SCQ2.5  |
|                         |                | 5920108        | V768    | 7881728              | 087.0   | 163896                 | SCA13.6 | 6350272  | OATO    |
| <b>GENERAL ELECTRIC</b> |                | 5920115        | V762    | 7881730              | 0A8.5   | 164113                 | ST1.014 | 6350451  | 0A5.8   |
| (See Thomson)           |                | 592211A        | V768    | 7881732              | 0A9.0   | 164113                 | VA40    | 6350461  | SCX4.3  |
|                         |                | 592901A        | V773    | 7881735              | 0A10.9  | 177208                 | SCB2.6  | 6350551  | SCX8.6  |
| <b>GENERAL MOTORS</b>   |                | 6470108        | VCR7    | 7881741              | OC14.4  | 2333641                | VCR18   | 6350591  | SCQ10.0 |
| 196195                  | OB4.6          | 653020A        | VCR33   | 7881746              | SCX13.6 | 30163200               | SQB5.7  | 6350621  | SCX8.6  |
| 196196                  | OB7.0          | 6530208        | VCR33   | 7881749              | 0A12.4  | 3051498                | SCB12.1 | 6350732  | FRM10.5 |
| 196206                  | 064.2          | 657010A        | VCR7    | 7881750              | QA11.7  | 3051593                | FR14.5  | 6350733  | FRQ112  |
|                         |                | 6570108        | VCR7    | 7881751              | SCX9.5  | 3713004                | FRX15.2 | 6350851  | SCX8.6  |
| <b>GIBBS</b>            |                | 657102K        | VCR13   | 7881753              | SCA12.5 | 4057268                | FR16.1  | 6350852  | SCX8.6  |
| 500000412               | SCX2.4         | 667051A        | VCR6    | 7881754              | SCX7.0  | 4100551                | VCR33   | 6350861  | 0A5.8   |
| 500004413               | 0A6.1          | 686075A        | VA22    | 7881756              | 0815.6  | 4100581                | VCR24   | 6350882  | QA6.1   |
|                         |                | 850A400018     | VPR16   | 7881757              | 009.8   | 4100582                | VCR24   | 6350931  | FRM9.7  |
| <b>GLADDING</b>         |                | 850A400041     | VPR16   | 7881758              | SCX5.1  | 4100584                | VCR24   | 6350951  | FRM9.7  |
| 21402                   | FRM12.1        | 850A400073     | VPR18   | 7881760              | SCX14.7 | 4132803                | VCR24 & | 6351001  | 005.8   |
| 27869                   | <b>FRM11.5</b> | 850P00023      | SCX4.9  | 7881761              | SCQ6.7  |                        | VCR33   | 6351021  | SCY4.2  |
|                         |                | 850P300005     | SCA4.2  | 7881763              | 0A6.1   | 4134171                | VCR24   | 6351022  | SCX5.1  |
| <b>GOLDCREST</b>        |                | 850P600022     | FRW9.7  | 7881769              | SCQ6.5  | 4136932                | VCR24   | 6351023  | 0A6.1   |
| 21494                   | QC7.8          | 850P600055     | SCY2.9  | 7881770              | SCQ10.0 | 4136951                | VCR24   | 6351026  | QA8.2   |
|                         |                | 850P600063     | SCY5.2  | 7881772              | SCX10.7 | 4615692                | SCX3.2  | 6351053  | SCQ6.7  |
| <b>GOLDSTAR</b>         |                | 850P600124     | SCB8.4  | 7881773              | SCQ10.0 | 4615693                | SCX4.3  | 6351091  | SCX7.4  |
| 321149B                 | ST.753&        | 850P600125     | SCB2.5  | 7881774              | SCX4.0  | 4622201                | SCQ4.3  | 6351122  | SCX18.5 |
|                         | ST1.165        | 850P600315     | SCA3.2  | 7881775              | SCX11.8 | 4622202                | SCX4.3  | 6351154  | SCAM    |
|                         | VA500          | 850P600325     | SCA8.9  | 7881782              | SCQ10.0 | 4622281                | SCA4.2  | 6351555  | SCAM    |
| 321218A                 | VA502          | 850P600326     | SCA3.5  | 7881783              | SCQ10.0 | 4682441                | FRM13.3 | 6351561  | \$003.5 |
| 321253A                 | VA504          | 850P700005     | SCX5.5  | 80A                  | 1W14A   | 4683995                | FRX22.4 | 6351961  | 0X5.9   |
| 321256A                 | VA503          | 850P700020     | SCX7.0  | 808                  | 1W14A   | 4683996                | FRX22.4 | 6354001  | SCX10.5 |
| 321256A                 | VA506          | 850P700023     | SCX4.9  | 9631312              | OS D6.7 | 4685111                | SCX5.1  | 6354011  | scx10.5 |
| 324080A                 | VCR6           | 99P1099        | SCY6.5  | 9631816              | 0812.4  | 4685116                | SCA4.0  | 6354031  | SCQ6.5  |
| 324081A                 | VCR6           | 99P3024        | SCX5.8  | 9631822              | QC7.0   | 46851162               | SCA4.0  | 6354041  | SCQ6.5  |
| 333209A                 | VPR26,         | 99P3045        | SCX7.4  | 9631833              | 0A10.9  | 4685118                | SCA2.3  | 6354051  | SCQ6.5  |
| 3332090                 | VPR26          | 99P9000        | SCY4.8  | 9631834              | 0A7.4   | 46851182               | SCA2.3  | 6354103  | SCY8.6  |
| 343175A                 | VPR17          | 99T1353        | SCX7.0  | 9631911              | 0812.4  | 4685119                | SCA4.0  | 6354106  | SCY8.6  |
| 386075A                 | ST1.165        | 99T1354        | SCY4.2  | 9631912              | 007.4   | 4686152                | SCY6.0  | 6354109  | SCY6.5  |
| 386075A                 | VA22           | 99T227         | SCX9.5  |                      |         | 4686153                | SCY6.0  | 6354121  | SCY3.5  |
| 386139A                 | VA504          | 99T2922        | SCY4.2  | <b>HARMON-KARDON</b> |         | 4686192                | SCX8.6  | 6354151  | SCY4.4  |
| 386192A                 | VPR31          | 99Y2922        | SCY5.7  | 01528406             | SCY6.0  | 4686201                | SCY3.5  | 6354161  | SCQ6.5  |
| 431014A                 | ST1.396        | 99Y0063        | SCY4.2  | 01528407             | SCX9.5  | 4686622                | FRY23.6 | 6354171  | SCX4.0  |
| 431014A                 | VA51           | MDF333447      | V773    | 01528408             | SCX2.4  | 4687032                | SCY7.0  | 6354181  | SCX9.2  |
| 431017A                 | ST1.218        | ODL450000BAR   | VCR33   | 01531953             | SCY4.2  | 4687923                | SCY6.5  | 6354211  | SCX9.5  |
| 431017A                 | VA52           | ODL450000BAR   | VCR33   | 01531954             | SCY2.2  | 4687925                | SCY5.2  | 6354231  | SCX5.5  |
| 431018A                 | ST1.230        | ODL451000AA    | VCR33   | 01531955             | SCQ10.0 | 4688031                | FRW8.5  | 6354241  | SCY6.0  |
| 431018A                 | VA203          | ODL550000AB    | VCR33   | 01531956             | SCY5.2  | 4688331                | SCX4.6  | 6354251  | SCY5.2  |
| 433-015A                | VA762          | <b>GRAFLEX</b> |         | 01535694             | FRX11.0 | 4688713                | SCQ6.0  | 6354255  | VPR18   |
| 434035A                 | VPR16          | 37744          | OC4.0   | 01535695             | SCX4.0  | 4688932                | FRW8.8  | 6354261  | SCQ5.6  |
| 4340350                 | VPR16          | 38125          | WP52    | 01535700             | SCY6.0  | 4690071                | FR3.7   | 6354271  | SCX5.1  |
| 434035E                 | VPR16          | 38179          | OSD11.0 | 01536072A            | FRV10.1 | 46900712               | FR3.7   | 6354281  | SCX3.2  |
| 434037B                 | VPR16          | 39086P2        | FRF12.4 | 14025006             | OAS4    | 4690311                | SCQ5.6  | 6354291  | SCY8.0  |
| 434037C                 | VPR16          | 39211P1        | WP53    | 14025044             | SCA8.6  | 4690321                | SCY52   | 6354311  | SCY6.5  |
| 4340370                 | VPR16          | 39211P2        | WP54    | 264201444            | SCY7.0  | 4690341                | FRW8.0  | 6354381  | SQY6.0  |
| 434038A                 | VPR17          | 42090P48       | SCX8.6  | 264201445            | SCY6.0  | 4690392                | SCY6.0  | 6354401  | SCX4.6  |
| 434175A                 | VPR17          | 42090P49       | SCX2.4  | 264201448            | SCY4.2  | 4690601                | SCX7.4  | 6354451  | SCY4.6  |
| 434181A                 | VPR26          | 42901 P1       | OSC7.3  | 264201452            | SCX4.0  | 4691264                | SCY1.5  | 6354471  | SCY7.0  |
| 434181B                 | VPR26          | 42981 P1       | WP53A   | 264201454            | SCY6.0  | 4836316                | SCQ2.0  | 6354472  | SCY8.0  |
| 435038A                 | VA505          | 42981 P2       | WP54A   | 264201457            | SCY4.2  | 4856323                | SCX9.5  | 6354481  | SCY4.2  |
| 452003A                 | SCA4.2         |                |         | 264201458            | SCY4.6  | 4973361                | SCQ6.0  | 6354484  | SCX3.5  |
| 452004A                 | SCA13.2        | <b>GRUNDIG</b> |         | 264202410            | FRX11.0 | 4991291                | FRX20.7 | 6354485  | SCY4.2  |
| 452007A                 | SCB6.6         | 0354330        | 0812.4  | 264202411            | FRW8.0  | 5324661                | VCR24   | 6354488  | SCY4.2  |
| 452011A                 | SCX7.4         | 1195           | SCX10.5 | 264202415            | FRX2.9  | 5380131                | VCR25   | 6354491  | SCX8.6  |
| 452014A                 | VA51           | 1214           | SCX5.1  | 264202418            | FRM8.0  | 5380132                | VCR25   | 6354512  | SCC12.6 |
|                         |                |                |         | 264202701            | FRX25.0 | 5380471                | VCR22   | 6354521  | SCQ5.6  |

= Part of the Assy

" = Kit May Not Include Tires

= Part of the Assy



| MFG. P/N | PRB NO. | MFG. P/N | PRB NO. | MFG. P/N  | PRB NO.     | MFG. P/N      | PRB NO. | MFG. P/N      | PRB NO. |
|----------|---------|----------|---------|-----------|-------------|---------------|---------|---------------|---------|
| 6354531  | SCQ10.0 | 6356432  | SCQ7.2  | 6876971   | ST1.014     | ICL           |         | JVc           |         |
| 6354601  | SCX7.0  | 6356441  | SCQ4.8  | 6876971   | VA40        | 900380416     | 069.0   | 10050501SW    | SCX15.2 |
| 6354621  | SCA4.5  | 6356443  | SCQ3.0  | 6879515   | SCQ5.3      |               |         | 100505165W    | SCX15.2 |
| 6354631  | SCY2.2  | 6356445  | SCQ4.8  | 6879515   | VA49        | INLAND        |         | 11431602T     | SCY8.0  |
| 6354632  | SCY2.2  | 6356451  | SCB2.6  | 6886792   | VA45        | 004414        | 0A8.2   | 120009041     | FRW10.1 |
| 6354633  | SCY2.9  | 6356472  | SCQ3.0  | 6886824   | SCQ5.3      | 010089        | SCB8.1  | 120209011     | FRM9.6  |
| 6354634  | SCY2.9  | 6356473  | SCX4.0  | 6886824   | VA47        | 040059        | FRM8.0  | 130371M       | SCQ10.0 |
| 6354661  | SCY9.0  | 6356521  | FRW7.1  | 6886971   | ST1.014     | 100092        | FR8.4   | 131471M       | SCY9.2  |
| 6354663  | SCY7.5  | 6356522  | FRW7.1  | 6886971   | FRW7.1      | 105059        | FR8.4   | 14631503T     | SCY4.6  |
| 6354664  | SCY3.5  | 6356571  | SCA9.2  | 6889671   | SCA9.2      | 4001069       | FR8.4   | 1490802T      | SCQ10.0 |
| 6354671  | SCA14.1 | 6356581  | SCA8.6  | 6889931   | SCA8.6      | 42075         | FR8.4   | 15241801T     | SCY4.6  |
| 63546714 | SCA14.1 | 6356622  | SCA5.4  | 6894301   | SCA5.4      | 480113        | FRM10.5 | 17001009T     | FRX7.5  |
| 6354882  | SCQ4.8  | 6356641  | SCB10.0 | 6894361   | SCB10.0     | 4840021       | OB10.9  | 17001010T     | SCY6.5  |
| 6354684  | SCQ6.0  | 6357054  | FRX14.7 | 6894362   | SCQ5.3      | 700013        | FRQ11.2 | 17001021T     | FRX11.2 |
| 6354701  | SCQ6.5  | 6357081  | FRW10.1 | 6897094   | VA758       | 705082        | FRM9.7  | 17150606T     | SCY5.0  |
| 6354702  | SCX3.5  | 6357082  | FRX11.7 | 6897095   | VA758       | 750106        | FRW9.7  | 17150901T     | SCY3.2  |
| 6354703  | SCX5.1  | 6357121  | FRM9.7  | 6975471   | VPR18       | 800025        | FRM11.2 | 17201021T     | FRX11.2 |
| 6354791  | SCX7.4  | 6357131  | FRW10.1 | 6975472   | VPR18       | 801039        | 0A8.2   | 1741302T      | SCY6.5  |
| 6354792  | SCY6.0  | 6357141  | FRW10.1 | 6975761   | VPR18       | 802039        | SCX8.0  | 18001016T     | SCX8.9  |
| 6354811  | SCX8.6  | 6357143  | FRM9.0  | 6975766   | VPR18       | 885063        | FR8.8   | 18200809T     | SCY4.4  |
| 6354821  | SCY6.0  | 6357146  | FRW10.1 | 6975768   | VPR18       | 900050A       | 0A3.1   | 18201303T     | FRW7.0  |
| 6354883  | SCX7.4  | 6357147  | FRM8.0  | 6977813   | VPR18       | 900052        | 0A3.1   | 182107111     | SCY4.2  |
| 6354892  | SCY9.2  | 6357152  | FRW10.1 | 6979842   | VPR18       | 900084        | FRY8.4  | 182112135T    | SCY6.7  |
| 6354901  | SCY4.2  | 6357161  | FRX9.7  | 6979911   | VPR18       | 900093        | FRY8.4  | 1821121381    | SCY6.5  |
| 6354912  | SCQ10.0 | 6357162  | FRX7.5  | 7022598   | SCX14.7     | 9004414       | 0A8.2   | 184001281     | SCX2.6  |
| 6354913  | SCQ10.0 | 6357163  | FRM9.6  | 7023321   | VCR25       |               |         | 18400417AT    | SCX15.2 |
| 6354961  | SCY5.2  | 6357293  | FRW7.0  | 7023331   | VCR25       |               |         | 184004171     | SCX15.2 |
| 6354971  | SCY4.4  | 6357301  | FRW8.5  | 7024552   | VCR25       |               |         | 184004311     | SCY14.7 |
| 6354991  | SCX7.0  | 6357302  | FRW10.7 | 7024553   | VCR25       | 19406071      | FRM7.5  | 18400443AT    | SCX15.2 |
| 6355001  | SCB14.0 | 6357321  | FRQ11.2 | 7024572   | VCR33       | 19980351      | SCQ6.7  | 18400443T     | SCX15.2 |
| 6355062  | SCY8.6  | 6357333  | FRM8.0  | 7029041   | VCR33       | 21V7009       | FRM10.5 | 18400443T     | SCX15.2 |
| 6355171  | SCQ10.0 | 6357351  | FRW10.1 | 7029052   | VCR24       | 21V7021       | FRM10.5 | 18650712T     | SCQ5.6  |
| 6355172  | SCQ10.0 | 6357372  | FRW12.0 | 7029072   | VCR24       | 42A44236P01   | OX5.9   | 18800708T     | SCX5.1  |
| 6355181  | SCX7.0  | 6357403  | FRX9.7  | 7029281   | VA45 & VA47 | C4480         | FRM10.5 | 18800939T     | FRX9.4  |
| 6355193  | SCQ6.0  | 6357411  | FRW10.1 |           |             | M5446P        | FRM10.5 | 1891003T      | SCY6.0  |
| 6355202  | SCY6.0  | 6357421  | FR11.6  | 7029291   | VCR24       |               |         | 19210703T     | SCY4.2  |
| 6355214  | SCX3.5  | 6357471  | FRX10.5 | 7029311   | VCR24       | J.I.L.        |         | 19210711T     | SCY4.2  |
| 6355218  | SCQ10.0 | 6357501  | FRX9.0  | 702932    | VCR33       | 23347         | SCX8.4  | 19210906T     | SCX9.2  |
| 6355251  | SCY9.2  | 6357502  | SCY6.0  | 7045632   | SCY15.2     | 233703        | FRQ11.2 | 19210923T     | SCX7.4  |
| 6355261  | SCY6.5  | 6357531  | FRZ11.0 | 7075763   | SCQ4.3      | 234462        | FR8.8   | 19401417T     | SCX15.2 |
| 6355271  | SCX7.4  | 6357561  | FRW8.0  | 7075766   | FRW7.1      | 234463        | FR8.8   | 19501108T     | SCX12.2 |
| 6355282  | SCA8.6  | 6358016  | FRW6.5  | 7078545   | SCX15.0     | 234652        | FRM9.7  | 2111202T      | SCY6.0  |
| 6355283  | SCA8.6  | 638213   | VPR6    | 7350031   | SCX4.3      | 235392        | 0A8.2   | 2441102T      | SCX7.4  |
| 6355291  | SCQ4.8  | 6383211  | VPR6    | 7351123   | SCY9.2      | 23590         | SCY8.6  | 30010220T     | SCA3.5  |
| 6355301  | SCQ5.6  | 6383213  | VPR6    | 7375446   | SCQ5.3      | 235901        | SCA8.9  | 30010230T     | SCA3.5  |
| 6355381  | SCX8.6  | 6383762  | VPR18   | 7375446   | VA49        | 236371        | SCX4.3  | 300104221     | SCY3.2  |
| 6355382  | SCX4.3  | 6383763  | VPR18   | 7376271   | VB7         | 236391        | SCX8.4  | 300106191     | SCQ2.5  |
| 6355411  | SCY6.0  | 6384223  | VPR18   | 7379912   | VB7         | 236392        | 0A8.2   | 300107181     | SCX2.4  |
| 6355421  | SCY3.2  | 6384224  | VPR6    | 7448906   | VPR18       | 23747         | SCX7.4  | 30010719T     | SCX3.5  |
| 6355431  | SCY1.5  | 6384225  | VPR6    | 7448907   | VPR18       | 23749         | SCY4.2  | 300507141.    | SCX1.9  |
| 6355451  | SCQ8.2  | 638425   | VPR18   | 7469901   | VPR5        | 23849         | SCQ6.5  | 30100411T     | SCA7.1  |
| 6355472  | SCA8.6  | 6384251  | VPR18   | 7469903   | VPR18       | 23968         | SCB12.5 | 30910011      | SCY6.0  |
| 6355503  | SCQ10.0 | 6384341  | VPR18   | 7660164   | OA9.4       | 24062         | SCQ5.6  | 3931202T      | SCY5.2  |
| 6355504  | SCX4.3  | 6384352  | VPR18   | 7660852   | SCX2.6      | 24141         | SCX8.0  | 4081203T      | SCX9.5  |
| 6355509  | SCX9.2  | 6384511  | VPR17   | 7660854   | SCY2.2      | 24241         | SCQ11.1 | 62412011      | SCX9.5  |
| 6355521  | SCY5.2  | 638762   | VPR6    | 7661012   | OA6.1       | 24242         | SCX4.6  | 7630601T      | SCQ10.0 |
| 6355561  | SCQ5.3  | 6413663  | VA46    | 7661521   | SCX8.9      |               |         | 8001602T      | SCY7.0  |
| 6355581  | SCA13.6 | 6413684  | ST1.243 | 766712    | SCX8.9      | JAVELIN       |         | 9731201CT     | FRM9.6  |
| 6355591  | SCA3.0  | 6413684  | VA02    | 7667611   | SCQ10.0     | 1432564100100 | SCC15.7 | DUNTK3975TEVO | VCR26   |
| 6355601  | SCA3.2  | 6500432  | VPR26   | 7667612   | SCX8.9      |               |         | DUNTK4090TEVO | VCR26   |
| 6355701  | SCY6.0  | 6825371  | ST1.014 | 7668061   | SCY6.0      | JENSEN        |         | E301164001    | FRX22.4 |
| 6355711  | SCX10.5 | 6825371  | VA40    | 7668062   | SCY5.2      | 012301        | SCX8.6  | E301437002    | FRX23.6 |
| 6355721  | SCY4.4  | 6861471  | ST1.113 | 7668791   | SCA8.9      | 10010500      | SCY9.2  | E69879-001    | SCX4.6  |
| 6355741  | SCX9.5  | 6861471  | VA41    | 7668793   | OA8.2       | 10010512      | SCQ6.0  | E69879-002    | SCQ4.0  |
| 6355771  | SCA3.2  | 6861481  | ST.670  | 8501746   | SCY5.7      | 1041110       | SCA14.1 | E69879-003    | SCQ4.0  |
| 6355772  | SCA3.2  | 6861481  | VA42    | 8511821   | SCX5.5      | 10851204A     | SCA14.1 | E69879002     | SCQ4.0  |
| 6355791  | SCX3.2  | 6861482  | ST.670  | 8513424   | SCY4.2      | 12020901      | FRM9.6  | E69879003     | SCQ4.0  |
| 6355811  | SCX9.5  | 6861482  | VA42    | 971123    | 0813.2      | 34141348      | SCX10.5 | E73390-001    | SCX2.4  |
| 6355821  | SCY4.6  | 6865372  | ST1.014 | 971126    | 0C13.2      | 42A40969F01   | SCX16.0 | E73390001     | SCX2.4  |
| 6355831  | SCY5.2  | 6865571  | ST1.014 | GL451V    | VCR33       | 42A41693P01   | SCX8.6  | E73463-001    | SCA3.5  |
| 6355841  | SCQ11.1 | 6865575  | ST1.014 | KK10111   | SCQ5.1      | 42B40818G01   | FRM10.2 | E73463-002    | SCQ3.2  |
| 6355854  | SCY6.5  | 6865575  | VA40    | SFGB3211  | FRX23.6     | 7040001A      | SCX16.0 | E73463-003    | SCQ4.0  |
| 635591   | SCA3.0  | 6871481  | ST.670  | X48004A   | ST1.014     | 7040002A      | SCY4.6  | E73463001     | SCA3.5  |
| 6355911  | SCA2.3  | 6875371  | ST1.014 |           |             | 7041202A      | SCX15.0 | E73463002     | SCQ3.2  |
| 6356081  | SCA13.6 | 6875371  | VA40    | HONDA     |             | A440013       | SCA14.1 | E73463003     | SCQ4.0  |
| 6356091  | SCB2.5  | 6875372  | ST1.014 | YEFRO3058 | SCX16.0     | A44G014       | SCX4.0  | E74011-001    | SCX1.9  |
| 6356101  | FRZ11.0 | 6875372  | VA40    |           |             | FP15711       | SCX8.6  | E74011001     | SCX1.9  |
| 6356103  | FRZ11.0 | 6875386  | ST1.165 | IBM       |             | FP16011       | SCX4.9  | E74305-001    | SCX2.9  |
| 6356111  | SCA3.2  | 6875386  | VA44    | 1707015   | 0815.6      | M0011         | SCX9.2  | E74305-002    | SCQ3.0  |
| 6356221  | SCY6.5  | 6875387  | ST1.165 | 365579    | GT27.6      | NSP0010505    | SCQ6.0  | E74305001     | SCX2.9  |
| 6356231  | SCX7.4  | 6875387  | VA44    | 6196949   | OB4.4       | NSP0010506    | SCX8.9  | E74305002     | SCQ3.0  |
| 6356400  | SCA6.1  | 6876043  | ST1.165 | 945091    | FRF14.7     | NSPDX0500     | SCY9.0  | E74347-001    | SCB2.8  |
| 6356401  | SCA3.0  | 6876043  | VA44    | 945109    | FRF17.5     | NSPDX0912     | SCQ6.0  | E74347-004    | SCA6.7  |
| 6356411  | SCA6.1  | 6876045  | ST1.165 | 945824    | FRC11.6     |               |         | E74347-007    | SCA6.7  |
| 6356413  | SCA6.1  | 6876045  | VA44    | 945825    | FRC15.7     |               |         | E74347001     | SCB2.8  |
|          |         |          |         |           |             |               |         | E74347004     | SCA6.7  |

\* = Replacement Belt

= Kit May Not Include Tires

A = Part of the Assy

| MFG. P/N       | PRB NO. | MFG. P/N    | PRB NO. | MFG. P/N     | PRB NO.  | MFG. P/N        | PRB NO.   | MFG. P/N      | PRB NO. |
|----------------|---------|-------------|---------|--------------|----------|-----------------|-----------|---------------|---------|
| E74347007      | SCA6.7  | PQM3000323  | SCQ8.0  | PU52645-1-3  | ST1.130  | PUS465146       | VCR9      | V43313-1      | SCY7.0  |
| E75950-002     | SCA3.0  | PQM3000324  | SCA11.5 | PU536752A    | VCR33    | PUS5374-3       | ST.988    | V43605-1      | 0X5.9   |
| E75950002      | SCA3.0  | PQM3000329  | SCQ3.2  | PU55371-3-8  | ST.988   | PUS5374-3       | VA18      | V43674-1      | 0A4.2   |
| EQ100709       | FRX25.0 | PQM300036   | SCQ2.2  | PU55373      | \$T.463. | QD8A-9006       | 0A4.0     | V43723-1      | SCQ11.1 |
| EG10259001     | FRX23.6 | PQM300037   | SCA14.1 | PU55373      | VA13     | RH-PX0179GEZZ   | VQR26     | V43821-001    | SCY4.8  |
| EG74124002     | FRW12.0 | PQM30004    | FRQ11.2 | P1)55374-3   | \$1.988  | RH-PX0180QEZZ   | VCR33     | V43830-001    | SCQ10.0 |
| EGMD4003       | SCY4.0  | PQM30004-2  | FRW7.1  | PU55374-3    | VA18     | RH-PX181GEZZ    | VCR9      | V44121-001    | SCQ6.5  |
| EGMP4004       | SCQ6.0  | PQM30004-3  | FRW7.1  | PU55574-3-8  | ST.988   | 13861           | Q617.2    | VA5001-800-IE | FRM9.7  |
| EGMD4019       | SCX4.3  | PRD300022-2 | SCA5.4  | P1)55374-3-6 | VA18     | 140291-001      | QA10.9    | VA5001-801-E  | SCQ5.6  |
| F0030414       | SCY6.0  | PRD300022-5 | SCX4.6  | PU55822A     | ST.948   | 1407652         | QA10.9    | VA5001-802-IE | SCX3.5  |
| F0030415       | SCY3.5  | PR0300022-6 | SCY5.0  | P1)55822A-10 | SL.948   | 140900          | QB13.2    | VA5001-803-E  | SCY6.0  |
| F0030416       | SCY4.6  | PRD30022-2  | SCA5.4  | P1)55822A-10 | VA756    | 140985          | 0X5.5     | VE-0118       | SCX9.2  |
| F0030418       | SCY6.7  | PR030022-3  | SCX4.6  | PU55822A-3   | ST.948   | T409852         | 0A5.4     | VE0118        | SCX9.2  |
| F0030419       | SCY3.5  | PRD300222   | SCA5.4  | PU55822A-4   | ST.948   | T41052          | QA9.0     | VKB3000-002H  | SCX4.9  |
| F0030420       | SCY4.6  | PRD40084-1  | SCX4.6  | PU55822A-4   | VA756    | 141052-001      | 0A8.5     | VKB3000-003H  | SCX8.9  |
| F4639001       | SCA12.0 | PR040084-2  | SCY6.0  | PU55822A-7   | ST.948   | 141147-001      | 0B21.1    | VKB3000-004H  | SCY7.0  |
| F4823          | 0B11.7  | PRD40084-3  | SCY2.9  | P1)55822A-8  | ST.948   | 141256          | 0610.9    | VKB3000-005H  | SCX8.0  |
| F4828          | 0B11.7  | PU22374-3-8 | ST.988  | P1)55822A-8  | VA756    | 141256-001      | 0A10.1    | VKB3000-006H  | SCX10.7 |
| F16014         | SCX5.1  | P1)40826-2  | 0Q5.8   | P1)55822A-9  | ST.948   | T41823          | SCA8.9    | VKB3000-007H  | SCX8.0  |
| FTGBR004       | FRM11.7 | PU41107-2   | FRX35.1 | PU55822A-9   | VA756    | 141823-001      | \$0) (8.6 | VKB3000-008H  | SCQ10.0 |
| 030005         | FRX23.6 | P1)41109-2  | FR17.2  | P1)56043-1-4 | ST.948   | 142123          | SCX8.6    | VKB3000-009H  | SCX3.5  |
| G3362-3        | SCQ15.9 | P1)41109-6  | *FR11.5 | P1)56043-1-4 | VA14     | T42331          | SCX9.5    | VKB3000-010H  | SCX7.0  |
| G3626-4        | FRX23.6 | PU41109-9   | FR20.5  | PU56044-1-4  | ST.948   | T42677          | 0A6.1     | VKB3000-011H  | SCX7.0  |
| GL-450         | VCR33   | PU41595     | OSC21.2 | P1)56044-1-4 | VA15     | 142766-001      | 0C12.4    | VKB3000-012   | SCX7.0  |
| GL-V450V       | VCR33   | PU41644     | SCA3.0  | PU56647A     | ST.771   | 142816-001      | 0A10.1    | VKB3000-013   | SCY7.0  |
| GL450V         | VCR33   | P1)41644-2  | SCB8.1  | P1)56647A-3  | ST.771   | 143534-001      | 0613.2    | VKB3000-015   | SCY7.2  |
| J L-A1         | FRX23.6 | PU41895-2   | FRX1Q.4 | PU56647A-4   | ST.771   | 143713-001      | 0611.7    | VKB3000-016   | SCX5.1  |
| JL-A15         | FRX23.6 | P1)41944    | SCX5.1  | PU56647A-5   | ST.771   | 143856-001      | SCQ6.7    | VKB3000-017H  | SCX4.6  |
| JL-A20         | FRX23.6 | PU41945     | SCQ6.0  | P1)56647A-6  | ST.771   | 143977-001      | SCA7.5    | VKB3000-019   | SCX8.6  |
| JL-F30         | FRX23.6 | PU41946     | 0A10.9  | PU56647A-7   | ST.771   | 144111-001      | SCQ11.1   | VKB3000-020H  | SCX5.1  |
| JL-F35         | FRX23.6 | PU41946-2   | QA11.7  | PU57658A-1   | ST.948   | 144330-001      | SCX8.6    | VKB3000-022   | SCY3.5  |
| N43060-1       | SCA9.2  | PU42164     | ST.707  | PU57658A-4   | ST.948   | T44848          | FRM14.7   | VKB3000-023   | SCY4.4  |
| NJL5141E-B     | VCR7    | PU42165-2   | ST1.54  | PU57658A-4   | VA756    | T44939-001      | SCX12.2   | VKB3000-024   | \$CY6.7 |
| PG\$30043A     | VCR9    | PU43762-2   | 0A9.4   | P1)576586-1  | ST.948   | 144940-001      | 0X5.5     | VKB3000-025   | SCX7.0  |
| PG\$30044A     | VCR33   | P1)43762-3  | FRY11.5 | P1)576586-3  | ST.948   | 145147-001      | FRW12.6   | VKB3000-026   | \$006.0 |
| PGS40032A      | VCR9    | PU44050     | FRY12.0 | P1)576586-3  | VA752    | 145201-001      | SCX12.2   | VKB3000-027   | SCY4.6  |
| P22.771        | ST.771  | PU44050     | 0SQ22.8 | PU57658B-4   | ST.948   | T45202-001      | 0) (5.9   | VKB3000-028H  | SCY6.0  |
| PN2Q2-S1       | VCR21   | PU44121     | FRX6.7  | PU57658B-4   | VA752    | 145601-001      | SCX7.4    | VKB3000-030   | SCX7.4  |
| PN202N-N1      | VCR21   | PU44160     | SCY7.5  | P1)576586-6  | ST.948   | 145625-001      | SCX8.6    | VKB3000-031H  | SCY5.2  |
| PN202S-S1      | VCR21   | P1)44683-2  | SCX4.0  | PU576586-6   | VA752    | 145730-001      | SCX8.0    | VKB3000-039   | SCY8.6  |
| POM30003-14    | SCQ3.6  | PU44863     | SCX9.5  | P1)57855     | V754     | 145786-001      | SOX8.0    | VKB3000-049   | SCX1.9  |
| PPU44912-3     | SC 66.0 | PU44863-2   | SCY4.0  | PU58141      | VCR9     | 145786-002      | SCX7.4    | VKB3000Q-050  | SCY5.2  |
| PQ40134A       | VPR20   | PU448632    | SCY4.0  | PU58640      | VCR33    | T45831          | SCX10.7   | VKB3000-052   | SCX5.1  |
| PQ401346       | VPR20   | PU44911     | SCC12.1 | P1)58645-1   | ST1.130  | 145834-001      | SCX8.9    | VKB3000-053   | SCX8.0  |
| PQ40252A-1     | VPR20   | PU44912     | FR6.9   | P1)58645-1   | VA150    | 145989-001      | SCX7.0    | VKB3000-054   | SCY4.2  |
| PQ402526       | VPR20   | P1)44912-2  | FR11.5  | P2)58645-1-1 | ST1.130  | 146026-001      | SCY7.0    | VKB3000-055   | SCY8.6  |
| PQ402526-2     | VPR20   | P1)44912-3  | SOB5.7  | P1)58645-1-1 | VA150    | 146105-001      | SCX9.5    | VKB3000-057   | SCY5.1  |
| PQ4025213-4    | VPR20   | P1)44912-5  | FR9.4   | P1)58645-1-3 | VA150    | 146257-001      | SCQ10.0   | VKB3000-064   | SCY4.6  |
| PQ42006        | VPR23   | PU449122    | FR11.5  | P1)58645-1-4 | ST1.130  | 147566-001      | FRM12.1   | VKB3000-066   | SCY5.2  |
| PQ4200613      | VPR23   | PU449123    | SCB5.7  | P1)58645-1-4 | VA150    | 148235-001      | SCQ6.5    | VKB3000-069   | SCX2.4  |
| PQ420068-5     | VPR23   | PU449125    | SCY7.5  | PU58646-1-1  | ST1.130  | T48306-Q01      | SCX1Q.7   | VKB3000-071   | SCX7.0  |
| PQ44130A       | VPR26   | P1)44918    | ST1.53  | P1)58046-1-3 | ST1.130  | 160831          | QC11.7    | VKB3000-073   | SCY4.4  |
| PQ44130A-3     | VPR26   | P1)44918-2  | ST1.31  | P1)58646-1-4 | ST1.130  | 16302-002       | 0A8.5     | VKB3000-075H  | SCX10.7 |
| P058645-1-1    | ST1.130 | P1)44918-3  | ST.453  | P1)58648-1-1 | ST1.130  | 166931          | 0A8.2     | VKB3000-077   | SCX2.4  |
| P058645-1-1    | VA150   | P1)44963-2  | SCX4.3  | P1)58648-1-3 | ST1.130  | T66934          | QA6.6     | VKB3000-086   | SCX2.6  |
| P058645-1-3    | ST1.139 | PU45275A    | VPR7    | P1)58648-1-4 | ST1.130  | T66935          | 0A9.4     | VKB3000-102   | SCX4.6  |
| P058645-1-3    | VA150   | P1)45697-3  | FR20.5  | P1)59925-1-1 | VCR33    | 1E6000414-01    | SCX9.5    | VKB3000-1048  | FRM9.2  |
| P058645-1-4    | 511.130 | PU46560     | FR5.1   | PU60508M     | V762     | 1E8000464-01/02 | \$CX8.6   | VKB3000-114   | SCY16.8 |
| P058645-1-4    | VA150   | PU47549A    | VPR7    | PU60559      | ST1.130  | TEB265497-01    | SCX7.4    | VKB3000-115   | SCY4.4  |
| PQM30003       | SCY5.7  | PU4811C     | ST1.115 | P1)60559-1-1 | ST1.130  | 1E6265499-02    | SCQ6.5    | VKB3000-134   | SCX8.6  |
| PQM30003-10    | SCA6.7  | PU48726     | SCQ3.6  | PU60621      | VCR33    | TEB267513-01    | SCX8.9    | VKB3000-136   | SCY7.0  |
| PQM30003-12    | SCQ6.5  | PU48764     | FRM10.2 | P1)60621-1-1 | VCR33    | 1E6294496-02    | SCQ10.0   | VKB3000-139   | SCY10.1 |
| PQM30003-13    | SCA4.2  | PU48806     | ST1.115 | P1)60621-1-2 | VCR33    | 1E6294497-01    | SCQ6.5    | VKB3000-144   | SCQ4.8  |
| PQM30003-14    | SCQ3.6  | P1)48941-2  | SCQ3.6  | PU61223      | VCR33    | 1E6305407-01    | SCY7.0    | VKB3000070    | SCQ6.5  |
| PQM30003-15    | SCQ2.2  | PU489412    | SCQ3.6  | PUM30003     | SCY5.2   | TEB313499-01    | FRX12.7   | VKB3000102    | SCX4.0  |
| PQM30003-16    | SCQ6.5  | P1)489676   | ST1.113 | P1)M30003-1  | SCY5.7   | 1E8313500-01    | SCX9.5    | VKB3000114    | SCY16.8 |
| PQM30003-17    | SCA2.3  | P1)489676   | VA10    | PUM30003-12  | SCQ6.5   | TEB313508-02    | SCX7.4    | VKB3000115    | SCY4.4  |
| PQM30003-18    | SCB5.7  | PU49164     | FRW10.7 | P1)M30003-15 | SCQ2.2   | 1E8319901-01    | FR12.5    | VKB3000139    | SCQ5.1  |
| PQM30003-19    | SC65.7  | P1)49557-2  | VCR4    | P1)M30003-2  | SCY7.5   | 1E6336416-01    | SCY5.2    | VKB3001-003H  | FRX11.5 |
| PQM30003-20    | SCA2.3  | PU50350     | SCQ3.6  | PUM30003-24  | SCA11.5  | TEB336459-01    | SCY8.6    | VKB3001-004H  | FRX11.5 |
| PQM30003-23    | SCQ8.0  | PU50958     | SCC7.5  | P1)M30003-25 | SCQ5.3   | 1E6344451-01    | FRZ12.1   | VK53001-006H  | FRX9.7  |
| PQM30003-24    | SCA11.5 | P1)50958-2  | SCQ10.0 | P1)M30003-26 | SCA7.5   | 1E6344466-01    | SCY8.0    | VKB3001-007   | FRW10.1 |
| PQM30003-25    | \$CO5.3 | PU50959     | FRM11.2 | PUM30003-3   | SCY4.0   | 1E6345472-01    | FRW9.1    | VKB3001-008   | FRW10.1 |
| PQM30003-26    | SCA7.5  | P1)50959-2  | FRM10.5 | P1)M30003-5  | SCX5.5   | 1E6345473-01    | SCQ8.2    | VKB3001-011   | FRY10.0 |
| PQM30003-28-14 | SCA3.5  | PU51033     | ST1.580 | PUM30003-6   | SCQ2.2   | 1E6345476-01    | SCX7.0    | VKB3001-012   | FRM9.2  |
| PQM30003-29    | SCQ3.2  | P1.151250   | ST.515  | P1)M30003-7  | SCA14.1  | 1E6352441-01    | SCX9.5    | VKB3001-013   | FRM9.2  |
| PQM30003-5     | SCX5.5  | PU51367A    | VPR10   | PUM30003-8   | SCA3.5   | TEB352444-01    | SCY4.6    | VKB3001-014   | FRW8.0  |
| PQM30003-6     | SCQ2.2  | PU51380A-2  | ST.463  | PUM300031    | SCY5.7   | 1E63547454-01   | SCX10.7   | VKB3001-015   | FRX11.0 |
| PQM30003-7     | SCA14.1 | P151380A-2  | VA11    | PUM300036    | SCQ2.2   | 1E6357454-01    | SCX10.7   | VKB3001-016   | FRW8.0  |
| PQM30003-8     | SCA3.5  | PU51390A    | VB4     | PUM300037    | SCA14.1  | TEB357454-02    | SCX7.4    | VKB3001-017   | FRM9.2  |
| PQM3000310     | SCA6.7  | PU51402A    | ST.689  | PUM30004     | FRQ11.2  | V1355031-001    | SCX12.2   | VKB3001-020   | FRW7.7  |
| PQM3000314     | SCQ3.6  | PU51402A    | VA12    | PUM30008     | SCA3.5   | V41745-1        | SCX8.9    | VKB3001-047   | FR10.8  |
| PQM3000317     | SCA2.3  | PU52135     | V753    | PUS36752A    | VCR33    | V42289-1        | SCX9.2    | VKB3001-048   | FRX9.7  |
| PQM3000319     | SCB5.7  | P1)52165-2  | ST1.54  | PU\$36977A   | VCR9     | V43061-1        | SCY5.2    | VKB3001-049   | FRW8.5  |
| PQM3000320     | SCA2.3  | PU52390A    | VB4     | PUS465136    | VCR9     | V43066-2        | SCX10.5   | VKGE141425-C  | SCX3.5  |

= Part of the Assy

= Kit May Not Include Tires

^ = Part of the Assy

# JVC ... LEAR

| MFG. P/N       | PRB NO. | MFG. P/N        | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N         | PRB NO. | MFG. P/N    | PRB NO. |
|----------------|---------|-----------------|---------|----------------|---------|------------------|---------|-------------|---------|
| VKGE96295S-A   | SCY6.0  | D16021704       | SCX4.6  | <b>KL H</b>    |         | <b>KORVETTE</b>  |         | 369820      | 0A8.5   |
| VKGE96362S-A   | SCX9.5  | D16021808       | SCX7.0  | 0223003903     | 0A14.0  | 8322B            | SCX4.3  | 373820      | 0A9.4   |
| VKGE96744S-A   | SCX3.5  | 016021908       | SCX4.6  | <b>KMC</b>     |         | 8324B            | SCX4.3  | 400         | SCX8.0  |
| YQM30003-1     | SCQ4.0  | D16022504       | SCX9.5  | NBLTH022GE00   | FRW9.7  | 932521B          | FR7.7   | 403920      | 0A10.9  |
| YQM30003-2     | SCQ4.0  | D16022604       | SCY3.5  | NBLTK0032GE00  | SCQ6.0  |                  |         | 408220      | FRM11.2 |
| YQM30003-3     | SCQ4.0  | D16022708       | FRX25.0 | NBLTK0041GE00  | SCQ6.0  | <b>KRACO</b>     |         | 409020      | SCQ10.0 |
| <b>K MART</b>  |         | 016022804       | SCY6.0  | NIDL0006GEZZ   | ST1.211 | 00167            | SCX8.4  | 413920      | SCQ10.0 |
| 171131032      | FRM11.5 | 016023108       | FRW9.1  | NIDL0006GEZZ   | VA61    | 00168            | SCX4.0  | 441820      | OB10.9  |
| 3330902        | FRX9.7  | 016023208       | SCX7.4  | NIDL0006GEZZ   | VPR16   | 00255            | FRM8.0  | 443020      | SCA8.9  |
| <b>KENWOOD</b> |         | D16023308       | SCY4.6  | NROLR0009GEZZ  | VCR16   | 00286            | FRM10.2 | 443620      | SCA8.9  |
| 16034008       | SCX4.6  | D16023408       | SCY4.6  | RHPX0042GEZZ   | VCR7    | 010344           | FRM10.5 | 458920      | FRM11.2 |
| <b>KENWOOD</b> |         | D16023808       | SCX4.0  | RHPX0046GEZZ   | VCR33   | 025              | OB10.1  | 459020      | FRM11.5 |
| 0504007        | 0615.6  | D16023908       | SCQ5.6  | RHPX0053GEZZ   | VCR26   | 0521400019.      | FRM10.5 | 463420      | SCX8.0  |
| 0584031        | OSC18.5 | D16024004       | SCY5.2  | RHPX0176GEZZ   | VCR26   | 090135           | FRM10.2 | 474920      | SCA8.9  |
| 0854029        | 0A10.9  | D16024104       | SCY2.9  | RHPX0218GEZZ   | VCR7    | 10214            | 009.8   | 475020      | SCX8.0  |
| 211271         | 006.6   | D16024204       | SCY6.5  | <b>KNIGHT</b>  |         | 10215            | FRM10.2 | 477820      | SCX8.0  |
| 21V7131        | SCQ3.0  | D16024308       | FRW8.5  | 28162          | 007.4   | 1500286          | FRM10.5 | 477920      | 0010.9  |
| 230373         | SCC12.6 | D16024408       | SCX2.6  | 83A19          | 0814.0  | 2110             | OAI2.4  | 478020      | 0A10.1  |
| 241471         | SCX7.0  | D16024508       | SCY4.6  | 96RX676        | 007.4   | 21403            | 0A4.2   | 478320'     | FRM11.5 |
| 241472         | 0A9.4   | D16024608       | FRM7.5  | TB999          | FF12.6  | 233060           | FRM10.5 | 485420      | SCA8.9  |
| 241473         | 0A6.6   | D16024708       | FRW10.1 | 10171          | 0014.4  | 234463           | FRM9.2  | 493020      | 0A10.1  |
| 4066           | 0A7.0   | 016024808       | SCY7.0  | TR1548         | 006.1   | 23465            | FRM9.7  | 493120      | SCX4.6  |
| 95755599       | SCQ3.6  | D16025108       | SCY6.7  | TR2887         | 0A8.5   | 23590            | SCA8.6  | 500420      | SCX4.9  |
| 95759147       | SCQ3.6  | D16025204       | SCY3.2  | <b>KODAK</b>   |         | 23591            | SCA8.6  | 500720      | SCA8.9  |
| D116029508     | SCX3.5  | D16025303       | FRY25.0 | 106125         | 009.0   | 23639            | SCX8.0  | 514120      | SCX2.4  |
| 016000113      | FR15.9  | D16025313       | FR27.3  | 117520         | OC11.2  | 23657            | SCX5.1  | 514620      | SCX10.7 |
| D16000404      | 009.8   | D16025508       | FRY10.0 | 117758         | 0014.0  | 2921400047       | FRM10.2 | 522620      | SCX4.3  |
| D16000504      | 0A13.2  | D1602604        | SCB3.6  | 120244         | RF30.6  | 310901           | FRM11.2 | 525520      | FRM11.5 |
| 016001204      | OB9.4   | D16026308       | SCX2.6  | 120766         | OSC10.2 | 40145            | FRM11.2 | 529720      | FRM11.5 |
| D16001304      | 089.4   | D16027108       | SCX5.5  | 132024         | 0015.6  | 43094            | FRM11.2 | 529820      | SCX3.5  |
| D16002104      | SCX5.1  | D16027608       | SCQ3.2  | 151770         | 006.1   | 444              | FRM11.2 | 533020      | SCQ11.1 |
| D16002204      | SCQ5.6  | 016028204       | SCQ2.5  | 162128         | RF29.4  | 45408            | FRM11.2 | 533420      | SCQ6.5  |
| D16003004      | SCX13.6 | D16028708       | FR8.2   | 164227         | 0010.1  | 480              | FRM11.2 | 543720      | FRM11.5 |
| D16003104      | SCY7.0  | D16029308       | SCQ3.6  | 165616         | 005.4   | 5045             | FRM8.0  | 543820      | FRM11.5 |
| D16004309      | SCY8.6  | 016029608       | SCX2.4  | 166002         | OC15.6  | 5539             | FR5.9   | 546220      | 0A4.2   |
| D16004409      | SCX3.5  | D16030903       | SCQ3.0  | 166044         | 0014.0  | 5535             | FRM11.5 | 548420      | SCX8.0  |
| D16004509      | 0A4.2   | 016031208       | SCQ3.2  | 166718         | OC10.9  | 570A             | FRM9.7  | 550720      | SCA8.6  |
| D16004605      | FRX15.2 | D16031404       | SCX5.5  | 166719         | 008.5   | 588083           | FRM9.7  | 557020      | SCX8.0  |
| D16004609      | FRX15.2 | D16031908       | SCX5.1  | 170060         | 004.6   | 6310233          | FRM9.7  | 559120      | SCX4.9  |
| 016005208      | SCX9.5  | 016032008       | SCQ2.0  | 170187         | OB5.0   | 70078            | FRM11.0 | 559420      | SCX4.3  |
| D16005303      | SCY5.7  | D16032108       | SCY3.2  | 171555         | GRO6    | 7026             | FRM11.0 | 559520      | SCX8.0  |
| D16005308      | SCY5.7  | D16032308       | SCX4.9  | 171959         | SCC31.2 | 73888            | 009.8   | 9915471     | SCX8.6  |
| D16005408      | SCX4.6  | 016032408       | SCQ7.8  | 172632         | OB13.2  | 75070            | FRM11.5 | 9915679     | SCX8.6  |
| D16005508      | SCX9.5  | D16032608       | SCX8.4  | 172632         | 0013.2  | 77072            | FRM11.5 | 9915935L    | SCQ10.0 |
| D16005608      | SCX10.5 | D16033208       | FRW8.0  | 172633         | 0013.2  | 88075            | FRM11.2 | TR101       | OB10.9  |
| D16005703      | FRX22.4 | D160334108      | SCX3.5  | 173357         | 007.4   | 9470903          | FRW9.7  | <b>LEAR</b> |         |
| D16005908      | SCX16.0 | 016035008       | SCX7.4  | 174244         | 008.2   | 950              | 0A4.2   | 3709402003  | FRM12.7 |
| D16006308      | SCX5.5  | D16035708       | SCX5.1  | 176603         | SCA4.5  | 99144            | SCQ6.5  | 3736400001  | FRM11.2 |
| D16006408      | SCY9.2  | 016035808       | SCQ4.6  | 176959         | SCC31.2 | 99153            | SCX2.6  | 3739401024  | FRM10.7 |
| D16006804      | SCY4.6  | 016039708       | SCX15.5 | 178837         | 008*2   | A50381           | FRM10.5 | 3739402003  | FRM13.3 |
| D16006908      | FRW8.5  | D16060104       | SCX15.0 | 178838         | 007.4   | ADAMII           | 009.8   | 3739402004  | 0015.6  |
| D16007008      | SCY6.7  | D16060408       | SCY3.2  | 178976         | 0015.6  | BT0004           | FRM9.7  | 7731126401  | FRM10.5 |
| D16007308      | FR8.2   | 016060508       | SCX15.5 | 178977         | OC14.0  | D43              | FRM10.5 | 7731426401  | OB14.0  |
| D16007704      | SCY7.0  | D16060608       | SCX15.2 | 179108         | SCC31.2 | JC0103           | FRM10.5 | 7732000093  | SCQ6.5  |
| D16007908      | FRW10.1 | D16060608       | SCY15.2 | 179285         | 006.6   | JC0140           | FRM9.7  | 7732400079  | FRM11.0 |
| D16008204      | SCX7.0  | KHGB0100R0      | FRY23.6 | 179583         | SCC28.7 | JCOM             | FRM10.2 | 7732400117  | FRM9.7  |
| 016008808      | SCX14.7 | PU48967B        | ST1.113 | 180328         | SCC4.6  | KCB2390          | FRM10.2 | 7732406079  | FRW10.7 |
| D16008908      | SCX3.2  | SH1102710085    | SCO3.2  | 180648         | SCC4.6  | KCB4090          | FRW9.7  | 7733404639  | SCX12.2 |
| D16009308      | SCQ3.6  | W05031400       | FRY23.6 | 181165         | RF29.4  | KID566A400172    | FRW8.5  | 7733441978  | FRM11.8 |
| 016010408      | SCQ3.6  | <b>KEYSTONE</b> |         | 184245         | SCB24.2 | KID550           | FRX9.7  | 7734400103  | SCX12.5 |
| 016010903      | SCY14.7 | 11668           | 007.4   | 184246         | 0013.6* | KID560A          | FR8.8   | 773440103   | FRM11.7 |
| D16010908      | SCY14.7 | 12077           | WP55B   | 184247         | SCB6.7  | KID5600          | FRW8.5  | 7734730006  | FRM9.7  |
| D16010918      | SCY14.7 | 12830           | 008.5   | 186648         | SCB12.5 | KID565           | SCA8.6  | 7735710021  | FRM9.7  |
| D16012208      | SCX9.2  | 13076           | 0011.7  | 187417         | SCB24.2 | KID565A          | FRW8.5  | 7735750006  | FRM10.5 |
| D16012308      | SCX3.5  | 14065           | 009.4   | 190308         | SCC31.2 | KID566           | FRW8.5  | 7735850014  | FRM11.7 |
| D16012514      | SCX2.4  | 15386           | FRF8.9  | 191751         | 0A7.4   | K105808          | SCX5.1  | 7736400001  | FRM11.2 |
| D16014014      | SCX3.2  | 15405           | 006.6   | 193566         | SCC7.5  | KID580C          | 0A7.0   | 7739000047  | FRM11.2 |
| D16015708      | SCQ3.0  | 17513           | STC1.20 | 195092         | SCC8.7  | KIS006           | 0A4.2   | 7739007014' | FRM9.7  |
| 016016908      | SCX3.2  | 17794           | STC1.20 | 195116         | SCC10.0 | KIS014           | 0A8.2   | 7739010022  | FRM9.7  |
| 016017608      | FRY25.0 | 17803           | ST1.19  | 196012         | 0A10.1  | KIS025           | OC9.8   | 7739020495  | FRM11.0 |
| D16018308      | SCX15.2 | 17949           | WP55A   | 198413         | SCC9.6  | KIS444           | FRX9.7  | 7739030005  | FRM8.5  |
| D16019104      | SCQ3.2  | 19003           | 0010.9  | 199094         | 0012.8  | <b>LAFAYETTE</b> |         | 7739040010  | FRM10.5 |
| D16019204      | SC 83.6 | 203930          | STC1.20 | 203930         | 0010.9  | 175120           | 0A8.5   | 7739057041  | FRW8.5  |
| D16019904      | SCQ3.2  | 206380          | OB17.2  | 206380         | SCB6.9  | 1756             | OB14.0  | 782487B     | SCX8.9  |
| D16020008      | FRW9.0  | 210645          | 007.8   | 210645         | 007.8   | 261120           | FRM13.3 | 873034020   | SCA8.9  |
| D16020608      | FRW7.7  | 221253          | 0010.1  | 221253         | 0010.1  | 343120           | SCA8.6  | 8730340420  | SCA8.6  |
| D16020708      | SCY7.0  | 221254          | 0010.9  | 221254         | 007.0   | 359920           | SCB28.2 | 8730341049  | SCX8.6  |
| D16020808      | SCY4.6  | 63828           | 003.8   | 63828          | OC11.2  | 362720           | 0A5.4   | 8730341428  | SCQ10.0 |
| 016021304      | SCY8.6  | 83829           | FRF8.5  | 83829          | OC12.1  | 362820           | SCX2.4  | 8730342010  | SCY8.6  |
| D16021408      | FRY10.0 | <b>KORTING</b>  |         | <b>KORTING</b> |         | 366820           | 0A8.5   | 8730342920  | SCA8.9  |
| 016021508      | SCX7.4  | 3522015         | OSD1.6  | 3522015        | OB10.9  | 367920           | FRM11.2 | 8730343420  | SCA8.6  |
|                |         | 5322017         |         | 5322017        | SCAI2.5 | 369520           | SCX8.6  | 8730344010  | SCA8.6  |
|                |         |                 |         |                |         |                  |         | 8730345010  | SCA8.6  |

\*=ReplacementBelt

\*\* = Kit May Not Include Tires

= Part of the Assy

| MFG. P/N       | PRB NO. | MFG. P/N        | PRB NO.  | MFG. P/N     | PRB NO. | MFG. P/N  | PRB NO. | MFG. P/N       | PRB NO. |
|----------------|---------|-----------------|----------|--------------|---------|-----------|---------|----------------|---------|
| <b>LENCO</b>   |         | <b>LaBELLE</b>  |          | 483535837115 | SCA11.5 | 6480385   | 0A4.0   | VDVS0011       | SCB2.8  |
| 0700061        | FRM13.3 | 62218           | OB10.9   | 483535837116 | SCA13.2 | 64804811  | SOQ6.5  | VDVS0012       | FRW12.6 |
| <b>LINCOLN</b> |         | 65235           | QB7.7    | 483535837118 | SCX8.6  | 64804812  | SCX9.5  | VDVS0013       | SCB14.0 |
| 38510183       | SCX7.4  | 65236           | OB11.7   | 483535837119 | SCY6.0  | 64804814  | SCC8.7  | VDVS0015       | SCB9.8  |
| 38510184       | SCX4.3  | 65237           | FRW10.1  | 483535837125 | SCA8.6  | 64804815  | OC13.2  | VDVS0017       | FRW12.6 |
| 38510232       | 0A4.2   | 65238           | QA5.4    | 483535837126 | SCA4.2  | 6400011   | OB14.0  | VDVS0018       | FR11.9  |
| <b>LLOYDS</b>  |         | 65239           | SCX15.0  | 483535837133 | SCA8.6  | 64000910  | SCX9.5  | VDVS0019       | SCC12.1 |
| 0161180801     | VA80    | 69218           | 0811.7   | 483535837136 | SCA10.5 | 64C0121   | 0A9.0   | VDVS0020       | SCA13.2 |
| 161180801      | ST1.205 | <b>MAGNAVOX</b> |          | 483535837137 | SCQ6.5  | 64C0123   | SOX8.6  | VDVS0021       | FRW12.0 |
| 161180801      | VA80    | 007392400008    | VPRA3    | 483535837138 | SCA7.1  | 64C0126   | FRM9.7  | VDVS0022       | SCB14.0 |
| 16178179       | ST1.205 | 104             | QB9.4    | 483535857043 | SCA5.4  | 64C0129   | SCX12.2 | VDVS0023       | SCY7.5  |
| 16178179       | VA80    | 144259          | SCA3.0   | 483546457137 | VPR26   | 64F0021   | FRM11.5 | VDV\$0024      | SCY4.2  |
| 16180801       | ST1.205 | 144260          | SCX8.6   | 483546457347 | VPR26   | 64K00120  | SCA8.9  | VDVS0029       | FRW12.0 |
| 16160801       | VA80    | 144263          | ST1.160  | 483546477057 | VPR4    | 64K0017   | FRM11.2 | VDVS0032       | SCY7.5  |
| 16442161       | SQA8.6  | 144267          | SCQ9.8   | 4H35820161   | SCQ6.5  | 64N0011   | SCX12.2 | VDVS0033       | SCY5.0  |
| 1M31           | FRM12.1 | 146967          | FRW12.6  | 4H35820176   | SCX7.0  | 64N00112  | SCX7.0  | VDVS0034       | SCY4.0  |
| 1M32           | FRM12.1 | 146968          | FRW12.6  | 4H35830138   | SCY8.6  | 64N00113  | SCX8.6  | VDVS0035       | SCX4.3  |
| 1M53           | FRM12.1 | 146969          | FRW12.6  | 4H35830201   | SCY5.2  | 64N00114  | SCX8.0  | VDVS0037       | SCX6.2  |
| 2A1414A        | FRM9.7  | 147756          | SCX2.9*  | 4H35830223   | SCX9.5  | 64N00116  | SCX7.0  | VDVS0038       | SCB14.0 |
| 2A15           | FRM9.7  | 147916          | SCB14.0  | 4H35830283   | SCY5.2  | 64N00117  | SCX10.7 | VDVS0039       | SCC12.5 |
| 2A156          | FRM9.7  | 148580          | ST1.330  | 4H35830284   | \$CY2.2 | 64N00118  | OC12.4  | VDVS0040       | SCA5.4  |
| 2A62           | FRM10.5 | 148664          | SCA4.5   | 4H35830285   | SCX7.0  | 64N0012   | SCA8.9  | VDVS0042       | SCB10.0 |
| 2M4707A        | FRM11.0 | 148668          | SCX8.6   | 4H35830286   | SCX8.6  | 64N00120  | FRM12.1 | VDVS0043       | SCX6.2  |
| 2M75           | FRM12.1 | 149432          | SCY3.2   | 4H35830287   | SCY3.5  | 64N00123  | SCA8.9  | VDVS0044       | SCB2.5  |
| 2V61           | FRM10.5 | 152412          | SCA13.2  | 4H35830327   | SCQ6.5  | 64N00127  | SCX5.1  | VDVS0045       | SCA4.5  |
| 2V76           | FRM10.5 | 152413          | SCQ6.5   | 4H35830328   | FRW9.2  | 64N00513  | \$006.5 | VDVS0046       | SCB8.1  |
| 2V7614A        | SCX2.4  | 152683          | ST1.230  | 4H35830362   | SCY6.5  | 64N00514  | 0A8.2   | VDVS0047       | S0610.0 |
| 2V83           | FRM11.5 | 155739          | ST1.370  | 5392400100   | 522915  | 64N0053   | OB12.4  | VDVS0048       | SCA8.9  |
| 2V96           | SCA8.6  | 155739          | VA28     | 6400011      | VCR33   | 64N00614  | SCA8.9  | VDVS0052       | SCA8.9  |
| 5224703610     | VPR17   | 155803          | SCB14.0  | 64001212     | 0A10.1  | 64N0062   | SCQ11.1 | VDVS0053       | SCC39.5 |
| 5274701110     | FRW9.7  | 155805          | FRW12.0  | 6407591      | SCX4.3  | 64N00620  | SCA8.6  | VIDVS0054      | SCQ4.3  |
| 5274701610     | SCA3.0  | 155806          | FRW12.0  | 6407594      | FR15.9  | 64N00621  | SCA7.5  | VDVS0055       | SCB8.1  |
| 5C41           | QA10.9  | 155807          | FRW12.6  | 6451430001   | SCX8.6  | 7010541   | SCA8.9  | VDVS0057       | SCB11.6 |
| 5G23305E       | V764    | 155813          | FRW12.6  | 6451430002   | FRW12.0 | 7011751   | FRM12.1 | VDVS0058       | SCA4.5  |
| 80001526       | FRQ11.2 | 155826          | SCY7.5   | 6451430003   | FRW12.0 | 7012502   | OB14.0  | VDVS0059       | SCA4.2  |
| 80001607       | FR8.2   | 18139027        | SCY5.0   | 6451430004   | FRW12.0 | 7012503   | QB14.0  | VDVS0060       | SCQ2.5  |
| 80001608       | SCB10.0 | 1813903         | VCR1     | 6451430005   | SCC12.1 | 70125C1   | 0A10.1  | VDVS0066       | SCB11.6 |
| 80002139       | FR3.6   | 185271          | VCR2     | 6451430006   | FR11.9  | 7013171   | 50(12.2 | VDVS0122       | SCA4.5  |
| 80002258       | SCQ3.0  | 185272          | SCA8.9   | 6451430007   | FR11.9  | 701404    | SCX12.2 | VDVS0212       | SCQX5.1 |
| 8M36           | SCA8.6  | 18C00124        | SCB9.5   | 6451430008   | SCA4.5  | 701405    | SCX12.2 | VXLS0165       | VB2     |
| 8V84           | SCA8.6  | 3253BK21        | VCR1     | 6451430009   | SCA13.2 | 701406    | SCX12.2 | VXLS0383       | VA215   |
| 9M20           | SCA8.6  | 44A0016         | 0A4.2    | 6451430010   | SCY7.5  | 701423    | SOX12.2 | VXLS0454       | VA215   |
| 9V23           | SCA8.6  | 44AK019         | SCA8.6   | 6451430011   | SCY4.2  | 701424    | SCX12.2 | VXLS0666       | VPR2    |
| 9V23114A       | SCX8.6  | 44C0015         | FRM7.5   | 6451430016   | SCA3.0  | 7014541   | FRM11.2 | VXLS0770       | VPR2    |
| 9V2372         | SCA8.6  | 44N00115        | SCA14.1  | 6451430017   | FRW12.6 | 7015481   | FRM11.2 | VXP0047        | ST.470  |
| 9V72A114A      | SCX8.6  | 44Y00110        | 0A10.1   | 6451430018   | SCB14.0 | 70164318  | SCX12.2 | VXP0174        | ST1.160 |
| 9V87           | SCA8.6  | 44Y00111        | SCX4.0   | 6451430019   | SCQ9.8  | 701667    | FRM11.5 | VXP0174        | VA23    |
| 9V88           | SCX7.0  | 44Y00112        | SCQ6.5   | 6451430020   | OX5.5   | 7016751   | FRM10.5 | VXP0213        | ST.752  |
| 9V95           | SCA8.6  | 44Y0014         | SCX4.9   | 6451430023   | SCX8.6  | 70A00410  | ST.536  | VXP0213        | VA200   |
| 9V95           | SCA8.6  | 44Y0Q19         | FRM9.7   | 6451430024   | FRW12.6 | 70B00113  | 0A4.2   | VXP0329        | ST1.330 |
| 9V95114A       | SCX8.6  | 482235810111    | SCQ10.0  | 6451430025   | FRW12.6 | 7000024   | ST.752  | VXP0329        | VA20    |
| E20101         | OC11.2  | 482235810113    | SCQ6.5   | 6451430027   | FR10.4  | 7000024   | VA200   | VXP0331        | ST1.230 |
| E20374         | QA104   | 482235810115    | SCX8.9   | 6451430028   | FR10.4  | 7000026   | ST1.160 | VXP0331        | VA25    |
| FK03013        | FRM115  | 482235810148    | SCQ6.5   | 6451430029   | FR10.4  | 7000028   | ST1.160 | VXP0334        | ST1.330 |
| FK03207        | SCX8.9  | 482235830778    | SCX5.1   | 6451430031   | FRX6.7  | 70N0075   | 0A4.2   | VXP0344        | ST1.330 |
| FK13689        | SCX8.6  | 482235830813    | FR21.5   | 6451430033   | SCA3.0  | 76210858  | OB12.4  | VXP0344        | VA26    |
| FK03740        | 0A7.4   | 482235830853    | FRX20.7  | 6451430037   | FRW12.6 | 76210868  | FRM12.1 | VXPS0047       | ST.470  |
| FK03901        | SCQ10.0 | 482235830928    | SCQ3.6   | 6451430039   | FRW12.6 | ICPN38TP1 | 10PN-38 | VXPS0054       | ST1.370 |
| FK04160        | FRM11.2 | 482235830929    | SCX8.6   | 6451430039   | FRW12.6 | PN205     | VCR26   | VXPS0054       | VA28    |
| FK04274        | FRM12.1 | 482235831132    | SCY7.5   | 6451430058   | SCA14.1 | VDV0022   | SCA13.2 | VXPS0076       | ST.670  |
| FK04975        | SCX8.6  | 482235831225    | SCQ7.2   | 6451430066   | SCQ6.5  | VDV0029   | FRW12.0 | VXPS0116       | ST1.165 |
| FK0D5480       | FRX11.3 | 482235831231    | SCY5.2   | 6451430070   | SCB14.6 | VDV0072   | SCB14.0 | VXPS0116       | VA27    |
| V33            | SCX4.3  | 482235831292    | SCY7.0   | 6451430076   | SCX4.9  | VDV00721  | SCB14.0 | VXZ0076        | VB6     |
| V56            | FRM11.2 | 482235831306    | SCX7.0   | 6451430081   | SCA14.1 | VDV0074   | SCA3.0  | VXZS0005       | VB1     |
| V5634A         | FRM11.2 | 483521027027    | VCR33    | 6451430098   | SCY4.6  | VDV00741  | SCA3.0  | VXZS0129       | VB1     |
| V58            | FRM10.5 | 483521667019    | V758     | 6451430100   | FRW10.7 | VDV0075   | SCX8.6  | VXZS0137       | VB1     |
| V92114A        | SCA8.6  | 483521837002    | VCR22    | 6451430101   | SCX7.4  | VDV0076   | OX5.5   | <b>MARANTZ</b> |         |
| Y55157A        | FRM12.1 | 483521837008    | VCR22    | 6451430102   | SCX6.2  | VDV0092   | SCQ9.8  | 0008891202     | SCX8.9  |
| V609100A       | QA10.1  | 483525227005    | IC P-N15 | 6451430103   | SCB14.0 | VDV0094   | FRW12.6 | 016178178      | ST1.205 |
| V612           | 0A8.5   | 483525227015    | ICP-N38  | 6451430104   | SCB12.5 | VDV0120   | SCC12.1 | 016178179      | ST1.205 |
| V62437A        | FRM11.5 | 483528097013    | VCR33    | 6451430108   | SCB14.0 | VDV0121   | FR11.9  | 1021281264010  | SCY4.2  |
| V642           | FRM9.7  | 48353583114     | SCQ7.8   | 6451430152   | SCB10.0 | VDV0122   | SCA4.5  | 1021264020     | SCQ5.7  |
| V670           | FRM10.5 | 483535837025    | SCA3.0   | 6451430153   | SCQ6.5  | VDV0123   | SCA13.2 | 1021264030     | SCY9.0  |
| V69713218A     | SCA8.9  | 483535837075    | FRQ11.2  | 6451430189   | SCB2.5  | VDV0124   | SCY6.3  | 1021264050     | FRX11.3 |
| V899(100A)     | SCX4.3  | 483535837076    | SCA14.1  | 6451430247   | SCA10.0 | VDV0125   | SCX4.9  | 102T264060     | SCX7.0  |
| VA7854100A     | SCA8.9  | 483535837077    | SCQ7.2   | 6451433018   | SCB2.5  | VDV0130   | SCX3.5  | 1531264010     | FRW6.5  |
| VC1921         | SCA8.6  | 483535837078    | \$CQ6.5  | 6495200057   | SCA8.9  | VDV0166   | SCQ4.0  | 1531264020     | SCY6.7  |
| VC2960         | SCA8.6  | 483535837105    | SCQ6.5   | 6495200218   | SCQ3.6  | VDV0212   | SCX5.1  | 1581264200     | SCQ6.0  |
| VC6099         | 0A10.1  | 483535837107    | SCY10.2  | 6480011      | SCX4.0  | VDV0216   | SCQ6.5  | 1581264210     | SCY5.0  |
| Y61607         | FRM9.7  | 483535837112    | SCA3.0   | 6480022      | 0A8.2   | VDV0217   | SCX8.6  | 1591264200     | \$CX5.1 |
| Y63407         | FRM9.7  | 483535837113    | SCC12.6  | 6480023      | OC10.5  | VDV0218   | SCY3.2  | 1591264210     | SCX4.3  |
| Y63907         | FRM9.7  | 483535837114    | SCQ7.8   | 6480381      | FRW8.5  | VDVS0001  | SCX8.0* | 1591264220     | FRX12.7 |
| Y854193A       | OB14.0  |                 |          | 64B0382      | 0A6.1   | VDVS0005  | FRX6.7  | 16178174       | ST1.205 |
|                |         |                 |          |              |         | VDVS0008  | SCX3.5  |                |         |

\* = Part of the Assy

" = Kit May Not Include Tires

= Part of the Assy

# MARANTZ . MONTGOMERY WARD

| MFG. P/N   | PRB NO. | MFG. P/N           | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N          | PRB NO. | MFG. P/N          | PRB NO. |
|------------|---------|--------------------|---------|----------------|---------|-------------------|---------|-------------------|---------|
| 16178362   | VPR14   | SQ4401             | FRM11.2 | 522C05502      | VPR3    | 19198007          | FRM12.1 | 521M03701         | SCA12.0 |
| 16178363   | VPR14   | SQ4461             | FRM11.2 | 522C055030     | VPR3    | 19198008          | FRM10   | 521 M03702        | SCA12.0 |
| 16180801   | STt205  |                    |         | 522C055040     | VPR7    | 19198009          | FRM10.5 | 521M04105         | SCX4.0  |
| 16180801   | VA80    | <b>MA THERS</b>    |         | 522006001      | SCX8.6  | 19198010          | FRM10.5 | 522400201         | ST1M14  |
| 161T264200 | SCY5.2  | 665431             | SCX8.9  | 522P00201      | ST.599  | 19198011          | FRM10   | 522A00201         | VA91    |
| 161T264210 | FRWTO   | 665500             | SCY5.0  | 522P00201      | VA90    | 25204007070       | SCX8.6  | 522A002010        | STt014  |
| 16441731   | SCQ2.5  | 665505             | SCQ5.7  | 524900301      | FR8.8   | 25201=7010A07     | SCX8.6  | 522A002010        | VA91    |
| 16442161   | SCA8.6  |                    |         | 641B101020     | ST:927  | 63198002          | SCX4.0  | 522901701         | VA96    |
| 16629251   | SCQ3.6  | <b>MEDALLION</b>   |         | 65210100H01    | FRZ7.5  | 63198003          | SCY8.6  | 5229017010        | ST.850  |
| 2007264010 | SCY2.9  | 487A               | SCX4.3  | 891K93203      | SCX4.0  | 65198             | FRM10.5 | 5229017010        | VA96    |
| 2007264020 | FR2a0   | 487B               | SCX2.6  | 891K93204      | SCX8.0  | 65198001          | SCX7.0  | 522B01801         | VA97    |
| 2007264040 | SCY5.2  | 516                | SCA8.9  | 904Y0114       | FRM12.7 | 65198002          | SCQ2.5  | 5229018010        | VA97    |
| 2016636140 | SCY6.0  | 65155221           | OA4.2   | 944005201      | SCX8.6  | 65198006          | SCA8.6  | 522902002         | VA98    |
| 2077264010 | SCQ6.0  | 65155384           | OA4.2   | L5210001H01    | FRW7.0  | 65198007          | FRM11.5 | 5220055010        | VPR3    |
| 216526410R | FRW10.1 | 65198001           | SCX7.0  | L5210002H01    | SCY4.6  | 65198010          | SCX4.3  | 5220055020        | VPR3    |
| 216526411R | FRW10.1 | 65198002           | SCX2.4  | L5210004H01    | SCX9.2  | 65198011          | SCX1a7  | 5220055030        | VPR3    |
| 21 V7099   | SCY7.8  | 65198003           | FRM12.1 | M04142628      | SCX4.0  | 65198034          | SCX7.4  | 522C055040        | VPR7    |
| 2255264010 | FRX25.0 | 65198004           | FRM10.5 | M04142629      | FRX23.6 | 67198001          | SCX13.6 | 522016101         | VPR18   |
| 2272264010 | SCX4.6  | 65198006           | SCA8.6  | M04162629      | FRZ3.6  | 67198003          | FRM9.7  | 5220174010        | VPR27   |
| 242T26412R | SCY5.2  | 65198009           | FRM10   | M04165550      | SCY8.0  | 67198004          | SCX8.9  | 522P002010        | ST.599  |
| 252T264110 | SCX4.3  | 65198010           | SCX4.3  | M04172713      | SCX4.6  | 67198005          | FRX9.7  | 522P002010        | VA90    |
| 2949264010 | FRX25.0 | 65198011           | SCX1a5  | M04172714      | FRW8.5  | 67198013          | SCX7.4  | 64113093010       | VA92    |
| 307Y264020 | SCQ6.5  | 65198012           | FRM11.5 | M04172715      | SCX7.0  | AMC87070A186      | OA8.2   | 6419094010        | VA93    |
| 313Y264010 | FRX6.7  | 65198014           | FRM9.7  | M04172716      | SCX2.9  | AMC1107050A07     | SCA8.9  | 6419101010        | ST.927  |
| 3435264010 | SCX9.2  | 65198015           | FRM1a2  | M04184713      | SCX4.9  | M1D7052A07        | SCX8.6  | 6419101020        | ST.927  |
| 3444264010 | SCY7.0  | 65198016           | FR8.8   | M05067552      | SCY6.0  | MNM6410A47        | FRM10.5 | 641052501         | VA754   |
| 3445264010 | SCY7.0  | 65198017           | SCA8.6  | M05111550      | FRM1t7  |                   |         | 641063601         | VA753   |
| 3448264010 | SCY101  | 65198018           | SCX4.3  | M05111551      | SCY1a5  | <b>MITSUBISHI</b> |         |                   |         |
| 3448264020 | SCY6.0  | 65198019           | FR8.8   | M05129551      | SCY6.7  | 10036501          | SCX3.2  | 6410711010        | VA95    |
| 35290322   | VCR21   | 65198020           | FRW8.5  | M05129552      | SCX3.5  | 10036504          | SCX14.5 | 891K93203         | SCY4.0  |
| 36904255   | VCR33   | 65198021           | 009.8   | M05147550      | SCY5.2  | 10058501          | SCY15.2 | 891K93204         | SCX8.0  |
| 4111264010 | SCX8.9  | 65198023           | FR8.8   | M05147551      | SCQ4.8  | 10058502          | SCX2.9  | 891K94303         | SCX4.0  |
| 4113264012 | SCY4.6  | 65196025           | FRW8.5  | M05155550      | SCY6.5  | 260P45101         | VCR21   | 891K94408         | FRW8.5  |
| 4197264010 | SCY5.2  | 65198026           | SCX4.0  | M05163552      | FRX9.0  | 260P45102         | VCR21   | 891K95708         | SCX16.0 |
| 4223264010 | SCY5.2  | 65198027           | SCY8.6  | M05163553      | SCQ4.8  | 264P30701         | VCR33   | 925C16701         | VCR22   |
| 4223264020 | SCY6.5  | 65198028           | SCX2.4  | M05174550      | SCQ5.6  | 264P30702         | VCR9 &  | 928015402         | VCR22   |
| 424Z264010 | SCX5A   | 65198032           | FRM9.7  | NM5176550      | SCY7.0  |                   | VCR33   | 928C15501         | VCR33   |
| 4276264010 | SCX5A   | 65198033           | FRX6.6  | M05202550      | SCX4.3  | 264P307020        | VCR9 &  | 928C15601         | VCR7    |
| 4278264010 | SCY6.0  | 65198034           | SCX8.0  | M05223713      | SCY5.2  |                   | VCR33   | 928C156010        | VCR7    |
| 4278264020 | SCY5.0  | 65198035           | SCA8.6  | M05223714      | SCQ6.0  | 266P00901         | VCR8    | 928016701         | VCR22   |
| 427Z264010 | SCX4.6  | 65198036           | SCX8.4  | M05232713      | FR7.7   | 268P009010        | VCR8    | 928C27601         | VCR22   |
| 427Z264020 | SCX3.5  | 65198037           | SCX4.0  | M05240713      | SCY7.0  | 266P014020        | VCR15   | 9280306010        | VCR9 &  |
| 434Z264010 | FRZ12.1 | <b>MERITON</b>     |         | M07558713      | FRX25.0 | 268P02601         | VCR9    |                   | VCR33   |
| 4367264010 | SCX9.2  | <b>ELECTRONICS</b> |         | M07602714      | OX5.5   | 268P045010        | VCR16   | 9480020010        | VPR27   |
| 4367264030 | SCQ6.5  |                    |         | M1713482       | FR8.8   | 299P03503         | NLA     | 9480020010        | VPR27/  |
| 4380264020 | SCX4.6  |                    |         | <b>MIDLAND</b> |         |                   | VCR21   |                   | VPRa6   |
| 4380264030 | FRW9.1  | 05314000019        | FRW9.7  | 12150021       | 0815.6  | 299P04208         | SCY15.2 | FRM2t4            | FR21.5  |
| 4380264050 | SCX4.6  | 56291280289        | FRM14.0 | 12198003       | SCX2.4  | 410216010         | SCX2.9  | GL450             | VCR33   |
| 4382264010 | SCX1a7  | 563501137506       | FRX1t2  | 12198004       | SCA8.6  | 410219680         | SCX3.2  | GL451             | VCR33   |
| 4382264020 | SCX7.4  | 56350137560        | FRX1t2  | 12198005       | OA8.5   | 410219700         | SCX14.5 | L521D026H01       | SCY6.0  |
| 4383264020 | FRZ12.1 | 56350154805        | FRM14.0 | 12198006       | SCX8.6  | 4102198680        | SCX3.2  | L52108011101      | SCQ5.7  |
| 4397264010 | FRW8.0  | 56350338982        | FRM9.7  | 12198008       | OA6.1   | 5210032010        | SCY8.2  | M04184713         | SCX4.9  |
| 4397264020 | SCY3.5  | 56360133785        | FRM11.5 | 12198008       | OA7.0   | 5210032020        | SCY8.0  | NM4184714         | SC06.0  |
| 8001602    | SCY7.0  |                    |         | 12198011       | SCA8.6  | 5210033010        | SCA6.7  | NM5232713         | FR7.7   |
| PX0501     | SCX16M  |                    |         | 12198012       | OA3.1   | 5210034010        | SCY9.2  | PU57855-01        | V754    |
|            |         |                    |         | 12198014       | OA6.1   | 5210040010        | SCA8.9  | PU5785501         | V754    |
|            |         |                    |         | 12198015       | OA10.9  | 5210041010        | FR1a8   | ROV90ZB           | OA5A    |
|            |         |                    |         | 12198016       | OA10.9  | 5210042010        | SCB6.6  |                   |         |
|            |         |                    |         | 12198018       | OATO    | 5210046010        | SCAT1   | <b>MONTGOMERY</b> |         |
|            |         |                    |         | 12198021       | OC14.4  | 5210049010        | SCB3.8  | <b>WARD</b>       |         |
|            |         |                    |         | 12198022       | OC10.9  | 5210050010        | FRM10.5 | 12601202          | FRW8.5  |
|            |         |                    |         | 12198023       | SCA12.5 | 521005020         | SC04.8  | 2012A119          | FRW12.6 |
|            |         |                    |         | 12198024       | OC11.2  | 5210053010        | SCB9.5  | 2012A128          | FRM11.2 |
|            |         |                    |         | 12198025       | OA10.9  | 5210062010        | SCB9.5  | 2012A132          | FRM10.5 |
|            |         |                    |         | 12198026       | FRM12.1 | 5210081010        | SCA1a5  | 3100032010        | 0013.2  |
|            |         |                    |         | 12198028       | SCX8.6  | 5210082010        | SCA3.0  | 3100032014        | 0011.2  |
|            |         |                    |         | 12198033       | FRM12.1 | 521L00401         | SCX4.0  | 3100032015        | OCa0    |
|            |         |                    |         | 12198034       | OBa0    | 521L00402         | SCX8.0  | 36MW175           | FR12.5  |
|            |         |                    |         | 12198035       | SCA8.9  | 521 M00501        | FRW8.5  | 36MW187           | SCX8.6  |
|            |         |                    |         | 12198036       | FRM12.7 | 521M0051          | FRW8.5  | 36MW283           | SCX8.6  |
|            |         |                    |         | 12198038       | SCA8.9  | 521M00801         | SCA9.6  | 36MW284           | SCX5.1  |
|            |         |                    |         | 12198039       | OA9.4   | 521 M01701        | SCX8.0  | 36MW285           | SCX14.7 |
|            |         |                    |         | 12198040       | OA7.0   | 521M01802         | SCQ5.3  | 36MW285           | FR12.5  |
|            |         |                    |         | 12198041       | FRM12.1 | 5211001902        | SCQ4.0  | 36MW75            | SCA8.9  |
|            |         |                    |         | 12198042       | FRM11.5 | 5211002301        | SC04.8  | 38MW33            | SCX8.6  |
|            |         |                    |         | 12198046       | SCX8.0  | 5211002501        | SC03.6  | 38N1W451          | SCQ1a0  |
|            |         |                    |         | 12198049       | SCX10/  | 521M02601         | SC06.5  | 390109            | FRX9.7  |
|            |         |                    |         | 12198051       | SC01a0  | 521 M02901        | SCQ5.6  | 39587             | FRM9.7  |
|            |         |                    |         | 12198052       | SCX10/  | 521M03001         | SCY9.2  | 39N1W115          | OBTO    |
|            |         |                    |         | 12198053       | SCX10.7 | 521 M03101        | SCX8.9  | 39MW122           | SCX4.0  |
|            |         |                    |         | 12198054       | SCA8.6  | 521 M03102        | SCX4.0  | 39MW147           | OA11.7  |
|            |         |                    |         | 140            | SCX8.6  | 521M03103         | FRX9.7  | 39MW202           | SCX8.6  |
|            |         |                    |         | 19198001       | FRM12.1 | 521M03105         | SCXa5   | 39MW232           | OA10.9  |
|            |         |                    |         | 19198003       | FRM11.5 | 521 M03401        | SCX3.2  | 39MW245           | FRM11.2 |
|            |         |                    |         | 19198005       | FRM12.1 | 521M03601         | SCX7.0  | 39MW326           | FRM14.0 |

\* = Replacement Belt

\*\*= Kit May Not include Tires

= Part of the Assy

# MONTGOMERY WARD ... NEC

| MFG. P/N   | PRB NO.  | MFG. P/N   | PRB NO.  | MFG. P/N        | PRB NO. | MFG. P/N        | PRB NO. | MFG. P/N   | PRB NO. |
|------------|----------|------------|----------|-----------------|---------|-----------------|---------|------------|---------|
| 39Mw329    | ST.536   | 900 Series | FRM12.1  | J39418          | SCA8.9  | 42P63025A35     | 004.2   | MR70       | FRM9.7  |
| 39Mw333    | 0A8.2    | 900 Series | omo. i   | J39521          | SQX7.0  | 42P63025A71     | 0814.0  | MR97       | FRM9.2  |
| 39Mw334    | SCX2.6   | 900 Series | 0011.2   | J39522          | SCX9.5  | 42P63025AA79    | 0812.4  | MUSTANG    |         |
| 39Mw498    | FRX11.7  | 900 Series | 009.0    | J39637          | SCA8.9  | 42X970213A02    | SCX4.9  | 4242683801 | FRM11.2 |
| 39Mw5      | FR15.9   | GA121238   | FRM11.2  | J39663          | FRM11.5 | 42X9702BA03     | FRM8.0  |            |         |
| 39Mw509    | FRM10.5  | GA121230   | FRM11.2  | J39954          | 0A4.2   | 42X97028A04     | SCX8.6  | NAD        |         |
| 39Mw52     | FR5.9    | GA121230   | FRM11.2  | J82138          | FRM11.2 | 42X9702BA05     | 0A4.0   | F44504     | FRY6.7  |
| 39Mw529    | FRM12.1  | GA12123E   | FRM11.2  | NBLIK0058GE00   | SCQ3.2  | 42X97214A01     | 0A10.1  |            |         |
| 39Mw53     | SCX4.9   | QA12123F   | FRM11.2  | NBLTK0059GE00   | SCA8.6  | 42X97214A05     | 0A6.1   | NAKAMICHI  |         |
| 39Mw555    | FRM12.1  | GA12223B   | FRM11.2  | ZCX16731A       | FR12.5  | 42X97214A06     | FRX9.7  | 0008782A   | FRW10.1 |
| 39Mw699    | FRM9.7   | GA122230   | FRM11.2  |                 |         | 44P60018A01     | W05     | 0008783A   | SCX7.0  |
| 39Mw734    | SCX10.7  | GA12325A   | FRM10.5  | <b>MORSE</b>    |         | 44P60018A04     | W05     | 0080034    | FRX6.7  |
| 39Mw741    | SCX8.0   | GA12325B   | FRM10.5  | 00064           | FRM9.7  | 49P60018A01     | W05     | 0003651    | 0X5.9   |
| 39Mw91     | FRM10.2  | GA123250   | FRM10.5  | 004042010       | SCA8.9  | 49P60018A73     | W05     | 0003668    | FRW10.1 |
| 46M030     | FRM10.5  | GA12326A   | FRM9.7   | 21V7013         | FRM11.5 | 49P60081A04     | W05     | 0005080    | 0A6.6   |
| 46M035     | FRW9.7   | GA12335A   | FRM10.5  | 21V7020         | FRM9.7  | 49P63025A61     | 01310.9 | 0005081    | SCQ6.7  |
| 46M039     | FRM10.2  | GA12335B   | FRM10.5  | 21V8500         | FRM10.5 | 59E60760A02     | W05     | 0005104    | FRQ13.6 |
| 46M048     | FRM9.7   | GA123350   | FRM10.5  | 29M946          | FRM12.1 | 59E60880A03     | W05     | 0005139    | SCX7.4  |
| 46M050     | FRM9.7   | GA12355A   | FRM10.5  | 46M0003         | SOA12.5 | 59E60880A04     | W05     | 0005334    | SCX4.6  |
| 46M059     | FRQ11.2  | GA12355B   | FRM10.5  | 46M006          | FRY12.0 | 59E60880A06     | W05     | 0005465    | 0A7.0   |
| 5610902    | FRM10.5  | GA123550   | FRM10.5  | 46M008          | FRM11.5 | 59E60919A04     | W05     | 0005699    | SCX7.0  |
| 580013     | FRM12.7  | GA12356A   | FRM9.7   | 46M012          | FRM11.2 | 59E60919A06     | W05     | 0008096    | FRM9.2  |
| 580054     | FRM9.7   | GA12425A   | FRM10.5  | 46M016          | FRM12.1 | 59E60919A08     | W05     | 0008097    | SCY4.4  |
| 61         | FRM11.2  | GA12425B   | FRM10.5  | 46M017          | FRM11.7 | 59E61456A01     | W05     | 0008098    | SCY9.0  |
| 62128038   | FRM13.3  | GA124250   | FRM10.5  | 46M022          | FRM10.5 | 59E61456A02     | W05     | 0008099    | SCQ4.8  |
| 623699     | SCX8.6   | GA12435A   | FRM10.5  | 46M023          | FRM10.5 | 59E61457A01     | W05     | 0008224    | SCY4.2  |
| 62377050   | FRM11.5  | GA12435B   | FRM10.5  | 46M024          | FRM12.0 | 59E61457A02     | W05     | 0008334A   | FRW8.8  |
| 623920     | SCX8.6   | GA124350   | FRM10.5  | 46M029          | FRM11.0 | 59E61457A03     | W05     | 0008343    | SCY6.5  |
| 62396997   | SCA8.6   | GA12455A   | FRM10.5  | 46M030          | FRM10.5 | 59E61458A01     | W05     |            |         |
| 62400431   | FRW8.5   | GA124555   | FRM 10.5 | 46M033          | FRM11.2 | 59E61458A02     | W05     |            |         |
| 62405856   | SCX2.4   | GA124550   | FRM10.5  | 46M034          | FRM12.7 | 59E61458A03     | W05     |            |         |
| 62459514   | FRM11.2  | GA12533A   | FRM11.2  | 46M035          | FRW9.7  | 59E61459A01     | W05     | NEC        |         |
| 62470917   | FR5.9    | GA1253313  | FRM11.2  | 46M036          | SCX8.4  | 59E61459A02     | W05     | 16175252   | VPRA1   |
| 62477164   | 0137.0   | GA12534A   | FRM11.2  | 46M038          | FRM12.1 | 59E61460A06     | W05     | 16178172   | ST1.205 |
| 62477644   | SCX4.0   | GA125348   | FRM11.2  | 46M039          | FRW10.1 | 59E61460A07     | W05     | 16178176   | ST1.205 |
| 62477946   | 0A11.7   | GA12543A   | FRM11.2  | 46M042          | FRW10.1 | 59E61985A01     | W05     | 16178176   | VA80    |
| 62480246   | FR15.9   | GA125438   | FRM11.2  | 46M043          | FRM10.5 | 59E61985A02     | W05     | 16178177   | ST1.205 |
| 62451870   | FRM10.2  | GA12544A   | FRM11.2  | 46M046          | FRW10.1 | 59E61985A03     | W05     | 16178177   | VA80    |
| 62492180   | FRM11.5  | GA125448   | FRM11.2  | 46M047          | FRM9.7  | 59E61985A04     | W05     | 16178178   | ST1.205 |
| 62493666   | SCX4.9   | QA12553A   | FRM11.2  | 46M048          | FRM11.0 | 59E61985A05     | W05     | 16178178   | VA80    |
| 62528923   | QA8.2    | GA125538   | FRM11.2  | 46M050          | FRM11.2 | 59E61985A06     | W05     | 16178179   | ST1.205 |
| 62528931   | SCX2.6   | GA12554A   | FRM11.2  | 46M051          | 0A7.0   | 59E61985A07     | W05     | 16178179   | VPRA1   |
| 62549947   | FRM14.0  | GA12554B   | FRM11.2  | 46M052          | SCX7.4  | 59E61985A08     | W05     | 16178361   | VPR14   |
| 62559292   | FRM11.5  | GA12724A   | FRM11.2  | 46M057          | SCQ5.6  | 59E61985A09     | W05     | 16178362   | VPR14   |
| 62582618   | FRM11.5  | GA12724B   | FRM11.2  | 46M058          | SCX10.5 | 59E61986A01     | W05     | 16178363   | VPR14   |
| 62589434   | FRM10.5  | GA12754A   | FRM 11.2 | 46M059          | FRQ11.2 | 59E61986A03     | W05     | 16180801   | ST1.205 |
| 62595604   | FRM10.5  | GA127548   | FRM11.2  | 46M060          | FRM10.5 | 59E61987A01     | W05     | 16180801   | VA80    |
| 62607750   | FRM9.7   | GC12001A   | FRM11.5  | 46M088          | 0A4.0   | 59E61987A02     | W05     | 16180802   | ST1.205 |
| 62629614   | FRM12.1  | GC12001B   | FRM11.2  | 46M38           | FR12.5  | 59E61988A02     | W05     | 16180802   | VA80    |
| 62662409   | FRM11.2  | GC12010A   | FRM11.5  | 71040101        | FRM11.2 | 59E62783A01     | W05     | 16183652   | VPR14   |
| 62670940   | SCA8.9   | GC12422A   | FRM11.2  | 71040297        | FR12.5  | 59E62783A02     | W05     | 16183653   | VPR14   |
| 52682973   | FRM11.2  | GC12422B   | FRM11.5  | 71040619        | FRM12.1 | 59E62783A03     | W05     | 16185251   | ST1.205 |
| 62685336   | SCA8.6   | GC12432A   | FRM11.5  |                 |         | 59E62784A04     | W05     | 16185251   | VA80    |
| 62685536   | SCA8.6   | GC12432B   | FRM11.2  | <b>MOTOROLA</b> |         | 59E62785A01     | W05     | 16185252   | ST1.205 |
| 62688866   | SCX1,0.7 | GC12452A   | FRM11.5  | 42063025A35     | 005.8   | 59E62891A01     | W05     | 16185252   | VA80    |
| 62738057   | FRX1iv   | GC12521A   | FRM11.5  | 4207970213A05   | 0A4.0   | 59E62892A01     | W05     | 16185853   | VPR11   |
| 62755024   | SCX9.5   | GC12531A   | FRM11.5  | 4240151F03      | 0A8.5   | 59E63555A01     | W05     | 16425501   | FRY16.0 |
| 62866640   | FRY10.7  | GC12532A   | FRW12.6  | 4240426801      | FRM11.2 | 59E63555A02     | W05     | 16425521   | 0012.1  |
| 62092900   | SCX4.6   | G012541A   | FRM11.5  | 424081G01       | FRM10.5 | 59E63555A04     | W05     | 16425531   | 007.0   |
| 62693214   | FRX10.5  | G012542A   | FRW12.6  | 4241225801      | FRM12.1 | 59E63555A05     | W05     | 16425541   | SCX9.2  |
| 62900474   | SCX10.5  | GC12551A   | FRM11.5  | 4241503G03      | FRM10.5 | 59E63555A06     | W05     | 16425551   | SCQ5.6  |
| 62900520   | SCY6.5   | GC12552    | FRW12.6  | 4242308P01      | FRM9.7  | 59E63555A07     | W05     | 16425561   | 0011.2  |
| 62900539   | SCX8.9   | GC12622A   | FRM11.5  | 4242561002      | SCB8.1  | 59E63556A01     | W05     | 16425791   | FR8.9   |
| 62904984   | SCY6.5   | GC12642A   | FRM11.5  | 4242683801      | FRM12.1 | 59E63556A02     | W05     | 16425971   | FR7.8   |
| 62918527   | FRQ11.2  | GC12652A   | FRM11.5  | 4242683802      | FRM12.1 | 59E63556A03     | W05     | 16429131   | SCQ3.0  |
| 62928026   | SCQ5.6   | J36388     | FRM13.3  | 4242683803      | FRM10.5 | 686             | FRM11.2 | 16429972   | SOB10.0 |
| 62956763   | FRW8.5   | J391070    | FRM11.0  | 4242683804      | FRM8.0  | 6868TME95MA/G/R | FRM11.2 | 16430212   | FRQ11.2 |
| 62979194   | FRX9.7   | J391171    | FRM10.5  | 4242683805      | FRM9.7  | 83 Series       | FRM11.2 | 16432191   | FR2.7   |
| 63071641   | FRW9.7   | J391188    | FRM9.7   | 4242996801      | FRM9.6  | 8TMFOSMA/G/R    | FRM11.2 | 16432192   | FR2.7   |
| 63190403   | SCY5.0   | J391203    | FRM10.5  | 4243114001      | FRM10.5 | 8TMF9SMA/G/R    | FRM11.2 | 16432421   | SCX8.0  |
| 63190624   | SCY5.7   | J391250    | SCX4.6   | 4243114001      | FRM9.7  |                 | FRM11.2 | 16434702   | FRQ11.2 |
| 67157      | 0B14.0   | J391278    | FRX10.5  | 4243393A16      | FRM9.7  | <b>MUNTZ</b>    |         | 16435081   | SCQ2.5  |
| 700A858273 | FRM11.5  | J391297    | FRW8.5   | 4243871A01      | FRM11.2 | 1269            | FRM9.2  | 16438611   | SCY7.5  |
| 700A858676 | FRM9.7   | J391300    | SCX10.5  | 4243871801      | FRM11.2 | 281002          | FRM9.2  | 16441731   | 5002.5  |
| 750A858273 | FRM11.2  | J391305    | SCY6.5   | 4244954G02      | SCA8.9  | 281013          | 0815.6  | 16442161   | SCA8.6  |
| 800054     | FR12.5   | J391306    | SCX8.9   | 4244954G03      | SCX9.5  | 281014          | FRM13.3 | 16442162   | SCA8.6  |
| 80Mw337    | 0A10.9   | J391391    | FRW8.5   | 42A43653U01     | SCA9.6  | 360196          | FRM9.7  | 16442731   | SCQ2.5  |
| 820048     | FRM8.0   | J391406    | SCQ5.6   | 4284046801      | FRM11.2 | 602000500       | FRM11.7 | 16629251   | SCQ3.6  |
| 82Mw88     | 0814.0   | J391432    | SCX4.0   | 42641045001     | FRM11.2 | 602001900       | FRM11.7 | 16631241   | SCA6.7  |
| 854A54     | 0B9.0    | J391491    | FRX10.5  | 42841225801     | FRM12.1 | 602002100       | FRM10.2 | 79V20038   | VB4     |
| 854A56     | 0B12.4   | J391498    | FRW8.5   | 42842683801     | FRM11.2 | 602002100       | FRM12.1 | 79V20041   | ST.689  |
| 654A908    | 0A8.2    | J391623    | FRW8.5   | 42842683803     | FRM11.5 | 602002200       | FRW9.1  | 79V20041   | VA12    |
| 8900111    | FR12.5   | J391645    | SCY6.5   | 4284268803      | FRM10.5 | 67A12321        | FRW10.7 | 79V20052   | SCY5.7  |
| 8999093    | FRM10.5  | J391657    | FRX9.7   | 4284283801      | FRM11.2 | ME114549A       | 0B11.7  | 79V20943   | SCQ5.7  |
| 899A2      | W11      | J39417     | FRW8.5   | 42843003801     | FRM11.7 | ME1145608       | 0A13.2  | 79V23059   | ST.463  |
|            |          |            | 0A5.4    | 42844954G02     | SCA8.9  | MR10            | 0615.6  | 79V23059   | VA13    |

= Part of the Assy

" = Kit May Not Include Tires

= Part of the Assy



# NEC ... PANASONIC

| MFG. P/N        | PRB NO. | MFG. P/N              | PRB NO. | MFG. P/N       | PRB NO. | MFG. P/N            | PRB NO. | MFG. P/N        | PRB NO. |
|-----------------|---------|-----------------------|---------|----------------|---------|---------------------|---------|-----------------|---------|
| 79V23066        | SCA14.1 | 482235830078          | SCA14.1 | VDVS0019       | SCC12.1 | 24602222            | FRM9.7  | PQFB13Z         | SCX5.1  |
| 79V23068        | FRM11.0 | 482235830096          | SCQ10.0 | VDVS0020       | SCA13.2 | 27300840            | SCQ3.0  | PQFB14Z         | SC06.0  |
| 79V24001        | VA18    | 482235830097          | SCX3.5  | VDVS0023       | SCY7.5  | 27301079            | SCA3.2  | PQFB15Z         | SCA12.0 |
| 79V24201        | VPR20   | 482235830098          | SCB12.5 | VDVS0024       | SCY4.2  | 27301162            | SCA3.2  | PQFB18Z         | SCA12.0 |
| 79V24802        | ST.988  | 482235830116          | SCQ5.6  | VDVS0029       | FRW12.0 |                     |         | PQFB21Z         | SCA12.0 |
| 79V24802        | VA18    | 482235830123          | SCQ10.0 | VDVS0037       | SCX6.2  | <b>ORRTRONIC</b>    |         | PQFB2Y          | SCA12.0 |
| 79V27134        | SCQ3.6  | 482235830126          | SCX4.6  | VDVS0038       | SCB14.0 | 371215000           | FRM9.2  | PQFB2Z          | SCA12.0 |
| 79V29379        | VP R20  | 482235830128          | SCY8.6  | VDVS0039       | SCB12.5 | 371800315           | 0816.4  | PQFB3Y          | SCX8.0  |
| 79V29402        | ST.948  | 482235830131          | OB15.6  | VDVS0040       | SCA5.4  |                     |         | PQFB3Z          | SCX8.0  |
| 79V29414        | SCA6.7  | 482235830132          | SCX4.9  | VDVS0042       | SCB10.0 | <b>PACKARD BELL</b> |         | PQFB4Z          | SCY6.5  |
| 79V29591        | VPR20   | 482235830133          | SCX15.0 | VDVS0043       | SCX6.2  | 141526402           | SCX4.9  | PQFB5Z          | SCY6.7  |
| 82247MS1        | VCR7    | 482235830135          | SCX13.6 | VDVS0044       | SCB2.5  | 180926402           | 0A5.8   | PQFB6Z          | SCX12.2 |
| 824110S1        | VCR7    | 482235830136          | SCY8.6  | VDVS0047       | SCB10.0 | 186926401           | 0A5.8   | PQFB7Z          | SCX4.9  |
| 82457PR1        | VCR9    | 482235830137          | SCX8.0  | VDVS0048       | SCA8.9  | 3739401001          | 0C14.4  | PQFB8Z          | SCA12.0 |
| 82457PS1        | VCR9    | 482235830138          | SCY8.6  | VDVS0052       | SCA8.9  | 415                 | FRM11.5 | PQFB9Z          | SCC14.8 |
| 82604PR1        | VCR9    | 482235830145          | SCX15.0 | VDVS0053       | SCB9.5  | 417                 | FRM11.5 | PQF11002Z       | PRO2    |
|                 |         | 482235830148          | SCX8.0  | VDVS0057       | SCB11.6 | 419                 | FRM11.5 | PQF11003Z       | PRO2    |
| <b>NIKKO</b>    |         | 482235830152          | SCX8.6  | VDVS0066       | SCB11.6 | 772068              | 0A10.1  | POF11004Y       | PRO2    |
| 7903180         | SCY3.5  | 482235830155          | SCQ6.7  | VDVS0066       | VB2     |                     |         | POF11004Z       | PRO2    |
| 7903190         | SCY6.0  | 482235830181          | SCQ6.5  | VXLS0165       | VA215   | <b>PANASONIC</b>    |         | PQF11007Z       | PRO2    |
| 7903200         | FRM9.6  | 482235830182          | FRX20.7 | VXLS0454       | VA215   | ON1102              | VCR10   | PQVD4Z          | SCX9.5  |
| 7903250         | SCY7.0  | 482235830189          | SCX12.2 | VXP0329        | ST1.330 | ON1105              | VCR11   | ODAK0006        | SCX2.4  |
| 7903360         | SCY8.6  | 482235830195          | SCA13.2 | VXP0329        | VA20    | ON2160              | VCR14   | ODB0001         | 0A5.8   |
| 7903400         | SCQ5.6  | 482235830196          | FRX22.4 | VXP0331        | ST1.230 | ON2160              | SCA3.0  | QDB0002         | SCX7.0  |
| 7903420         | FRW8.5  | 482235830224          | FRX23.6 | VXP0331        | VA25    | 144259              | SCX8.6  | Q DB0003        | SCA12.5 |
| 7903450         | SCX4.3  | 482235834017          | SCX3.2  | VXPS0054       | ST1.370 | 144263              | ST1.160 | QDB0005         | SCA12.5 |
| 7903550         | FRW6.5  | 482235870194          | STC.823 | VXPS0054       | VA28    | 144263              | VA23    | QDB0007         | SCX4.3  |
| 7903610         | SCX7.4  | 482245100736          | SCA14.1 | VXP50076       | ST.670  | 144267              | SCQ9.8  | 0080008         | SCA8.6  |
| 7903670         | FRX10.5 | 48224512215302        | SCX2.4  | VXPS0116       | ST1.165 | 146967              | FRW12.6 | 'QDB0009        | SCX4.0  |
|                 |         | 482252810032          | STC.742 | VXPS0116       | VA27    | 146968              | FRW12.6 | QDB0012         | 0B7.6   |
| <b>NIPPON</b>   |         | 482252810078          | STC.823 | VXZ0076        | VB6     | 146969              | FRW12.6 | QDB0013         | 0A6.6   |
| 19496531        | SCX8.9  | 482252820059          | ST.828  | VXZ50129       | VB1     | 147756              | SCX2.9* | QDB0014         | 0A4.0   |
|                 |         | 482252870183          | SCX2.4  | VXZ50137       | VB1     | 147916              | SCB14.0 | QDB0016         | 0815.6  |
|                 |         | 482252870186          | STC.823 | <b>NUTONE</b>  |         | 148664              | SCA4.5  | QDB0018         | SCX5.1  |
|                 |         | 482252880147          | STC.823 | 6614A          | FRW10.1 | 152412              | SCA13.2 | QDB0021         | 0C9.8   |
| <b>NOREL CO</b> |         | 4822528X10162         | SCX2.4  | <b>OLYMPIC</b> |         | 152683              | ST1.230 | QDB0022         | FF12.6  |
| 130302215302    | FR12.5  | 482269120023          | SCX2.4  | 40SC217        | FRM11.2 | 152683              | VA25    | QDB0025         | 0A7.4   |
| 130302215443    | SCX2.4  | 482269144660288       | OA.53   | 42843003B01    | FRM11.2 | 155739              | ST1.370 | QDB0026         | 0B10.9  |
| 130302221126    | SCA8.9  | 482269148611          | SCQ5.6  | 60SD63B        | FRM11.2 | 155739              | VA28    | QDB0026         | 0B10.9  |
| 13034440282     | SCX2.4  | 482269148613          | SCX11.8 | 8336           | FRM11.2 | 155803              | SCB14.0 | QDB0027         | FRM11.7 |
| 30076           | SCX8.6  | 482269149521          | SCA12.0 | A48451         | FRM12.1 | 155806              | FRW12.0 | QDB0030         | 0A13.2  |
| 30077           | SCX2.6  | 482269149522          | SCB28.2 | BLA60669       | FR14.1  | 185272              | SCB9.5  | Q DB0031        | OB13.2  |
| 30123           | SCQ10.0 | 482269149529          | SCA10.5 | BLA70595       | 0812.4  | 236104              | FRM11.2 | QDB0034         | OB10.9  |
| 30126           | SCX4.6  | 482269149604          | SCB24.2 | BLJ70719       | FRM11.2 | 23B106              | FRM11.2 | QDB0035         | FF12.6  |
| 30128           | SCX13.6 | 482269149608          | SCA12.0 | BLJ70747       | SCQ11.1 | 281002              | SCX13.6 | QDB0037         | 0A8.5   |
| 30137           | SCX8.0  | 482269149609          | SCB28.2 | BLJ70747       | SCQ11.1 | 364619000           | SCQ6.5  | QDB0041         | 089.0   |
| 30138           | SCY8.6  | 482269149614          | SCX4.3  | BLJ707886      | FRM11.5 | 364656400           | FRX15.2 | Q DB0042        | 0A8.5   |
| 30148           | SCX8.4  | 482269149663          | SCB12.5 | BL71535        | FR14.1  | 3713001             | SCQ6.5  | QDB0042         | 0A8.5   |
| 310328401102    | SCX10.7 | 4822691R651010        | SCB16.6 | <b>ONKYO</b>   | FRM12.1 | 79V25304            | FRM9.7  | QDB0043         | SCQ10.0 |
| 310410605403    | SCX8.9  | 4822691VU95000        | SCX8.0  | 246020100      | SCY3.2  | 8A11090             | FRM12.1 | QDB0044         | 0A10.1  |
| 310720401100    | FRM13.3 | 4822691VU95001        | SCQ5.6  | 246020106      | FRX9.7  | 8SR3020             | FRM12.1 | QDB0047         | SCB16.6 |
| 310730300100    | FRM13.3 | 4822691VU95002        | SCX8.6  | 246020107      | SCX8.6  | 8SR505              | FRM12.1 | QDB0048         | 0A10.9  |
| 3583005497      | SCQ6.7  | 4822691VU95003        | SCB12.5 | 246020108      | SCX3.2  | 8SR802              | FRM15.2 | QDB0049         | OB5.6   |
| 35830123        | SCQ10.0 | 4822691VVT49609       | SCB28.2 | 246020109      | SCX2.6  | A110684A            | V775    | QDB0050         | SCX11.8 |
| 35834035102     | SCY6.5  | 4822691VVT88245       | ST.965  | 246020119      | SCY5.2  | ENC86811            | SCY6.3  | Q DB0051        | 0C9.8   |
| 35870194        | STC.823 | 4822691W189826        | ST.965  | 246020121      | SCY2.2  | EW02X0454           | SCB14.0 | Q DB0052        | SCA11.1 |
| 482216300915    | SCX2.6  | 4822691X21500692      | ST1.21  | 246020129      | FRW10.1 | EW02X0576           | FRW12.0 | QDB0053         | SCA11.1 |
| 482216300916    | STC.742 | 4822691X4034004       | STC.742 | 246020132      | SCY3.5  | EW02X0580           | SCB12.0 | QDB0054         | 0A9.0   |
| 482216300921    | OA.53   | 52810225              | STC.823 | 246020134      | FR9.0   | EW02X0850           | SCA5.4  | QDB0055         | 0A9.4   |
| 482216301027    | SCB21.2 | 52810227              | STC.742 | 246020134      | SCX3.2  | EW02X0906           | SCB10.0 | QDB0058         | SCA11'1 |
| 482217500964    | STC.742 | 52880326              | STC.823 | 246020222      | FRX6.7  | EW02X0907           | SCQ6.5  | QDE10060        | OC12.4  |
| 482217501126    | SCX8.6  | X4034004              | STC.742 | 246020243      | FRM9.7  | EW02X0953           | ST1.165 | QDB0061         | 0A10.1  |
| 482217501252    | STC.823 | <b>NORTH AMERICAN</b> |         | 246020243      | FRM7.0  | EW02X0953           | VA27    | Q DB0062        | SCX7.0  |
| 482221200617    | SCB18.1 | <b>PHILIPS</b>        |         | 246020243      | FRM7.0  | EW02X2594           | SCB8.2  | QDB0063         | 0815.6  |
| 482221200688    | SCX4.6  | 483535837075          | FRQ11.2 | 246020245      | SCY7.0  | LN59                | VCR33   | QDB0065         | FRM12.7 |
| 482221200692    | ST1.21  | 483535837076          | SCA14.1 | 246020248      | SCX7.4  | N288510             | OB14.0  | Q DB0066        | OC14.4  |
| 482221200726    | SCA14.1 | 483535837077          | SCQ7.2  | 246020252      | FRW9.1  | N28852A             | OC10.9  | QDB0070         | 089.4   |
| 482221201012    | STC.823 | 483535837078          | SCQ6.5  | 246020253      | SCX4.0  | ON2160              | VCR14   | QDB0073         | FRM13.3 |
| 482221201016    | SCX4.3  | 7044250019            | ST1.230 | 246020254      | SCX5.1  | PBE14719            | PRO2    | Q DB0076        | 0A11.7  |
| 482221201074    | SCB28.2 | 7044250019            | VA25    | 246020254      | SCY5.1  | PBE5100             | SCX4.6  | QDB0082         | SCX3.5  |
| 482235830007    | SCX2.4  | 7044250156            | ST.752  | 246020259      | FRY10.0 | PBE5171             | SCX2.9  | QDB0083         | SCX9.5  |
| 482235830009    | SCB12.5 | 7044250156            | VA20    | 246020262      | SCY5.2  | PN150NV             | VCR22   | QDB0083         | SCX9.5  |
| 482235830014    | SCB21.2 | 7044250160            | ST1.160 | 246020272      | SCX4.0  | PN158NV             | VCR23   | <b>ODB00831</b> | SCX9.5  |
| 482235830015    | SCB24.2 | 7044250160            | ST1.160 | 246020272      | SCY4.6  | PN205               | VCR26   | QDB0083         | SCX9.5  |
| 482235830016    | SCA12.0 | 7044250160            | VA23    | 246020277      | SCX7.4  | PQDV102             | SCY4.4  | QDB0083         | SCA9.6  |
| 482235830017    | SCB28.2 | 7044250160            | VA23    | 246020277      | SCY5.2  | PQDV37              | SCQ11.1 | QDB0084         | SCY5.2  |
| 482235830018    | SCB16.6 | 7044250337            | ST1.370 | 246020278      | SCY5.2  | PQDV3Z              | SCQ11.1 | QDB0085         | SCA11.1 |
| 482235830026    | SCB18.1 | 7044250337            | VA28    | 246020279      | FRW8.5  | PQDV4Z              | SCX9.5  | QDB0086         | SCX4.0  |
| 482235830045    | SCX11.8 | 7044250414            | ST1.330 | 246020289      | SCY5.2  | PQDV5Z              | SCX12.2 | QDB0087         | SCA7.5  |
| 482235830048    | SCX8.6  | 7044250414            | VA26    | 246020293      | SCY3.5  | PQFB10002Z          | SCX5.1  | Q DB0088        | 0A8.2   |
| 482235830051    | SCX12.2 | 7044250414            | VA26    | 246020294      | SCY3.5  | PQFB10004Z          | SCX5.1  | QDB0089         | SCX8.6  |
| 482235830052    | SCX4.9  | VDV0074               | SCA3.0  | 246020297      | SCY7.0  | PQFBIOZ             | SCY5.2  | QDB0090         | SCX2.4  |
| 482235830054    | SCQ6.5  | VDV0122               | SCA4.5  | 24602132       | SCX3.2  | PQFB11Z             | SCY4.0  | QDB0095         | 0A3.1   |
| 482235830055    | SCX7.0  | VOVS0018              | FR11.9  | 24602134       | FRX6.7  | POFB12Z             | SCX5.1  | Q DB0097        | SCQ5.6  |

\* = Replacement Belt

\*\* = Kit May Not Include Tires

= Part of the Assy



# PANASONIC ... PANASONIC

| MFG. P/N  | PRB NO. | MFG. P/N  | PRB NO. | MFG. P/N  | PRB NO. | MFG. P/N     | PRB NO. | MFG. P/N      | PRB NO.  |
|-----------|---------|-----------|---------|-----------|---------|--------------|---------|---------------|----------|
| QDB0099   | \$006.5 | QDB0241   | FRM11.7 | QDBT0008  | SCX3.5  | RYA0290      | SCX9.5  | VDV0123       | SCA13.2  |
| QDB0100   | SCX8.0  | QDB0243   | SCY3.5  | 04B-10009 | KA11.1  | SFGB3211     | FRX22.4 | VDV0124       | SCY6.0   |
| 0060103   | SCX2.4  | QD/30244  | SCY6.0  | QD5T0010  | SCY3.5  | SJY90060     | FRX22.4 | VCA0125       | SCX4.9   |
| QDB0106   | SCY8.6  | QDB0245   | SCY4.4  | QDBT0011  | FRM10.5 | SJY900802    | FRX23.6 | VDV0128       | SCX3.2   |
| 0050107   | SCA7.5  | QDB0246   | FRW9.2  | QDBT0012  | SCY4.6  | SJY900803    | FRX23.6 | VDV0130       | SCX3.5   |
| Q080108   | \$QX4.0 | QDB0247   | SCY5.2  | QDEA0006  | SCX3.5  | SJY900902    | FRX23.6 | V0V0135       | SCA13.2  |
| Q050109   | SCQ5.6  | Q DB0248  | FRW9.1  | 000353    | SCX8.4  | SMQ1056      | SCY5.2  | VDV0136       | SCA3.5   |
| QDB(110   | SCQ8.0  | 0080249   | SCY4.2  | QDP1-0011 | FRM10.5 | SMQ1372      | SCX9.5  | VDV0138       | SQB7.1   |
| 0060111   | SCA8.9  | QD130252  | FRW12.0 | QDQK0003  | STC.742 | SMQ140       | SCY9.0  | VDV0144       | SCA3.2   |
| QDB0113   | SCX8.6  | 0080253   | SCX4.3  | QDQK0005  | SCX4.9  | SMQ1502      | FRW10.7 | VDV0148       | SCQ6.5   |
| QD50114   | SCX4.0  | QDB0255   | SCY8.0  | QDQK0006  | SCX2.6  | SMQ1554      | SCQ10.0 | VDV0149       | SCB10.0  |
| QDB0117   | SCA8.9  | Q0B0256   | SCY4.2  | QUN1623   | FRX9.7  | SMQ1588      | SCY6.5  | VDV0154       | SCA4.5   |
| QDB0118   | SCY4.6  | Q Q0257   | SCY8.6  | QXD0038   | ST.536  | SMQ1668      | FRW10.1 | VDV0155       | SC B8.1  |
| QDB0120   | QC13.2  | QD50259   | SCX2.9  | QXD0065   | ST.536  | SMQ1688      | FRW10.1 | VDV0157       | SCB2.6   |
| Q050121   | SCY8.6  | QDB0267   | FRW9.0  | QXD0066   | ST.536  | \$MQ1776     | SCY7.0  | VDV0166       | SCQ4.0   |
| 0060122   | 0A3.1   | QDB0268   | SCY4.4  | QXL0054A  | 0A4.2   | SMQ1788      | FRW7.0  | VDV0167       | SCQ4.6   |
| QDB0123   | SCA11.1 | QDB0269   | FRX9.5  | QXL0074   | 0A4.2   | SMQ1988      | SCY7.0  | VDV0170       | SCA4.0   |
| QDB0124   | SCY8.6  | QDB0270   | SCY3.5  | QXL0450A  | 0A4.2   | SMQ20Q3      | SCY7.0  | VDV0209       | SCA4.5   |
| 0080126   | SCA8.6  | QDB0271   | SCY2.2  | QXL0903   | 0A4.2   | SMQ2011      | SCY6.0  | VDV0212       | SCY5.1   |
| QDB0128   | SCQ6.0  | Q DB0272  | FRZ5.1  | QXL0994   | FRM11.2 | SMQ2062      | SCY8.0  | VDV0215       | SCA5.0   |
| QDBQ129   | SCQ6.0  | QDB0273   | SCY3.5  | QXL1138   | FRM9.6  | SMQ2134      | FRW7.1  | VDV0216       | SCQ6.5   |
| QDB0130   | SCA8.6  | Q050274   | SCY4.2  | QXL9873   | 0A4.2   | SMQ2168      | SCY5.2  | VDV0217       | SCX8.6   |
| QDB0131   | SCA8.6  | QD50279   | SCX7.4  | QXLB844   | 0A4.2   | SMQ2182      | SCX9.2  | V0V0218       | SCY3.2   |
| QPB0132   | 0A4.0   | 0080280   | SCX4.0  | QXMA0012  | ST.536  | SMQ2184      | SCY4.6  | VDV0230       | SCC12.1  |
| QDB0133   | SCX9.2  | 00B0281   | FRW10.1 | QXP0319   | ST.536  | SMQ2418      | FRW8.5  | VDV02318      | SCY3.2   |
| Q0B0134   | FRM13.3 | Q0B0282   | FRX5.7  | QXP0320   | ST.536  | SMQ2438      | SCY5.2  | VDV05016      | 005.8    |
| QDB0135   | FRM12.7 | QDB0283   | SCX5.1  | QXP0328   | ST.536  | SMQ2542      | SCY4.4  | VDV0502       | OC4.2    |
| QDB0136   | SCY7.4  | QDB0284   | SCY3.5  | QXP0373   | ST.536  | SMQ2556      | FRW10.1 | V0V25         | OSD13.4  |
| QDB0137   | FRX11.3 | 0080266   | SCY3.5  | QXPK0022  | ST.536  | SMQ2770      | FRW8.0  | VDV3          | OSC7.3   |
| 0080140   | SCX7.0  | 0080287   | SCQ5.6  | QXPM001   | ST.536  | SMQ2792      | SCY4.2  | VDV32         | 0011.2   |
| Q0B0141   | FRX9.7  | Q080288   | SCY5.2  | QXRA0001  | ST.536  | SMQ2836      | FRW10.1 | VDV5002       | OC11.2   |
| QDB0142   | SCY5.2  | QDB029Q   | SCX3.2  | RDV00061  | SCQ5.6  | SMQ3042      | FRX7.5  | VCJ/5014      | SCQ22.0  |
| 0050143   | SCY6.7  | QDB0291   | FRW9.1  | RDV0007   | FRW6.1  | SMQ3044      | SCX7.0  | VDV5015       | SCC8.7   |
| 0050144   | SCX4.3  | 0080292   | SCY8.0  | RDV0009   | FRX9.5  | SMQ3070      | SCY4.2  | VDV5016       | 005.8    |
| QDB0148   | SCX4.0  | 0080293   | SCY2.2  | REA/0014  | SCY1.2  | SMQ3076      | SCY4.6  | VDV5019       | SCC12.1  |
| Q0130150  | SCY10.2 | 0080294   | SCY4.4  | RDV0015   | FR8.2   | SMQ\$098     | SCX4.3  | VDV5020       | FR11.5   |
| C12130152 | SCQ10.0 | Q0B0295   | SCY5.2  | RDV0021   | FRW6.1  | SMQ3100      | SCY5.2  | VDV5022       | QA4.2    |
| QDB0154   | SCY7.0  | QDB0296   | SCY2.9  | RDV0024   | SCA3.5  | SMQ3760      | SCY7.0  | VDV5023       | QC9.4    |
| Q080155   | FRM14.0 | Q0130297  | FRW8.0  | RDV0032   | SCY8.0  | SMQ3770      | SCY7.8  | VDV5024       | FR20.5   |
| QDB0156   | SCX2.9  | 00B0306   | FRW5.0  | RDV0036   | SCQ4.0  | SMQ394       | FRM1Q.2 | VDV5025       | FR17.2   |
| 0050157   | OB6.6   | QDB0308   | SCX7.4  | RDV1082A  | FR8.2   | SMQ4066      | \$CY6.5 | VDV5026       | OC3.7    |
| 0080160   | SCX9.5  | Q1130309  | SCX4.9  | RPV10Z    | FRW10.1 | SMQ4200      | SCY4.6  | VDV5027       | 005.8    |
| QDB0162   | SCX12.2 | Q0B0310   | SCY4.2  | RDV11Z    | SCY5.2  | SMQ4626      | SCY7.0  | VDV5028       | OC6.1    |
| Q0130163  | QA7.4   | QDB0311   | FRX13.1 | RDV12Z    | SCX5.1  | SMQ4824      | SCY4.4  | VDV5029       | SCC7.5   |
| 0080166   | QA11.7  | QDB0312   | SCY5.2  | RDV22Z    | SCY2.2  | SMQ4830      | SCY5.2  | VDV5030       | SCC3.0   |
| QD130167  | SCY4.6  | Q0130313  | SCY3.5  | RDV35Z    | SCY2.2  | SMQ4898      | FRW7.0  | VDV5031       | 0A10.9   |
| 0080168   | SCX2.9  | QDB0315   | SCX8.6  | RDV47ZA   | SCY3.2  | SMQ540       | SCX5.1  | VDV5032       | SCX5.1*  |
| QDB0169   | SOY7.Q  | QDB0317   | SCY4.6  | RDV48ZA   | SCY7.0  | SMQ570       | SCX5.1  | VDV6          | SCA12.5  |
| QDB0170   | FRM14.7 | Q050318   | FRX7.8  | RDV8Z     | SCX7.4  | SMQ714       | SCX8.0  | VDV7          | FR16.0   |
| Q0B0173   | SCX11.8 | 0080319   | SCY3.2  | RDV90Z8   | 0X5.5   | SMQK2002     | SCX7.0  | VDV8          | FR14.5   |
| Q080176   | SCY6.0  | QDB0323   | FRW8.5  | RFB102ZA  | SCY9.2  | SMQT1065     | FRY2.9  | VDV9          | FRY17.0  |
| Q050177   | FRM11.7 | QPB0324   | FRW9.2  | RFB10Z    | FRW10.1 | SMQT1163     | SCQ5.6  | VDVD0023      | SCY7.5   |
| QD50179   | FRX13.1 | QDB0325   | SCY5.2  | RFB111ZA  | SCQ10.0 | SMQT1179     | FRW8.5  | VDVD0043      | SCQ6.5   |
| 0080181   | 0A9.4   | QDBQ327   | SCY4.6  | RFB112ZA  | SCQ6.5  | TROQ3        | SCA8.6  | VDVS0001      | SCX8.0*  |
| QDB0182   | SCY4.6  | QDB0328   | SCY5.2  | RFB113ZA  | SCY7.3  | TR003C       | SCA8.6  | VDVS0002      | SCB2.8   |
| QDB0185   | SCX4A.  | QDB0329   | SCY3.5  | RFB116ZA  | SCY3.2  | UN10015      | ICP-F38 | VDVS0003      | SCB9.8   |
| QDB0186   | FRW8.0  | Q0130332  | SCX3.5  | RFB117ZA  | SCX5.1  | VA450026     | SCA6.7  | VDVS0004      | *A13.2   |
| 0080193   | SCX9.5  | QDB0333   | FRW7.0  | RF8118ZA  | SCY6.5  | VMS0200      | VA210   | VDVS0005      | FRX6.7   |
| QDB0195   | 0A6.1   | QDB0334   | SCY3.5  | RFB119ZA  | SCY10.2 | VDV0020      | SCA13.2 | VDVS0008      | SCX3.5   |
| 0060199   | SCY8.6  | QDB0339   | SCQ6.0  | RFB11Z    | SCQ10.0 | VDV0070      | SCC6.3  | VDVS0011      | SCB2.8   |
| QP131201  | SCY6.0  | Q080341   | FRW8.5  | RFB121ZA  | SCY5.2  | VDV0071      | FRW12.6 | VDVS0012      | FRW12.6  |
| 0080202   | FRM15.2 | 0080342   | \$Q06.0 | RFB12Z    | FRW8.5  | V4V0072      | SCB14.0 | VDVS0012C     | FRW12.6  |
| QD80203   | FRX5.1  | QDB0344   | SCY5.2  | RFB13Z    | SCY6.7  | VDV00721     | SCB14.0 | VDVS0013      | SCB14.0  |
| QDB0205   | SCY1.5  | QDB0350   | FRX4.7  | RFB16Z    | FRM7.5  | VDV0074      | SCA3.0  | VDVS0015      | SCB9.8   |
| QDB0206   | SCY4.2  | QDB1070   | 0A7.0   | RFB19Z    | SCY4.6  | VDV00741     | SCA3.0  | VDVS0016      | SCA9.6   |
| Q080207   | SCY6.7  | QDB1077   | SCB24.2 | RFB1Z     | FRW7.0  | VDV0075      | SCX8.6  | VDVS0017      | FRW12.6  |
| QDB0210   | SCY9.2  | Q01310771 | OSC22.8 | RFB20Z    | FRY10.7 | VDV0076      | 0X5.5   | VDVS0018      | FR11.9   |
| QDB0212   | SCY9.2  | QDB1078   | 0A12.4  | RFB21Z    | SCX5.1  | VDV0078      | FR18.2  | VDVS0018A     | FR11.9   |
| QDB0214   | SCY1.5  | 008141    | 0A9.4   | RFB22Z    | SCX5.1  | VDV0079      | 007.8   | VDVS0019      | SCC12.1  |
| Q050215   | 50Y8.0  | Q0B3351   | FF12.8  | RFB28Z    | SCY5.0  | VDV0080      | 005.8   | VDVS0020      | SCA13.2  |
| 0080218   | SCY6.5  | Q0134673  | OB9.4   | RFB29Z    | SCY4.6  | VDV0081      | FR19.6  | VDVS0021      | FRW12.0  |
| QDB0219   | FRW10.1 | QDBA00Q1  | SCY8.6  | RFB2Z     | SCY4.6  | VDV0092      | SCQ9.8  | VDVS0022      | SCB14.0. |
| Q050220   | SCY6.0  | QDBA0005  | SCA13.2 | RFB6Z     | SCY10.5 | VDV0094      | FRW12.6 | VDVS0023      | SCY7.5   |
| 0080221   | SCY6.0  | QDBA0007  | SCX4.3  | RFB7Z     | SCY4.6  | VDV0094A/B/C | FRW12.6 | VDVS0024      | SCY4.6   |
| 0080226   | FRX9.7  | QDBA0008  | SCA8.9  | RFB8Z     | SCY4.4  | vovoioi      | SCX3.2* | VDVS0026      | SCQ6.5   |
| Q0130228  | SCX4.3  | QDBA0009  | SCX4.0  | RFB99ZA   | SCY4.2  | VDV0102      | SCX7.0  | VDVS0028      | SCB7.1   |
| Q0190229  | SOY12.7 | Q013K0001 | SCX8.4  | RFB9Z     | SCY6.0  | VDV0104      | SCA7.5  | VDVS0029      | FRW12.0  |
| QDB0230   | SCY2.2  | QDBK0002  | SCX2.6  | RMG0121   | SCQ4.8  | VDV0105      | SCA3.0  | VDVS0029A/B/C | FRW12.0  |
| QDB0234   | SCY3.5  | QDBK0003  | SCX8.6  | RMG0158   | SCQ4.8  | VDV0106      | SCY9.0  | VDVS0031      | SCY4.2   |
| QDB0235   | SCY7.0  | QDBK0006  | SCX2.4  | RMG0228K  | SCA4.5  | VDV0107      | SCY6.5  | VDVS0032      | SCY7.5   |
| Q0B0236   | FRM12.1 | QDBK0009  | SCQ10.0 | RMG0268K  | SCQ4.8  | VDV0110      | SCX4.3  | VDVS0033      | SCY5.0   |
| 0080237   | SCX17.7 | QDBK0010  | SCY5.2  | RMQ195A   | FRW10.1 | VDV0117      | SCX3.5  | VDVS0034      | SCY4.0   |
| QD50238   | FRZ5.1  | QDBT0002  | OB7.0   | RMQ311A   | SCY6.0  | VDV0120      | SCC12.1 | VDVS0035      | SCX4.3   |
| 0050239   | SCY2.2  | QDBT0003  | 0A6.1   | RMQ565ZA  | FRM9.7  | VDV0121      | FR11.9  | VDVS0036      | \$C514.0 |
| QD130240  | SCY7.8  | Q01310004 | 0A8.2   | RMQ607Z   | SCX10.7 | V0V0122      | SCA4.5  | VDVS0037      | SCX6.2   |

= Part of the Assy

\*=- Kit May Not Include Tires

= Part of the Assy

# PANASONIC ... PENNEY,JC

| MFG. P/N | PRB NO. | MFG. P/N    | PRB NO. | MFG. P/N           | PRB NO. | MFG. P/N    | PRB NO.  | MFG. P/N    | PRB NO. |
|----------|---------|-------------|---------|--------------------|---------|-------------|----------|-------------|---------|
| VDVS0038 | SCB14.0 | VXP0292     | ST1.182 | YEFRO30406         | SCY5.7  | 171131002   | FRM10.5  | 66052600310 | VA54    |
| VDVS0039 | SCB12.5 | VXP0329     | ST1.330 | YEFRO3052          | SCQ4.0  | 171131003   | FRM10.5  | 6813256     | SCX9.5  |
| VDVS0040 | SCA5.4  | VXP0329     | VA20    | YEFRO3056          | SCX15.2 | 175007133   | FRM8.0   | 6816564     | SCX9.5  |
| VDVS0042 | SCB10.0 | VXP0330     | VPR1    | YEFRO3056A         | SCX15.2 | 175049001   | FRM10.5  | 6831751     | FRM11.0 |
| VDVS0043 | SCX6.2  | VXP0331     | ST1.230 | YEFRO3059          | SCQ4.0  | 175049003   | FRM10.5  | 6831901     | FRM9.6  |
| VDVS0044 | SCB2.5  | VXP0331     | VA25    | YEFRO3066          | SCQ15.9 | 175049015   | 0A8.2    | 6865575     | ST1.014 |
| VDVS0045 | SCA4.5  | VXP0334     | ST1.330 | YEFRO3069B         | SCX8.6  | 1891003     | SCQ6.0   | 6865575     | VA40    |
| VDVS0047 | SCB10.0 | VXP0343     | VA204   | YEFRO3070          | SCX15.0 | 19406531    | SCX8.9   | 6875372     | ST1.014 |
| VDVS0048 | SCA8.9  | VXP0344     | ST1.330 | YEFRO3073          | SCX4.0  | 199335      | VKT113** | 6875372     | VA40    |
| VDVS0049 | FRW7.3  | VXP0344     | VA26    | YEFRO3074          | SCY15.2 | 199336      | VKT160** | 6886792     | VA45    |
| VDVS0050 | SCQ4.3  | VXP0351     | VA751   | YEFRO6052          | SCQ4.0  | 199337      | VKT18**  | 6886971     | ST1.014 |
| VDVS0052 | SCA8.9  | VXP0401     | ST1.243 |                    |         | 19980351    | SCQ6.7   | 6886971     | VA40    |
| VDVS0053 | SCB9.5  | VXP0401     | VA21    | <b>PENNE Y, JC</b> |         | 2001800077  | SCX10.7  | 6975471     | VPR18   |
| VDVS0054 | SCQ4.3  | \\(P0433    | ST1.230 | 0001741011         | SCX10.7 | 200643128   | FRM12.1  | 6975472     | VPR18   |
| VOVS0057 | SCB11.6 | VXP0433     | VA203   | 0005610902         | FRM10.5 | 20150000296 | SCX8.9   | 6979842     | VPR18   |
| VDVS0058 | SCA4.5  | VXP0463     | VA202   | 10059616           | FR11.9  | 202AV       | IW11     | 7376271     | VB7     |
| VDVS0059 | SCA4.2  | VXP0469     | ST1.243 | 10059624           | FR11.9  | 21V0002     | FRY10.7  | 7661521     | FRM11.0 |
| VDVS0060 | SCQ2.5  | VXP0515     | VA202   | 10059632           | FR11.9  | 23ST462     | 10/05    | 7668793     | SCA8.9  |
| VDVS0065 | SCB6.6  | VXP0518     | VPR2    | 10059780           | SCY7.5  | 2575512300  | OC9.8    | 88912002    | SCX8.9  |
| VDVS0066 | SCB11.6 | VXP0521     | ST1.165 | 10060259           | SCY4.2  | 2575513900  | SCX4.0   | 921400      | 0A8.2   |
| VDVS0069 | SCA3.0  | VXP0521     | VA22    | 101010295          | SCQ6.5  | 2575515100  | 0A8.2    | 923400      | 0A6.1   |
| VDVS0070 | SCC12.6 | VXP0523     | *VA217  | 101010304          | SCX8.9  | 2575515901  | SCX9.5   | 9575510900  | OC11.2  |
| VDVS0122 | SCA4.5  | VXP0581     | VA201   | 10308211           | SCQ6.5  | 2575516500  | SCQ5.6   | 9575511000  | 0A13.2  |
| VDVS0289 | SCA4.5  | VXP0595     | VA213   | 10308229           | SCB14.0 | 25755171    | SCX4.0   | 971247      | 0A4.0   |
| VDX0050  | SCQ4.3  | VXP0599     | ST.753  | 10308294           | SCB12.5 | 2575517103  | SCX4.0   | 99T2839     | SCY14.7 |
| VEK2115  | VCR33   | VXP0599     | VA212   | 11420782           | FRX9.7  | 2575517800  | SCA8.9   | 99T6163     | SCY14.7 |
| VEK3309  | VCR33   | VXP0675     | ST1.396 | 11437894           | SCA4.5  | 2575517900  | 0A5.4    | EW02X0454   | SCY6.3  |
| VEKS2501 | VCR33   | VXP1121     | VPR1    | 11516259           | SCC12.1 | 2575518002  | SCX8.6   | EW02X0578   | FRW12.0 |
| VEKS3578 | VCR22   | VXP518      | VPR2    | 11563285           | SCA13.2 | 2575518200  | SCQ11.1  | PQM30003-10 | SCA6.7  |
| VEKS4577 | VCR33   | VXP521      | VA22    | 11708062           | FRW12.0 | 25755187    | SCQ6.5   | POM30003-14 | SC03.6  |
| VEKS4589 | VCR33   | VXP675      | ST1.495 | 11708070           | FRW12.0 | 2575518700  | SCQ6.5   | PU48967B    | ST1.113 |
| VEKS5201 | VCR33   | VXP50047    | ST.470  | 11708088           | FRW12.0 | 25755192    | SCQ11.1  | PU48967B    | VA10    |
| VEPO019A | VCR22   | VXP50054    | ST1.370 | 11762689           | SCQ5.6  | 2575522700  | 087.6    | PU49164     | FRW10.7 |
| VMG38    | 0B7.6   | VXP50054    | VA28    | 11762861           | ST.685  | 2971301     | SCQ6.5   | PU50350     | SCQ3.6  |
| VMG39    | 0A11.7  | VXP50069    | ST1.165 | 11763185           | SCQ4.8  | 30177180    | SCB14.0  | PU51390A    | VB4     |
| VMG76    | SCA9.6  | VXP50069    | VA22    | 11763406           | SCA8.9  | 30268300    | OB14.0   | PU51402A    | ST.689  |
| VXA2552  | VCR23   | VXP5006P    | ST1.243 | 12181020           | SCA10.0 | 310901      | FR5.9    | PU51402A    | VAI2    |
| VXA2588  | VCR23   | VXP50075    | ST.773  | 12181038           | SCQ6.5  | 3330902     | FRX9.7   | PU55822A    | ST.948  |
| VXAS1174 | VCR33   | VXP50076    | ST.670  | 1220896            | SCY14.7 | 366932700   | SCA4.5   | PUM30003    | SCY5.2  |
| VXDS0091 | VCR33   | VXP50116    | ST1.165 | 12311577           | SCB2.5  | 3713004     | FRX15.2  | PUM30003-1  | SCY5.7  |
| VXG0015  | VPR2    | VXP50116    | VA27    | 12601201           | FRW8.5  | 386075A     | ST1.165  | PUM30003-2  | SCY7.5  |
| VXG2     | FR15.9  | VX20076     | VB6     | 12904215           | SCY5.2  | 4006064     | SCX8.6   | PUM30003-3  | SCY4.0  |
| VXL0997  | VA207   | VX20129     | VB1     | 13603709           | SCY5.2  | 40091605600 | FRM9.7   | PUM30003-7  | SCA14.1 |
| VXL1154  | VPR1    | VX20165     | VB2     | 1412564900800      | SCQ6.5  | 40091711600 | FRM9.7   | PUM30004    | FRQ11.2 |
| VXL1229  | VPR2    | VXZS0005    | VB1     | 144258             | SCB14.0 | 42A44234P01 | FRM9.7   | QBT0143     | SCB24.2 |
| VXL1324  | VPR2    | VXZS0129    | VB1     | 144259             | SCA3.0  | 42B40286J01 | FRM10.5  | 00B0003     | SCA12.5 |
| VXL1325  | VPR2    | VXZS0137    | VB1     | 144260             | SCX8.6  | 42B41045C01 | FRM11.5  | QDB0016     | 0B15.6  |
| VXL1371  | VPR1    | VXZS0145    | VB1     | 144261             | OX5.5   | 42V43871A03 | FRM12.1  | QDB0021     | OC9.8   |
| VXL1415  | VPR2    | VXZS0165    | VB2     | 144263             | ST1.160 | 434037D     | VPR16    | QDB0022     | FF12.6  |
| VXL1481  | VPR26/  | W696        | FRX9.7  | 144263             | VA23    | 452023A     | SCQ5.7   | Q DB0026    | FRM11.7 |
|          | VPR3    | X36460260   | SCQ15.9 | 144265             | ST.752  | 452024A     | SCB10.0  | QDB0027     | FRM11.7 |
| VXL1743  | VPR3/   | XAMQ27P150W | VCR3    | 144265             | VA200   | 452030A     | SCA8.9   | 0080028     | SCA8.9  |
|          | VPR26   | XAMV0019    | VCR2    | 144267             | SCQ9.8  | 500000412   | SCX2.4   | 0080031     | 0A13.2  |
|          | VPR26   | XAMV125     | VCR1    | 144605             | FRW12.6 | 500000413   | SCQ6.5   | QDB0037     | 0A8.5   |
| VXL1858  | VPR3/   | YAAR01002   | FRM11.2 | 1449958            | SCX3.2* | 5610902     | FRM10.5  | QDB0041     | 0A10.9  |
| VXL1858  | VPR26   | YAFB01003   | FRW10.7 | 146968             | FRW12.6 | 60126064    | 0A5.4    | QDB0042     | 0A9.0   |
| VXL1902  | VPR3/   | YAFRO1002   | FRM11.2 | 147079             | SCX4.6  | 60126127    | SCA8.9   | 0080043     | OC9.8   |
|          | VPR26   | YAFRO1003   | FRM11.0 | 147756             | FRM11.0 | 6020001044  | FRM12.1  | QDB0050     | SCQ11.1 |
| VXLS0081 | ST.470  | YAFRO1007   | FRM7.5  | 147916             | SCB14.0 | 631023      | 0A10.1   | 00B0058     | SCQ11.1 |
| VXLS0081 | VA204   | YAFRO1008   | SCQ2.5  | 148664             | SCA4.5  | 6310232     | 0B12.4   | QDB0060     | OC12.4  |
| VXLS0165 | VB2     | YAFRO1012   | SCX7.0  | 152412             | SCA13.2 | 6310233     | 0A10.9   | QDB0061     | *A1 0.1 |
| VXLS0383 | VA215   | YAFRO1014   | FRM10.2 | 152683             | ST1.230 | 6350021     | SCX7.0   | Q DB0062    | 0A9.0   |
| VXLS0386 | VPR26   | YAFRO1015   | FRM11.5 | 152683             | VA25    | 6350051     | 0A4.6    | QDB0065     | FRM12.7 |
| VXLS0454 | VA215   | YAFRO1018   | FRX10.5 | 155739             | ST1.370 | 6350202     | 0A4.6    | 00B0066     | OC14.4  |
| VXLS0455 | VPR1    | YAFRO1019   | FRM11.0 | 155739             | VA28    | 6350371     | SCX9.5   | QDB0068     | OC14.4  |
| VXLS0475 | VPR1    | YAFRO1020   | FR8.8   | 155803             | SCB14.0 | 6350951     | FRM9.7   | QDB0070     | 0A8.5   |
| VXLS0549 | VPR27   | YAFRO1022   | FRQ11.2 | 156678             | SCA3.2  | 6354231     | SC05.6   | QDB0082     | SCQ2.5  |
| VXLS0587 | VPR26   | YAFRO1023   | FRM10.5 | 156679             | SCA2.3  | 6355282     | SCA8.6   | QDB0083     | SCQ10.0 |
| VXLS0616 | VPR27   | YAFX018013  | 0A4.2   | 157053             | SCQ5.3  | 6355291     | SCQ4.8   | QDB0084     | SCX4.9  |
| VXLS0666 | VPR2    | YAFX018014  | 0A4.2   | 157061             | SCA3.2  | 6355561     | SCQ5.3   | QDB0113     | SCX8.6  |
| VXLS0738 | VPR26   | YEFRO3001   | SCQ10.0 | 157062             | SCA3.0  | 6355581     | SCA13.6  | QDB0114     | SCX4.0  |
| VXLS0761 | VPR2    | YEFRO3004   | FRM9.7  | 157064             | FRZ11.0 | 6355591     | SCA3.0   | QDB0117     | SCA8.9  |
| VXLS0770 | VPR2    | YEFRO3005   | SCX4.0  | 157065             | SCA13.6 | 6355601     | SCA3.2   | 0080118     | SCY8.6  |
| VXLS0836 | VPR26   | YEFRO3006   | SCX4.0  | 158190             | ST1.165 | 6356081     | SCA13.6  | 00B0123     | SCA8.9  |
| VXLS1014 | VPR26   | YEFRO3011   | SCY6.5  | 158190             | VA44    | 6356091     | SCB2.5   | QDB0124     | SCA8.6  |
| VXLS1014 | VPR26   | YEFRO3012A  | SCX8.4  | 16178362           | VPR14   | 6356101     | FRZ11.0  | QDB0125     | SCX7.0  |
| VXP0171  | ST1.160 | YEFRO3013   | SCX7.4  | 16180801           | ST1.205 | 6356111     | SCA3.2   | QDB0126     | SCA8.6  |
| VXP0174  | ST1.160 | YEFRO3014   | FRM10.5 | 16180801           | VA80    | 6356451     | SCB2.6   | 00B0133     | SCA8.6  |
| VXP0174  | VA23    | YEFRO3023   | SCX8.6  | 16183653           | VPR14   | 6357531     | FRZ11.0  | 0080134     | FRM13.3 |
| VXP0213  | ST.752  | YEFRO3025   | SCQ8.2  | 163879             | SCA3.2  | 6383213     | VPR6     | QDB0136     | SCA8.6  |
| VXP0213  | VA200   | YEFRO3026   | FRM9.7  | 163880             | SCB2.5  | 6383762     | VPR18    | 00B0137     | FRM11.5 |
| VXP0242  | ST1.182 | YEFRO3030   | FRW8.5  | 163895             | FRZ11.0 | 652000      | 0A8.2    | 0080141     | FRM9.6  |
| VXP0243  | ST.752  | YEFRO3032   | SCX8.9  | 163896             | SCA13.6 | 65274600711 | SCA9.2   | QDB0142     | 0A5.4   |
| VXP0245  | ST1.160 | YEFRO3035   | SCX12.2 | 164113             | ST1.014 | 65274603210 | SCB9.5   | QDB0143     | SCX7.0  |
| VXP0245  | VA23    | YEFRO3040A  | SCY5.7  | 164113             | VA40    | 66052600310 | ST1.152  | 0060219     | FRX9.7  |

\* = Replacement Belt

!! = Kit May Not Include Tires

^ = Part of the Assy

# PENNEY,JC ... PIONEER

| MFG. P/N  | PRB NO. | MFG. P/N        | PRB NO.  | MFG. P/N       | PRB NO. | MFG. P/N     | PRB NO. | MFG. P/N          | PRB NO. |
|-----------|---------|-----------------|----------|----------------|---------|--------------|---------|-------------------|---------|
| QDB9      | 0A4.6   | YP401           | FRX22.4  | VDVS0032       | SCY7.5  | 35830076     | SCX8.6  | VOVS0047          | SCB10.0 |
| QDBK0001  | SCX8.6  | YP600           | FRX22.4  | VDVS0033       | SCY5.0  | 35830077     | SCX2.4  | VDVS0048          | SCA8.9  |
| QDBK0002  | SCX2.6  | YP701           | FRX35.1  | VDVS0034       | SCY4.0  | 35830123     | SCQ10.0 | VDVS0052          | SCA9.5  |
| QDBK0005  | SCA8.6  | <b>PENTAGON</b> |          | VDVS0037       | SCX6.2  | 35830131     | SCX15.0 | VDVS0053          | SCB9.5  |
| QDBK0006  | SCX2.4  |                 |          | VDVS0038       | SCB14.0 | 35830135     | SCX13.6 | VDVS0055          | SCB8.1  |
| QDBT0002  | OB7.0   | 340000102       | 0A14.0   | VDV#0039       | SQB12.5 | 35830138     | SQX8.6  | VDVS0057          | SCB11.6 |
| QOBT0009  | 0A5.8   | 340000103       | *AI 2.4  | VDV#0042       | SCB10.0 | 35830145     | SCX15.0 | VDVS0058          | SCA4.5  |
| QDQK0002  | SCX2.6  | 340000104       | SCX16.0  | VDVS0043       | SCX6.2  | 35830148     | SCY8.6  | VDVS0059          | SCA4.2  |
| QMA0012   | ST.536  |                 |          | VDVS0044       | SCB2.5  | 35830152     | SCX8.6  | VDVS006p          | \$002.5 |
| QXL0844   | 0A4.2   | <b>PHIL CO</b>  |          | VDVS0045       | SCA4.5  | 35830181     | SCQ6.5  | VDVS0066          | SCB11.6 |
| VDV0020   | SCA13.2 | 0728777308      | VCR1     | VDVS0046       | SCB8.1  | 35830182     | FRX20.7 | VXLS0165          | VB2     |
| VDV0072   | SCB14.0 | 07287774        | ST1.130  | VDV#0047       | SCB10.0 | 35830189     | SCX12.2 | VXLS0383          | VA215   |
| VON/00721 | SCB14.0 | 0728777415      | VA26     | VDVS0048       | SCA8.9  | 4003536      | SCX12.2 | VXLS0454          | VA215   |
| VEJ0074   | SCA3.0  | 0728777442      | ST.752   | VDVS0052       | SCA8.9  | 4013534      | SCX12.2 | VXLS0666          | VPR2    |
| VDV00741  | SCA3.0  | 0728777445      | VA200    | VDV#0053       | SCB9.5  | 4014408      | SCQ5.6  | VXP0329           | ST1.330 |
| VDV0075   | SCX8.6  | 0728777442      | ST1.160  | VDVS0054       | SCQ4.3  | 402573010120 | SCY9.5  | VXP0329           | VA20    |
| VOV0076   | OX5.5   | 0728777445      | VA23     | VDVS0055       | SCB8.1  | 402573020180 | OA3.1   | VXP0331           | ST1.230 |
| VDV0092   | SC09.8  | 0728777447      | \$T1.160 | VDVS0057       | SCB11.6 | 44Y00123     | FRM9.6  | VXP0331           | VA25    |
| VDV0094   | FRW12.6 | 0728777447      | VA23     | VDVS0058       | SCA4.5  | 44Y00124     | SCQ6.0  | VXP0054           | ST1.370 |
| VDV0105   | SCA3.0  | 0728778297      | VCR1     | VDVS0059       | SCA4.2  | 44Y00125     | SCX3.5  | VXP0054           | VA28    |
| VDV0120   | SCC12.1 | 0728817303      | VCR2     | VDVS0060       | SCQ2.5  | 482235830076 | SCX8.6  | VXP0076           | ST.670  |
| VDV0121   | FR11.9  | 0728817477      | VCR2     | VXLS0866       | VPR2    | 482235830077 | SCX2.4  | VXP0116           | ST1.165 |
| VDV0122   | SCA4.5  | 0728817571      | FR11.9   | VXP0174        | ST1.160 | 482235830078 | SCA14.1 | VXP0116           | VA27    |
| VQV0123   | SCA13.2 | 0728817572      | FR11.9   | VXP0174        | VA23    | 482235830096 | SCX9.5  | VXZ0076           | VB6     |
| VDV0124   | SCY6.3  | 0728817573      | FR11.9   | VXP0213        | ST.752  | 482235830116 | SCQ5.6  | VXZS0129          | VB1     |
| VDV0125   | SCX4.9  | 0728977112      | VCR26    | VXP0213        | VA200   | 482235830137 | SCQ5.6  | VXZS0137          | VB1     |
| VDV0148   | SCQ6.5  | 0728977415      | ST1.330  | VXP0329        | ST1.330 | 482235830148 | SCY8.6  | VWT49608          | SCX12.2 |
| VDV0216   | SCQ6.5  | 0728977415      | VA26     | VXP0329        | VA20    | 482235830155 | SCQ6.7  | WT49663           | OB12.4  |
| VDV0217   | SCX8.6  | 0728977612      | SCC12.1  | VXP0331        | ST1.230 | 48223583041  | OB12.4  |                   |         |
| VDV0218   | SCY3.2  | 0746100462      | SCA13.2  | VXP0331        | VA25    | 482235830921 | SCY4.0  | <b>PHONEMA TE</b> |         |
| VDVD00741 | SCA3.0  | 0746100504      | SCY7.5   | VXP0334        | ST1.230 | 482235830928 | SCX8.6  | 2300089           | SCA11.5 |
| VCA#0002  | SOB2.8  | 0746100523      | SCY4.2   | VXP0344        | ST1.330 | 482235831226 | SCQ7.2  | 230086000         | SCX8.0  |
| VDVS0003  | SCB9.8  | 325002066       | OA4.2    | VXP0344        | VA26    | 482252890321 | VPR25   | 240141            | SCX4.3  |
| vpvs0004  | OA13.2  | 325002088       | OA4.2    | VXP#0054       | ST1.370 | 482269120023 | SCX2.4  | 3200081           | SCX12.2 |
| VDVS0005  | FRX6.7  | 325002569       | SCA8.6   | VXPS0054       | VA28    | 48226915858  | FRM13.3 | <b>PILOT</b>      |         |
| VDVS0008  | SCX3.5  | 3250028162      | SCX2.4   | VXPS0076       | ST.670  | 48226916017  | SCX12.2 | 414021A           | ST.253  |
| VDVS0011  | SCB2.8  | 325003055       | OB10.9   | VXPS0116       | ST1.165 | 48226916117  | SCX12.2 | 452003A           | SCA4.2  |
| VDVS0012  | FRW12.6 | 325003061       | OA8.5    | VXPS0116       | VA27    | 48226918000  | SCX4.3  | 452004A           | SCA13.2 |
| VDVS0013  | SCB14.0 | 325003062       | OB10.9   | VXZ0076        | VB6     | 48226918585A | FRM11.2 | 452011A           | SCX7.4  |
| VDVSOQ15  | SCB9.8  | 3250031108      | OA5.4    | VXZS0005       | VB1     | 48226919000  | SCX4.0  | 452020A           | SCX3.5  |
| VDVS0018  | FR11.9  | 325003186       | SCX8.6   | VXZS0129       | VB1     | 48226919002  | SCQ6.5  | 986447            | OC11.2  |
| VDVS0019  | SCC12.1 | 325003498       | *AI 0.9  | VXZS0137       | VB1     | 483535837075 | FRQ11.2 | 986449            | 0011.2  |
| VDVS0020  | SCA13.2 | 3250076106      | OA8.5    | VXZS0165       | VB2     | 483535837076 | SCA14.1 | 987408            | OB14.0  |
| VDV#0022  | SCB14.0 | 3250076107      | QA7.0    | <b>PHILIPS</b> |         | 483535837077 | SCQ7.2  |                   |         |
| VDVS0023  | SCY7.5  | 325007672       | OC11.2   | 00917          | SCX8.6  | 483535837078 | SCQ6.5  |                   |         |
| VDVS0024  | SCY4.2  | 3250081216      | FRM14.0  | 01200100       | FRM10.5 | 483535837132 | SCQ4.8  |                   |         |
| VDVS0028  | SC B7.1 | 325177120       | FRM11.5  | 01616          | SCX4.3  | 4835830165   | FR5.1   | <b>PIONEER</b>    |         |
| VDVS0029  | FRW12.0 | 483535837075    | FRQ11.2  | 1003582        | SCQ10.0 | 4835830182   | FRX20.7 | OCNT021           | SCQ6.7" |
| VDVS0032  | SCY7.5  | 483535837076    | SCA14.1  | 1003585        | SCQ10.0 | 4H35820111   | FRX11.3 | A1 0N286060       | FRM12.1 |
| VDVS0033  | SCY5.0  | 483535837077    | SCQ7.2   | 101            | SCQ10.0 | 4H35620112   | SCQ6.5  | AEB197            | SCY6.5  |
| VDV#0034  | SCY4.0  | 483535837078    | SCQ6.5   | 1013586        | FR13.4  | 4H35820113   | SCQ6.5  | AXW008            | FRW10.7 |
| VDVS0035  | SQX4.3  | 6451430102      | SCX6.2   | 104            | SCQ10.0 | 4H35820119   | SCQ6.5  | AXW025            | FRW8.5  |
| VDVS0036  | SCB14.0 | 6451430152      | SCA10.0  | 105            | OC13.2  | 4H35820121   | SCQ6.5  | AXW026            | SCX8.4  |
| VDVS0037  | SCX6.2  | 6451430153      | SCQ6.5   | 1503300        | FR13.4  | 4H35820122   | FRW10.1 | AXW036            | SCX4.6  |
| VDVS0038  | SCB14.0 | 6451430189      | SCB2.5   | 16301012       | SCX8.6  | 4H35830131   | SCQ10.0 | AXW037            | SCY5.0  |
| VOVS0039  | SCB14.0 | VDS0122         | SCA4.5   | 1753303        | SCX7.0  | 4H35830133   | SC015.9 | AZN1046           | SCX8.6  |
| VDVS0040  | SCA5.4  | VDV0020         | SCA13.2  | 2003515        | SCX2.4  | 4H35830135   | SCX13.6 | AZN1054           | SCY7.8  |
| VDVS0042  | SCB10.0 | VDV0072         | SCB14.0  | 2003531        | SCX12.2 | 4H35830137   | SCY8.6  | AZN1124           | FRX13.1 |
| VDVS0043  | SCX6.2  | VDV00721        | SCB14.0  | 201025         | SCX12.2 | 4H35830138   | FR5.1   | AZN1147           | SCY6.0  |
| VDVS0044  | SCB2.5  | VDV0074         | SCA3.0   | 201035         | SCX12.2 | 4H35830165.  | FRX20.7 | AZN1298           | FRW8.5  |
| VDVS0047  | SCB10.0 | VDV0075         | SCA3.0   | 22RH811        | SCX12.2 | 4H35830182   | FRX20.7 | AZN1506           | SCY5.0  |
| VDVS0057  | SCB11.6 | VDV0076         | SCX8.6   | 22RH843        | SCA8.6  | 4H35830195   | SCA13.2 | AZN1507           | SCX6.2  |
| VDVS0072  | SCB14.0 | VDV0092         | OX5.5    | 22RR332        | OA5.4   | 4H35830216   | FRX22.4 | AZN1798           | PRQ2    |
| VDVS0122  | SCA4.5  | VDV0094         | SCQ9.8   | 22RR44M        | SCY8.6  | 4H35830223   | SCX18.5 | CNR002            | FRM8.0  |
| VDW0101   | SCX3.5  | VDV0101         | FRW12.6  | 22RR482/44M    | SCY8.6  | 4H35830224   | SCA9.6  | CN R022           | SCX14.7 |
| VXLS0165  | VB2     | VDV0122         | SCX3.2*  | 30009VU9500    | SCX8.6  | 4H35830224   | FRY23.6 | CNR055            | SCX4.0  |
| VXP0174   | ST1.160 | VDV0123         | SCA4.5   | 30096          | SCX8.6  | 6451430152   | SCA10.0 | CNT006C           | FRM6.1  |
| VXP0174   | VA23    | VDV0124         | SCA13.2  | 30033          | SCX8.6  | 6451430153   | SCQ6.5  | CNT008            | FRW7.7  |
| VXP0213   | ST.752  | VDV0125         | SCY6.3   | 30033542       | SCA12.5 | 6495200218   | SCQ3.6  | CNT012B           | SCX14.7 |
| VXP0213   | VA200   | VDV0130         | SCX4.9   | 30016          | SCX12.2 | 944408       | OA9.4   | CNT016            | FRW8.5  |
| VXP0329   | ST1.330 | VDV0136         | SCX3.5   | 30018          | SCB16.6 | VDV0074      | SCA3.0  | C NT022           | SCA8.9  |
| VXP0329   | VA20    | VDV0216         | SCQ6.5   | 30033          | SCQ2.5  | VDV0122      | SCA4.5  | CNT024            | OA4.6   |
| VXP0331   | ST1.230 | VDV0217         | SCX8.6   | 30051          | SCX12.2 | VDV0212      | SCX5.1  | CNT025            | FRW6.5  |
| VXP0331   | VA25    | VDV0218         | SCY3.2   | 3007617501126  | SCX12.2 | VDVS0018     | FR11.9  | CNT026            | SCX3.5* |
| VXP0344   | ST1.330 | VDV029          | FRW12.0  | 3007716300915  | SCX8.6  | VDVS0019     | SCT12.1 | CNT027            | FRW12.0 |
| VXPS0054  | VA26    | VDVS0012        | FRW12.6  | 30095095003    | SCX2.4  | VDVS0020     | SCA13.2 | CNT032            | FR8.2   |
| VXP#0054  | ST1.370 | VDVS0013        | SCB14.0  | 30116          | SCA12.5 | VDVS0023     | SCY7.5  | CNT035            | FRW12.0 |
| VXP#0054  | VA28    | VDVS0018        | FR11.9   | 30126          | SCQ10.0 | VDVS0024     | SCY4.2  | CNT044            | FRM10.5 |
| VXPS0076  | ST.670  | VDVS0019        | SCC12.1  | 30128          | QA9.4   | VDVS0029     | FRW12.0 | CNT046            | SCX9.5  |
| VXPS0116  | ST1.165 | VDVS0021        | SCA13.2  | 30128          | SCX4.3  | VDVS0037     | SCX2.4  | CNT047            | SCX4.3  |
| VXPS0116  | VA27    | VDVS0022        | FRW12.0  | 30300100       | SCX13.6 | VDVS0038     | SCB14.0 | CNT049            | SCX6.2  |
| VXZS0005  | VB1     | VDVS0022        | SOB14.0  | 310328401103   | FRM13.3 | VDVS0039     | SCB12.5 | ONT050            | SCX8.6  |
| VXZS0129  | VB1     | VDVS0023        | SCY7.5   | 31041065403    | SCX10.7 | VDVS0040     | SCA5.4  | CNT051            | SCY5.2  |
| VXZS0137  | VB1     | VDVS0024        | SCY4.2   | 35830037       | SCX8.9  | VDVS0042     | SCB10.0 | CNT053            | SCX8.4  |
| X36700630 | VPRA1   | VDVS0029        | FRW12.0  | 35830045A1     | SCX8.0  | VDVS0043     | SCX2.6  | CNT054            | SCX5.1  |
|           |         |                 |          |                | SCX11.8 | VDVS0044     | SCB2.5  |                   |         |

= Part of the Assy

\*\*= Kit May Not Include Tires

= Part of the Assy

# PIONEER ... QUASAR

| MFG: P/N | PRB NO. | MFG: P/N | PRB NO. | MFG: P/N       | PRB NO. | MFG: P/N            | PRB NO. | MFG: P/N                 | PRB NO. |
|----------|---------|----------|---------|----------------|---------|---------------------|---------|--------------------------|---------|
| CNT055   | SCY6.0  | PEB1127  | SCQ4.3  | REB355         | SCY4.6  | 52APBT2             | SCB16.6 | 4290371A30               | SCY2.9  |
| CNT056   | SCY5.5  | PEB1138  | SCA3.5  | REB369         | SCY6.7  | 52APBT3             | SCX12.2 | 4290371A35               | SCX7.4  |
| CNT057   | SCX6.2  | PEB1154  | SCQ4.8  | REB377         | FRW7.3  | 52BFMT3             | SCX12.2 | 4290371A42               | SCY5.2  |
| CNT058   | SCX4.3  | PEB1169  | SCQ5.3  | REB378         | SCX4.3  | 52BPBT1             | SCB16.6 | 4290371A54               | SCQ10.0 |
| CNT066   | SCX9.5  | PEB1186  | SCX7.4  | REB381         | SCX5.8  | 52BPBT2             | SCB16.6 | 4290371A56               | SCX7.4  |
| CNT067   | SCY6.0  | PEB183   | FR21.5  | REB390         | SCX3.5  | 52BPBT3             | SCX12.2 | 4290371A90               | SCX4.6  |
| CNT068   | SCQ4.0  | PEB185   | SCY4.0  | REB391         | FRX10.5 | 53BFMT1             | SCB16.6 | 4290371A97               | FRM8.0  |
| CNT068B  | SCQ4.0  | PEB224   | FR21.5  | REB395         | FRX5.7  | 53BFMT2             | SCB16.6 | 4290371A98               | FRX22.4 |
| CNT070   | SCY6.5  | PEB226   | SCY6.7  | REB398         | SCY4.6  | 53BFMT3             | SCX12.2 | 4290397A31               | SCY4.2  |
| CNT073   | SCX5.5  | PEB314   | SCQ2.0  | REB402         | SCQ5.6  | 53BPBT1             | SCB16.6 | 4290397A41               | FRW10.1 |
| CNT074   | SCX8.0  | PEB315   | SCA4.5  | REB411         | FRW8.0  | 53BPBT3             | SCX12.2 | 4290428A16               | SCB9.5  |
| CNT075   | SCX4.0  | QZE1001  | SCB2.5  | REB413         | SCX4.3  | 60                  | SCX13.6 | 4290428A17               | FRX6.7  |
| CNT079   | SCX8.6  | QZN1017  | VA45    | REB417         | SCY8.0  | 60BPBT2             | SCB12.5 | 4290428A18               | 0A13.2  |
| CNT080   | SCX4.0  | QZN140   | SCQ5.3  | REB424         | SCY6.0  | 60HFMT1             | SCX13.6 | 4290428A19               | SCA3.0  |
| CNT088   | SCX4.0  | QZN144   | SCA3.2  | REB428         | FRM9.6  | 60HFMT2             | SCX13.6 | 4290428A20               | SCY5.7  |
| CNT091   | SCX15.5 | QZN 147  | FRZ11.0 | REB435         | SCX4.6  | 60HPBT2             | SCX13.6 | 4290428A26               | SCA3.0  |
| CNT092   | SCX4.0  | QZN148   | SCA13.6 | REB436         | SCX4.0  | 61BPBT2             | SCB12.5 | 4290428A35               | SCX3.5  |
| CNT095   | SCX8.9  | REB012   | SCX6.2* | REB446         | SCX4.3  | 62APBT2             | SCB12.5 | 4290428A49               | SCB9.5  |
| CNT096   | SCQ3.6  | RES013   | SCX3.5  | REB449         | FRW9.6  | 70AFMT1             | SCB12.5 | 4290428A84               | SCA4.5  |
| CNT097   | FRW10.1 | REB051   | 0C10.9  | REB453         | FRW9.6  | 7304589             | 0612.4  | 4290467A09               | FRW8.5  |
| CNT1020  | SCX1.9  | REB056   | SCX4.0* | REB454         | SCX6.2  | 7312439             | SCX12.2 | 4290467A11               | SCX4.6  |
| CNT1046  | SCQ8.8  | REB057   | SCX7.4  | REB455         | SCQ3.0  | 7342139             | SCQ11.1 | 4290467A20               | FRW7.7  |
| CNT1047  | SCY1.5  | REB077   | SCY12.7 | REB457         | SCY9.0  | 791636              | SCB16.6 | 4290467A21               | SCX7.4  |
| CNT1053  | SCX1.9  | REB093   | SCX3.5* | REB458         | SCY8.0  | 7931636             | SCB16.6 | 4290467A22               | SCY4.2  |
| CTN1030  | SCY1.5  | REB1013  | FRW8.5  | REB467         | FRW9.6  | 7933447             | SCX8.9  | 4290467A23               | SCY4.6  |
| CTN1047  | SCY1.5  | REB1054  | FRW9.1  | REB468         | SCY6.5  | 7935034             | SCB16.6 | 4290467A24               | SCY5.2  |
| DEB1104  | SCQ3.0  | REB1055  | SCX5.5  | REB476         | FRW9.6  | 80BFMT1             | SCX12.2 | 4290473A04               | SCY4.2  |
| E317000  | FRX35.1 | REB1062  | SCQ8.0  | REB480         | FRW9.6  | 80BFMT2             | SCX12.2 | 42X90371A94              | SCY6.5  |
| E81700   | FRW12.0 | REB107   | FRX13.1 | REB483         | FRW8.0  | 81YFMT1             | SCX12.2 | 42(90371A97              | FRW8.0  |
| ENT1009  | SCX3.5  | REB1112  | FR8.2   | REB485         | FRW8.0  | 81YFMT2             | SCX12.2 | 48(90478A34              | VCR26   |
| ENT1014  | SCX8.6  | REB1120  | SCQ3.0  | REB488         | FR8.2   | 9343363             | SCB16.6 | 4990369A18               | ST.752  |
| ENT1018  | SCX15.2 | REB1127  | SCY6.0  | REB491         | SCY5.0  | 9344154             | SCB16.6 | 4990369A18               | VA200   |
| ENT1020  | SCX2.4  | REB114   | SCY7.8  | REB492         | SCY6.3  |                     |         | 4990369A22               | ST1.160 |
| ENT1023  | SCX8.4  | REB115   | SCX4.0* | REB494         | SCY7.0  |                     |         | 6590236A15               | VCR2    |
| HNT102   | FRX25.0 | REB1152  | SCY5.0  | REB495         | SCX4.3  |                     |         | 6590339A15               | VCR1    |
| HNT104   | SCX7.0* | REB1157  | FR8.2   | REB500         | FRW9.6  |                     |         | EW02X0454                | SCY6.3  |
| HNT105   | SCX7.4  | REB1158  | SCQ6.0  | REB501         | FRW7.7  |                     |         | EW02X0578                | FRW12.0 |
| HNT106   | SCY3.5* | REB1159  | SCX7.4  | REB502         | SCQ5.3  |                     |         | EW02X0638                | ST.670  |
| HNT107   | SCA11.5 | REB116   | SCX9.5  | REB503         | SCY7.5  |                     |         | EW02X0906                | SCB10.0 |
| HNT111   | SCY6.0  | REB1160  | SCX7.0  | REB512         | SCY7.8  |                     |         | EW02X0907                | SCQ6.5  |
| HNT112   | FRW8.5  | REB1163  | FRW7.7  | REB514         | SCY7.0  |                     |         | EW02X0953                | ST1.165 |
| HNT117   | SCY6.0* | REB133   | SCY6.7  | REB517         | FRW8.5  |                     |         | EW02X0953                | VA22    |
| HNT118   | SCY4.4  | REB134   | SCX8.4  | REB519         | FRW9.2  |                     |         | PQM30003-25              | SCQ5.3  |
| HNT119   | SCX5.5* | REB135   | SCX6.2* | REB522         | FRW9.1  |                     |         | QDB0359                  | SCA5.4  |
| HNT120   | SCX7.0* | REB150   | FRY10.4 | REB529         | FRW9.0  |                     |         | QDB0360                  | FRW8.5  |
| HNT121   | FRX11.5 | REB155   | SCX4.0  | REB530         | SCQ4.0  |                     |         | RFB48Z                   | SCY5.2  |
| HNT122   | FRW10.1 | REB156   | SCY7.0  | REB531         | SCX2.9  |                     |         | SJY90080                 | FRX22.4 |
| HNT123   | SCY5.7  | REB159   | SCQ5.6  | REB532         | SCX4.3  |                     |         | SMQP1009                 | SCQ6.0  |
| HNT124   | SCX7.0  | REB185   | SCY4.6  | REB533         | FRW9.0  |                     |         | SMQ P1022                | SCY4.6  |
| HNT125   | SCY3.5  | REB189   | FRZ7.5  | REB540         | FRW9.1  |                     |         | VDGS0057                 | SCB11.6 |
| HNT126   | SCY3.5  | REB190   | SCY8.0  | REB544         | SCX4.3  |                     |         | VDGS0200                 | VA210   |
| HNT127   | SCY7.8  | REB191   | SCY3.5  | REB551         | SCX6.2  |                     |         | VDV0020                  | SCA13.2 |
| HNT128   | SCA4.0  | REB196   | FRW10.7 | REB552         | FRM9.6  |                     |         | VDV0047                  | SCQ9.8  |
| HNT130   | SCX4.9  | REB205   | SCY11.7 | REB555         | SCY7.0  |                     |         | VDV0 072                 | SCB14.0 |
| HNT131   | SCX5.5* | REB211   | FRW9.6  | REB558         | FRW8.5  |                     |         | VDV00721                 | SCB14.0 |
| HNT132   | FRX11.2 | REB212   | SCQ5.6  | REB580         | FRW9.6  |                     |         | VDV0074                  | SCA3.0  |
| HNT137   | FRW9.0  | REB228   | SCX3.2  | REB610         | 0C10.9  |                     |         | V0V00741                 | SCA3.0  |
| HNT138   | SCX8.0  | REB230   | FRY10.0 | RFB544         | SCX4.3  |                     |         | VDV0075                  | SCX8.6  |
| HNT139   | SCQ4.8  | REB231   | SCY2.2  | RYA0290        | SCX9.5  |                     |         | VDV0076                  | OX5.5   |
| HNT140   | SCY6.0* | REB232   | SCY8.2  | VEB058         | SC B3.8 |                     |         | VDV0092                  | SCQ9.8  |
| HNT146   | SCY6.7  | REB240   | SCY8.2  | VEB060         | SCX2.9  |                     |         | VDV0094                  | FRW12.6 |
| HNT151   | SCX7.0  | REB251   | SCY6.7  | VEB1077        | SCX4.6  |                     |         | VDV0101                  | SCX3.2* |
| HNT152   | FRW9.2  | REB264   | SCX4.3  | VEB1184        | SCQ4.0  |                     |         | VDV0120                  | SCC12.1 |
| HNT153   | SCX5.1  | REB265   | SCY8.6  | XE61077        | SCX4.3  |                     |         | VDV0121                  | FR11.9  |
| HNT155   | SCY2.2  | REB266   | SCY8.0  |                |         |                     |         | VDV0122                  | SCA4.5  |
| HNT158   | SCY7.3  | REB270   | FRM10.5 |                |         |                     |         | VDV0123                  | SCA13.2 |
| HNT162   | SCY6.5  | REB271   | SCQ2.5  |                |         |                     |         | VDV0124                  | SCY6.3  |
| HNT166   | FRW7.3  | RE B272  | SCY4.0  |                |         |                     |         | VDV0125                  | SCX4.9  |
| HNT167   | SCY4.2  | REB277   | SCX11.8 |                |         |                     |         | VDV0130                  | SCX3.5  |
| HNT168   | SCY2.9  | REB283   | SCQ5.6  |                |         |                     |         | VDV0212                  | SCX5.1  |
| HNT172   | FRZ12.1 | REB286   | SCY5.0* |                |         |                     |         | VDV0216                  | SCQ6.5  |
| HXX297   | FRV7.1  | REB289   | FRW7.0  |                |         |                     |         | VDV0217                  | SCX8.6  |
| KEB004   | FRX23.6 | REB290   | FRY10.0 |                |         |                     |         | VDV0218                  | SCY3.2  |
| N284141  | FR15.9  | REB291   | FRY10.7 |                |         |                     |         | VDV00074                 | SCA3.0  |
| N284170  | FRM16.3 | REB292   | SCY4.2  |                |         |                     |         | VDVS0001                 | SCX8.0* |
| N284190  | 0A14.0  | REB299   | SCY4.2  |                |         |                     |         | VDVS0005                 | FRX6.7  |
| N28420   | SCQ6.0* | REB300   | SCY5.7  |                |         |                     |         | VDVS0008                 | SCX3.5  |
| N28607   | FRX35.1 | REB309   | FRY10.7 |                |         |                     |         | VOVS0011                 | SCB2.8  |
| N286210  | FRZ7.5  | REB314   | FRW7.0  |                |         |                     |         | VDVS0012                 | FRW12.6 |
| N28851   | 0B14.0  | REB317   | SCQ2.5  |                |         |                     |         | VDVS0013                 | SCB14.0 |
| N28852A  | 0C10.9  | REB330   | FRY10.7 |                |         |                     |         | VDVS0015                 | SC89.8  |
| N28853A  | 0C10.9  | REB350   | SCY5.7  |                |         |                     |         | vbv80017                 | FRW12.6 |
| OE3314   | SCQ2.0  | REB352   | FRM11.5 |                |         |                     |         | VDVS0018                 | FR11.9  |
| PEB1013  | SCQ4.3  | REB353   | SCO5.6  |                |         |                     |         | VDVS0019                 | SCC12.1 |
| PEB1072  | SCY1.5  | REB354   | SCQ5.6  |                |         |                     |         | vbvs0320                 | SCA13.2 |
|          |         |          |         | <b>PONTIAC</b> |         |                     |         |                          |         |
|          |         |          |         | 0287412        | 0AI2.4  |                     |         |                          |         |
|          |         |          |         | 02FT7412       | 0AI2.4  |                     |         |                          |         |
|          |         |          |         | 11AMFT1        | SCB16.6 |                     |         |                          |         |
|          |         |          |         | 11APBT1        | SCB16.6 |                     |         |                          |         |
|          |         |          |         | 1223664        | SCB12.5 |                     |         |                          |         |
|          |         |          |         | 1223674        | SCX13.6 |                     |         |                          |         |
|          |         |          |         | 1224158        | SCX8.6  |                     |         |                          |         |
|          |         |          |         | 16002827       | SCX12.2 |                     |         |                          |         |
|          |         |          |         | 26810173       | FRM10.5 |                     |         |                          |         |
|          |         |          |         | 38510183       | SCX7.4  |                     |         |                          |         |
|          |         |          |         | 38510184       | SCX4.3  |                     |         |                          |         |
|          |         |          |         | 38510232       | 0A4.2   |                     |         |                          |         |
|          |         |          |         | 46KFMT1/2      | SCX12.2 |                     |         |                          |         |
|          |         |          |         | 50HPBT1        | SCX13.6 |                     |         |                          |         |
|          |         |          |         | 51XFMT1        | SCX12.2 |                     |         |                          |         |
|          |         |          |         | 51XFMT2        | SCX12.2 |                     |         |                          |         |
|          |         |          |         | 51XPBT1        | SCQ11.1 |                     |         |                          |         |
|          |         |          |         | 52AFMT3        | SCX12.2 |                     |         |                          |         |
|          |         |          |         | 52APBT1        | SCB16.6 |                     |         |                          |         |
|          |         |          |         |                |         | <b>PORSCHE AUDI</b> |         |                          |         |
|          |         |          |         |                |         | 42-683804           | FRM8.0  |                          |         |
|          |         |          |         |                |         | 42683804            | FRM8.0  |                          |         |
|          |         |          |         |                |         |                     |         | <b>PORTA VIDEO</b>       |         |
|          |         |          |         |                |         | 431017A             | ST1.218 |                          |         |
|          |         |          |         |                |         | 431017A             | VA52    |                          |         |
|          |         |          |         |                |         | 452003A             | SCA4.2  |                          |         |
|          |         |          |         |                |         | 452004A             | SCA13.2 |                          |         |
|          |         |          |         |                |         | 452019A             | FRW12.6 |                          |         |
|          |         |          |         |                |         | 62D80000901         | VPR7    |                          |         |
|          |         |          |         |                |         | 62D80001506         | FRM11.5 |                          |         |
|          |         |          |         |                |         |                     |         | <b>PROTON</b>            |         |
|          |         |          |         |                |         | 10010500            | SCY9.2  |                          |         |
|          |         |          |         |                |         | 10010512            | SCQ5.6  |                          |         |
|          |         |          |         |                |         | 18400122            | SCX2.6  |                          |         |
|          |         |          |         |                |         | 18400417            | SCX15.0 |                          |         |
|          |         |          |         |                |         | 281077              | SCX4.0  |                          |         |
|          |         |          |         |                |         | 281098              | SCY6.3  |                          |         |
|          |         |          |         |                |         | E0118               | SCX9.2  |                          |         |
|          |         |          |         |                |         |                     |         | <b>PRO TONO MINIFONE</b> |         |
|          |         |          |         |                |         | 59052               | SCX4.6  |                          |         |
|          |         |          |         |                |         |                     |         | <b>QUASAR</b>            |         |
|          |         |          |         |                |         | 144259              | SCA3.0  |                          |         |
|          |         |          |         |                |         | 144260              | SCX8.6  |                          |         |
|          |         |          |         |                |         | 144263              | ST1.160 |                          |         |
|          |         |          |         |                |         | 144263              | VA23    |                          |         |
|          |         |          |         |                |         | 144267              | SCQ9.8  |                          |         |
|          |         |          |         |                |         | 146967              | FRW12.6 |                          |         |
|          |         |          |         |                |         | 146968              | FRW12.6 |                          |         |
|          |         |          |         |                |         | 146969              | FRW12.6 |                          |         |
|          |         |          |         |                |         | 147756              | SCX2.9* |                          |         |
|          |         |          |         |                |         | 147916              | SCB14.0 |                          |         |
|          |         |          |         |                |         | 148664              | SCA4.5  |                          |         |
|          |         |          |         |                |         | 152412              | SCA13.2 |                          |         |
|          |         |          |         |                |         | 152683              | ST1.230 |                          |         |
|          |         |          |         |                |         | 152683              | FRM10.5 |                          |         |
|          |         |          |         |                |         | 155739              | SCX7.4  |                          |         |
|          |         |          |         |                |         | 155739              | SCX4.3  |                          |         |
|          |         |          |         |                |         | 155803              | 0A4.2   |                          |         |
|          |         |          |         |                |         | 4290241A15          | SCQ6.5  |                          |         |
|          |         |          |         |                |         | 4290241A16          | SCB14.0 |                          |         |
|          |         |          |         |                |         | 4290241A17          | SCB12.5 |                          |         |
|          |         |          |         |                |         | 4290241A48          | FRW12.0 |                          |         |
|          |         |          |         |                |         | 4290241A49          | FRW12.0 |                          |         |
|          |         |          |         |                |         | 4290275A47          | FRW12.0 |                          |         |
|          |         |          | </      |                |         |                     |         |                          |         |

# QUASAR ... REALISTIC

| MFG. P/N   | PRB NO.  | MFG. P/N       | PRB NO. | MFG. P/N        | PRB NO.  | MFG. P/N       | PRB NO. | MFG. P/N        | PRB NO.  |
|------------|----------|----------------|---------|-----------------|----------|----------------|---------|-----------------|----------|
| VDVS0022   | SCB14.0  | 21V002         | FRM11.5 | B1042           | \$CX15.0 | 66136(14876)   | SCX16.0 | 86252(14834)    | SCQ6.7   |
| VDVS0023   | SCY7.5   | 21V003         | FRM10.2 | 66001           | SCX2.8   | 136136(148768) | SCX16.0 | B6254(121401)   | FRM10.2  |
| VDV\$0024  | SCY4.2   | 21V7000        | SCX3.5  | B6004           | FRW10.7  | 86137(14876)   | SCX4.0  | 66254(121402)   | FRM10.2  |
| VDVS0028   | SCB7.1   | 21V7008        | FRM9.7  | B6004(14910)    | FRM10.5  | B6137(14912)   | SCX4.0  | 86254(121402A)  | FRM10.2  |
| VDVS0029   | FRW12.0  | 21V7012        | FRM9.7  | 66004(14928K)   | FRM10.5  | B6138          | FRX9.4  | 66254(121818)   | FRM10.2  |
| VJNS002D   | SCA13.2  | 21V7017        | FRW8.5  | 86021(14300)    | OAI2.4   | B6142(121832)  | FRW9.7  | B6254(131197)   | FRM10.2  |
| VDVS0032   | SCY7.5   | 21V7020        | FRM10.5 | 56021(14333)    | OAI2.4   | B6144(14915)   | FRM10.2 | 86254(141920)   | FRM10.2  |
| VDVS0033   | SCY5.0   | 21V7021        | FRM10.2 | B6021(14840)    | OAI2.4   | 86144(14916)   | FRM10.2 | 86254(14943)    | FRM10.2  |
| VQVS0034   | SCY4.0   | 21V7028        | SCY6.5  | 86021(14843)    | OAI2.4   | 136144(14916A) | FRM10.2 | 86254(14945)    | FRM10.2  |
| VDVS0035   | SCX4.3   | 21V7032        | FRM11.5 | 136021(14909A)  | OAI2.4   | B6146          | FRX12.7 | B6254(1494513)  | FRM10.2  |
| VDVS0037   | SCX6.2   | 21 V7037       | FRM10.5 | 136021(14909TO) | OAI2.4   | B6147(121823)  | OA6.6   | B6255           | FRM9.7   |
| VQVS0038   | \$CB14.0 | 21W0117        | FRM10.2 | 66021(14919)    | OAI2.4   | 86149(145012)  | 007.4   | 66258           | FRM10.2  |
| VDVS0039   | SCB12.5  | 21W6025        | FRM8.0  | B6021(14999)    | OAI2.4   | 66155(145015)  | SCX2.6  | B6258(121835)   | FRM9.7   |
| VDVS0040   | SCA5.4   | 21W7130        | SCX9.5  | B6031(CYPFXVII) | OA6.1    | 86155(14890)   | SCX2.6  | 136258(121835R) | FRM9.7   |
| VDVS0042   | SC B10.0 | 21 W7306       | FRM8.0  | 86040(141020)   | SCX9.5   | 86158          | SCX9.5  | 86260(14720)    | SCX11.8  |
| VDVS0043   | SCX6.2   | 23582341       | OA7.0   | 86040(14859)    | SCX9.5   | 86159          | SCX18.5 | 86262(14828)    | SCQ10.0  |
| VDVS0044   | SC 62.5  | 23612721       | OA6.1   | B6040(14861)    | SCX9.5   | 86160          | SCY9.2  | B6263(14828)    | SCX4.0   |
| VDVS0045   | SCA4.5   | 257518002      | SCX8.4  | 86040(14862)    | SCX9.5   | 66162(14896)   | SCA8.9  | 86264(14828)    | SCX5.1   |
| VDVS0046   | SCB8.1   | 2575512300     | 089.4   | 66040(14865)    | SCX9.5   | 86165          | OA6.1   | B6266(121814)   | SCX11.8  |
| VCA\$0047  | SCB10.0  | 2575515901     | SCQ10.0 | 86040(14884)    | SCX9.5   | B6166          | OA8.2   | 86266(121815)   | SCX11.8  |
| VDVS0048   | SCA8.9   | 2575516500     | SCX10.7 | 86040(14891)    | SCX9.5   | B6167          | 0014.4  | B6270(14925)    | FRM11.0  |
| VDVS0052   | SCA8.9   | 25755171       | SCX4.0  | 66041(14882)    | OA10.9   | B6167(14707)   | OC13.2  | 66271(14925A)   | SCA8.6   |
| VDVS0053   | SCB9.5   | 25755180       | SCX8.4  | 86042(14882)    | OA8.5    | 86167(14712)   | OC13.2  | B6271(14925A)   | SCA8.6   |
| VDVS0054   | SC04.3   | 2575515400     | SCX8.4  | 66056           | SCA3.5   | B6167(14808)   | 0013.2  | 86272           | FRM9.7   |
| VDVS0055   | SCB8.1   | 25755210       | SCX4.0  | 86058(14880)    | OA10.1   | 86167(14901)   | 0013.2  | B6272(121831)   | SCX3.5   |
| VQVS0057   | SCB11.6  | 25755221       | SCY8.6  | 86059(14808)    | OA10.1   | 66167(14902)   | OC13.2  | B6273(121813)   | SCX10.5  |
| VDVS0058   | SCA4.5   | 25755222       | FRX16.8 | 66068           | SCX4.0   | 86167(14973)   | Q13.2   | B6274(14826)    | SCX9.5   |
| VDVS0059   | SCA4.2   | 25755247       | SCQ10.0 | B6069(14927)    | SCX8.4   | 66168(141487)  | FRM11.5 | 66275           | SCX3.5   |
| VENSOC160  | SC02.5   | 25755309       | FRM9.2  | 136070          | OA16.4   | 86170(144001)  | FRM11.5 | 66275(14826)    | SCX9.5   |
| VDVS0065   | SCB6.6   | 2601000125     | SCA8.9  | 86073(14850)    | OA5.4    | 86173(145015)  | OX5.9   | 86275(14836)    | SCX9.5   |
| VDVS0066   | SCB11.6  | 275520900      | SCQ10.0 | 86076(14856)    | SCY15.2  | 66175(14972)   | 0013.2  | B6276           | SCY8.6   |
| VDVS0069   | SCA3.0   | 293788         | OA10.9  | B6086(14827)    | SCA8.6   | B6177(14972)   | SCAI2.5 | 66276(14836)    | SCY8.6   |
| VDVS0070   | SQC12.6  | 3280707        | SCX4.3  | B6086(14852)    | SCX8.6   | B6179(14874)   | SCX7.0  | B6277(14944)    | FRM10.2  |
| vovsoi 22  | SCA4.5   | 34251701       | SQX11.8 | B6086(14894)    | SCY8.6   | 86180(14874)   | OA4.0   | B6277(14946)    | FRM10.2  |
| WQ122      | SCA4.5   | 343317030      | SC06.7  | 66088           | FRW9.1   | 136186(14887)  | OA5.4   | B6278(131195)   | FRM10.5  |
| VXLS0137   | VPR26    | 34A0038        | SCQ6.7  | B6092(121826)   | FRM11.5  | B6187(14887)   | SCA8.9  | B6279           | SCX4.9   |
| VXL\$0383  | VA215    | 40037070       | SCA8.6  | 86093(14855)    | SCQ11.1  | B6190(14972)   | 0811.7  | 86279(121813)   | SCY4.6   |
| VXL\$0454  | VA215    | 40037080       | SCY4.6  | 86094           | SCY9.2   | 66191(125088)  | FRM11.7 | B6280           | SCX2.9   |
| VXL\$0455  | VPR1     | 4006064        | FRM12.1 | 86094(143003)   | SCX9.2   | B6192          | FRZ12.1 | 86280(121813)   | SCQ2.5   |
| VXL\$0475  | VPR1     | 411020(156040) | SCX9.5  | 86096           | SCQ6.0   | 86193(14827)   | SCX5.1  | B6281(14889)    | SCY6.5   |
| VXL\$0587  | VPR26    | 411020(66113)  | OA7.0   | 86098(14858)    | SCQ11.1  | 56193(148275)  | SCY5.2  | 86282           | FRZ12.1  |
| VXL\$0666  | VPR2     | 422570(RC0033) | FR2.9   | B6099(14858)    | QA6.6    | B6193(148415)  | SCY5.2  | 86282(14889)    | FRM11.5  |
| VXL\$0738  | VPR26    | 422931(56331)  | FRX25.0 | 86101(14911)    | FRM12.1  | B6193(14873)   | SCY5.2  | 66283(131196)   | SCY8.6   |
| V->CLS0770 | VPR2     | 422949(86137)  | FRX14.5 | 86103(14909)    | OA11.7   | B6193(14879)   | SCY5.2  | B6284(121818)   | FRM10.2  |
| VXL\$0836  | VPR26    | 422951(B6351)  | FRX10.5 | 86103(14909A)   | OA11.7   | B6194          | FRZ13.2 | 86285           | FRY11.0  |
| VXP0174    | ST1.160  | 42640818G01    | FRM10.2 | 136103(14909TO) | OA11.7   | 66198(121834)  | FRM9.2  | 86286           | FRY10.0  |
| VXP0174    | VA23     | 43256(66355)   | SCY4.6  | 66103(14912A)   | OA11.7   | B6203          | FRM11.2 | 66289(14888)    | SCQ6.0   |
| VXP0213    | ST.752   | 4700075        | SCX8.6  | 86103(14919)    | OA11.7   | 66204(122088)  | FRM9.7  | 66290           | SCX4.9   |
| VXP0213    | VA2(0)   | 521000401      | FRM11.5 | B6103(14999)    | OA11.7   | B6205(122088)  | FRM12.1 | B6290(14888)    | SCY5.2   |
| VXP0329    | ST1.330  | 56209133920    | SCA8.6  | B6104(143003)   | OA3.1    | B6206          | FRM11.2 | 86291           | SCY9.0   |
| VXP0329    | VA20     | 56209179580    | SCX10.5 | B6107(121390)   | FRM10.2  | 86209(126012)  | FRM9.7  | B6292           | SCQ10.0  |
| VXP0331    | ST1.230  | 56350137560    | FRX11.2 | B6107(125026)   | FRM10.2  | 136210(293788) | OA10.9  | 66293(14829)    | SCX7.0   |
| VXP0331    | VA25     | 5635027919     | FRM11.0 | B6109(141974)   | SCX12.2  | 86211(14974)   | OA6.1   | B6295           | FRY11.0  |
| VXP0344    | ST1.330  | 56350338985    | FRM11.0 | 66109(312034)   | SCX12.2  | 86215(121822)  | SCA8.9  | B6298(121836)   | SCX4.3   |
| VXP0344    | VA26     | 56360133785    | FRM11.5 | 66110           | SCX4.6   | 86216(121822)  | SCX4.0  | B6299(121836)   | SCA8.6   |
| VXP0521    | ST1.165  | 6350031        | SCX4.3  | 86113(14890)    | OA7.0    | 86218(14878)   | SCQ6.7  | 136300(14835K)  | SCX8.6   |
| VXPS0047   | ST.470   | 6350212        | FRM11.5 | B6113(411020)   | OA7.0    | B6222(14899)   | OX5.9   | 86300(14848)    | SCY8.6   |
| VXPS0054   | ST1.370  | 6350273        | OA7.0   | B6114(121819)   | FRM9.7   | B6223(14894)   | SCA8.9  | 66302(14918)    | FRM9.2   |
| VXPS0054   | VA28     | 6350371        | SCX9.5  | 66114(121819B)  | FRM9.7   | B6223(14895)   | SCA8.9  | B6302(14926)    | FRM10.2  |
| VXPS0076   | ST.670   | 6350471        | OX5.5   | B6114(121827)   | FRM9.7   | B6223(14899)   | SCA8.9  | B6304           | FRY10.0  |
| VXPS0116   | ST1.165  | 6350601        | OX5.5   | 86114(121833)   | FRM9.7   | 86224(14894)   | SCX7.0  | 66304(14829)    | FRM9.2   |
| VXPS0116   | VA27     | 6350611        | SCY8.6  | 66115(14864)    | SCY4.6   | 86225(14895)   | OX5.9   | B6305           | FRW9.2   |
| VXZ0076    | VB6      | 6350701        | FRW9.7  | B6116(14913)    | FRM9.7   | 86226(14895)   | SCA8.9  | B6305(14602)    | FRW9.2   |
| VXZS0005   | V81      | 6350732        | FRM10.5 | 86117(141975)   | FRM12.7  | 86227(14892)   | SCA8.6  | B6305(14771)    | FRW8.5   |
| VXZS0129   | V131     | 6350931        | FRM9.2  | B6118(14865)    | OX5.5    | B6228(141919)  | FRM11.2 | 66305(14838)    | FRW8.5   |
| VXZS0137   | VB1      | 6350961        | 0)(6.9  | 136118(14865B)  | OX5.5    | 66230          | SC 69.5 | B6305(14877)    | FRW8.5   |
| VXZS0145   | V81      | 6351023        | OX5.9   | 86118(14896)    | OX5.5    | 86232(14821)   | SCQ6.7  | 86307           | FRW9.2   |
|            |          | 6354241        | SCQ6.0  | 86122(14657)    | SCA10.0  | 86233(14821)   | OA4.0   | B6307(14877)    | SCY8.6   |
|            |          | 6354251        | SCY5.2  | 86122(14866)    | SCA10.0  | B6234          | SCX7.4  | B6308(14837)    | SCX7.0   |
|            |          | 6354261        | SCX5.1  | B6123(131173)   | SCQ10.0  | 86235          | FRM9.6  | 66309(14837)    | SCX9.5   |
|            |          | 6354281        | SCX2.9  | B6125(131173)   | SCQ10.0  | B6236(121820)  | FRM11.5 | 86312           | SCX8.4   |
|            |          | 6357081        | FRX10.5 | 86126(14867)    | SCX8.4   | 66237(14881A)  | FRX11.2 | 86312(121816)   | SCY8.6   |
|            |          | 7668054        | SCX2.6  | 86126(14887)    | SCX8.4   | 86238(14898)   | SCX9.5  | 66313           | SCX4.3   |
|            |          | 7661521        | SCX9.5  | 86128           | SCX7.0   | 86242          | SCQ10.0 | 86316(121815)   | SCQ6.7   |
|            |          | 7667611        | SCA8.9  | B6130(121819)   | SCA2.3   | 86242(14885)   | SCX9.5  | 86317           | FRM15.2  |
|            |          | 7668062        | SCY5.2  | 86131(14869)    | SCA8.9   | B6243          | FRM9.6  | 86317(422949)   | FRX14.5  |
|            |          | A110684        | FRX14.5 | B6132           | SCX9.2   | B6244(14823)   | SCY8.6  | 86320(14849)    | SCX5.1   |
|            |          | ATN18200809C   | SCX4.6  | 66133           | SCY9.2   | 86245          | SCQ10.0 | 86321(14849)    | FRX10.5  |
|            |          | ATN182112161   | SCY5.7  | 86134(14707)    | 0139.4   | 86245(14897)   | SCY8.6  | B6323(14849)    | SCX2.9   |
|            |          | B0186(14944)   | FRM11.0 | 86134(14711)    | OB9.4    | B6246          | SCX8.9  | 66325(14838)    | FRM9.6   |
|            |          | B0201          | FRX6.7  | B6134(14712)    | 089.4    | 136247(205517) | OA6.6   | 66326           | \$0010.0 |
|            |          | B0202          | SCA4.5  | 86134(14808)    | 0139.4   | B6248(121821)  | SCA8.9  | 66327           | FRY10.4  |
|            |          | B0304          | FRM9.7  | 66134(14883)    | 069.4    | B6250(14833)   | SCX9.5  | B6327(121830)   | FRM10.2  |
|            |          | B0394          | SCY4.4  | B6135(14883)    | SCX10.7  | B6252          | SCX7.0  | B6328(14925)    | FRM11.0  |
|            |          | B0558          | SCA8.6  | 86136           | SCX16.0  | 86252(14833)   | SCQ6.7  | B6328(14925A)   | FRM11.0  |

**RCA**  
(See Thomson)

**REALISTIC**

0333370 SCQ11.1  
0971193 OA6.1  
0971246 OA8.2  
0971247 OA4.0  
11404900 SCY8.6  
16011132 SCX3.2  
16011151 SCX10.5  
175049003 FRM9.7  
2090500001 80010.0  
2015000296 SCA8.9  
205517(66247) OA6.6  
2104013002 SCX11.8  
211271 007.4

= Part of the Assy

"= Kit May Not Include Tires

= Part of the Assy

# REALISTIC ... SANYO/FISHER

| MFG. P/N             | PRB NO. | MFG. P/N              | PRB NO.     | MFG. P/N      | PRB NO.      | MFG. P/N      | PRB NO.     | MFG. P/N            | PRB NO.      |
|----------------------|---------|-----------------------|-------------|---------------|--------------|---------------|-------------|---------------------|--------------|
| B6329(14903)         | FRM8.0  | <b>RECORD-O-PHONE</b> |             | 10000186059   | SCX7.0       | 62569002283   | V767        | 37093000            | SCX2.6       |
| B6331(422931)        | FRX25.2 |                       | 47000500    | 0812.4        | 10000215088  | SCY6.0        | 65153600011 | ST1.152             | 37102000     |
| 66332(14848)         | SCX5.1  | <b>RECORDEX</b>       |             | 10000215091   | SCY6.5       | 65153600011   | VA56        | 37110100            | SCY14.7      |
| B6336(121813R)       | SCY4.6  |                       | 88033       | 0A6.1         | 10000215102  | SCY6.0        | 65253611610 | VPR31               | 37120500     |
| B6338                | FRW8.0  | 88134                 | 0A5.6       | 10000252037   | SCY7.5       | 65254625710   | VPR18       | 37121600            | SCY5.7       |
| 66340(14818)         | SCA7.5  | 88139                 | OB6.6       | 10000268040   | SCY4.2       | 65264601111   | VPR9        | 37125400            | SCY9.2       |
| B6341                | FRW10.1 | 88142                 | OB7.2       | 10000268055   | SCX7.0       | 65274600210   | SCA10.5     | 46214700            | FRW8.5       |
| B6341(14818)         | FRX9.7  | 88143                 | OB7.2       | 10000268059   | SCX7.0       | 65274600711   | SCB9.2      | 46214800            | SCY6.7       |
| B6343(121837)        | SCX4.0  | 88150                 | OB8.8       | 10000307159   | SCY7.5       | 65274600720   | SCB8.6      | 47003300            | SCX8.6       |
| B6344(141921)        | FRM9.7  | 88152                 | OB9.4       | 10000607156   | SCY4.2       | 65274600811   | FRW9.7      | 47003500            | FRX9.4       |
| B6345(1480719)       | SCX10.5 | 88154                 | OB11.7      | 10000607159   | SCY7.5       | 65274601820   | SCQ4.8      | 47077200            | SCQ6.0       |
| B6346(14870K)        | SCX3.2  | 88165                 | OB19.5      | 15274501520   | SCX3.2       | 65274601910   | FRW8.8      | 47171400            | SCY7.5       |
| B6348(14875)         | SCX9.5  | <b>ROAD STAR</b>      |             | 153600011     | VA56         | 65274603210   | SCB9.5      | 47378200            | SCY8.0       |
| B6349                | SCX8.9  |                       | 0010949     | SCX8.4        | 2139401055   | VCR21         | 65274603710 | SCB9.2              | 47405100     |
| 86349(14928K)        | SCX10.5 | 0010958               | SCX3.2      | 21394010552   | VCR21        | 65274701110   | FRW9.7      | 47405200            | FRW9.6       |
| B6350(14842)         | SCX10.5 | 0024024               | SCX4.0      | 21394010552V  | VCR21        | 66054609410   | VA760       | 58678200            | SCY7.3       |
| B6351(422951)        | FRX10.5 | 050400282             | SCQ11.1     | 23091102323V  | VCR7         | 66219001000   | VCR26       | 47843300            | SCY6.5       |
| B6355(43256)         | SCY4.6  | <b>ROBERTS</b>        |             | 23091102402V  | VCR7         | 66419000100   | VCR15       | 58575000            | SCY6.0       |
| B6356(131203)        | SCA8.9  |                       | 43070       | FR14.1        | 23091120204  | VCR33         | 69000470310 | VCR21               | 58590700     |
| B6358(14839T)        | SCX8.0  | 5203                  | FR12.5      | 23091120204V  | VCR33        | 69000470410   | VCR21       | 58592900            | SCY6.0       |
| B6359                | SCX8.9  | 600303                | OSD11.0     | 23091120207   | VCR33        | 6900270026    | VCR7        | 58601100            | SCY4.2       |
| B6360(14601)         | SCY4.6  | 600701                | VR9.0       | 25747011102V  | FRW9.7       | 6900470310    | VCR21       | 58602900            | SCY6.5       |
| B6360(14904)         | SCY4.6  | 600702                | VR4.6       | 3005005033    | VCR21        | 90002503308V  | ST1.218     | 58637500            | SCY6.7       |
| B6361(121811)        | SCA12.5 | 6213                  | FR14.0      | 30050050331V  | VC R21       | 90002503308V  | VA53        | 58672600            | SCY4.2       |
| B6362                | SCX8.0  | 6214                  | OSD3.8      | 5153600011    | ST1.152      | 90002700262V  | VCR7        | 58673400            | SCY6.5       |
| 66363                | FRM11.0 | 6245                  | FR12.5      | 51536000114   | ST1.152      | 90004703104V  | VCR21       | 58734800            | FRW7.7       |
| B6364                | FRW10.1 | 6246                  | OSD14.0     | 51536000114V  | VA56         | 90004704109V  | VCR21       | 58738100            | FR8.2        |
| B6366                | FRM10.2 | 63000900              | FR14.1      | 51536000114V  | VA56         | 91036011281V  | VCR33       | 58831500            | SCY4.6       |
| B6367                | FRM10.2 | 6309                  | FR14.1      | 51896000546   | VCR33        | 91036050385V  | VCR33       | 8030020             | 0A7.0        |
| B6368                | FR23.6  | 6309                  | FR14.1      | 51896000546V  | VCR33        | 9106011281V   | VCR33       | 6010030             | FRM9.6       |
| B6369                | FR23.6  | 663013700             | FR14.1      | 5224703910    | ST1.218      | <b>SANSUI</b> |             | 60300900            | FRZ13.2      |
| B6370                | FRW10.7 | 6631200               | FR14.1      | 5224703910    | VA53         |               | 0016680801  | SCY5.7              | 60301000     |
| 86370(14942)         | FRM10.5 | 663129                | 0A9.0       | 52247042208   | ST1.218      | 0018511416    | SCX10.5     | 60301100            | SCY8.6       |
| 86370(14942R)        | FRM10.5 | 663136                | SCA8.9      | 52247042208V  | VA53         | 0018511417    | SCY9.2      | 60301300            | FR7.7        |
| B6371                | SCX10.5 | 663200                | FR14.1      | 52247042208V  | ST1.218      | 0019210703    | SCY4.2      | 60301300            | FR7.7        |
| B6374                | FRM10.5 | 663246                | FR14.1      | 52247042208V  | VA53         | 0019210924    | SCY7.0      | 60301400            | SCX7.0       |
| B6375                | SCQ6.0  | 663347                | SCX8.0      | 52247042208V  | VPR31        | 001921924     | SCY7.0      | 60301400            | SCX7.0       |
| B6377                | FRM9.7  | 663386                | SCX8.9      | 52247042208V  | VPR9         | 0019401417    | SCX15.2     | 60301500            | SCQ11.1      |
| B6379                | FRW10.1 | 66387                 | SCX7.0      | 52536116102V  | ST.977       | 07508600      | SCX4.9      | 60301500            | SCQ11.1      |
| B6380                | FRX15.2 | 66388                 | SCX2.4      | 52537011105V  | VA55         | 07526900      | SCX3.5      | 60301600            | SCY5.2       |
| B6382                | FRX11.0 | 66388                 | SCX7.0      | 52537011105V  | VPR9         | 07526900      | FRY10.7     | 60301700            | SCX4.6       |
| 66388                | FRM9.6  | 66388                 | SCX7.0      | 52537011105V  | SCB2.5       | 07686600      | FRW6.5      | 60301800            | FRY10.0      |
| B6431                | SCX8.9  | 66388                 | SCX2.4      | 52546001111   | SCY6.7       | 07686700      | SCX5.1      | 60301900            | SCQ5.6       |
| B6439                | SCA13.2 | 66600302              | 0AI2.4      | 52546001111V  | SCA10.5      | 07686900      | SCY3.5      | 60302000            | SCX7.4       |
| 86497                | SCA9.2* | 66600701              | OSD11.0     | 5271601210    | SCA10.5      | 07687000      | SCY5.2      | 60302100            | SCX7.4       |
| B6503                | SCQ10.0 | 88111                 | 0A10.9      | 5271601210V   | SCA10.5      | 07687000      | SCY5.2      | 60302100            | SCX7.4       |
| B6509                | FRX9.7  | 881124                | FR14.0      | 5274600510    | FRW9.7       | 07708600      | SCX7.4      | 60302200            | OX5.5        |
| 86513                | SCX4.6  | 88208                 | FR12.5      | 52746005100V  | FRW9.7       | 07709400      | FRW10.1     | 60302400            | SCY4.0*      |
| 86514                | FRW8.0  | 88584                 | 0A9.0       | 52746007100V  | SCB9.2       | 07711900      | SCY4.6      | 60302500            | FRM8.0       |
| B6518                | FRW10.1 | 905068                | 0814.0      | 5274600711    | SCB9.2       | 07714600      | SCX4.3      | 60302600            | OX5.5        |
| B6539                | SCX9.5  | M9053                 | FR14.1      | 52746007119V  | SCB9.2       | 07733900      | SCX4.6      | 60302400            | FRX25.0      |
| B6540                | SCX7.4  | M92138                | FR14.1      | 5274600720    | SCB8.6       | 07734200      | SCQ4.0      | 60320800            | FRX25.0      |
| B6570                | SCX13.6 | M9214C                | OSD3.8      | 52746007207V  | SCB8.4       | 07976700      | SCX7.4      | 60321200            | FRX25.0      |
| B6595                | SCY5.7  | <b>RO TEL</b>         |             | 5274600811    | FRW9.7       | 09412600      | FRW9.1      | 60321400            | FRX25.0      |
| B6600                | SCX9.2  |                       | 092036021   | SCX4.6        | 52746008114V | FRW9.7        | 09412700    | SCQ4.0              | 60321600     |
| 86611                | FRW9.1  | 092036023             | SCX3.5      | 5274601110    | SCB3.6       | 09412800      | SCX5.1      | 60321700            | FRX23.6      |
| B6614                | SCA8.6  | <b>SABA</b>           |             | 52746011103V  | SCB3.6       | 09414700      | SCX7.4      | 60321700            | FRY25.0      |
| B6618                | SCA8.6  |                       | 62989600124 | SCA8.9        | 52746011200V | SCB3.6        | 09440800    | FRW8.0              | 60321900     |
| B6650                | SCX5.1  | <b>SAMPO</b>          |             | 5274601210    | SCB2.5       | 09440900      | SCX5.1      | 60322200            | FRX25.0      |
| B6653                | SCA7.5  |                       | 03BELT6120  | SCY4.4        | 52746012108V | SCB2.5        | 09473800    | FRY10.0             | 84504900     |
| B6656                | 0A14.8  | 32BELT6119            | SCY4.6      | 52746024101V  | SCA9.2       | 13006600      | FRY25.0     | PU489678            | ST1.113      |
| B6657                | SCX4.6  | 37BELT6083            | SCX8.6      | 5274603210    | SCB9.5       | 13037410      | FRX25.0     | PU489678            | VA10         |
| QB1386               | ST.536  | 37BELT6090            | SCY5.2      | 52746032104V  | SCB9.5       | 2024075907    | SCY4.6      | REB483              | FRW8.0       |
| Q080058              | SCQ11.1 | 856ELT6083            | SCX8.6      | 5274701110    | FRW9.7       | 27119900      | FRW8.8      | REB552              | FRM9.6       |
| QDB0114              | SCX4.0  | BELT6110              | FRW10.1     | 52747011102   | FRW9.7       | 27401600      | FRW6.5      | <b>SANYO/FISHER</b> |              |
| QD80131              | SCA8.9  | BELT6119              | SCY4.4      | 52747011102V  | FRW9.7       | 27413400      | FRW8.5      |                     | 0-1014-03990 |
| 0080135              | FRM12.7 | <b>SAMSUNG</b>        |             | 52747011306   | FR9.4        | 27472900      | FRW9.1      | 0-4014-01150        | VCR33        |
| R1083                | FRM10.2 |                       | 00000370837 | FRW9.2        | 52747013102  | SCX5.5        | 2783800     | SCY7.0              | 0-4014-01154 |
| R448039A             | SCA12.5 | 00000370846           | SCX5.1      | 52747013102V  | SCX5.5       | 27838000      | SCY7.0      | 0-4014-01170        | VCR22        |
| RA0097(14819)        | 0A4.2   | 00000370855           | SCX4.3      | 52747013306   | SCY5.2       | 37003500      | FRW9.6      | 0-4014-01180        | VCR22        |
| RA0117               | 0A4.2   | 00000370858           | SCX4.3      | 52747013306V  | SCY5.2       | 37010300      | SCX15.0     | 0-4014-01180        | VCR22        |
| RA0145               | 0A4.2   | 0000048066            | FRX21.6     | 5274701610    | SCA3.0       | 37010400      | SCX3.2      | 0-4014-02780        | VCR33        |
| RA0154               | 0A4.2   | 00001860591           | SCX7.4      | 52747016107V  | SCA3.0       | 37020900      | SCX5.5      | 0-4014-03750        | VCR33        |
| RA0157(14889)        | 0A4.2   | 00002520373           | SCY7.5      | 52747016107V  | SCA3.0       | 37020900      | SCX5.5      | 0-4014-05790        | VCR33        |
| RA0161(14827)        | 0A4.2   | 00002680558           | SCY4.2      | 52747016204V  | SCA3.0       | 37025200      | SCY3.2      | 1039-14-01          | SCX4.0       |
| RA0210(14832)        | 0A4.2   | 00002680558           | SCX7.0      | 6052600310    | ST1.152      | 37027300      | SCX14.7     | 1240-06-02          | FRY2.9       |
| RC0002               | W11     | 00002680558           | SCY4.2      | 6052600310V   | ST1.152      | 37032300      | SCX15.0     | 1240-06-20          | FRY2.9       |
| R00007(131010)       | W03     | 00002680558           | SCY4.2      | 6052600310V   | VA54         | 37041100      | SCX15.0     | 1240-09-05          | FRW7.1       |
| RC0033(422570)       | FR2.9   | 00002680558           | SCY4.2      | 60536044114V  | VA763        | 37046600      | SCX3.2      | 1240-09-06          | FRW7.0       |
| <b>RECORD-A-CALL</b> |         | 00002680558           | SCY4.2      | 60546094107V  | VA760        | 37060500      | FRW8.8      | 1260-12-02          | FRW8.5       |
|                      | 5JG7358 | SCX10/                | SCY7.0      | 62139401055   | VCR21        | 37068300      | SCX9.5      | 1303-12-01          | FRW8.5       |
|                      | 5JG7448 | SCA13.2               | SCY4.2      | 621394010552V | VCR21        | 37088500      | SCX5.1      | 1303-12-03          | FRW8.5       |
|                      | 5JF7346 | PRO1                  | SCY7.5      | 62309112020   | VCR33        | 37090500      | SCY6.5      | 131-2-400120        | FRM11.5      |
|                      |         | 10000100106           | SCX7.4      | 62569002038   | V764         | 37092100      | SCY7.0      | 131-2-4804-00120    | FRY10.4      |
|                      |         | 10000100107           | SCQ5.6      | 62569002130   | V764         | 37092900      | SCX15.2     | 131-2-610200        | FRM10.5      |

\* = Replacement Belt

= Kit May Not Include Tires

^ = Part of the Assy



# SANYOFISHER ... SANYO/FISHER

| MFG. P/N         | PRB NO. | MFG. P/N         | PRB NO. | MFG. P/N           | PRB NO. | MFG. P/N         | PRB NO. | MFG. P/N           | PRB NO. |
|------------------|---------|------------------|---------|--------------------|---------|------------------|---------|--------------------|---------|
| 132-91734700     | FRM10.5 | 141-2-5649-04200 | SCY5.7  | 141-2-5649-20300   | SCX5.5  | 141-2-5641-16300 | FRX9.5  | 141-2-5641-35900   | SCY5.0  |
| 132-91831700     | FRY10.7 | 141-2-5649-94300 | SCY7.0  | 141-2-5649-20600   | SCX8.0  | 141-2-5641-16800 | SCQ8.2  | 141-2-5641-36000   | SCY7.3  |
| 132-91831701     | FRY10.7 | 141-2-5649-04500 | SCX5.1  | 141-2-5649-20900   | SCX9.5  | 141-2-5641-16801 | SCQ8.2  | 141-2-5641-36600   | SCX4.0  |
| 132-91851700     | FRM10.5 | 141-2-5649-04700 | SCY7.5  | 141-2-5649-21100   | SCY6.7  | 141-2-5641-16900 | SCY6.0  | 141-2-5641-37000   | SCQ16.0 |
| 1330-15-03       | FRM7.5  | 141-2-5649-04800 | SCY6.0  | 141-2-5649-21200   | SCQ5.3  | 141-2-5641-17000 | SCQ10.0 | 141-2-5641-37100   | SCX3.2  |
| 134-2-6302-10200 | FRX25.0 | 141-2-5649-05000 | SCY6.7  | 141-2-5649-21600   | SCY8.0  | 141-2-5641-17200 | SCQ6.0  | 141-2-5641-37600   | SCY6.0  |
| 134-2-6302-10400 | FRX25.0 | 141-2-5649-05400 | SCX4.9  | 141-2-5649-21900   | SCX14.0 | 141-2-5641-17300 | SCY9.0  | 141-2-5641-37700   | SCY5.2  |
| 134-2-6302-10500 | FRW9.7  | 141-2-5649-06100 | SCY4.6  | 141-2-5649-22000   | SCX12.2 | 141-2-5641-17500 | SCQ10.0 | 141-2-5641-38800   | SCX8.0  |
| 134-2-6302-10700 | FRX25.0 | 141-2-5649-06300 | SOO7.1  | 141-2-5649-22400   | SCX8.4  | 141-2-5641-18000 | SCX10.5 | 141-2-5641-39000   | SCX8.0  |
| 134-2-6302-10800 | FRX25.0 | 141-2-5649-06400 | SOXA5   | 141-2-5649-22600   | SCX2.9  | 141-2-5641-18200 | SCY7.0  | 141-2-5641-39100   | SCX8.9  |
| 134-2-6302-10900 | FRX25.0 | 141-2-5649-06600 | SCQ5.6  | 141-2-5649-22900   | SCX6.2  | 141-2-5641-18300 | SCQ8.2  | 141-2-5641-39700   | SCQ10.0 |
| 134-2-6302-11600 | FR25.0  | 141-2-5649-06700 | SCA5.4  | 141-2-5649-23300   | SCY6.5  | 141-2-5641-18301 | SCQ8.2  | 141-2-5641-40000   | SCX4.3  |
| 139-176700       | FRY10.7 | 141-2-5649-06900 | SCY8.0  | 141-2-5649-23400   | SCQ11.1 | 141-2-5541-18400 | SCY5.2  | 141-2-5641-40300   | SCX8.6  |
| 141-0-6611-02300 | STC.953 | 141-2-5649-07000 | SCQ6.0  | 141-2-5649-23500   | SCQ5.1  | 141-2-5641-18401 | SCY5.2  | 141-2-5641-41000   | SCY9.2  |
| 141-2-25200      | SCY4.6  | 141-2-5649-07100 | SCO5.6  | 141-2-5649-24200   | SCY8.2  | 141-2-5641-18500 | SCY7.0  | 141-2-5641-41101   | SCX8.4  |
| 141-2-5419-01200 | PRO2    | 141-2-5649-07200 | SCX3.5  | 141-2-5649-24500   | SCY8.2  | 141-2-5641-18600 | SCX4.6  | 141-2-5641-41600   | SCX4.9  |
| 141-2-5519-09001 | SCX10.7 | 141-2-5649-07500 | SCX9.2  | 141-2-5649-24600   | SCX8.6  | 141-2-5641-18700 | SCX9.5  | 141-2-5641-41700   | SCQ4.0  |
| 141-2-5619-00100 | FRX9.0  | 141-2-5649-07700 | SCY7.0  | 141-2-5649-25300   | SCY4.2  | 141-2-5641-18800 | SCQ11.1 | 141-2-5641-41900   | SCY4.2  |
| 141-2-5619-00600 | FRM9.2  | 141-2-5649-07800 | SCY5.7  | 141-2-5649-25600   | SCX9.2  | 141-2-5641-19100 | SCY7.0  | 141-2-5641-42000   | SCY8.6  |
| 141-2-5619-01000 | FRM13.3 | 141-2-5649-08500 | SCQ6.0  | 141-2-5649-26500   | SCY6.5  | 141-2-5641-19500 | SCY10.5 | 141-2-5641-42100   | SCY7.3  |
| 141-2-5619-01100 | FRX6.6  | 141-2-5649-08700 | SCY8.0  | 141-2-5649-26600   | SCQ5.3  | 141-2-5641-20100 | SCX10.5 | 141-2-5641-42200   | SCY3.2  |
| 141-2-5619-01200 | FRW9.0  | 141-2-5649-08800 | SCY6.5  | 141-2-5649-26800   | SCQ5.3  | 141-2-5641-20200 | SCQ6.0  | 141-2-5641-42400   | SCY4.6  |
| 141-2-5619-01300 | FRW7.0  | 141-2-5649-08900 | SCX4.6  | 141-2-5649-26900   | SCQ11.1 | 141-2-5641-20300 | SCY5.2  | 141-2-5641-42500   | SCY4.2  |
| 141-2-5619-01400 | FRW9.2  | 141-2-5649-09000 | SCY7.3  | 141-2-5649-27100   | SCQ5.6  | 141-2-5641-20400 | SCY3.5  | 141-2-5641-42600-A | SCY1.5  |
| 141-2-5619-01800 | FRW7.7  | 141-2-5649-09100 | SCA4.5  | 141-2-5649-27500   | SCX10.5 | 141-2-5641-20500 | SCQ10.0 | 141-2-5641-43400   | SCX4.9  |
| 141-2-5619-01900 | FRX25.0 | 141-2-5549-09200 | FRM10.2 | 141-2-5649-27600   | SCX7.4  | 141-2-5641-20600 | SCX8.6  | 141-2-5641-43900   | SCX4.9  |
| 141-2-5619-01911 | FRX25.0 | 141-2-5649-09300 | SCY10.5 | 141-2-5649-27700   | SCX4.3  | 141-2-5641-20700 | SCY7.0  | 141-2-5641-44000   | SCX5.1  |
| 141-2-5619-02000 | FRW7.7  | 141-2-5649-09400 | SCQ6.7  | 141-2-5649-27800   | SCY6.5  | 141-2-5641-21300 | SCY7.0  | 141-2-5641-44100   | SCX2.6  |
| 141-2-5619-02400 | FR8.2   | 141-2-5649-09600 | SCY5.2  | 141-2-5649-27900   | SCY2.9  | 141-2-5641-21400 | SCY7.0  | 141-2-5641-44200   | SCQ8.8  |
| 141-2-5619-02700 | FRW7.7  | 141-2-5649-09700 | SCY6.7  | 141-2-5649-28000   | SCY4.2  | 141-2-5541-21500 | SCX7.4  | 141-2-5641-44301   | SCQ6.7  |
| 141-2-5611-00300 | FRY10.7 | 141-2-5649-09800 | SCY4.4  | 141-2-5649-28100   | SCY5.0  | 141-2-5641-21600 | SCY3.2  | 141-2-5641-44500   | SCY5.7  |
| 141-2-5611-00301 | FRY10.7 | 141-2-5649-09900 | SCQ4.0  | 141-2-5649-28200   | SCX7.4  | 141-2-5641-21700 | SCY5.2  | 141-2-5641-44600   | SCQ8.8  |
| 141-2-5611-00501 | FRY8.4  | 141-2-5649-10000 | SCX9.2  | 141-2-5649-28300   | SCX5.5  | 141-2-5641-21800 | SCX10.5 | 141-2-5641-44709   | SCY4.0  |
| 141-2-5611-02702 | FRM12.1 | 141-2-5649-10100 | SCY6.0  | 141-2-5649-28500   | SCX5.5  | 141-2-5641-22000 | SCX4.9  | 141-2-5641-44600   | SCX4.3  |
| 141-2-5611-03000 | FRW10.1 | 141-2-5649-10200 | SCQ10.0 | 141-2-5649-29400   | SCX13.6 | 141-2-5641-22900 | SCY4.6  | 141-2-5641-45001   | SCA2.3  |
| 141-2-5611-03500 | FRW10.1 | 141-2-5649-10300 | SCY4.2  | 141-2-5649-29500   | SCY5.7  | 141-2-5641-23100 | SCY4.2  | 141-2-5641-45200   | SCA12.0 |
| 141-2-5611-04900 | FRX4.9  | 141-2-5649-10500 | SCX4.9  | 141-2-5649-29600   | SCQ6.7  | 141-2-5641-23400 | SCQ11.1 | 141-2-5641-45300   | SCQ8.8  |
| 141-2-5611-04001 | FRW9.7  | 141-2-5649-10600 | SCA4.5  | 141-2-5649-29700   | SCX4.9  | 141-2-5641-23700 | SCQXTO  | 141-2-5641-45400   | SCX6.2  |
| 141-2-5611-04200 | FRX25.0 | 141-2-5649-10900 | SCQ6.0  | 141-2-5649-30200   | SCY8.6  | 141-2-5641-23800 | SCY6.7  | 141-2-5641-45500   | SCY6.5  |
| 141-2-5611-04201 | FRA25.0 | 141-2-5649-11000 | SCX7.4  | 141-2-5649-30300   | SCQ4.3  | 141-2-5641-23971 | SCQ6.5  | 141-2-5641-45700   | SCX5.5  |
| 141-2-5611-04300 | FRM9.6  | 141-2-5649-11100 | SCQ5.1  | 141-2-5649-30400   | SCX5.5  | 141-2-5641-23972 | SCX7.4  | 141-2-5641-47700   | SCY3.5  |
| 141-2-5611-04500 | FRW10.1 | 141-2-5649-11200 | SCY8.0  | 141-2-5649-31000   | SCY6.0  | 141-2-5641-24100 | SCY5.2  | 141-2-6541-26700   | SCY7.4  |
| 141-2-5611-04501 | FRW10.1 | 141-2-5649-11300 | SCQ10.0 | 141-2-5649-31400   | SCQ6.5  | 141-2-5641-24200 | SCY6.7  | 141-2-6541-26800   | SCY6.0  |
| 141-2-5611-04700 | FRW8.0  | 141-2-5649-11400 | SCX4.3  | 141-2-5649-32700   | SCQ10.0 | 141-2-5641-24500 | SCYTO   | 141-2-6541-27000   | SCX5.1  |
| 141-2-5611-04800 | FRX7.5  | 141-2-5649-11700 | SCY5.2  | 141-2-5641-00100   | SCC15.7 | 141-2-5641-24800 | SCY4.6  | 141-2-6541-27100   | SCA13.2 |
| 141-2-5611-04900 | FRW9.1  | 141-2-5649-12000 | SCA6.7  | 141-2-5641-00200   | SCX9.5  | 141-2-5641-24800 | SCY7.0  | 141-2-6541-27300   | SCY9.0  |
| 141-2-5611-05000 | FRW9.1  | 141-2-5649-12300 | SCA5.4  | 141-2-5641-00501   | FRY8.4  | 141-2-5641-25200 | SCY2.2  | 141-2-6541-27400   | SCX7.0  |
| 141-2-5611-05271 | FRW8.0  | 141-2-5649-12700 | FRW10.1 | 141-2-5641-01201   | SCA13.2 | 141-2-5641-25300 | SCY5.2  | 141-2-6541-27709   | SCY5.2  |
| 141-2-5611-05272 | FRW8.8  | 141-2-5649-12800 | SCY4.4  | 141-2-5641-03300   | SCY7.0  | 141-2-5641-25500 | SCY7.0  | 141-2-6541-27800   | SCY5.2  |
| 141-2-5611-05300 | FRW8.5  | 141-2-5649-13300 | SCY4.2  | 141-2-5641-05400   | SCX4.6  | 141-2-5641-25700 | SCY7.0  | 141-2-6541-28100   | SCQ6.5  |
| 141-2-5611-05500 | FRX11.7 | 141-2-5649-13400 | SCY7.0  | 141-2-5641-06500   | SCY3.2  | 141-2-5641-25800 | SCY6.0  | 141-2-6541-25300   | SCY7.0  |
| 141-2-5611-05600 | FRX25.0 | 141-2-5649-13600 | SCQ6.0  | 141-2-5641-06502   | FRM11.5 | 141-2-5641-26000 | SCQ10.0 | 141-2-6541-28800   | SCY4.6  |
| 141-2-5611-05900 | FRW8.0  | 141-2-5649-13800 | SCY5.2  | 141-2-5641-06600   | SCX8.9  | 141-2-5641-26200 | SCQ11.1 | 141-2-6541-29100   | SCY6.0  |
| 141-2-5611-06100 | FRW9.2  | 141-2-5649-14000 | SCY2.2  | 141-2-5641-08401   | SCY4.2  | 141-2-5641-26400 | SCX9.2  | 141-2-6541-29200   | SCX5.1  |
| 141-2-5611-06300 | FRW7.1  | 141-2-5649-14100 | SCY5.2  | 141-2-5641-08700   | SCY4.4  | 141-2-5641-26500 | SCY8.6  | 141-2-6541-30000   | SCY5.0  |
| 141-2-5611-06800 | FRW8.5  | 141-2-5649-14200 | SCQ5.6  | 141-2-5641-09001   | SCX9.5  | 141-2-5641-26600 | SCY4.2  | 141-2-6541-30100   | FRW7.0  |
| 141-2-5611-07000 | FRW6.5  | 141-2-5649-14600 | SCQ10.0 | 141-2-5641-09200   | SCY8.0  | 141-2-5641-26700 | SCX7.4  | 141-2-6541-30200   | SCX4.6  |
| 141-2-5611-07500 | FRX9.5  | 141-2-5649-15000 | SCX4.9  | 141-2-5641-09200-A | SCY8.0  | 141-2-5641-26728 | SCY7.0  | 141-2-6541-30800   | SCX3.5  |
| 141-2-5611-07700 | FRW7.0  | 141-2-5649-15200 | SCY7.0  | 141-2-5641-09300   | SCX10.5 | 141-2-5641-27900 | SCQ19.0 | 1412564919800      | SCX9.2  |
| 141-2-5611-08200 | FRW7.0  | 141-2-5649-15700 | SCX7.4  | 141-2-5641-09500   | OA4.2   | 141-2-5641-28300 | SCX5.5  | 1412564925600      | SCX9.2  |
| 141-2-5611-08400 | FRW9.1  | 141-2-5649-15800 | SCY6.0  | 141-2-5641-10600   | SCX8.9  | 141-2-5641-29100 | SCY6.0  | 143-0-230V-54950   | VCR22   |
| 141-2-5629-00200 | OB5.8   | 141-2-5649-16100 | SCY3.2  | 141-2-5641-10700   | SCX8.4  | 141-2-5641-29300 | SCX8.0  | 143-0-4101-00100   | SCY4.2  |
| 141-2-5621-03100 | FRM10.5 | 141-2-5649-16200 | SCY3.5  | 141-2-5641-11000   | SCY6.7  | 141-2-5641-29501 | SCY6.3  | 143-0-4104-00100   | ST1.420 |
| 141-2-5621-03200 | OA9.4   | 141-2-5649-16300 | FRW9.0  | 141-2-5641-11100   | SCQ10.0 | 141-2-5641-29700 | SCX4.9  | 143-0-4104-00200   | ST1.420 |
| 141-2-5621-03300 | SCX3.5* | 141-2-5649-16500 | SCY5.2  | 141-2-5541-11300   | SCY2.9  | 141-2-5641-30100 | FRW7.0  | 143-0-4104-00300   | ST1.420 |
| 141-2-5621-03301 | SCX3.5  | 141-2-5649-16600 | SCY7.0  | 141-2-5641-11500   | SCY8.6  | 141-2-5641-30200 | SCX4.6  | 143-0-4204-00      | VA08    |
| 141-2-5621-03600 | OA3.8   | 141-2-5649-16700 | SCY2.9  | 141-2-5641-11600   | SCY4.2  | 141-2-5641-30500 | SCY7.0  | 143-0-4204-00100   | ST1.243 |
| 141-2-5621-03700 | SCX8.9  | 141-2-5649-16800 | SCB3.8  | 141-2-5641-11700   | SCX7.4  | 141-2-5641-30600 | SCY09.8 | 143-0-4204-00100   | VA02    |
| 141-2-564-00501  | FRY8.4  | 141-2-5649-16900 | SCQ4.8  | 141-2-5641-11800   | SCX8.0  | 141-2-5641-30700 | SCY10.5 | 143-0-4204-00300   | ST.985  |
| 141-2-5642-00100 | SCX7.4  | 141-2-5649-17000 | SCY4.2  | 141-2-5641-12100   | SCQ10.0 | 141-2-5641-30800 | SCX4.6  | 143-0-4204-00300   | VA01    |
| 141-2-5642-00200 | SCQ6.7  | 141-2-5649-17100 | SCX9.5  | 141-2-5641-12200   | SCY4.6  | 141-2-5641-31000 | SCY9.0  | 143-0-4204-00400   | ST.985  |
| 141-2-5642-00300 | SCQ4.8  | 141-2-5649-17200 | SCY6.0  | 141-2-5641-12400   | SCY2.9  | 141-2-5641-31100 | SCX9.5  | 143-0-4294-00400   | VA01    |
| 141-2-5642-00400 | SCY5.2  | 141-2-5649-17300 | SCX7.0  | 141-2-5641-12600   | SCY8.0  | 141-2-5641-31300 | SCY6.7  | 143-0-4204-00700   | ST1.130 |
| 141-2-5649-00201 | SCX8.6  | 141-2-5649-17400 | SCY3.5  | 141-2-5641-12700   | SCX4.3  | 141-2-5641-31400 | SCY7.0  | 143-0-4204-00700   | VA08    |
| 141-2-5649-00700 | SCX2.6  | 141-2-5649-17500 | SCY1.5  | 141-2-5641-12800   | SCQ10.0 | 141-2-5641-31900 | SCX4.0  | 143-0-4304-00100   | SCY4.2  |
| 141-2-5649-00800 | SCQ6.5  | 141-2-5649-17600 | SCY4.0  | 141-2-5641-13500   | SCX7.4  | 141-2-5641-32300 | SCY4.6  | 143-0-4604-00700   | VPR19   |
| 141-2-5649-0170  |         |                  |         |                    |         |                  |         |                    |         |



# SANYO/FISHER ... SHARP

| MFG. P/N         | PRB NO. | MFG. P/N             | PRB NO. | MFG. P/N        | PRB NO.  | MFG. P/N    | PRB NO.  | MFG. P/N     | PRB NO.      |
|------------------|---------|----------------------|---------|-----------------|----------|-------------|----------|--------------|--------------|
| 143-0-6611-03800 | VA106   | 147-2-5611-00300     | FRM10.5 | 614-228-3257    | SCQ4.3   | R-4470003   | SCX8.9   | 522P00201    | VA90         |
| 143-0-6621-01201 | ST.685  | 147-2-5611-00301     | FRM10.5 | 614-233-8322    | SCX5.1   | R-4470028   | SCX7.4   | 641B10102    | ST.927       |
| 143-0-6621-01201 | VA101   | 147-2-5611-00501     | FRY8.4  | 614-234-1377    | SCY7.0   | R-4470033   | SCY7.0   | 65302013     | VCR33        |
| 143-0-6621-01202 | ST.685  | 147-2-5641-00501     | FRY8.4  | 614-237-5426    | SCY5.7   | R-4470040A  | FRX25.0  | 653020B      | VCR33        |
| 143-0-6621-01202 | VA101   | 147-2-5641-00600     | SCX12.2 | 614-247-9209    | SCQ6.0   | R-4470053   | SCX4.3   | 70114347     | FRX21        |
| 143-0-6621-10340 | ST.685  | 147-2-5641-00800     | SCQ6.5  | 614-253-2539    | SCX9.5   | R-4470054   | SCX4.3   | 70115406     | VCR33        |
| 143-0-6621-10340 | VA06    | 147-2-5641-02100     | 0A5.8   | 614-253-2546    | SCX10.5  | R-4470055   | SCX6.2   | 70323310     | VPR20        |
| 143-0-6621-10350 | ST.685  | 147-2-5641-03400     | SCX4.3  | 614-955-087     | SCY4.2   | R-4470057A  | SCX15.2  | 70326530     | ST1.211      |
| 143-0-6621-10350 | VA103   | 147-2-5641-06600     | SCA8.9  | 620-128-3839-R  | SCY6.5   | R-4470091A  | SCX9.5   | 70326530     | VA30         |
| 143-0-6621-14370 | ST1.208 | 147-2-5641-08700     | SCX5.1  | 620-128-6250    | SCX7.0   | R-4470093   | SCY6.5   | 70326538     | ST1:211      |
| 143-0-662T-14730 | ST1.208 | 147-2-5641-09001     | SCX8.9  | 620-128-6526    | SCY8.6   | R-4470210   | SCA8.9   | 70326538     | VA30         |
| 143-0-6621-14730 | VA105   | 147-2-5641-09300     | SCX10.7 | 620-128-6724    | SCY8.2   | R-447021 0A | SCA8.9   | 70326575     | ST1.211      |
| 143-0-6621-15620 | ST1.118 | 147-2-5641-10600     | SCQ10.0 | 620-128-6755    | SCY9.2   | R-4470245   | SCX8.0   | 70326575     | VA30         |
| 143-0-662T-15620 | VA100   | 147-2-5641-11100     | SCX10.7 | 620-128-6762    | SCX11.8  | R-4470245A  | SCQ 10.0 | 70342123     | SCQ3.6       |
| 143-0-6621-15621 | ST1.118 | 147-2-5641-11700     | SCX8.0  | 620-128-6786    | SCY9.0   | R-4470246   | SCQ6.7   | 850A200004   | VA501        |
| 143-0-6621-15621 | VA104   | 147-2-5641-11800     | SCQ10.0 | 620-128-6823    | SCQ5.6   | R-4470325   | SCY2.2   | 850A200005   | VA551        |
| 143-0-662T-14730 | ST1.208 | 147-2-5641-12200     | SCX4.3  | 620-185-4718    | SCY6.3   | R-4470397   | SCX8.6   | 850A400018   | VPR16        |
| 143-0-7411-20001 | ST.685  | 147-2-5641-12700     | SCX4.3  | 620-185-8020    | SCX7.0   | R-4470399   | SCQ8.2   | 850A400041   | VPR16        |
| 143-0-7411-20001 | VA07    | 147-2-5641-12800     | SCQ10.0 | 620-185-8143    | SCY4.2   | R-4470399D  | SCQ8.2   | 850A800005   | VA551        |
| 143-0-741T-2001  | VA07    | 147-2-5641-13800     | SCX4.3  | 620-187-8141    | SCY7.0   | R-4470412   | SCX16.0  | 850P600022   | FRW9.7       |
| 143-0-7504-00400 | SCA8.9  | 147-2-5641-14125-002 |         | 620-197-7646    | SCY4.0   | R-4470543A  | FRW7.1   | 850P600124   | SCB8.4       |
| 143-0-7504-00900 | SCB8.4  |                      |         | 620-199-7873    | SCY7.3   | R-4470565   | FRW7.1   | 850P600125   | SCB2.5       |
| 143-2-4204-00    | ST1.130 | 147-2-5641-19300     | SCX10.7 | 620-205-9068    | SCY5.7   | R-4470685   | SCY6.7   | 850P700023   | SCX4.9       |
| 143-2-5641-03200 | SCA2.3  | 147-2-5641-90800     | SCQ6.5  | 620-205-9594    | SCY9.2   | R-4470708   | SCX8.0   | 880601       | SCX4.2       |
| 143-2-560T-01000 | SCA8.9  | 151-02-27            | FRW7.0  | 620-212-2632    | SCQ6.0   | R-4470725   | SCX14.7  | 928829101    | VCR9 & VCR33 |
| 143-2-5611-01701 | FRY19.6 | 151-07-02            | FRM11.0 | 620-212-2649    | SCX8.9   | R-4470729   | SCY4.6   |              | VCR9 & VCR33 |
| 143-2-5621-01700 | SCX7.0  | 1710-06-03           | SCX4.6  | 620-212-2656    | SCY6.6   | R-4470737   | SCY8.0   | 9288291010   | VCR9 & VCR33 |
| 143-2-562T-01802 | FRX35.1 | 174-10-11            | SCQ10.0 | 620-212-26632   | SCQ6.0   | R-44707768  | SCQ8.2   |              | VCR33        |
| 143-2-562T-02300 | SCA3.2  | 189-10-03            | SCY6.0  | 621-000-5781    | VCR33    | R-4470787   | SCY7.8   | ASIG070      | SCQ4.0       |
| 143-2-5621-02400 | SCY5.2  | 1AC4F2AU000070       | V769    | 621-000-5880    | VCR22    | R-4470808   | SCY6.7   | NSPFP30611   | SCY7.0       |
| 143-2-5621-03200 | SCA2.3  | 297-13-01            | SCQ6.0  | 621-000-5897    | VCR22    | R-4470833   | SCY6.5   | NSPF P30711  | SCX3.5       |
| 143-2-5621-03300 | SCA3.2  | 300066               | FRX10.5 | 624-12-01       | SCX9.5   | R-4470912   | SCX4.9   |              |              |
| 143-2-5621-03400 | SCA3.2  | 333-09-02            | FRW10.7 | 632-227-8677    | SCX7.4   | R-4470987   | SCY6.0   |              |              |
| 143-2-5621-03700 | SCA3.0  | 393-12-02            | SCQ5.6  | 632-228-11585   | SCY5.7   | R-4471046   | SCX15.5  |              |              |
| 143-2-5641-00100 | SCC15.7 | 4-1164-01160         | V766    | 632-228-1509    | SCX9.5   | R-4471059   | SCQ8.0   | 0032820010   | STt350       |
| 143-2-5641-01000 | SCX8.9  | 4-1164-031600        | V756    | 632-231-2623    | SCX8.9   | R-4471150   | SCX4.6   | 03E139       | MAMA         |
| 143-2-5641-01201 | SCA13.2 | 4-1164-031610        | V756    | 632-504-7607    | SCX15.5  | R-4471151   | SCX10.7  | 07A008402    | SCX8.6       |
| 143-2-5641-02300 | SCA3.2  | 4-1164-031611        | V756    | 632-504-7614    | SCX15.2  | R-447139    | SCX4.3   | 205230       | SCX4.3       |
| 143-2-5641-02302 | SCA3.2  | 4-1164-03162         | V756    | 632-517-0763    | SCQ3.0   | R-447773    | SCQ10.0  | 205355       | SCX8.9       |
| 143-2-5641-02400 | SCY5.0  | 4-1164-031620        | V756    | 632-536-9228    | SCX15.0  | R-447853    | SCQ10.0  | 205357       | FRX21.6      |
| 143-2-5641-02500 | SCB4.2  | 4-1164-131600        | V763    | 632-554-7398    | SCQ3.0   | R-447857    | FRM10.5  | 205359       | SCX8.6       |
| 143-2-5641-02600 | SCA4.5  | 4-1164-21160         | V762    | 632-594-1349    | SCY2.2   | R-447920    | SCX7.4   | 205385       | FR0112       |
| 143-2-5641-02800 | SCY6.5  | 4-1164-23160         | V762    | 766-76-11       | SCX7.0   | R-447930    | SCX7.4   | 205386       | SCX8.6       |
| 143-2-5641-03200 | SCA2.3  | 4-1164-231600        | V762    | 889-12-02       | SCX8.9   | R-447932    | SCX7.0   | 205390       | SCQ5.5       |
| 143-2-5641-03300 | SCA3.2  | 4-1164-25160         | V771    | 947-09-03       | FRM9.7   | R-447933    | SCX4.6   | 205409       | SCX1a5       |
| 143-2-5641-03400 | SCA3.2  | 4-202V-15200         | VCR7    | 973-12-01       | FRW10.1  | TP4067-010  | SCQ4.0   | 205411       | SCX8.6       |
| 143-2-5641-03600 | SCA4.0  | 401403990            | VCR22   | ATN-10851204B   | SCX4.0   |             | FRM11.2  | 205412       | 0X5.9        |
| 143-2-5641-03700 | SCA3.0  | 407-016-7205         | VCR33   | ATN-1240-09-058 | FRW7.1   |             | FRM10.2  | 205414       | SC8.6        |
| 143-2-5641-04    | SCB11.6 | 407-098-3201         | VCR22   | ATN-1523-18-01  | SCY5.2   | VHR-0500    | VPR24    | 205415       | SCY8.6       |
| 143-2-5641-04001 | SCQ2.5  | 42B41045C01          | FRM11.2 | ATN-15590901B   | FRX9.7   | VT-u2900    | SCX5.5   | 206231       | SCQ10.0      |
| 143-2-5641-04200 | SCQ5.7  | 547-16-02            | SCX7.4  | ATN-17001027    | SCX9.2   | VT-u4720    | SCX4.3   | 206351       | SCX5.1       |
| 143-2-5641-04300 | SCC12.6 | 561-09-02            | FRW10.7 | ATN-1710-06-03  | SCX4.6   | VT-u5550    | FRZ12.1  | 206357       | SCX5.1       |
| 143-2-5641-04700 | SCA5.4  | 613-022-0158         | VPR24   | ATN-1715-06-06  | SCY5.2   | VT-u5571    | FRX13.1  | 206386       | SCX7.4       |
| 143-2-5641-04800 | SCB11.6 | 613-022-2534         | VA761   | ATN-1715-06-06  | SCY5.2   | VT-u5710    | FRM7.5   | 206390       | SCX7.0       |
| 143-2-5641-04900 | SCA3.5  | 613-022-2978         | SCA6.7  | ATN-17200905    | SCX5.5   |             |          | 206409       | SCX10.5      |
| 143-2-5641-05001 | SCB8.2  | 613-022-2985         | SCA3.0  | ATN-18001007    | SCX7.4   |             |          | 206409       | SCX15.5      |
| 143-2-5641-05100 | SC B2.8 | 613-037-4752         | ST.685  | ATN-18001009    | SCX9.5   | 000010020   | VCR20    | 207221       | SCC15/       |
| 143-2-5641-05300 | SCA7.5  | 613-037-4752         | VA07    | ATN-1820-08-09  | SCY4.6   | 0002G00010  | VCR7     | 207386       | SCX8.9       |
| 143-2-7504-00    | SCB8.4  | 613-037-4875         | ST1.208 | ATN-1820-13-03  | FRZ7.5   | 0002G00020  | VCR9     | 208386       | SCY3.5       |
| 143-2-7504-00100 | SCA7.5  | 613-037-4875         | VA105   | ATN-18200809    | SCX4.6   | 0150100001  | V763     | 211232       | SCX8.6       |
| 143-2-7504-00101 | SCA7.5  | 613-054-6391         | SCA7.5  | ATN-18200809C   | SCX4.6   | 0150100006  | V763     | 216357       | ST.536       |
| 143-2-7504-00200 | SCX4.6  | 613-077-3586         | VA759   | ATN-18201303    | FRW7.0   | 0150100007  | V758     | 217230       | 0A7.0        |
| 143-2-7504-00201 | SCX4.6  | 613-083-7110         | V769    | ATN-18201320    | SCQ8.0   | 0150100007  | V760     | 219230       | ST.536       |
| 143-2-7504-00300 | SCA4.2  | 613-093-4031         | SCA6.1  | ATN-18211240    | SCY7.5   | 0150700002  | V760     | 219357       | ST.536       |
| 143-2-7504-00400 | SCA8.9  | 613-093-7667         | V769    | ATN-182112142   | SCX9.5   | 01740002    | SCQ6.0   | 21V7021      | FRW10.7      |
| 143-2-7504-00500 | SCA8.1  | 613-096-0177         | V769    | ATN-182112173   | SCY5.7   | 18210705    | SCY4.2   | 21V7034      | SCQ10.0      |
| 143-2-7504-00600 | SCA8.9  | 613-097-8981         | VPR24   | ATN-18211222    | SCX7.0   | 18211211    | SCX5.5   | 21V7044      | FRX9.7       |
| 143-2-7504-00700 | SCA4.2  | 613-097-8998         | VA104   | BK1             | VKT159** | 182112142   | SCY5.7   | 21V7047      | SCX9.5       |
| 143-2-7504-00800 | SCA5.4  | 613-097-9018         | SCA3.5  | BK2             | VKT147** | 182112161   | SCX5.5   | 21V7048      | SCY4.2       |
| 143-2-7504-00900 | SCB8.4  | 613-097-9025         | SCB8.2  | BK3             | VKT162** | 182112173   | SCY7.0   | 4081203      | SCX9.5       |
| 143-2-7504-00900 | SCB8.4  | 613-112-7876         | V769    | BK4             | VKT163** | 18211221    | SCX7.0   | 40A139       | FRW8.5       |
| 143-2-7504-01    | SCA3.0  | 613-2985             | SCA3.0  | BK6             | VKT163** | 19210703    | SCY4.2   | 42B41045C01  | FR01t2       |
| 143-2-7504-01000 | SCA4.2  | 613-4875             | VA105   | BK7             | VKT164** | 21611       | SCX5.5   | 5610902      | FRYm4        |
| 143-2-7504-01100 | SCA3.0  | 614-133-3427         | SCX6.2  | FB6+368144400   | FRW6.5   | 434037D     | VPR16    | 7470001      | SCQ6.0       |
| 143-2-7504-01300 | SCB8.4  | 614-133-4127         | SCX7.0  | GEC-008C18      | FRM11.2  | 452030A     | SCA8.9   | 90AVDV0154   | SCA4.5       |
| 143-9-4300-57500 | V755    | 614-133-4165         | SCY3.5  | GEC-MD4003      | SCY4.0   | 511392A     | VCR6     | 90AVDV0155   | SCB8.1       |
| 143-9-4300-57501 | V755    | 614-195-5087         | SCY4.2  | GEC-MD4004      | SCQ6.0   | 511393A     | VCR6     | 91RPEB14031  | FRX9.0       |
| 143-9-4300-6800  | V755    | 614-196-2924         | SCX9.2  | LN59            | SCY4.2   | 521004001   | SCA8.9   | 91RPEB14032  | SCX3.5       |
| 143-9-5100-40900 | VPR4    | 614-204-4681         | SCY6.0  | M2022AB         | V769     | 521004601   | SCA7.1   | 91 RPBE14033 | SCX5.1       |
| 1432750400700    | SCA4.5  | 614-204-8740         | SCY4.2  | MAT-E-0266      | SCX8.9   | 521004901   | SCB3.8   | 9115610902   | FR110.4      |
| 147-2-5002-00    | SCX8.9  | 614-205-5373         | SCX5.5  | MD4010          | SCX8.9   | 521005001   | FRM10.5  | 91U10022500  | SCY9.0       |
| 147-2-5003-00    | FRY10.7 | 614-207-4619         | SCQ2.5  | 0-4014-04000    | VCR22    | 521D05301   | SCX7.0   | 91U21V7021   | FRV10.7      |
| 147-2-5003-01    | FRY10.7 | 614-211-4742         | SCQ8.8  | PN150SAN        | VCR22    | 5221301701  | ST.850   | 91U21V7034   | SCQ10.0      |
| 147-2-5115-01    | FRW8.5  | 614-212-9562         | SCY4.2  | OF-01253        | VCR22    | 522B01701   | VA96     | 92LBELT025   | SCX9.2       |
| 147-2-5611-00200 | 0A5.8   | 614-219-9961         | SCX9.5  | R-4470001       | VCR22    | 522B01801   | VA97     | 92LBELT128A  | SCQ6.5       |
|                  |         |                      |         | R-4470002       | SCX4.0   | 522CO5503   | VPR3     | 92LBELT152A  | SCX8.9       |
|                  |         |                      |         |                 |          | 522P00201   | ST.599   | 92LBELT1589A | SC05/        |

\* = Replacement Belt

= Kit May Not Include Tires

= Part of the Assy

# SHARP ... SONY

| MFG. P/N        | PRB NO.  | MFG. P/N       | PRB NO.   | MFG. P/N       | PRB NO.  | MFG. P/N        | PRB NO. | MFG. P/N      | PRB NO. |
|-----------------|----------|----------------|-----------|----------------|----------|-----------------|---------|---------------|---------|
| 92LBELT15896    | SCQ4.8   | NBLTH0054AFZZ  | FRX9.4    | NBLTK0060GE00  | SCA3.5   | NBLIK0272AFZZ   | SCY6.0  | 62080591506   | SCA6.7  |
| 92LBELT1746A    | SqQ4.3   | NBLTH0057AFZZ  | FRM11.0   | NBLTK0062GE00  | SC83.6   | NBLTK0277AFZZ   | SCX9.5  | 92080590710   | FRX11.5 |
| 92LMBELT1651 B  | SCX4.9   | NBLTH0058AFZZ  | FRM9.6    | NBLIK0065GE00  | SCA13.2  | NBLTK0279AFZZ   | SCY6.7  | <b>SHURE</b>  |         |
| 92LMBELT1658A   | SCX9.0   | NBLTH0061AFZZ  | FRW10.1   | NBLTK0081AFZZ  | FRM7.0   | NBLIK0286AFZZ   | SCX14.7 | 205222        | SCX8.6  |
| 92LMBELT1658B   | SCX6.2   | NBLTH0063AFZZ  | FRW10.1   | NBLTK0083AFZZ  | FRW8.5   | NBLTK0287AFZZ   | SCX8.6  | 205230        | SCX2.6  |
| 92LMBLET1676B   | SQX9.2   | NBLTH0064AF00  | FRW10.1   | NBLTK0101AFZZ  | SCY8.6   | NB LTK0290AF00  | SCX4.3  | 205325        | SCX10.7 |
| 92LXXHP37045    | FRX20.7  | NialTH0065AFZZ | FRW10.1   | NBLTK0103AFZZ  | SCX7.0   | NB LTK0352AF00  | SCX6.2  | 205355        | SCX8.6  |
| 935378          | SCX2.4   | NBLTH0066AFZZ  | FRW8.5    | NBLTK0104AFZZ  | SCY5.2   | NBLIK0392AFZZ   | SCX6.2  | 205356        | SCX8.6  |
| 93T2780050190   | SCX8.4   | NBLTH0067AFZZ  | FRY10.0   | NBLTK0105AFZZ  | SCX7.4   | NBLIK0393AFZZ   | SCQ5.1  | 205357        | 0A8.2   |
| 94CR001 001     | SCY6.0   | NBLTH0069AFZZ  | FRX12.7   | NBLTK0106AFZZ  | SCX8.0   | NBLTK0479AFZZ   | SCA4.0  | 205359        | FRX21.6 |
| 94CR002001      | SCY1.5   | NBLTH0070AFZZ  | FRY10.0   | NialTK0107AFZZ | SCX8.4   | NBLTK0481AFZZ   | SCX7.4  | 205385        | SCX8.6  |
| 94CR003001      | SCY1.5   | NBLTK0071AFZZ  | FRM8.0    | NBLTK0111AFZZ  | SCY7.0   | NBLTK0487AFZZ   | SCQ3.2  | 205386        | FRM11.2 |
| 94FH3141B1025   | SCQ6.0   | NBLTH0073AFZZ  | FRX6.7    | NBLTK0112AFZZ  | SCX14.7  | NaLTK0488AFZZ   | SCY6.0  | 205390        | SCA8.9  |
| 94FH316011090   | SCY5.2   | NBLTH0075AFZZ  | FRX9.0    | NBLIK0113AFZZ  | SCX8.9   | NBLTK0496AFZZ   | SCY5.2  | 205399        | SCQ6.5  |
| 94FH316011114   | SCX8.9   | NBLTK0076AFJJ  | FRX11.5   | NBLTK0116AFZZ  | SCX2.6   | NBLTK0497AFZZ   | SCY4.6  | 205409        | SCQ5.6  |
| 94FH319051001   | SCQ10.0  | NBLTH0076AFZZ  | FRX11.5   | NBLTK0117AFZZ  | SCX7.4   | NBLTK0498AFZZ   | SQA5.4  | 205411        | SCA8.9  |
| 94FH319051044   | SCY5.2   | NBLTH0080AF00  | FRX25.0   | NBLTK0121AFZZ  | SCQ8.2   | NBLTK0499AFZZ   | SCA4.5  | 205412        | 0A6.1   |
| 94FH319051106   | SCQ10.0  | NBLTK0082AF00  | FRW10.1   | NBLTK0123AFZZ  | SCY5.0   | NBLTK0502AFZZ   | SCQ4.6  | 205414        | SCY8.6  |
| 94FH31T36011Q7  | SCY5.0   | NBLTH0084AFZZ  | FRX11.7   | NBLTK0i 24AFZZ | SCX9.2   | NBLTK0505AFZZ   | SCA4.5  | 206230        | SCX8.9  |
| 94FH3113601108  | SCY2.9   | NBLTH0085AFZZ  | FRW9.1    | NBLTK0125AFZZ  | SCQ5.6   | NBLTK0509AFZZ   | SCY8.6  | 206231        | SCQ10.0 |
| 94R17200905     | SCX5.5   | NBLTK0088AF00  | FRW10.1   | NBLTK0i 26AFZZ | SCX8.9   | NBLTK0512AFZZ   | SOQ10.0 | 206325        | SCX10.7 |
| 94R18001010     | SCX9.2   | NBLTH0089AFZZ  | FR23.6    | NBLIK0127AFZZ  | SCX7.4   | NBLTK0514AFZZ   | SCQ6.0  | 206326        | SCX4.6  |
| 94R18001012     | SCQ7.2   | NBLTK0091AFZZ  | FRM12.7   | NBLTK0128AFZZ  | SCQ6.0   | NBLTKM0006GE00  | SCX4.9* | 206328        | SCX8.0  |
| 94R18210703     | SCX4.0   | NBLTH0093AF00  | FR20.0    | NBLIK0130AFZZ  | SCX4.6   | NBLTKM0008AG00  | 0A10.1  | 206351        | SCX5.1  |
| 94R18210705     | SCY4.2   | NBLTH0103AFZZ  | FRY6.7    | NBLTK0133AFZZ  | SCX8.6   | NBLTKM001QG E00 | SCX7.0* | 206355        | SCY9.2  |
| 94R182112141    | SCY5.7   | NBLTH0110AFZZ  | FRW9.6    | NBLTK0134AFZZ  | SCY5.0   | NBLTKM0015GE00  | 0X5.9   | 206357        | SCX5.1  |
| 94R182112142    | SCX9.5   | NBLTH0114AFZZ  | FRW7.7    | NBLTK0135AFZZ  | SCX8.9   | NBLTKM0020A000  | SCX10.5 | 206386        | SCX8.0  |
| 94R18211221     | SCX7.0   | NBLTHG22       | 0A10.1-   | NBLTK0136AFZZ  | SCX8.0   | NBLTKM0029AG00  | SCY6.0  | 206390        | SCX7.0  |
| 94R18211222     | SCX7.0   | NB LTK0001AWZZ | SCQ5.3    | NBLTK0139AFZZ  | SCX10.7  | NBLTKM0031AG00  | SCX7.0  | 206409        | 0A10.9  |
| 94R18650712     | SCY5.7   | NBLIK0001GE00  | SQC12.1   | NBLTK0140AFZZ  | SCQ8.2   | NBLTKM0037AG00  | SQX10.7 | 207221        | 0A10.9  |
| 94R18650985     | SCX9.2   | NBLTK0002AFZZ  | 0A10.9    | NBLTK0141AFZZ  | SCQ6.7   | NBLTKM0050AF00  | SCX7.0  | 207386        | 0A9.0   |
| 94R18651124     | SCX4.0   | NBLTK0002AGZZ  | 0A10.9    | NBLTK0142AFZZ  | SCX9.2   | NIDL0005GEZZ    | ST1.350 | 211232        | SCX8.6  |
| 94R18800708     | SCQ5.6   | NBLTK0002AWZZ  | SCQ2.2    | NBLTK0143AFZZ  | SCQ6.7   | NIDL0005GEZZ    | VA60    | 217230        | 0A7.0   |
| 94R18800942     | SCQ10.0  | NBLTK0003AWZZ  | SCQ5.1    | NBLTK0144AFZZ  | SCX8.0   | NIDL0006GEZZ    | ST1.211 | 219230        | ST.536  |
| 94R18800952     | SQ111.1  | NB LTK0004AWZZ | SCY4.0    | NBLTK0145AFZZ  | SCX5.1   | NIDL0006GEZZ    | VA61    | 232023        | SCA8.9  |
| 94R18808152     | SCQ11.1  | NBLIK0004GE00  | SCB14.0   | NBLIK0148AFZZ  | SCY8.6   | NPAIR0117AFSA   | \$T.999 | <b>SINGER</b> |         |
| 94R19210703     | SOY4.2   | NBLIK0005GE00  | SC10.5    | NBLIK0149AFZZ  | SCX1 1.8 | NPLYV0051 GEZZ  | ST1.46  | 33400P14      | 0A6.1   |
| 94R19210904     | SCY5.0   | NBLTK0006GE00  | SCB8.4    | NBLTK0150AFZZ  | SCX7.4   | NPLYV0103GEZZ   | ST1.016 | 33400P19      | 0.411.7 |
| 94R19210924     | SCX7.0   | NB LTK0007AWZZ | SCQ6.7    | NBLTK0151AFZZ  | SCX5.1   | NPLYVoi 03GEZZ  | VA67    | 42090P48      | SCX8.6  |
| 94R82112173     | SCY5.7   | NialTK0008GE00 | SC Bi 0.5 | NBLTK0152AFZZ  | SCX8.4   | NPLYV0107GEZZ   | ST1.016 | 42090P49      | SCX2.6  |
| 94R18501314     | SCY4.2   | NBLTK0009AWZZ  | SCX4.6    | NBLIK0153AFZZ  | SCQ5.6   | NPLYV0107GEZZ   | VA63    | 42901 P1      | OSCT.3  |
| 94R18502206     | SCY5.2   | NBLTK0009GE00  | SCB3.2    | NBLTK0154AFZZ  | SCX7.4   | NPLYV0111 GEZZ  | ST1.016 | 43332P1       | 061.2   |
| 95Y100900       | SCY3.2   | NBLIK0010AWZZ  | SCQ6.0    | NaLTK0155AFZZ  | SCX9.5   | NPLYV0111GEZZ   | VA63    | 43892P1       | 085.2   |
| 95Y100910       | SCX4.6   | NBLTK0010GE00  | SCX5.1    | NBLIK0156AFZZ  | SCQ6.5   | NPLYVoi 2GEZZ   | ST1.016 | 43893P1       | 0810.9  |
| 960G001         | SCX8.9   | NBLIK0011GE00  | SCX4.0    | NBLTK0i 57AFZZ | SCQ6.7   | NPLYV0112GEZZ   | VA63    | V021103001    | SCX8.4  |
| 97M360200201D   | FR20.0   | NBLTK0013GE00  | SCX2.6    | NBLTK0166AFZZ  | SCY6.5   | NROL0005GEZZ    | VPR9    | V021703001    | SCX10.7 |
| 97MXX18001007   | SCX7.4   | NBLTK00140E00  | SCB8.1    | NBLTK0167AFZZ  | SCQ4.0   | NROL0009GEZZ    | VPR17   | V063013005    | SCX8.9  |
| 99LPP40070      | FR21.5   | NBLTK0015GE00  | SCB14.0   | NBLIK0168AF00  | SCQ5.6   | NROL0013GEZZ    | VPR16   | <b>SONY</b>   |         |
| BELT3543A       | SCX8.6   | NBLTK0020GE00  | SCB2.5    | NBLTK0174AFZZ  | SCX7.4   | NROLR0005GEZZ   | VPR9    | 0-037-205     | 0A7.0   |
| 8ELT3737A       | SCQ6.7   | NBLIK0021GE00  | SCY5.2    | NBLTK0 76AFZZ  | SCX2.4   | NROLR0007GEZZ   | VPR8    | 0-051-094     | 009.8   |
| 8ELT3737B       | 0X5.9    | NBLTK0022GE00  | SCX7.0    | NBLTK0177AFZZ  | SCX8.4   | NROLR0009GEZZ   | VPR16   | 2-101-131-00  | SCY5.2  |
| BELT3863A       | SCX8.6   | NBLTK0023GE00  | SCY5.0    | NBLTK0i 78AFZZ | SCX7.0   | NROLR0013GEZZ   | VPR17   | 2-101-264-00  | SCY4.6  |
| BELT3863B       | SCX7.4   | NBLTK0024GE00  | SCY7.5    | NBLIK0181AFZZ  | SCY8.0   | PHPX0099GEZZ    | VCR33   | 2-258-093     | SCX2.4  |
| BELT3863C       | SCX8.9   | NBLTK0025GE00  | SCX2.6    | NBLTK0i 82AFZZ | SCX8.9   | RCNVR0006GEZZ   | V770    | 2-258-127     | 0A4.2   |
| BELT38630       | SCY3.5   | NBLIK0026AG00  | SCX8.6    | NBLTK0183AFZZ  | SCX7.0   | RCNVR0035GEZZ   | V771    | 2-297-000     | SCY7.0  |
| FK05377         | F R V\C7 | NBLIK00260E00  | SCB2.8    | NBLTK0184AFZZ  | SCQ6.0   | RH-PX0233GEZZ   | VCR26   | 3-007-625     | 0013.2  |
| FTGBR001        | FRQ11.2  | NBLTK0027GE00  | SCQ6.5    | NBLTK0185AFZZ  | SCY6.5   | RHPX0042GEZZ    | VCR7    | 3-031-205     | 0A7.4   |
| MELVCO038GEZZ   | VPR26    | NBLTK0028GE00  | SCY3.2    | NBLTK0188AFZZ  | SCY4.6   | RHPX0090GE02    | VCR12   | 3-050-247     | 0A10.1  |
| MLEVF0085GEZZ   | VPR9     | NBLTK0029GE00  | SQX1.9    | NBLTK0192AFZZ  | SCX8.9   | RHPX0099GEZZ    | VCR33   | 3-056-247     | 0611.7  |
| MLEVF0281GEZZ   | VPR26    | NBLTK0030GE00  | SCY6.0    | NBLTK0194AFZZ  | SCX7.4   | RHPX0153GEZZ    | VCR24   | 3-077-625     | 0013.2  |
| MLEVF0416GEZZ   | VPR26    | NBLTK0031GE00  | SCX3.5    | NBLTK0195AFZZ  | SCY5.2   | RHPX0176GEZZ    | VCR26   | 3-103-050-00  | 0A10.1  |
| MLEVF0416GEZZ   | VPR26    | NBLTK0032GE00  | SCQ6.0    | NBLIK0200AFZZ  | SCX7.4   | RHPX0180GEZZ    | VCR33   | 3-103-090-00  | CA10.9  |
| MLEVF0416GEZZ   | VPR26    | NBLIK0033GE00  | SCX4.6    | NBLIK0201AFZZ  | SCX8.4   | RHPX0181GEZZ    | VCR9    | 3-103-103-00  | FR15.9  |
| NBLEK0003AWZZ   | SCQ5.1   | NBLTK0035GE00  | SCX4.9    | NBLTK0202AFZZ  | SCX8.0   | RLMPM0008GEZZ   | VCR40   | 3-103-205-00  | 0A7.4   |
| NBLTH0005AGZZ   | FRM11.0  | NBLTK0038GE00  | SCA10.5   | NBLIK0203AF00  | SCQ4.0   | RTUNE0149GEZZ   | V759    | 3-128-115-00  | FR25.0  |
| NBLTH0007AGZZ   | FRW8.5   | NBLTK0039GE00  | SCA3.5    | NBLTK0204AFZZ  | SCX5.1   | RTUNE0188GEZZ   | V759    | 3-140-043-00  | FR15.9  |
| NBLTH0007GE00   | FRM12.1  | NBLIK0040AG00  | SQX7.0    | NBLTK0205AFZZ  | SCQ6.0   | RTUNE0216GEZZ   | V759    | 3-140-050-00  | FR15.9  |
| NBLTH0008GE00   | FRW9.7   | NBLIK0041AG00  | SCQ6.7    | NBLTK0207AFZZ  | SCX9.5   | RTUNE0301GEZZ   | V759    | 3-140-520     | SCY7.0  |
| NBLTH0010GE00   | FRW9.7   | NBLTK0041GE00  | SCQ6.0    | NBLTK0208AFZZ  | SCX5.1   | SRGBO07N02      | SCQ3.6  | 3-143-124-00  | SCY7.3  |
| NBLTH00120E00   | FRW9.7   | NBLTK0042AG00  | 0X5.9     | NBLTK0209AFZZ  | SCX3.5   | <b>SHERWOOD</b> |         |               |         |
| NBLTH0014GE00   | FRY10.4  | NBLTK0044GE00  | SCX4.9    | NBLIK0210AF00  | SCX6.2   | 5708908000      | SCX9.2  | 3-143-124-99  | FR15.9  |
| NBLTH0015GE00   | FRM14.0  | NBLTK0045AFZZ  | SCX10.5   | NBLIK0211AFZZ  | SCQ6.7   | D144E13         | SCX15.2 | 3-145-124-99  | SCY7.0  |
| NBLTH0017GE00   | FRM14.0  | NBLTK0045GE00  | SCA10.5   | NELTK0213AFZZ  | SCX7.0   | <b>SHINTOM</b>  |         |               |         |
| NBLTH0022GE00   | FRW9.7   | NBLTK0046GE00  | SCA8.6    | NBLTK0214AFZZ  | SCX5.1   | 62080000922     | VPR4    | 3-303-122-00  | SCQ5.6  |
| N (3LTH0028GE00 | FRW9.7   | NBLTK0047GE00  | SCQ2.5    | NBLTK0215AFZZ  | SCX5.1   | 62080001526     | FRQ11.2 | 3-305-524-00  | SCX5.5  |
| NBLTH0029GE00   | FRY10.7  | NBLTK0048AG00  | SCX8.6    | NBLTK0216AFZZ  | SCX5.1   | 62080001607     | FRM8.0  | 3-305-524-01  | SCY5.2  |
| NBLTH0029GEZZ   | FRY10.7  | NBLTK0048GE00  | SCB8.4    | NBLTK0217AFZZ  | SCY4.6   | 62080001608     | SCA10.0 | 3-306-008-00  | SCY2.2  |
| NBLTH0034GE00   | FRW9.7   | NBLTK0049AG00  | FRM11.2   | NBLTK0224AFZZ  | SCY8.2   | 62D60002139     | FR3.6   | 3-306-366-00  | SCX4.6  |
| NBLTH0038GE00   | FRW9.2   | NBLTK0050AG00  | SCX7.4    | NBLTK0226AFZZ  | SCY5.2   | 62080002264     | SCB2.5  | 3-306-803-00  | SCY5.0  |
| NBLTH0039GE00   | FR9.4    | NBLTK0053AF00  | SCX7.0    | NBLTK0235AF00  | SCX3.2   | 62080590710     | FRM11.5 | 3-306-803-11  | SCY5.2  |
| NBLTH0040GE00   | FRW10.7  | NBLTK0053GE00  | SCQ4.0    | NBLTK0238AFZZ  | SCY5.2   | 62080590917     | SCA14.1 | 3-306-815-00  | SCY4.4  |
| NBLTH0042GE00   | FRW7.1   | NBLTK0054GE00  | SCX1.9    | NBLTK0247AFZZ  | SCX3.2   | 62080591103     | SCA7.5  | 3-307-366-00  | SCX4.6  |
| NBLTH0050AFZZ   | FRW10.1  | NBLIK0055GE00  | SCA8.6    | NBLTK0248AFZZ  | SCQ10.0  | 62080591106     | SCA7.5  |               |         |
| NBLTH0051AF00   | FRW10.1  | NBLTK0058GE00  | SCQ3.2    | NBLTK0263AFZZ  | SCY6.5   |                 |         |               |         |
| NBLTH0052AF00   | FRM11.7  | NBLTK0059G Eoo | SCA8.6    | NBLTK0270AFZZ  | SCX8.0   |                 |         |               |         |

^ = Part of the Assy

\* = Kit May Not Include Tires

= Part of the Assy

# SONY ... SONY

| MFG. P/N     | PRB NO. | MFG. P/N     | PRB NO. | MFG. P/N     | PRB NO. | MFG. P/N     | PRB NO. | MFG. P/N      | PRB NO. |
|--------------|---------|--------------|---------|--------------|---------|--------------|---------|---------------|---------|
| 3-307-483-00 | FRW8.5  | 3-412-264-02 | SCQ6.7  | 3-513-060    | SCY3.5  | 3-548-876-00 | SCQ10.0 | 3-583-515     | FR4.2   |
| 3-307-919-00 | SCY11.7 | 3-412-264-03 | SCX2.6  | 3-513-061    | SCY3.5  | 3-549-739    | SCA8.9  | 3-583-530     | SCX8.9  |
| 3-308-460-00 | SCY6.7  | 3-412-264-04 | SCX3.5  | 3-513-062    | SCX8.6  | 3-549-778    | FRM11.0 | 3-584-029     | SCQ10.0 |
| 3-311-808-0  | SCY3.5  | 3-418-208-00 | OSC10.2 | 3-513-066    | SCX4.9  | 3-551-006    | FRQ11.2 | 3-585-874     | SCX8.9  |
| 3-311-808-00 | SCY3.5  | 3-422-094-00 | OA7.4   | 3-513-066-99 | SCX4.9  | 3-551-503    | FR19.6  | 3-590-707-00  | SCX9.0  |
| 3-312-409-00 | SCQ4.0  | 3-423-094    | OA7.0   | 3-513-066-XX | SCX4.9  | 3-553-540    | SCY2.2  | 3-590-708     | SCQ5.6  |
| 3-313-335-00 | SCX7.0  | 3-425-143-00 | OA10.9  | 3-513-151    | SCQ4.0  | 3-553-928    | SCX9.5  | 3-590-783     | SCY9.0  |
| 3-313-816-00 | SCQ8.8  | 3-426-162    | OB10.1  | 3-513-153    | SCY4.6  | 3-554-103    | SCX2.4  | 3-590-784     | SCX5.1  |
| 3-313-816-01 | SCQ8.8  | 3-427-325    | OA10.1  | 3-515-154    | OA8.2   | 3-554-103-00 | SCY2.2  | 3-592-445     | FRW8.5  |
| 3-313-823-00 | SCQ6.7  | 3-431-149    | OB8.5   | 3-517-245    | SCX3.5  | 3-554-106    | SCY2.2  | 3-592-603     | SCY9.0  |
| 3-314-515-00 | SCY3.5  | 3-431-150    | OB8.2   | 3-527-150-99 | SCX7.0  | 3-554-707    | SCQ8.2  | 3-592-603-00  | SCY9.0  |
| 3-318-143-01 | SCY9.2  | 3-434-015-00 | ST.750  | 3-527-150-XX | SCX7.0  | 3-555-035    | SCX8.0  | 3-592-604     | SCX4.3  |
| 3-319-030-01 | SCX4.6  | 3-434-044-01 | SCX4.9  | 3-527-152    | SCY3.5  | 3-555-035-00 | SCX8.0  | 3-592-604-00  | SCX4.3  |
| 3-319-630-11 | FRW8.8  | 3-434-103-00 | SCX4.3  | 3-527-152-XX | SCX4.3  | 3-555-234    | SCY8.6  | 3-593-603-00  | SCY9.0  |
| 3-319-710-01 | FR8.2   | 3-434-110-00 | SCX8.4  | 3-528-063    | SCY6.0  | 3-556-492-01 | SCX8.0  | 3-593-609     | SCX4.9  |
| 3-325-387-01 | SCY7.8  | 3-434-110-XX | SCX8.4  | 3-530-181    | SCY7.0  | 3-558-349    | FRX11.5 | 3-593-609-00  | SCX4.9  |
| 3-325-651-01 | SCX4.6  | 3-436-081-00 | OA11.7  | 3-530-181-99 | SCY7.0  | 3-558-349-00 | FRW12.0 | 3-594-331-01  | SCY3.2  |
| 3-329-695-01 | SCY8.0  | 3-437-109-03 | OC14.0  | 3-530-182    | OA8.2   | 3-558-705    | FRW9.1  | 3-594-332-01  | SCX15.0 |
| 3-338-334-01 | SCY3.5  | 3-437-190    | OB13.2  | 3-531-145    | SCY8.6  | 3-558-706-00 | FRX11.2 | 3-595-944-01  | SCY4.0  |
| 3-339-703-11 | SCX8.9  | 3-437-191-02 | FR25.0  | 3-531-646    | SCX5.1  | 3-558-707    | SCQ5.6  | 3-595-998-01  | SCX6.2  |
| 3-341-267-01 | SCY7.5  | 3-438-053    | OA10.9  | 3-531-844    | SCQ10.0 | 3-558-707-00 | SCQ6.0  | 3-596-010-01  | SCX4.9  |
| 3-343-966-01 | SCY4.6  | 3-440-134    | SCY6.5  | 3-531-845-00 | SCQ6.5  | 3-558-724-00 | FRW9.1  | 3-596-139-01  | FRW7.3  |
| 3-344-058-01 | SCX4.0  | 3-444-110    | SCX8.6  | 3-531-940    | SCY6.0  | 3-558-734    | FRW9.1  | 3-596-183-01  | SCX6.2  |
| 3-344-059-01 | SCQ5.6  | 3-445-054    | OA11.7  | 3-531-940-99 | SCY6.3  | 3-561-595    | SCX4.6  | 3-596-184-01  | FRW7.3  |
| 3-344-115-01 | SCX15.5 | 3-448-104    | FRM15.2 | 3-532-213    | SCY7.0  | 3-561-596    | SCX1.9  | 3-596-825-01  | FRW7.1  |
| 3-349-814-01 | SCY8.6  | 3-451-108    | OB11.7  | 3-533-089    | SCY8.0  | 3-561-645    | SCY2.2  | 3-596-931-01  | SCY4.2  |
| 3-352-727-01 | SCY4.2  | 3-453-040    | SCX4.6  | 3-533-360    | SCX3.5  | 3-561-850    | FRW9.2  | 3-597-103-01  | SCY6.7  |
| 3-354-868-01 | SCY6.5  | 3-453-111    | SCX14.7 | 3-533-360-00 | SCX3.5  | 3-561-850-11 | FRW9.2  | 3-597-104-01  | SCQ6.0  |
| 3-354-868-11 | SCY6.5  | 3-453-112    | SCQ6.0  | 3-533-361    | SCX4.3  | 3-561-892    | SCQ6.0  | 3-597-337-01  | SCY10.2 |
| 3-355-614-01 | SCY8.6  | 3-453-112-00 | SCQ6.0  | 3-533-362    | SCY5.2  | 3-561-892-00 | SCY6.3  | 3-597-727-01  | FRW8.0  |
| 3-356-345-01 | SCY5.2  | 3-453-113    | SCX8.4  | 3-533-363    | SCY6.0  | 3-562-456    | SCX9.5  | 3-598-848-01  | SCY4.2  |
| 3-356-603-01 | SCQ2.5  | 3-453-113-00 | SCX8.4  | 3-533-363-00 | SCY6.0  | 3-562-456-00 | SCQ2.5  | 3-598-883-01  | SCY4.2  |
| 3-356-604-01 | FRW8.5  | 3-453-180    | SCX4.6  | 3-533-547-99 | SCY10.5 | 3-562-462    | SCX2.4  | 3-599-137     | FRX11.5 |
| 3-356-730-01 | FRW8.0  | 3-454-003    | OA11.7  | 3-533-720-00 | SCX5.1  | 3-563-031    | FRW10.1 | 3-599-983     | SCQ11.1 |
| 3-356-744-01 | FRW8.0  | 3-454-004    | SCX4.6  | 3-533-721-00 | SCQ6.5  | 3-564-088    | FRW8.5  | 3-600-929     | SCX8.6  |
| 3-358-230-01 | SCQ6.0  | 3-454-040    | SCX4.9  | 3-533-928    | SCX9.5  | 3-564-088-00 | FRW8.5  | 3-601-099-01  | FR16.9  |
| 3-358-272-01 | SCX6.2  | 3-454-043    | SCX10.7 | 3-533-943-00 | SCX8.6  | 3-564-135    | FRW8.5  | 3-613-149-00  | FRZ14.5 |
| 3-359-417-01 | FR8.2   | 3-454-044    | SCX5.1  | 3-534-779    | SCQ5.6  | 3-564-319    | FRM8.0  | 3-613-149-01  | FRZ14.5 |
| 3-359-466-01 | SCX2.9  | 3-454-103    | SCX4.9  | 3-534-779-00 | SCQ5.6  | 3-564-319-00 | FR8.2   | 3-613-150-00  | FR19.6  |
| 3-359-467-01 | FRW8.0  | 3-458-116    | OA10.1  | 3-535-253    | SCX9.5  | 3-564-613    | SCX1.9  | 3-613-150-01  | FRY19.6 |
| 3-359-497-01 | FRW8.0  | 3-458-206    | OA10.9  | 3-535-427    | SCY5.2  | 3-564-866    | SCY5.2  | 3-616-150-01  | FR19.6  |
| 3-362-989-01 | SCY5.2  | 3-459-021-00 | OA11.7  | 3-535-820    | FR20.5  | 3-564-866-00 | SCY5.2  | 3-618-090-02  | FRM15.2 |
| 3-364-600-01 | FRW8.5  | 3-462-131    | SCY7.0  | 3-536-447    | SCX9.5  | 3-564-909    | SCY4.4  | 3-618-091     | FRW9.7  |
| 3-364-777-01 | SCX7.4  | 3-462-132    | SCX10.7 | 3-536-448    | SCQ5.6  | 3-564-909-00 | SCY4.6  | 3-618-091-00  | FRW9.7  |
| 3-367-284-01 | SCX15.2 | 3-462-133    | SCY5.2  | 3-536-451    | SCY8.6  | 3-565-498    | SCB6.7  | 3-618-091-02  | FRM9.7  |
| 3-369-918-01 | SCY5.0  | 3-462-162    | SCX8.6  | 3-536-684    | SCQ6.7  | 3-565-523    | FRW10.1 | 3-618-092-00  | SCA9.2  |
| 3-369-931-01 | SCX8.6  | 3-469-931-01 | SCX8.6  | 3-536-704    | SCX7.0  | 3-569-730-01 | FRW8.0  | 3-618-092-03  | SCA9.2  |
| 3-371-571-01 | FRX11.0 | 3-464-120    | SCX9.2  | 3-536-704-00 | SCY7.0  | 3-569-738-00 | SCY6.5  | 3-618-093-03  | OB10.1  |
| 3-371-868-01 | SCX4.3  | 3-465-120    | SCX9.5  | 3-536-705    | SCQ6.7  | 3-570-096    | SCY5.2  | 3-618-125-00  | OA1.2   |
| 3-371-869-01 | SCY3.5  | 3-465-149    | SCX7.4  | 3-536-713    | FRM12.7 | 3-570-117    | SCX5.1  | 3-618-125-03  | SCX4.3  |
| 3-372-514-01 | SCQ8.0  | 3-465-182    | SCQ6.7  | 3-536-732-00 | SCA7.5  | 3-570-167    | SCY8.6  | 3-619-144-00  | FRW12.6 |
| 3-374-323-01 | SCQ8.8  | 3-472-186    | OC14.4  | 3-536-764    | OA9.0   | 3-570-201    | SCY4.4  | 3-6198-091-02 | FRW9.7  |
| 3-375-149-01 | SCQ7.8  | 3-472-187    | OC14.4  | 3-537-184    | FR14.6  | 3-570-702    | SCY3.5  | 3-625-091-00  | FR11.5  |
| 3-375-375-01 | SCX3.2  | 3-472-187-02 | OC9.0   | 3-537-185    | SCA7.5  | 3-570-768    | SCY2.9  | 3-630-458-00  | OC6.6   |
| 3-375-375-02 | SCX3.2  | 3-472-188    | OX5.5   | 3-537-186    | SCX5.1  | 3-570-904    | SCY5.2  | 3-630-501     | OC4.0   |
| 3-377-420-11 | SCY4.4  | 3-472-189    | OC14.0  | 3-537-187    | SCX8.9  | 3-570-910    | SCX2.6  | 3-630-501-0   | OC4.0   |
| 3-377-688-01 | SCX8.0  | 3-472-332-XX | OC14.0  | 3-538-025    | SCY8.0  | 3-570-910-00 | SCY2.9  | 3-630-536-00  | FR18.7  |
| 3-382-859-02 | SCQ6.7  | 3-480-135    | SCY8.0  | 3-538-025-99 | SCY8.2  | 3-571-154    | SCY5.2  | 3-630-536-01  | FR18.7  |
| 3-382-860-02 | SCX6.2  | 3480-136     | SCY4.4  | 3-538-827-00 | SCX5.1  | 3-571-750    | FRW8.0  | 3-630-537     | FR10.4  |
| 3-383-448-01 | SCX4.9  | 3-480-136-00 | SCX4.6  | 3-538-931    | SCY9.2  | 3-571-815    | SCQ6.0  | 3-630-537-00  | FR10.4  |
| 3-384-485-01 | SCY6.5  | 3-488-056    | SCQ8.2  | 3-539-221    | SCX9.5  | 3-572-153    | FRM7.5  | 3-630-538     | OSC22.0 |
| 3-385-752-01 | SCY4.0  | 3-488-104    | FRM15.2 | 3-539-222    | SCY3.5  | 3-573-121    | FRM7.5  | 3-630-538-00  | OSC22.0 |
| 3-385-829-01 | SCX4.9  | 3-489-114    | SCX9.2  | 3-539-223    | SCQ5.6  | 3-573-122    | SCX2.6  | 3-630-545-01  | FR21.6  |
| 3-385-833-01 | SCY6.5  | 3-491-224    | SCA13.2 | 3-539-223-00 | SCX5.5  | 3-573-153    | FRM7.5  | 3-630-580-01  | OA6.6   |
| 3-387-776-01 | SCQ2.0  | 3-491-225    | SCQ6.5  | 3-541-169    | SCA10.5 | 3-573-911    | FRM6.1  | 3-630-581-01  | OA3.2   |
| 3-391-107-01 | FRW7.7  | 3-491-226    | SCQ10.0 | 3-541-170    | SCX8.0  | 3-573-911-21 | FRW6.5  | 3-630-582-01  | OA4.2   |
| 3-391-134-01 | FRW8.0  | 3-491-227    | OA5.8   | 3-541-171-00 | SCX8.0  | 3-576-062    | SCY4.2  | 3-630-696-01  | OB4.2   |
| 3-391-192-0  | FRW7.7  | 3-491-363    | SCX7.0  | 3-541-463    | FR18.7  | 3-576-919    | SCX4.6  | 3-630-699-01  | OB4.2   |
| 3-391-457-01 | SCQ4.8  | 3-491-365    | SCY8.6  | 3-542-322    | SCX9.5  | 3-576-919-00 | SCQ4.8  | 3-635-324-00  | SCQ4.0  |
| 3-392-967-01 | SCX14.5 | 3-499-042    | SCY5.2  | 3-542-450-00 | SCQ10.0 | 3-577-029    | SCY7.8  | 3-639-354-00  | OB13.2  |
| 3-397-442-01 | SCX3.2  | 3-499-042-XX | SCY5.2  | 3-542-458    | SCX9.5  | 3-578-222    | SCY5.2  | 3-639-386-00  | SCB9.5  |
| 3-397-443-01 | SCX15.0 | 3-500-118    | SCQ6.0  | 3-542-458-00 | SCQ10.0 | 3-578-328    | FRX10.5 | 3-642-541-00  | SCC17.8 |
| 3-401-027-00 | FR13.4  | 3-500-119    | OX5.5   | 3-543-409    | SCY5.0  | 3-578-335    | SCX13.6 | 3-642-542-00  | SCB11.3 |
| 3-401-040-00 | OB6.4   | 3-500-120    | SCX8.0  | 3-543-978-00 | FRX10.5 | 3-578-511    | FRX10.5 | 3-642-543-00  | SCC9.6  |
| 3-401-042-00 | OA6.1   | 3-500-241    | SCQ6.5  | 3-545-600    | SCY9.2  | 3-578-511-00 | FRX10.5 | 3-642-544-00  | SCX8.4  |
| 3-401-049-00 | OB10.1  | 3-501-031    | SCX9.5  | 3-545-601    | SCY4.6  | 3-578-512    | SCY6.5  | 3-642-545-00  | SCX11.8 |
| 3-401-050-00 | FR13.4  | 3-502-122    | SCY6.0  | 3-545-601-99 | SCY5.0  | 3-578-512-00 | SCY6.5  | 3-642-546-00  | OSC10.2 |
| 3-401-050-01 | FR13.4  | 3-506-040    | SCY7.0  | 3-545-601-XX | SCY5.0  | 3-579-050    | SCX13.6 | 3-642-547-00  | FRZ14.5 |
| 3-401-103-00 | FR13.4  | 3-507-088    | SCX10.7 | 3-545-602-00 | SCY5.2  | 3-580-807-00 | SCX8.6  | 3-642-741-00  | FR018.2 |
| 3-401-153-00 | FR13.4  | 3-507-115-00 | SCX3.5  | 3-547-602    | SCY5.2  | 3-581-343    | SCX8.9  | 3-643-470-00  | SCX8.4* |
| 3-403-429-00 | OB11.7  | 3-507-116    | SCY3.2  | 3-547-760    | SCY5.2  | 3-581-539    | FRY10.0 | 3-644-705-00  | FR8.8   |
| 3-405-646-00 | OB9.4   | 3-508-107    | SCQ6.5  | 3-547-822    | SCY11.7 | 3-582-117    | FRX12.7 | 3-645-098-00  | SCX7.4  |
| 3-407-042    | SCX20.7 | 3-509-105    | SCA8.9  | 3-547-822-00 | SCY12.7 | 3-582-118    | SCQ6.7  | 3-646-026-00  | ST1.19  |
| 3-407-042-00 | OA6.1   | 3-509-107    | SCX4.3  | 3-547-876    | SCQ10.0 | 3-582-389    | SCX11.8 | 3-646-027     | ST1.19  |
|              |         |              |         |              |         |              |         |               |         |

# SONY ... SYLVANIA

| MFG. P/N      | PRB NO. | MFG. P/N     | PRB NO. | MFG. P/N      | PRB NO.  | MFG. P/N   | PRB NO. | MFG. P/N   | PRB NO. |
|---------------|---------|--------------|---------|---------------|----------|------------|---------|------------|---------|
| 3-646-130-00  | SCX4.3  | 3-725-562-01 | SCQ4.8  | 4-928-974-01  | SCX4.6   | 1128004    | SQQ4.0  | 3910264010 | FRW10.1 |
| 3-646-1300-00 | SCX4.6  | 3-735-674-01 | VPR26   | 4-931-470-01  | SCQ8.0   | 1140001    | FRM11.2 | 4103264030 | SCX8.4  |
| 3-646-186-00  | FRY19.6 | 3-735-691-01 | SCA6.7  | 4-931-471-01  | SCQ7.8   | 1152101    | SCX8.6  | 4107264010 | SCX5.1  |
| 3-646-187-00  | FR18.5  | 3-735-709-01 | SCA3.0  | 4-934-520-01  | SCX7.0   | 1152102    | 0A10.1  | 4107264020 | SCX7.0  |
| 3-646-188-00  | SCC15.7 | 3-827-489-00 | FR23.6  | 4-934-521-01  | SCY10.5  | 1160001    | 0A9.4   | 4111264010 | SCX5.6  |
| 3-646-189-00  | SCA6.1  | 3-907-943-01 | SCY3.5  | 4-949-430-01  | FR5.9    | 1160002    | 0A8.2   | 4129264010 | SCQ4.0  |
| 3-646-190-00  | SCY13.3 | 3-908-638-01 | SCY7.5  | 4-954-635-01  | SCX11.8  | 1168201    | SCX8.9  | 4168264010 | SCX5.1  |
| 3-546-306-00  | SCA6.1  | 3-912-896-01 | SCX9.2  | 4-957-304-01  | SCX2.4   | 1160501    | FRM12.7 | 4367264010 | SCX8.9  |
| 3-646-489-00  | SCA6.1  | 3-912-898-01 | SCX9.2  | 4-957-797-01  | SCX4.0   | 1172201    | SCA8.9  | 4367264012 | SCX8.9  |
| 3-646-564-00  | SCA6.1  | 3-913-845-01 | SCX8.6  | 4-964-476-01  | SCX5.5   | 1172202    | 0A3.1   | 4367264020 | OX5.9   |
| 3-647-508-00  | SCX10.5 | 3-913-846-01 | SCX6.2  | 4-964-477-01  | SCQ5.3   | 1172603    | FRM10.5 | 4367264033 | SCQ6.0  |
| 3-648-002     | SCC9.6  | 3-915-787-01 | SCY4.0  | 491752201     | SCA5.4   | 1172604    | SCX7.4  | 4380264052 | SCQ4.8  |
| 3-643-002-00  | SCC9.6  | 3-915-802-01 | SCY6.7  | 491752202     | SCA5.4   | 1172605    | SCX8.0  | 4383264010 | FRZ12.1 |
| 3-648-003     | SCB10.5 | 3-917-176-01 | SCX8.9  | 492028801     | SCC4.3   | 1172631    | SCX10.5 | 5000375005 | SCA5.2  |
| 3-548-003-00  | SCB10.5 | 3-920-580-01 | SCY4.6  | 492897401     | SCX4.6   | 1172632    | SCX8.9  | 5000517005 | SCA3.2  |
| 3-648-004     | SCC17.8 | 3-921-000-01 | SCY6.5  | 493147001     | SCQ8.0   | 1172651    | SCQ5.6  | 5000958005 | SCY4.4  |
| 3-648-004-00  | SCC17.8 | 3-924-681-01 | SCY3.5  | 493452001     | SCX7.0   | 1172652    | SCQ6.0  | 5001342005 | SCY5.2  |
| 3-648-422-XX  | SCA6.1  | 3-924-682-01 | SCX4.0  | 8-719-118-33  | VCR30    | 1172801    | FRM9.2  | 50108      | SCX4.9  |
| 3-649-241     | FR15.3  | 3-924-817-01 | FRW10.1 | 8-719-411-12  | VCR10    | 1176001    | SCX8.0  | 5420       | SCQ10.0 |
| 3-649-241-00  | FR15.3  | 3-924-818-01 | SCQ3.0  | 8-719-902-96  | VCR32    | 1210027    | SCX12.2 | 5610902    | FRY10.7 |
| 3-652-522-00  | FRQ13.6 | 3-924-873-01 | SCY6.0  | 8-729-025-92  | VCR20    | 12510039   | 0A8.2   |            |         |
| 3-653-324-00  | SCX4.0  | 3-946-511-01 | SCA6.1  | 8-729-926-31  | VCR24    | 12510044   | SCX8.0  |            |         |
| 3-653-387-00  | SCQ3.2  | 3-949-030-01 | SCQ5.6  | 8-759-144-33  | VCR17    | 12601202   | FRW8.5  |            |         |
| 3-653-442-00  | FRY10.2 | 3-980-444-00 | FRX12.5 | 9-930-066-40  | 0A4.2    | 1510702    | FRM10.5 |            |         |
| 3-653-450-00  | SCB10.5 | 331381600    | SCQ8.8  | 9-981-092-00  | SCY5.2   | 17200905   | SCX5.5  |            |         |
| 3-653-452-00  | OX5.5   | 331381601    | SCQ8.8  | 9-981-099-00  | FRW10.1  | 18210703   | SCY4.2  |            |         |
| 3-653-465-00  | FRM11.7 | 333970311    | SCX8.9  | 9-981-166-00  | FR2.9    | 18211204   | SCY7.5  |            |         |
| 3-654-100-00  | FR14.6  | 334405801    | SCX4.0  | 9-981-197-00  | FRW7.0   | 18211221   | SCY7.3  |            |         |
| 3-654-100-01  | FR14.6  | 334405901    | SCQ5.6  | 9-996-606-01  | FRM11.5  | 1891003    | FRX16.8 |            |         |
| 3-654-501-00  | SCX7.0  | 335486811    | SCY6.5  | 9-996-626-01  | SCA14.1  | 19210703   | SCY4.2  |            |         |
| 3-654-501-XX  | SCX7.0  | 335489801    | SCY6.5  | 9-996-651-01  | SCA7.5   | 20000016   | SCA7.5  |            |         |
| 3-654-617-03  | ST.925  | 335660301    | SCQ2.5  | 9-996-674-01  | SCA6.7   | 2020000500 | FR21.5  |            |         |
| 3-655-135-00  | FRM12.1 | 335660401    | FRW8.5  | A-6706-479-A  | ST.925   | 20VF013    | SCY7.5  |            |         |
| 3-655-969-00  | FRW8.8  | 335823001    | SCQ6.0  | A-6746-072-A  | VPR26    | 2381104    | SCX10.5 |            |         |
| 3-656-038     | FRQ18.2 | 335941701    | FR8.2   | A-6750-053-A  | VPR5     | 5610902    | FRM10.5 |            |         |
| 3-656-038-00  | FRQ18.2 | 335946601    | SCX2.9  | A-6759-344-A  | VPRA2    | 80001      | FRY10.7 |            |         |
| 3-655-465-00  | FRM11.7 | 335949701    | FRW8.0  | E69611001     | SCY3.2   | 8001602    | SCB11.3 |            |         |
| 3-656-471-00  | SCC15.7 | 336460001    | FRW8.5  | H-6351-554-H  | SCA8.1   | 8891202    | SCX8.9  |            |         |
| 3-657-035-99  | SCX8.6  | 336991801    | SCY5.0  | H-6351-555-H  | SCA8.1   | 90740020   | FRM11.7 |            |         |
| 3-659-047-00  | SCB10.5 | 337186801    | SCX4.6  | H-6975-761-H  | VPR18    | 91076      | FRM9.7  |            |         |
| 3-659-301-00  | SCB14.6 | 337186901    | SCY3.5  | X-3458-0-18   | STC1.75  | 91076F     | FRM10.5 |            |         |
| 3-659-397-00  | SCX11.8 | 337251401    | SCQ8.0  | X-3460-20     | ST.536   | 91161H     | FRY10.7 |            |         |
| 3-659-397-XX  | SCX11.8 | 337432301    | SCX8.9  | X-3517-008    | ST.536   | 97312010   | FRX9.7  |            |         |
| 3-659-471-00  | SCA10.5 | 337514901    | SCQ7.8  | X-3646-026-0  | ST1.110  |            |         |            |         |
| 3-661-565-00  | SCY11.7 | 337537501    | SCX3.2  | X-3646-026-2  | \$11.110 |            |         |            |         |
| 3-661-708-00  | FRQ11.2 | 337537502    | SCX3.2  | X-3646-027-0  | ST1.110  |            |         |            |         |
| 3-662-347-00  | SCA10.5 | 337768801    | SCX8.0  | X-3652-510-3  | VPR5     | 2205       | 087.7   |            |         |
| 3-664-304-00  | SCQ4.0  | 338285902    | SCQ6.7  | X-3653-310-0  | ST.515   |            | 0C4.4   |            |         |
| 3-664-304-11  | SCA4.0  | 338286002    | SCY6.5  | X-3653-310-00 | ST.515   |            |         |            |         |
| 3-664-306-00  | SCA6.1  | 338344801    | SCX4.9  | X-3653-315-0  | ST.925   |            |         |            |         |
| 3-664-310-00  | FR11.6  | 338448501    | SCY6.5  | X-3653-315-0  | VA70     |            |         |            |         |
| 3-664-327-03  | SQA3.2  | 338575201    | SCY4.0  | X-3653-315-00 | ST.925   | 0002111202 | SCQ5.6  |            |         |
| 3-664-328-00  | SCA3.2  | 338582901    | SCX4.9  | X-3653-315-3  | ST.925   | 0004403000 | SCA8.6  |            |         |
| 3-664-329-00  | SCQ7.2  | 339296701    | SCX14.5 | X-3653-315-3  | VA70     | 0007630601 | SCA9.6  |            |         |
| 3-667-328-00  | SCA6.1  | 339744201    | SCX3.2  | X-3653-317-0  | ST.515   | 0008891202 | SCX8.9  |            |         |
| 3-668-173-00  | SCQ3k2  | 339744301    | SCX15.0 | X-3653-330-3  | VPR5     | 102126405R | FRX11.2 |            |         |
| 3-668-785-00  | SCB8.1  | 345311300    | SCX8.4  | X-3659-324-0  | ST.776   | 12510040   | SCY5.2  |            |         |
| 3-668-946-00  | SCQ4.8  | 351306699    | SCX4.9  | X-3659-337-0  | VPR5     | 2061264010 | SCX8.0  |            |         |
| 3-669-327-00  | SCA4.2  | 351306600    | SCX4.9  | X-3661-520-0  | ST.515   | 2061264020 | SCX8.0  |            |         |
| 3-669-933-01  | SCX8.0  | 354560199    | SCY5.0  | X-3661-520-00 | ST.515   | 2061264030 | SCX3.5  |            |         |
| 3-671-077-00  | SCA5.0  | 3545601XX    | SCY5.0  | X-3669-307-0  | VPRA2    | 2061264040 | SCY4.0  |            |         |
| 3-671-078-00  | SCX4.6  | 356245600    | SCQ2.5  | X-3669-307-6  | VPRA2    | 21V7020    | SCY4.4  |            |         |
| 3-671-094-00  | SCX9.2  | 3618091      | FRM9.7  | X-3670-063-0  | VPRA1    | 21V7036    | FRW10.1 |            |         |
| 3-671-098-00  | SCQ7.2  | 361809100    | FRW9.7  | X-3675-850-5  | VPR5     | 307726402  | FRY10.0 |            |         |
| 3-671-120-00  | SCQ5.3  | 363935400    | OB13.2  | X-3682-033-1  | VPRA1    | 3295264010 | 0A6.1   |            |         |
| 3-671-253-00  | FRM11.0 | 364347000    | SCX8.4  | X-3684-337-1  | VPRA2    | 3338264010 | FRW9.2  |            |         |
| 3-672-602-00  | SCX7.0  | 3660801200   | SCY12.7 | X-3690-114-1  | VPR13    | 3340264010 | SCX8.6  |            |         |
| 3-676-059-00  | FRW8.0  | 366430411    | SCA4.0  | X-3690-646-1  | VPR13    | 3358264210 | FRY10.7 |            |         |
| 3-676-176-00  | SCQ8.8  | 372550301    | SCA5.4  | X-3691-646-1  | VPRA2    | 3358264220 | SCX8.6  |            |         |
| 3-675-517-00  | SCA6.1  | 4-804-642-00 | FR23.6  | X-3717-215-3  | VPR2     | 3358264220 | SCX5.1  |            |         |
| 3-679-171-00  | SCX7.0  | 4-827-489-XX | FR23.6  | X-3727-770-01 | VPR26    | 3388264010 | SCX8.0  |            |         |
| 3-661-424-00  | SCX2.6  | 4-836-884-00 | FR23.6  | X-3727-770-1  | VPR26    | 3388264020 | SCY2.2  |            |         |
| 3-681-444-00  | FRY6.7  | 4-850-664-00 | FR23.6  | X-4920-346-1  | ST.525   | 3411260    | SCQ5.6  |            |         |
| 3-681-446-00  | FRW7.0  | 4-885-735-00 | SCX2.6  |               |          | 3411264010 | SCX9.5  |            |         |
| 3-681-447-0   | SCQ6.0  | 4-890-912-00 | FRW10.7 |               |          | 3411264020 | SCQ5.6  |            |         |
| 3-681-447-00  | SCQ6.0  | 4-891-942-00 | FRM10.5 |               |          | 3412264010 | SCQ5.6  |            |         |
| 3-686-546-01  | SCX1.9  | 4-908-591-01 | SCA6.7  |               |          | 3412264020 | SCX7.0  |            |         |
| 3-688-066-01  | SCQ3.2  | 4-917-522-01 | SCA5.4  |               |          | 3412264030 | SCY4.0  |            |         |
| 3-706-860-00  | SCQ2.2  | 4-917-522-02 | SCA5.4  |               |          | 3412264040 | SCY2.2  |            |         |
| 3-711-856-01  | FRW7.1  | 4-917-548-01 | SCQ2.0  |               |          | 3426264010 | SCY3.5  |            |         |
| 3-713-670-01  | SCA8.1  | 4-917-548-02 | SCQ2.0  |               |          | 3435254010 | SCX8.4  |            |         |
| 3-717-910-01  | FRZ7.5  | 4-920-288-01 | SCC4.3  |               |          | 3435264020 | SCX8.9  |            |         |
| 3-717-921-01  | SCX3.5  | 4-927-649-01 | SCQ4.6  |               |          | 3483264020 | SCX7.0  |            |         |
| 3-719-123-01  | FR7.7   | 4-928-951-01 | SCQ6.0  |               |          | 3903264010 | SCX5.1  |            |         |
| 3-725-503-01  | SCA5.4  | 4-928-951-21 | SCX5.8  |               |          |            | FRQ11.2 |            |         |

<sup>A</sup> = Part of the Assy

" = Kit May Not Include Tires

<sup>A</sup> = Part of the Assy

# SYLVAN IA ... TEAC

| MFG. P/N     | PRB NO. | MFG. P/N         | PRB NO. | MFG. P/N        | PRB NO.  | MFG. P/N   | PRB NO. | MFG. P/N       | PRB NO.  |
|--------------|---------|------------------|---------|-----------------|----------|------------|---------|----------------|----------|
| 141420763    | FRM12.1 | VDVS0057         | SCB11.6 | 97312010        | FRX9.7   | 15A-0073   | FRM11.5 | B-6650         | SCX5.1   |
| 144258       | SCB14.0 | VDVS0058         | SCA4.5  |                 |          | 15A-0074   | FRM11.7 | 13-6653        | SCA7.5   |
| 144259       | SCA3.0  | VDVS0059         | SCA4.2  | <b>TANDBERG</b> |          | 15A-0075   | FRM12.1 | B6497          | SCX9.2   |
| 144259260    | SCX8.6  | VDVS0060         | SCQ2.5  |                 |          | 117.3      | OB10.9  | 15A-0076       | FR2.9    |
| 144259261    | OX5.5   | VDVS0122         | SCA4.5  |                 |          | 15A-0077   | FRW7.0  | RA1445         | PRO1     |
| 144259267    | SCA9.6  | VPS0054          | VA28    |                 |          | 15A-0078   | FR7.5   |                |          |
| 144259606    | FRW12.6 | VXLS0165         | VB2     |                 |          | 15A-0079   | FRX7.5  | <b>TA TUNG</b> |          |
| 147756       | SCX2.9* | VXLS0666         | VPR2    |                 |          | 15A-0080   | FRW8.5  | PU51390A       | VB4      |
| 482235810115 | SCQ6.5  | VXLS0770         | VPR2    |                 |          | 15A-0081   | FRX9.0  | PU51402A       | ST.689   |
| 483535837075 | FRQ11.2 | VXP0174          | ST1.160 |                 |          | 15A-0082   | FRW9.1  | PU51402A       | VA12     |
| 483535837076 | SCA14.1 | VXP0174          | VA23    |                 |          | 15A-0083   | FRW9.2  | PU55373        | ST.463   |
| 483535837077 | SCQ7.2  | VXP0213          | ST.752  |                 |          | 15A-0084   | FRX9.7  | PU55373        | VA13     |
| 483535837078 | SCQ6.5  | VXP0213          | VA200   |                 |          | 15A-0085   | FRW10.1 | PU55374        | ST.988   |
| 6305371H     | SCQ10.0 | VXP0329          | ST1.330 | <b>TANDY</b>    |          | 15A-0086   | FRX10.5 | PU55374        | VA18     |
| 6350611H     | SCX2.6  | VXP0329          | VA20    | 15A-0001        | SCA2.3   | 15A-0087   | FRW12.6 | PUM30001       | SCY5.2   |
| 6350801H     | OA5.8   | VXP0331          | ST1.230 | 15A-0002        | SCQ2.5   | 15A-0088   | FRY13.4 | PUM30003-7     | SCA14.1  |
| 6451430001   | FRW12.0 | VXP0331          | VA25    | 15A-0003        | SCA3.0   | 15A-0089   | FRX15.2 | PUM30003-8     | SCA3.5   |
| 6451430002   | FRW12.0 | VXP0344          | ST1.330 | 15A-0004        | SCA3.2   | 15A-0090   | FR20.0  |                |          |
| 6451430003   | FRW12.0 | VXP0344          | VA26    | 15A-0005        | SCA4.5   | 15A-0091   | FRX20.7 | <b>TEAC</b>    |          |
| 6451430008   | SCA4.5  | VXPS0054         | ST1.370 | 15A-0006        | SCQ4.8   | 15A-0092   | FRX22.4 | 1608261011     | SCQ5.6   |
| 6451430023   | SCX8.6  | VXPS0054         | VA28    | 15A-0007        | SCA5.4   | 15A-0093   | FR23.6  | 2760772300     | FRW7.3   |
| 6451430102   | SCX6.2  | VXPS0076         | ST.670  | 15A-0008        | SCA6.1   | 15A-0094   | FRX23.6 | 50123213       | FRY17.0  |
| 6451430103   | SCB14.0 | VXPS0116         | ST1.165 | 15A-0009        | SCA6.7   | 15A-0095   | FRY23.6 | 50123251       | SCX10.7  |
| 6451430104   | SCB12.5 | VXPS0116         | VA27    | 15A-0010        | SCA7.5   | 15A-0096   | FRX25.0 | 50123830       | FRX14.5  |
| 6451430152   | SCB10.0 | VXZ0076          | VB6     | 15A-0011        | SCQ8.2   | 15A-0097   | FRY25.0 | 501253400      | FRX14.5  |
| 6451430153   | SCQ6.5  | VXZS0005         | VB1     | 15A-0012        | SCA8.6   | 15A-0098   | FRX25.0 | 5012534000     | FRX14.5  |
| 6451430189   | SCB2.5  | VXZS0129         | VB1     | 15A-0013        | SCA8.9   | 15A-0099   | FRX35.1 | 5027142        | OA10.1   |
| 649520057    | SCA8.9  | VXZS037          | VB1     | 15A-0014        | SCA9.2   | 15A-0112   | ST.685  | 50273161       | SCQ6.7   |
| 74140611     | OA8.2   |                  |         | 15A-0015        | SCA9.6   | 15A-0113   | ST.752  | 50274712       | SCQ6.7   |
| 7660854H     | SCX2.4  | <b>SYMPHONIC</b> |         | 15A-0016        | SCA10.0  | 15A-0114   | ST.925  | 50276940       | OA10.1   |
| 80460VM      | SCX2.4  | 10022500         | SCY8.6  | 15A-0017        | SCA10.5  | 15A-0115   | ST.985  | 50277590       | 0612.4   |
| 80478VM      | SCX8.6  | 13301503         | FRM7.5  | 15A-0018        | SCA12.0  | 15A-0116   | ST1.014 | 5027759000     | OA12.4   |
| 9230024      | OC10.5  | 140914           | FRM14.7 | 15A-0019        | SCA12.5  | 15A-0117   | ST1.160 | 50279980       | OB14.0   |
| VDV0072      | SCB14.0 | 141006           | 006.1   | 15A-0020        | SCA13.2  | 15A-0118   | ST1.211 | 50302120       | OA14.0   |
| VDV00721     | SCB14.0 | 141012           | 0911.7  | 15A-0021        | SCA14.1  | 15A-0119   | ST1.230 | 50302471       | SCX5.1   |
| VDV0074      | SCA3.0  | 141064           | SCX7.4  | 15A-0022        | SCB2.3   | 15A-0120   | ST1.243 | 50302480       | SCX9.5   |
| VDV00741     | SCA3.0  | 142417           | FRM11.2 | 15A-0023        | SCB3.2   | 15A-0121   | ST1.330 | 50332531       | OB13.2   |
| VDV0075      | SCX8.6  | 142418           | FRM11.5 | 15A-0025        | SCB8.1   | 15A-0122   | ST1.350 | 50332560       | OA9.4    |
| VDV0076      | OX5.5   | 142419           | FRM12.1 | 15A-0026        | SC 88.6  | 15A-0123   | ST1.420 | 50820310       | OA10.9   |
| VDV0092      | SCQ9.8  | 142421           | FRM10.5 | 15A-0027        | SCB9.5   | 15A-0126   | SCQ11.1 | 50831102       | FRX11.7  |
| VOV0094      | FRW12.6 | 142508           | SCX4.6  | 15A-0028        | SC B10.5 | 915200860A | PRO1    | 50833400       | FRX11.5  |
| VDV0101      | SCX3.2* | 142514           | SCA12.0 | 15A-0029        | SCB12.5  | 919002860A | SCX9.2  | 50834970       | FRX11.7  |
| VDV0122      | SCA4.5  | 142517           | FRM11.2 | 15A-0030        | SCB14.0  | B-0201     | FRX6.7  | 50845160       | OA7.0    |
| VDV0123      | SCA13.2 | 142526           | SCQ4.0  | 15A-0031        | SCA14.1  | B-0202     | SCA4.5  | 50846462       | SCX10.7  |
| VDV0124      | SCY6.3  | 142528           | SCX8.9  | 15A-0032        | SCB14.6  | B-0205     | SCX2.9  | 51901190       | FRX11.3  |
| VDV0125      | SCX4.9  | 149920           | OB9.0   | 15A-0033        | SCC15.7  | B-0218     | SCY6.0  | 51912210       | SCY8.6   |
| VDV0130      | SCX3.5  | 17001015         | SCQ8.2  | 15A-0034        | SCQ4.0   | B-0394     | SCY4.4  | 51930150       | FRY10.4  |
| VDV0216      | SCQ6.5  | 21 V0046         | SCY5.2  | 15A-0035        | SCX4.3   | B-0554     | FRM11.0 | 51930170       | SCY6.7   |
| VDV0217      | SCX8.6  | 21VFO04          | SCY7.0  | 15A-0036        | SCX4.6   | B-0555     | SCA14.1 | 51934510       | SCA6.7   |
| VDV0218      | SCY3.2  | 80000922         | VPR4    | 15A-0037        | SCX4.9   | B-0556     | SC07.2  | 51940740       | FRW9.2   |
| VDV029       | FRW12.0 | 800011306        | VCR15   | 15A-0038        | SCX5.1   | B-0557     | SCA6.7  | 51940750       | SCY7.8   |
| VDVS0005     | FRX6.7  | 80001526         | FRQ11.2 | 15A-0039        | SCQ5.6   | B-0558     | SCA8.6  | 5199044000     | FRW10.1  |
| VDVS0008     | SCX3.5  | 80001607         | FR8.2   | 15A-0040        | SCX7.0   | B-1018     | SCY4.0  | 5199098000     | SCY8.0   |
| VDVS0011     | SC B2.8 | 80001608         | SCB10.0 | 15A-0041        | SCX7.4   | B-1042     | SCX15.0 | 55300100       | SCQ4.0   |
| VDVS0012     | FRW12.6 | 80001626         | FRQ11.2 | 15A-0042        | SCX8.0   | B-6003     | SCX9.5  | 55300150       | FRM12.7  |
| VDVS0013     | SCB14.0 | 800018307        | VCR33   | 15A-0043        | SCX8.4   | 13-6056    | SCA3.5  | 55300150       | FRM13.3  |
| VDVS0015     | SCB9.8  | 800018308        | VCR33   | 15A-0044        | SCX8.6   | B-6057     | SC02.5  | 55300281       | SCY10.2  |
| VDVS0018     | FR11.9  | 800019308        | VCR33   | 15A-0045        | SCX8.9   | B-6068     | SCX4.0  | 55300710       | OA13.2   |
| VDVS0019     | SCC12.1 | 80002139         | FR3.6   | 15A-0046        | SCX9.2   | B-6070     | OA16.4  | 5530073000     | FRM9.7   |
| VDVS0020     | SCA13.2 | 800022320        | VCR6    | 15A-0047        | SCX9.5   | B-6076     | SCY15.2 | 55301241       | SCX9.5   |
| VDVS0021     | FRW12.0 | 800022321        | VCR6    | 15A-0048        | SCQ 10.0 | B-6086     | SCX8.0  | 55301251       | SCY7.4   |
| VDVS0022     | SCB14.0 | 80002264         | SCB2.5  | 15A-0049        | SCX13.6  | B-6092     | SCX4.6  | 5530290        | SCX7.0   |
| VDVS0023     | SCY7.5  | 800023139        | FR3.6   | 15A-0050        | SCX14.7  | B-6122     | SCA10.0 | 55308050       | FRX11.7  |
| VDVS0024     | SCY4.2  | 80590710         | FRQ11.2 | 15A-0051        | SCX16.0  | B-6130     | SCA2.3  | 55308060       | SCQ6.5   |
| VDVS0028     | SCB7.1  | 80590917         | SCA14.1 | 15A-0052        | SCY4.0   | B-6136     | SCX16.0 | 55308070       | SCY3.5   |
| VDVS0029     | FRW12.0 | 805916301        | VCR22   | 15A-0053        | SCY4.2   | B-6159     | SCX18.5 | 55340110       | 0616.4   |
| VDVS0032     | SCY7.5  | 805916316        | VCR22   | 15A-0054        | SCY4.6   | B-6160     | SCY9.2  | 55340320       | SCX7.4   |
| VDVS0033     | SCY5.0  | 96227            | OB9.0   | 15A-0055        | SCY5.0   | B-6230     | SCB9.5  | 55340850       | SCX8.4   |
| VDVS0034     | SCY4.0  | A102442          | OB14.0  | 15A-0056        | SCY5.2   | B-6292     | SCQ10.0 | 55340930       | FRX11.3  |
| VDVS0035     | SCX4.3  | A200149          | OA10.9  | 15A-0057        | SCY5.7   | B-6293     | SCX7.0  | 55340951       | SCX4.3   |
| VDVS0037     | SCX6.2  | SM042            | OA8.5   | 15A-0058        | SCY6.0   | B-6317     | FRM15.2 | 55340990       | FRZ12.1  |
| VDVS0038     | SCB14.0 | SM2045           | OB14.0  | 15A-0059        | SCY7.0   | B-6321     | FRX10.5 | 55341100       | SCQ6.5   |
| VDVS0039     | SCB12.5 |                  |         | 15A-0060        | SCY7.5   | 13-6331    | FRX25.0 | 55341350       | SCX4.3   |
| VDVS0040     | SCA5.4  | <b>TANASHIN</b>  |         | 15A-0061        | SCY8.0   | B-6349     | SCX8.9  | 55341540       | FRZ12.1  |
| VDVS0042     | SCB10.0 | 10851204         | FRX9.7  | 15A-0062        | SCY8.6   | B-6359     | SCX8.9  | 5534154000     | SCY5.0   |
| VDVS0043     | SCX6.2  | 1172603          | FRM10.5 | 15A-0063        | SCY9.0   | B-6369     | FR23.6  | 55341550       | SCY4.4   |
| VDVS0044     | SCB2.5  | 1172632          | SCX8.9  | 15A-0064        | FRM7.7   | B-6374     | FRM10.5 | 5534155000     | SCY4.4   |
| VDVS0045     | SCA4.5  | 1172652          | SCQ6.0  | 15A-0065        | FRM8.0   | B-6375     | SCQ6.0  | 55341780       | FRX13.1  |
| VDVS0046     | SCB8.1  | 12602102         | FRW8.5  | 15A-0066        | FRW8.5   | B-6380     | FRX15.2 | 55342520       | SCY3.2   |
| VDVS0047     | SCB10.0 | 1510702          | FRM10.5 | 15A-0067        | FRM9.6   | B-6438     | SCX10.7 | 55342530       | SCQ10.0  |
| VDVS0048     | SCA8.9  | 2016636140       | SCQ6.0  | 15A-0068        | FRM9.7   | B-6439     | SCA13.2 | 55342840       | FRZ12.1  |
| VDVS0052     | SCA8.9  | 2381104          | SCX10.5 | 15A-0069        | FRM10.2  | B-6514     | FRW8.0  | 55342850       | SCX7.4   |
| VDVS0053     | SCB9.5  | 3931202          | SCQ5.6  | 15A-0070        | FRM10.5  | B-6518     | FRW10.1 | 55342920       | SCY5.1   |
| VDVS0054     | SCQ4.3  | 5610902          | FRY10.7 | 15A-0071        | FRW10.7  | B-6614     | SCA8.6  | 55343630       | FRX22.4  |
| VDVS0055     | SCB8.1  | 8891202          | SCX8.9  | 15A-0072        | FRM11.0  | B-6618     | SCA8.6  | 553437000      | SCB14.6* |

= Replacement Belt

\*\* = Kit May Not Include Tires

= Part of the Assy

| MFG. P/N    | PRB NO.  | MFG. P/N           | PRB NO.  | MFG. P/N           | PRB NO. | MFG. P/N | PRB NO. | MFG. P/N | PRB NO.       |
|-------------|----------|--------------------|----------|--------------------|---------|----------|---------|----------|---------------|
| 5534370000  | OA14.8   | 5600735500         | FRW8.0   | <b>TELECTRO</b>    |         | 123059   | OA6.1   | 152413   | SCQ6.5        |
| 55343710    | OB18.0   | 5800772000         | SCQ6.0   | TE270              | 0016.0  | 123060   | SCB7.0  | 152422   | ST.470        |
| 55343920    | SCY5.2   | 5800788801         | SCQ4.6   | TB999              | FF12.6  | 123061   | FRW10.7 | 152434   | VPR6          |
| 55343930    | SCX4.6   | 5801414000         | SCY5.2   | 10171              | OC14.4  | 123311   | SCX2.4  | 152663   | SCC12.1       |
| 55344160    | OA7.0    | 6024684000         | SCY4.2   | 10242              | OA12.4  | 123312   | SCX8.0  | 152665   | FR11.9        |
| 5534416000  | OA7.0    | 6024685000         | SCX7.0   | 10243              | 008.2   | 123581   | OA8.5   | 152666   | FR11.9        |
| 55344447000 | SCX8.0   | 9259006000         | SCQ5.3   | TR1548             | 006.1   | 123586   | OA8.5   | 152667   | FR11.9        |
| 55344460    | FRW8.0   | 9260046800         | SCY7.3   | TR1614             | OA10.1  | 123587   | 0014.0  | 152668   | VPR1          |
| 5534446000  | FRW7.7   | 9260049100         | SCY6.7   | TR2387             | OA8.5   | 124126   | OB11.7  | 152673   | SCY7.5        |
| 55344470    | \$CY8.2  | 9260049500         | SCY7.3   | TR8614             | 0811.7  | 127057   | SCX8.6  | 152674   | ST1.330       |
| 5534447000  | SCX8.0   | 9278010300         | SCQ6.0   | <b>TEL EFUNKEN</b> |         | 127117   | OB7.0   | 152674   | VA20          |
| 55344841    | SCX3.5   | 9278010400         | FRW7.3   | 339730708          | OA14.0  | 127211   | OA12.4  | 152683   | \$11.230      |
| 55344970    | SCY5.2   | 9278011000         | SCY5.0   | 339730709          | OA13.2  | 127525   | FRM14.7 | 152683   | VA25          |
| 55344980    | SCY5.2   | 9278011001         | SCY5.0   | 339730711          | OB15.6  | 12752844 | SCX8.6  | 152688   | VPR1          |
| 55345040    | FRY10.4  | 9278012400         | SCY5.0   | 70023370           | FRM14.7 | 127575   | FR15.9  | 152713   | SCY4.2        |
| 5534504000  | FRW10.6  | 9278026100         | SCX7.0   | 7023370            | FRW9.7  | 127894   | OA8.2   | 152751   | FR21.5        |
| 55345050    | FRM8.0   | 9278026800         | FRW7.1   | 70270840           | OA5.8   | 128041   | SCX4.9  | 154676   | SCB7.1        |
| 55345281    | FRX11.9  | 9278027200         | SCX8.4   | 70285544           | FRW9.7  | 128244   | SCX8.6  | 154709   | SCY4.4        |
| 55345300    | SCX8.0   | 9278048400         | FRW8.5   | 71101551           | OA16.4  | 128564   | W03     | 155574   | ST 1.243      |
| 55345680    | SCX7.0   | 9278103300         | SCQ6.0   | 71101552           | OA7.0   | 1364113  | ST1.014 | 155574   | VA21          |
| 5534573000  | SCX8.0   | 9278114400         | FRW7.1   | <b>TELEX</b>       |         | 138669   | SCX12.2 | 155739   | ST1.370       |
| 55345740    | SCQ6.0   | 9278132600         | SCY6.7   | 5043801            | OA10.9  | 138672   | SCX10.7 | 155739   | VA28          |
| 55346170    | SCY8.6   | 9278151900         | SCY5.0   | 5145401            | SCX13.6 | 141064   | SCX7.4  | 155752   | VPR1          |
| 5534617000  | SCY8.6   | 9278187000         | FRW9.1   | 52571000           | 069.0   | 144075   | VCR3    | 155803   | \$0614.0      |
| 5534690000  | FR15.3   | 9278190700         | SCQ6.0   | 52571001           | OA6.1   | 144258   | SCB14.0 | 155805   | FRW12.0       |
| 5534692000  | FR16.9   | 9278199200         | SCX4.6   | 86407001           | SCB16.6 | 144259   | SCA3.0  | 155806   | FRW12.0       |
| 5534767000  | FRX11.5  | 9278202800         | SCY7.3   | 86407003           | SCA4.5  | 144260   | SCX8.6  | 155807   | FRW12.0       |
| 553476800   | SCX8.0   | 9278208500         | SCY5.7   | 86407004           | SCB18.1 | 144261   | OX5.5   | 155813   | SCY7.5        |
| 5534799000  | SCX8.6   | 9278219000         | SCY5.7   | 86407005           | OB13.2  | 144262   | ST1.160 | 155826   | SCY5.0        |
| 5534810000  | FRY10.0  | 9278247200         | SCX9.2   | 86631012           | SCQ4.8  | 144262   | VA23    | 156172   | SCY4.0        |
| 55348420    | FRM7.5   | 9278254300         | SCY4.0   | 86631013           | SCA7.5  | 144263   | ST1.160 | 156678   | SCA3.2        |
| 5534853000  | SCA10.5* | 9278289300         | SCX4.3   | V063013005         | SCX8.9  | 144265   | ST.752  | 156795   | VCR33         |
| 5700075100  | FRW8.5   | 9278290300         | SCY5.2   | <b>TENNA</b>       |         | 144265   | VA200   | 156796   | SCX4.9        |
| 5700075200  | SCX7.4   | 9278293400         | SQX7.0   | 1711302003         | FRM9.7  | 144266   | FRW12.6 | 157030   | VB7           |
| 5700077700  | SCX2.9   | 9297148000         | SCQ5.3   | 171131001          | FRY8.4  | 144267   | SCQ9.8  | 157033   | ST1.014       |
| 5700078300  | SCY4.6   | 9A00245100         | ST1.130  | 171131002          | FRM10.5 | 144598   | SCX8.0  | 157033   | VA40          |
| 5700166300  | SCY5.0   | 9A00245100         | VA150    | 171131003          | FRY10.7 | 144604   | VCR 1   | 157053   | SCQ5.3        |
| 5700166700  | FRY10.0  | 9A00246600         | SCA2.3   | 171131003          | FRY10.7 | 144605   | FRW12.6 | 157061   | SCA3.2        |
| 5700388200  | FRX10.5  | 9A00454100         | VPR4     | 171131005          | SCQ2.5  | 144606   | FRW12.6 | 157062   | SCA3.0        |
| 5700393900  | SCY7.8   | 9A00462990         | FRY11.5  | 171131008          | SCX7.0  | 144606   | SCX3.2  | 157062   | FRZ11.0       |
| 5700584800  | SCY4.0   | 9A00463500         | FRW8.0   | 171131009          | FR8.4   | 144958   | SCY4.4  | 157064   | SCA3.2        |
| 5700584900  | SCX4.6   | 9A00463600         | SQ1310.0 | 171131010          | FR8.4   | 145709   | FRW12.6 | 157065   | SCY15.6       |
| 5700585000  | FRW6.5   | 9A00465500         | FR3.6    | 171131010          | FR8.4   | 146962   | FRW12.6 | 157068   | VCR25 •       |
| 5700632300  | SCY5.0   | 9A01113700         | FRQ11.2  | 171131010          | FR8.4   | 146967   | FRW12.6 | 158190   | ST1.165       |
| 5700633700  | SCQ6.0   | 9A01114500         | SCQ6.5   | 171131017          | FR8.8   | 146968   | FRW12.6 | 158190   | VA44          |
| 5700633900  | FRW7.3   | 9A01116900         | SCA7.5   | 171131020          | FR8.8   | 146969   | FRW12.6 | 158917   | SCA3.0        |
| 5700646100  | FRW10.1  | 9A01119700         | VPR4     | 171131022          | FR8.8   | 147060   | VA46    | 158918   | SCA2.3        |
| 5700646200  | SCX5.5   | 9A01122900         | SCA14.1  | 171131034          | FR8.8   | 147063   | ST.390  | 160018   | ST1.914       |
| 5700646300  | SCQ6.0   | 9A01126300         | VCR22    | 171131034          | FR8.8   | 147063   | VA03    | 160806   | VPR18         |
| 5700647200  | SCY4.2   | 9A01128700         | VCR22    | 171131035          | FR8.8   | 147079   | SCX4.6  | 161757   | VCR5          |
| 5700698500  | FRW9.2   | 9A03903400         | SCA8.9   | 171131037          | FR8.8   | 147079   | SCX3.5  | 162528   | FRW8.8        |
| 5700759500  | SCY6.3   | 9A03914600         | SCA4.0   | 171131038          | FR8.8   | 147080   | VPR6    | 162662   | ST1.211       |
| 5700772100  | SCQ5.6   | <b>TECHNICOLOR</b> |          | 171131040          | FR8.8   | 147138   | SCA7.5  | 162662   | VA30          |
| 5700772300  | FR8.2    | 5500100            | OB10.9   | 171131045          | FR8.8   | 147756   | SCX2.9" | 162961   | VPR18         |
| 5700793300  | SCA6     | 5500200            | OB14.0   | 171131046          | FR8.8   | 147756   | FRW12.6 | 162961   | ST1.014       |
| 5700793400  | SCQ3.6   | 5500500            | SCA8.6   | 171131047          | FR8.8   | 147880   | FRW12.6 | 162990   | SCA13.6       |
| 570803901   | VPR20    | 5500503            | OB12.4   | <b>THOMSON</b>     |         | 147881   | FRW12.6 | 163809   | SCA3.2        |
| 57080917200 | SCX4.6   | 5500509            | OB8.0    | 101148             | FR2.0   | 147882   | FRW12.6 | 163879   | SCA3.2        |
| 57080917300 | FRW6.5   | 5500511            | OB7.0    | 101445             | WB08    | 147883   | SCA9.6  | 163880   | SC52.5        |
| 57081277500 | FRM9.7   | 5500514            | OB7.7    | 101457             | OC10.5  | 147916   | SCB14.0 | 163895   | FRZ11.0       |
| 57081621700 | FRW7.3   | 5500600            | OB1.7    | 101458             | FR2.0   | 148193   | ST1.243 | 163896   | SCA13.6       |
| 57081689400 | FRW9.6   | 5500900            | SQB18.1  | 10292              | 0614.0  | 148193   | VA02    | 164089   | VA49          |
| 57081694100 | FRW8.8   | 5501100            | SCB21.2  | 105392             | OS014.9 | 148580   | ST1.330 | 164113   | ST1.014       |
| 57081747500 | FRW8.8   | 5501200            | SCB14.0  | 107093             | 087.6   | 148580   | VA26    | 164113   | VA40          |
| 57081769200 | FR8.2    | 5501300            | SC1310.5 | 110292             | 0813.2  | 148597   | VPR1    | 164425   | SCA6.1        |
| 57081840600 | FRW7.7   | <b>TECHNICS</b>    |          | 110625             | OA8.2   | 148664   | SCA4.5  | 164447   | SCQ7.2        |
| 5800019800  | SCY7.8   | RDV108ZA           | FR8.2    | 110754             | OA8.2   | 148666   | SCA13.2 | 164757   | VCR5          |
| 5800034800  | SCY6.5   | SFG B3211          | FRX22.4  | 11092              | 0814.0  | 148666   | SCQ6.5  | 165201   | OA14.9        |
| 5800036300  | SCX2.4   | <b>TEKNIKA</b>     |          | 11206A             | 0512.4  | 148668   | SCX8.6  | 165202   | 066.6         |
| 5800063100  | FRX11.5  | VDVS0042           | SCB10.0  | 116810             | 0813.2  | 148773   | VCR26   | 165856   | FRM9.6        |
| 5800104100  | SCX2.9   | VDVS0043           | SCX6.2   | 116842             | 005.4   | 148809   | VB3     | 165860   | <b>0813.2</b> |
| 5800106700  | SCY7.8   | VDVS0044           | SCB10.0  | 116847             | OB14.0  | 149026   | FR21.5  | 165993   | OA4.0         |
| 5800106800  | SQO6.7   | VDVS0047           | SCA8.9   | 116849             | OB10.9  | 149045   | FR2.0   | 165994   | SCX8.6        |
| 5800106900  | FR8.2    | VDVS0048           | SCA10.0  | 116857             | OB13.2  | 149235   | SCA13.6 | 166221   | FRM7.5        |
| 5800275200  | FRY11.5  | VDVS0049           | SCA8.9   | 116865             | OA12.4  | 149389   | VCR2    | 166222   | OA6.6         |
| 5800275300  | SCQ6.0   | VDVS0052           | SCA8.9   | 116882             | 0814.0  | 149432   | SCY3.2  | 166260   | SC B12.1      |
| 5800291300  | SCQ3.6   | VDVS0053           | SC B9.5  | 116887             | 01314.0 | 149639   | SCY3.5  | 166498   | FRM14.0       |
| 5800342700  | SCY6.7   | VXLS0383           | VA215    | 117240             | SCX7.0  | 150569   | SCA8.6  | 166647   | SCX4.0        |
| 5800390700  | SCX2.9   | VXPS0116           | ST1.165  | 117241             | SCX7.4  | 150570   | SCQ4.8  | 166796   | SCA10.5       |
| 5800419200  | SCQ6.5   | VA27               | VA27     | 120525             | FRM16.8 | 150571   | SCQ5.8  | 166797   | SCA10.0       |
| 5800591300  | SCQ3.6   |                    |          | 120619             | FRM11.2 | 150572   | SCY4.2  | 166860   | OB13.2        |
| 5800597900  | SCQ6.5   |                    |          | 120670             | SCA8.9  | 150614   | ST1.113 | 167221   | FRX7.8        |
| 5800603700  | SCX8.4   |                    |          | 120671             | SCA7.5  | 150614   | VA41    | 167222   | OA6.1         |
| 5800642700  | SCY6.7   |                    |          |                    |         | 150650   | ST.670  | 167260   | SCA12.5       |
|             |          |                    |          |                    |         | 150650   | VA42    | 167347   | FRM10.5       |
|             |          |                    |          |                    |         | 152412   | SCA13.2 | 167362   | SCX10.7       |

= Part of the Assy

= Kit May Not Include Tires

= Part of the Assy



# THOMSON ... THOMSON

| MFG. P/N | PRB NO. | MFG. P/N | PRB NO.  | MFG. P/N  | PRB NO.  | MFG. P/N | PRB NO. | MFG. P/N | PRB NO. |
|----------|---------|----------|----------|-----------|----------|----------|---------|----------|---------|
| 167498   | FRM14.0 | 189650   | SCA4.0   | 206972    | VPR26    | EA1X1007 | SCY4.2  | EA1X785  | SCX4.6  |
| 167647   | SCX4.0  | 190063   | SCB11.6  | 207493    | VA763    | EA1X1008 | SCY4.6  | EA1X789  | SCX3.2  |
| 167721   | FRM7.5  | 190749   | SCA4.5   | 207655    | VPR23    | EA1X1009 | SCX8.4  | EA1X79   | SCX8.9  |
| 167756   | SCA8.9  | 190895   | VCR33    | 207799    | VA760    | EA1X1010 | SCY7.5  | EA1X796  | FRX9.6  |
| 167782   | SCQ2.5  | 191091   | VCR23    | 208001    | VPR5     | EA1X1011 | SCY4.2  | EA1X80   | SCX9.2  |
| 167796   | SCA10.5 | 191252   | SCQ4.0   | 208218    | OB1.5    | EA1X1015 | SCX4.6  | EA1X801  | FRX9.7  |
| 167952   | FRM11.5 | 191253   | FRW7.1   | 208737    | SCQ4.0   | EA1X1016 | SCY9.2  | EA1X803  | SCY4.4  |
| 168040   | OC9.8   | 191341   | V772     | 208882    | ICP-N38  | EA1X1020 | SCX5.5  | EA1X805  | SCQ6.7  |
| 168041   | 0A4.6   | 191355   | VPR18    | 209449    | VCR24    | EA1X1021 | SCY4.2  | EA1X806  | SCY9.0  |
| 168875   | SCX10.7 | 191368   | VA758    | 209452    | VCR24 &  | EA1X1022 | SCY4.0  | EA1X808  | SCY6.7  |
| 169130   | 0A8.2   | 192179   | SCA8.1   |           | VCR33    | EA1X1024 | SCY7.3  | EA1X810  | SCY5.5  |
| 169131   | SCX4.0  | 192236   | VPR9     | 210841    | VA763    | EA1X1025 | SCY4.6  | EA1X812  | FRW9.1  |
| 169297   | 0A9.0   | 192242   | ST1.152  | 211283    | SCQ4.8   | EA1X1026 | SCY4.6  | EA1X814  | FRW8.5  |
| 169447   | SCX2.6  | 192242   | VA54     | 211287    | SCQ2.5   | EA1X1030 | SCY4.2  | EA1X815  | SCY5.7  |
| 169752   | FRX9.7  | 192478   | VPR6     | 211575    | SCC12.6  | EA1X1031 | SCX5.5  | EA1X816  | SCQ6.0  |
| 169967   | 0A6.1   | 192858   | SC B9.2  | 211710.   | ST.773   | EA1X1032 | SCX4.6  | EA1X817  | SCY4.6  |
| 170228   | SCA8.9  | 193145   | SCB2.5   | 211767    | ST1.165  | EA1X1033 | SCX7.0  | EA1X818  | SCY3.5  |
| 170667   | SCX10.7 | 193687   | SCB3.6   | 211767    | VA27     | EA1X1035 | SCY4.2  | EA1X835  | SCY6.0  |
| 170909   | SCX10.7 | 193995   | VPR18    | 211787    | ST.670   | EA1X1037 | SCY4.2  | EA1X836  | FRW10.1 |
| 171068   | 0A6.1   | 194010   | VCR24    | 211788    | SCB10.0  | EA1X1038 | SCX5.5  | EA1X837  | SCY5.0  |
| 171069   | 0A6.1   | 194011   | VCR33    | 21180     | SCQ5.6   | EA1X1039 | SCY6.7  | EA1X838  | FRX11.5 |
| 171143   | FRX11.7 | 194093   | SCQ5.1   | 211800    | SCQ5.6   | EA1X1042 | SCY6.7  | EA1X839  | SCQ6.0  |
| 171220   | FRM11.5 | 194883   | VA45 &   | 211805    | SCA8.9   | EA1X1043 | SCY4.6  | EA1X841  | FRW9.1  |
| 171534   | FRM12.1 |          | VA47     | 211832    | SCQ6.5   | EA1X1044 | SCY7.3  | EA1X845  | SCA8.6  |
| 171633   | FRM11.5 | 194965   | VPR18    | 212274    | SCA4.0   | EA1X1047 | SCX4.6  | EA1X850  | SCY6.0  |
| 171762   | SCX8.6  | 194968   | VCR24    | 212475    | SCQ3.0   | EA1X1048 | SCX8.9  | EA1X851  | SCX2.9  |
| 171863   | SCA8.6  | 195283   | VCR33    | 212503    | SC B10.0 | EA1X1050 | SCY6.0  | EA1X856  | FRW9.2  |
| 172348   | SCA8.6  | 195284   | VCR24    | 212888    | VCR24    | EA1X1051 | SCY4.0  | EA1X858  | SCY4.4  |
| 173695   | SCA6.1  | 195286   | VCR24    | 213847    | VPR27    | EA1X1055 | SCX4.6  | EA1X861  | SCY7.8  |
| 173715   | SCA3.0  | 195651   | VPR18    | 215670    | WP66     | EA1X1056 | SCX4.9  | EA1X862  | SCY5.2  |
| 174717   | VPR18   | 196489   | V772     | 215671    | WP67     | EA1X1058 | SCY4.4  | EA1X864  | SCX7.4  |
| 174758   | SCQ4.8  | 196213   | V777     | 215989    | VPR8     | EA1X1059 | SCX3.2  | EA1X866  | FRW7.7  |
| 174759   | SCQ3.0  | 196738   | SCA4.2   | 217888    | SC05.1   | EA1X1064 | SCX4.9  | EA1X868  | SCY6.5  |
| 174815   | VCR25   | 196861   | VP R2    | 218259    | SCA4.0   | EA1X1066 | SCQ3.0  | EA1X870  | SCX8.4  |
| 177194   | VA45    | 197849   | SCQ2.5   | 218351    | VCR24    | EA1X1068 | SCY6.0  | EA1X871  | FRM9.0  |
| 177197   | VA45    | 198893   | SCA5.4   | 218488    | SCA4.2   | EA1X1069 | SCX8.9  | EA1X872  | SCX3.2  |
| 177206   | SCQ5.3  | 198978   | VCR24    | 218488    | SCQ4.3   | EA1X1070 | SCX6.2  | EA1X873  | SCY9.0  |
| 177206   | VA47    | 198980   | VCR24    | 219769    | WP69     | EA1X1071 | SCY6.0  | EA1X874  | SCY6.0  |
| 177208   | SCB2.6  | 198981   | VCR33    | 219770    | WP68     | EA1X1076 | SCY6.0  | EA1X876  | SCY5.1  |
| 179476   | VPR18   | 199095   | VKT84**  | 221925    | SCY4.2   | EA1X1077 | SCY3.5  | EA1X878  | SCY7.4  |
| 179848   | SCA2.3  | 199332   | VKT85**  | 222509    | SCQ2.2   | EA1X1145 | SCY6.5  | EA1X879  | SCY4.4  |
| 180460   | SCQ3.0  | 199333   | VKT88**  | 224944    | VPR23    | EA1X1159 | SCY9.2  | EA1X880  | SCX5.5  |
| 180572   | FRW7.1  | 199334   | VKT165** | 225034    | SC03.6   | EA1X1160 | SCX12.2 | EA1X881  | SCY6.5  |
| 180575   | SCQ4.3  | 199335   | VKT113** | 225036    | SC07.2   | EA1X1161 | SCQ5.6  | EA1X883  | SCY7.4  |
| 181203   | VPR18   | 199336   | VKT160** | 226658    | FRW8.0   | EA1X1162 | SCX7.0  | EA1X884  | SCX4.6  |
| 182197   | SCX4.0  | 199337   | VKT18**  | 226659    | SCX5.5   | EA1X1163 | SCY4.2  | EA1X885  | SCX4.6  |
| 182198   | FRW7.1  | 199347   | VKT170** | 228638    | 0A9.4    | EA1X1166 | SCY4.2  | EA1X891  | SCY7.0  |
| 182944   | VPR18   | 1A10079  | SCY4.2   | 234320    | GT11.7   | EA1X1168 | SCY4.6  | EA1X892  | SCX8.9  |
| 182994   | SCB82   | 1A10091  | SCX7.0   | 234321    | GT8.5    | EA1X1169 | SCX5.5  | EA1X893  | SCX10.7 |
| 183053   | VCR24   | 1A10256  | SCY5.0   | 239306    | FRF13.4  | EA1X1172 | SCY7.5  | EA1X895  | SCX8.0  |
| 183264   | SCY4.2  | 1A10257  | SCY4.6   | 240779    | 0A12.4   | EA1X1175 | SCX6.2  | EA1X897  | SCX4.6  |
| 183779   | SCQ4.0  | 1A10604  | SCX7.0   | 250200    | VPR26    | EA1X1176 | SCQ6.0  | EA1X903  | SCY6.5  |
| 184412   | SCY4.4  | 1A10813  | SCX6.2   | 39911     | W03      | EA1X1182 | SCY6.5  | EA1X906  | SCQ6.7  |
| 184461   | VCR33   | 1A11164  | SCY6.0   | 40x41     | OB14.0   | EA1X1183 | SCY6.5  | EA1X907  | SCY5.5  |
| 184464   | VCR25   | 1A11210  | SCX9.5   | 418489    | FR F13.4 | EA1X1185 | SCX7.0  | EA1X908  | SCY4.0  |
| 184465   | VCR25   | 1A11212  | SCY5.7   | 51469681  | FRW12.6  | EA1X1193 | SCY4.2  | EA1X913  | SCY2.2  |
| 184717   | SCA8.1  | 1A11574  | SCY5.2   | 52853     | FRF14.5  | EA1X1287 | SCX7.0  | EA1X914  | SCX7.0  |
| 185042   | VCR25   | 1A11747  | SCY4.0   | 709679    | FR12.6   | EA1X1312 | SCY4.2  | EA1X915  | FRW9.2  |
| 185043   | VCR25   | 1A11769  | SCY7.3   | 740097    | SCX3: 5  | EA1X1314 | SCY4.4  | EA1X916  | SCQ5.3  |
| 185200   | VCR33   | 1A11805  | FRX20.7  | 740102    | SCQ6.5   | EA1X1370 | SCY6.7  | EA1X917  | SCX8.9  |
| 185208   | ICP-F38 | 1A13514  | SCA4.0   | 740116    | SCX8.0   | EA1X1388 | SCY1.5  | EA1X920  | FRX9.0  |
| 185271   | SCA8.9  | 1A13543  | SCA3.2   | 740255    | FRM12.1  | EA1X1398 | SCY7.3  | EA1X923  | SCX4.9  |
| 185272   | SCB9.5  | 1A13767  | SCY6.0   | 740565    | FRM10.5  | EA1X1399 | SCY4.0  | EA1X924  | SCX7.0  |
| 185421   | VA215   | 1A16073  | SCQ2.2   | 740591    | FRM12.1  | EA1X1423 | SCY5.2  | EA1X925  | SCY3.5  |
| 186141   | SCY4.2  | 1A19911  | SCX7.0   | 740794    | 0A4.2    | EA1X1424 | SCY4.2  | EA1X926' | SCY4.6  |
| 186465   | VPR9    | 200087   | V772     | 740808    | SCA8.9   | EA1X146  | FR8.8   | EA1X927  | SCQ4.3  |
| 186480   | ST1.152 | 201040   | VA763    | 740913    | FRM10.5  | EA1X1466 | SCY3.5  | EA1X932  | SCY4.8  |
| 186480   | VA56    | 201042   | SCB9.5   | 741636    | SCQ6.5   | EA1X1467 | SCX8.0  | EA1X934  | SCX9.5  |
| 186485   | FRW9.7  | 201102   | VPR31    | 741644    | SCX4.0   | EA1X1470 | SCX8.4  | EA1X935  | SCX8.0  |
| 186486   | SCA9.2  | 201191   | V767     | 742319    | SCA8.9   | EA1X1505 | SCX5.1  | EA1X936  | SCY3.5  |
| 186987   | SCY4.2  | 201879   | SCA4.5   | 76043E    | 0A8.2    | EA1X155  | FRM11.2 | EA1X937  | SCY6.7  |
| 187107   | SCX5.5  | 201989   | VA760    | 8034      | FF12.6   | EA1X240  | SCX8.9  | EA1X939  | SCQ3.6  |
| 187756   | SCA8.6  | 202113   | VPR18    | 831412B   | FRF17.0  | EA1X296  | FRX9.7  | EA1X951  | SCX4.0  |
| 187878   | ST1.152 | 202146   | SCA9.6   | 8340779   | 0A12.4   | EA1X340  | SCX8.9  | EA1X952  | SCX4.9  |
| 187878   | VA56    | 202432   | VCR33    | 98799     | WB09     | EA1X341  | SCQ7.2  | EA1X954  | SCY4.6  |
| 187882   | FRW9.7  | 202569   | VPR26/   | 98830     | 007.4    | EA1X403  | SCQ7.2  | EA1X963  | SCX7.4  |
| 187883   | SCA9.2  |          | VPR43    | E1X1465   | SCY5.2   | EA1X507  | SCY3.2  | EA1X968  | SCY4.6  |
| 188188   | VA215   | 203045   | VCR24    | EA01X1287 | SCX7.0   | EA1X711  | SCQ5.6  | EA1X970  | SCY4.2  |
| 188638   | VCR23   | 203046   | VCR24    | EA1163    | OB14.0   | EA1X712  | SCX4.6  | EA1X972  | SCX9.5  |
| 188737   | SCQ4.3  | 204077   | SCX5.1   | EA1164    | 0A4.0    | EA1X734  | SCX7.4  | EA1X976  | SCY4.6  |
| 188738   | SCB81   | 206105   | V772     | EA1240    | 0614.0   | EA1X746  | SCA4.5  | EA1X977  | SCY5.2  |
| 189011   | VPR6    | 206133   | SCB5.7   | EA1X1002  | SCX8.6   | EA1X747  | SCQ6.0  | EA1X979  | SCX5.1  |
| 189013   | FRW6.5  | 206698   | WB09     | EA1X1003  | SCY4.4   | EA1X749  | SCX3.2  | EA1X980  | CQ10.0  |
| 189014   | SCX4.6  | 206948   | SCA3.0   | EA1X1005  | SCY7.5   | EA1X750  | SCX10.5 | EA1X981  | SCY7.5  |
| 189292   | V778    | 206949   | SCC12.6  | EA1X1006  | SCY8.2   | EA1X774  | SCX8.0  | EA1X982  | SCX4.9  |

\* = Replacement Belt

= Kit May Not Include Tires

= Part of the Assy

Mfg.# to PRB#



# THOMSON ... TOSHIBA

| MFG. P/N  | PRB NO. | MFG. P/N   | PRB NO.  | MFG. P/N   | PRB NO. | MFG. P/N       | PRB NO.        | MFG. P/N | PRB NO.  |         |
|-----------|---------|------------|----------|------------|---------|----------------|----------------|----------|----------|---------|
| EA1X984   | SCX7.4  | EW2X752    | ST1.370  | SKI D0265  | VA200   | <b>THORENS</b> |                | 25755221 | SCQ10.0  |         |
| EA1X987   | SCY4.2  | EW2X752    | VA28     | \$ KID0574 | VA21    |                | CB503          | FR20.0   | 25755222 | FRY17.2 |
| EA1X988   | SCY7.3  | EW2X762    | ST1.230  | S KI D0580 | VA26    |                | 08908          | FRM12.1  | 25755226 | SCY6.0  |
| EA1X993   | SQO3.6  | EW2X762    | VA25     | SKID0650   | VA42    |                | 08965          | FRM12.1  | 25755236 | FRM11.5 |
| EA1X997   | SCAI2.0 | EW2X850    | SCA5.4   | SKI D0674  | VA20    |                |                |          | 25755237 | SCX12.2 |
| EA2X1537  | SCX4.6  | EW2X876    | SCB14.0  | SKI D0683  | VA25    |                |                |          | 25755240 | SCX9.5  |
| EA2X1914  | SCY4.2  | EW2X906    | SCSI 0.0 | SKID0739   | VA28    |                | <b>TOSHIBA</b> |          | 25755241 | SCX7.0  |
| EA2X1915  | SCY7.3  | EW2X907    | SCQ6.5   | SKI D0767  | VA27    |                | 20728016       | FRX16.8  | 25755242 | SCX5.1  |
| EA3742    | FR8.8   | EW2X953    | ST1.165  | SKI D2501  | VA60    |                | 20728021       | FRY23.6  | 25755243 | SCY4.6  |
| EA4028    | FRM11.2 | EW2X953    | VA22     | SKID2502   | VA22    |                | 20728023       | FRY23.6  | 25755247 | SCQ10.0 |
| EA40X190  | FRM12.1 | EW2X983    | SCB2.5   | SKID2503   | VA61    | 20728026       | FRX25.0        | 25755257 | FRM11.5  |         |
| EA40X26   | OB13.2  | EW41X32    | VCR1     | SKID2504   | VA01    | 20728121       | FRX25.0        | 25755264 | SCY11.7  |         |
| EA40X311  | 005.0   | EWA1X789   | SCX3.2*  | SKI D2507  | VAI2    | 20728137       | FR23.6         | 25755266 | SCX8.0   |         |
| EA40X36   | OB10.9  | ICP-N38    | ICP-N38  | SKI D2508  | VA10    | 20728611       | FRX25.0        | 25755267 | SCY5.2   |         |
| EA5M2     | PRO2    | ICPN38     | ICP-N38  | SKID2510   | VA02    | 257297         | SCX8.0         | 25755272 | SCY6.3   |         |
| EP2X512   | ST.685  | MDF8VA3421 |          | SKI D2511  | VA201   | 257298         | SCY6.7         | 25755279 | SCX7.0   |         |
| EW02X0492 | SCB8.4  | RMW003     | FR2.0    | SKID2512   | VA18    | 257307         | \$CX13.6       | 25755284 | SCQ4.0   |         |
| EW02X0580 | SCB12.5 | RMW004     | FR2.2    | SKI D2513  | VA204   | 257308         | SCX7.4         | 25755285 | SCY7.5   |         |
| EW02X0582 | SCX6.2  | RT1234     | 0A6.1    | SKID2516   | VA03    | 257310         | SCX10.5        | 25755288 | \$CX2.6  |         |
| EW02X0953 | ST1.165 | RT1236     | SCX8.9   | SKI D2518  | VA202   | 257314         | SCQ10.0        | 25755290 | SCX7.0   |         |
| EW02X0953 | VA27    | RT16303    | OB11.7   | SKI Q2522  | VA30    | 257316         | FRX12.7        | 25755291 | SCY12.7  |         |
| EW02X3033 | SCQ4.3  | RT16337    | OB13.2   | SKI D2523  | VA08    | 257325         | SCX9.5         | 25755292 | SCX10.7  |         |
| EW2X011   | SCX5.1  | RT16398    | QC5.4    | S KI D2525 | VA104   | 257326         | FRY10.7        | 25755295 | SCY9.0   |         |
| EW2X0454  | W/6.3   | RT2236     | SQX8.9   | SKI D2529  | VA105   | 257328         | SCX10.5        | 25755296 | SCQ8.6   |         |
| EW2X0512  | ST.685  | RT2449     | 0A7.4    | SKI 42538  | VA90    | 257329         | SCX12.2        | 25755298 | SCX7.0   |         |
| EW2X0578  | FRW12.0 | RT250      | 0A10.9   | SKI D2542  | VA07    | 257335         | SCX7.4         | 25755307 | KX14.0   |         |
| EW2X0953  | ST1.165 | RT2507     | SCX8.0   | SKI Q2552  | VA1 00  | 257336         | SCY5.2         | 25755351 | SCY7.8   |         |
| EW2X0953  | VA27    | RT2509     | QA10.9   | SKI Q2556  | VA96    | 257342         | SOQ5.6         | 25755379 | SCX7.Q   |         |
| EW2X11    | SCX5.1  | RT2551     | 0816.4   | SKI D2557  | VA504   | 257348         | SCX8.0         | 25755393 | SCY7.5   |         |
| EW2X180   | ST1.191 | RT2820     | FRY12.0  | SKI D2558  | VA97    | 257351         | SCX7.4         | 25755416 | SCY3.5   |         |
| EW2X201   | ST.79Q  | RT3408     | SCX4.9   | SKI D2560  | VA23    | 257352         | FRY10.4        | 25755417 | SCY6.0   |         |
| EW2X2594  | SC B8.2 | RT3546     | SCX8.9   | SKI Q2561  | VA50    | 257373         | FRW7.0         | 25755434 | FRW9.6   |         |
| EW2X2597  | SCA4.5  | RT36Q7     | FRW8.5   | SKPL6200   | VA41    | 257374         | SCY5.2         | 25755443 | SCY4.2   |         |
| EW2X268   | SCY9.0  | RT3758     | SCX10.7  | SKPL6201   | VA13    | 257376         | SCX3.2         | 25755482 | 5006.0   |         |
| EW2X2783  | SCA8.9  | RT3798     | FRM10.5  | SKPL6202   | VA09    | 257377         | SCX7.4         | 25755483 | SCQ3.0   |         |
| EW2X2786  | VA215   | RT434      | FRX7.5   | SKPL6204   | VA46    | 257379         | SCX7.0         | 25755490 | SCY5.2*  |         |
| EW2X3032  | FRW7.1  | RT4349     | FRW9.7   | SKPL6206   | VA04    | 257380         | FRW9.1         | 25755506 | SCX9.5   |         |
| EW2X305   | ST1.113 | RT4833     | FRM12.1  | SKPL6207   | VA47    | 257382         | SCX8.9         | 25755507 | SCY5.2   |         |
| EW2X305   | VA41    | RT6270     | 0A5.4    | SKPL6209   | VA49    | 257387         | SCX5.1         | 25755515 | FRW6.5   |         |
| EW2X3055  | SCQ4.3  | RT6282     | FRM9.6   | SKPL6215   | VA54    | 257389         | SCX9.5         | 25755521 | SCY5.0   |         |
| EW2X318   | \$CO5.3 | RT6880     | QA5.8    | SKPRO203   | VPR18   | 257404         | SCY6.0         | 25755522 | SCY5.2   |         |
| EW2X320   | SCA3.2  | RT6894     | FRW8.5   | SKPRO597   | VPR1    | 257414         | SCY6.0         | 25755527 | FRW9.2   |         |
| EW2X321   | SCA3.0  | SKBK0095   | VKT84**  | SKPR3501   | VPR8    | 257416         | SCY3.5         | 25755528 | SCQ5.3   |         |
| EW2X322   | FRZ11.0 | SKBK0332   | VKT85**  | SKPR3503   | VPR10   | 257417         | SCY6.0         | 25755529 | SCY7.0   |         |
| EW2X323   | SCA13.6 | SKBK0333   | VKT88**  | SKPR3506   | VPR5    | 257418         | FRM9.6         | 25755530 | FRW10.1  |         |
| EW2X327   | SCX4.6  | SKBK0335   | VKT113** | SKPR3508   | VPR2    | 257430         | FRW10.1        | 25755531 | SCY6.0   |         |
| EW2X335   | ST1.014 | SKBK0336   | VKT160** | SKPR3510   | VPR7    | 257431         | SCY8.6         | 25755537 | SCY8.0   |         |
| EW2X335   | VA40    | SKBK0337   | VKT18**  | SKPR3513   | VPR17   | 257434         | FRM9.6         | 25755538 | SCX5.5   |         |
| EW2X358   | ST1.243 | SKBK0347   | VKT170** | SKTR3005   | ST.390  | 257435         | SCY4.6         | 25755548 | SCX7.0   |         |
| EW2X358   | VA02    | SKBK0501   | VKT159** | SKTR3006   | ST.463  | 257441         | FRW8.0         | 25755549 | SCX8.0   |         |
| EW2X370   | SCA14.1 | SKBK0502   | VKT147** | SKTR3008   | ST.515  | 257442         | SCY4.2         | 25755551 | SCX7.0   |         |
| EW2X382   | SCB14.0 | SKBK0503   | VKT162** | SKTR3009   | ST.599  | 257448         | FRW8.5         | 25755552 | SCY5.0   |         |
| EW2X383   | SCQ9.6  | SKBK0506   | VKT163** | SKTR3010   | ST.670  | 257457         | SCY5.2         | 25755555 | FRW9.2   |         |
| EW2X384'  | FRW12.6 | SKBK0507   | VKT164** | SKTR3011   | ST.675  | 257466         | SCY5.2         | 25755564 | SCX5.5   |         |
| EW2X385   | SCA3.0  | SKBK0508   | VKT151** | SKTR3012   | ST.685  | 257481         | FRW8.5         | 25755573 | SCY9.0   |         |
| EW2X386   | SC: →   | SKBK0509   | VKT139** | SKTR3015   | ST.689  | 257482         | SCQ6.0         | 25755578 | SCY4.6   |         |
| EW2X387   | OX5.5   | SKBK0511   | VKT148** | SKTR3016   | ST.752  | 257483         | SCX2.9         | 25755579 | SCY5.2   |         |
| EW2X388   | SCY9.0  | SKBK0512   | VKT150** | SKTR3018   | ST.753  | 257484         | SCY4.6         | 25755581 | SCY6.3   |         |
| EW2X389   | SCQ4.8  | SKBK0512   | VKT152** | SKTR3020   | ST.776  | 257497         | SCX8.0         | 25755589 | SCX10.5  |         |
| EW2X390   | SCB5.7  | SKBK0513   | VKT100** | SKTR3021   | ST.850  | 257503         | FRW8.5         | 25755590 | SCY416   |         |
| EW2X391   | FRQ11.2 | SKBK0515   | SCB11.6  | SKTR3022   | ST.925  | 257504         | SCY5.2         | 25755592 | SCX7.0   |         |
| EW2X392   | FRW12.0 | SKBK0516   | SCA8.1   | SKTR3025   | ST.948  | 257505         | SCY3.5         | 25755594 | SCY5.0   |         |
| EW2X393   | SCX7.4  | SKBK0517   | CKT2     | SKTR3027   | ST.977  | 257506         | SCA9.2         | 25755600 | FRW8.0   |         |
| EW2X396   | SCY6.0  | SKBK0519   | SCA5.4   | SKTR3028   | ST.985  | 257507         | SCY5.2         | 25755663 | SCQ10.0  |         |
| EW2X407   | SCA13.2 | SKBK052Q   | SC B9.5  | SKTR3029   | ST.988  | 257515         | FRX6.7         | 25755718 | FRX25.0  |         |
| EW2X408   | SCA4.5  | \$KKB0521  | SCX5.1   | SKTR3033   | ST1.113 | 257521         | SCY4.6         | 25755790 | SCY5.2*  |         |
| EW2X409   | FRW12.0 | SKBK0522   | VKT175** | SKTR3034   | ST1.118 | 257522         | SCY5.2         | 257564   | SCY5.2   |         |
| EW2X410   | SCB14.0 | SKBK0525   | VKT177** | SKTR3035   | ST1.130 | 257525         | FRW10.1        | 257578   | SCY4.6   |         |
| EW2X415   | SCX4.9  | SKBK0526   | CKT1     | SKTR3038   | ST1.152 | 2575501A       | FRM11.0        | 257579   | SCY5.2   |         |
| EW2X438   | ST1.370 | SKBK0527   | VKT176** | SKTR3042   | ST1.160 | 25755109       | OC11.7         | 257580   | SCY4.6   |         |
| EW2X438   | VA28    | SKBK0530   | CKT1     | SKTR3043   | ST1.165 | 25755122       | OC13.2         | 25759006 | SCY7.0   |         |
| EW2X454   | SCY6.3  | SKBK0531   | VKT156** | SKTR3046   | ST1.18  | 25755123       | OC9.8          | 25759008 | SCY5.7   |         |
| EW2X492   | SCB8.4  | SKBK0532   | VKT161** | SKTR3048   | ST1.205 | 25755125       | SCQ11.1        | 25759013 | SCX7.4   |         |
| EW2X511   | ST1.113 | SKBK0533   | CKT1     | SKTR3049   | ST1.208 | 25755138       | SCX8.6         | 25759015 | SCX8.9   |         |
| EW2X511   | VA41    | SKBK0534   | SCA5.4   | SKTR3052   | ST1.211 | 25755139       | SCQ4.0         | 25759021 | SCQ11.1  |         |
| EW2X512   | ST.670  | SKGR7302   | VA210    | SKTR3056   | ST1.230 | 25755150       | FRM11.2        | 25759023 | SCQ6.0   |         |
| EW2X512   | VA42    | S KOR7304  | VA505    | SKTR3059   | ST1.243 | 25755151       | O8.2           | 25759026 | SCY6.3   |         |
| EW2X538   | SCY6.7  | SKGR7305   | VA501    | SKTR3060   | ST1.330 | 25755154       | SCX8.0         | 25759028 | SCX5.5   |         |
| EW2X576   | SCB14.0 | SKG R7308  | VA212    | SKTR3062   | ST1.350 | 25755171       | SCQ4.0         | 25759030 | SCY8.6   |         |
| EW2X577   | FRW12.0 | SKGR7310   | VA94     | SKTR3063   | ST1.370 | 25755187       | SCY6.5         | 25759037 | SCX9.5   |         |
| EW2X578   | FRW12.0 | SKGR7321   | VA98     | SKTR3065   | ST1.46  | 25755190       | OA9.4          | 25759041 | SCX9.5   |         |
| EW2X579   | FRW12.0 | SKID0113   | VA40     | VDVS0044   | SCB2.5  | 25755192       | SCQ11.1        | 25759043 | FRW10.1  |         |
| EW2X580   | SQB12.5 | SKID0188   | VA215    | VXP0343    | ST.470  | 25755203       | FRQ11.2        | 25759046 | SCX8.4   |         |
| EW2X582   | SCX6.2  | SKID0190   | VA44     | VXP0521    | ST1.165 | 25755204       | SCX7.0         | 25759047 | SCQ6.0   |         |
| EW2X638   | ST.670  | SKID0194   | VA45     | VXP0521    | VA22    | 25755210       | OA13.2         | 25759051 | SCX7.0   |         |

= Part of the Assy

\*\*= Kit May Not Include Tires

= Part of the Assy

# TOSHIBA ... WOLLENSAK

| MFG. P/N   | PRB NO.  | MFG. P/N   | PRB NO. | MFG. P/N               | PRB NO. | MFG. P/N                | PRB NO. | MFG. P/N            | PRB NO. |
|------------|----------|------------|---------|------------------------|---------|-------------------------|---------|---------------------|---------|
| 25759052   | SCY4.0   | 70342031   | FR21.6  | R22755150              | FRM11.5 | <b>VIEWLEX</b>          |         | 72P016              | OC9.0   |
| 25759071   | SCQ8.0   | 70342033   | SCX4.3  | R22755153              | SCX8.6  | 673505                  | OB11.7  | 72P019              | OA7.4   |
| 25759072   | SCY8.6   | 70342034   | SCX13.6 | R22755154              | SCA7.5  | 67370800                | OB6.1   | 72P020              | OA10.1  |
| 25759075   | SCY6.3   | 70342035   | SCA13.2 | R22755169              | SCX12.2 | 67370900                | SCA8.9  | 72P031              | OSC10.2 |
| 25759080   | SCY6.3   | 70342036   | SCA5.6  | R22755171              | OB15.6  | 67371400                | GT8.5   | 72P109              | OA7.4   |
| 25759083   | SCY6.0   | 70342037   | SCY9.2  | R22755182              | SCQ11.1 | 673719M00               | FRF9.0  | 72P195              | OC10.9  |
| 25759084   | SCY4.2   | 70342040   | SCX11.8 | R22755185              | SCY7.0  | 67372100                | OSD10.0 |                     |         |
| 25759093   | SCY6.3   | 70342051   | SCX4.3  | R22755186              | SCX10.7 | 67372200                | OC9.8   | <b>WEBSTER-ECHO</b> |         |
| 25759097   | SCX10.5  | 70342053   | OA9.4   | R22755187              | SCY6.5  | 67372300                | FRX10.9 | 14125               | OC10.9  |
| 25759099   | SCY7.0   | 70342059   | SCX4.3  | R22755192              | SCQ11.1 | A16571                  | OB3.8   | 141293              | OC12.4  |
| 25759100   | SCY2.9   | 70342060   | SCQ2.5  | R22755201              | SCX7.0  | A8682001                | FRF12.4 | 141922              | OC7.8   |
| 25759107   | SCX7.0   | 70342061   | SCY11.7 | R22755203              | FRY10.7 | B3164003                | GT11.7  | 16335               | OC9.0   |
| 25759117   | SCX7.0   | 70342064   | FRQ11.2 | R22755208              | FRM11.5 | B3164004                | GT8.5   | 17864               | OC12.4  |
| 25759118   | SCY6.5   | 70342073   | FRX4.3  | R22755247              | SCX7.0  | 8341003                 | FRF13.4 | 20481               | OAI2.4  |
| 25759120   | SCX4.6   | 70342074   | SC B7.0 | R22761196              | SCQ6.5  |                         |         |                     |         |
| 25759124   | SCY7.8   | 70342078   | SCX7.0  | R25755139              | SCQ4.0  | <b>VIKING</b>           |         |                     |         |
| 25759133   | SCY9.0   | 70342082   | FRM10.2 | R25755153              | SCX8.6  | 5043802                 | OA10.9  | 70690               | FRM11.2 |
| 25759135   | SCY8.2   | 70342083   | SCQ3.6  | R25755169186           | SCQ11.1 | 5043901                 | OA11.7  | 70691               | FR8.4   |
| 25759139   | SCX7.4   | 70342084   | SCA6.7  | R2575517102            | SCQ4.0  | 5078701                 | OA11.7  | 70692               | FR8.4   |
| 25759142   | SCX7.4   | 70342092   | FR2.7   | R2575517301            | SCQ5.6  | 5078702                 | OA10.9  | 70693               | OA8.2   |
| 25759143   | SCY8.6   | 70342099   | SCY6.5  | R2575520102            | OA5.8   | 5078703                 | OB10.9  | 70694               | SCA8.9  |
| 25759165   | SCAI2.5  | 70342100   | FRM9.6  | R2575520403            | SCX7.0  | 514501                  | OB14.0  | 70695               | OB13.2  |
| 25759166   | SCY9.0   | 70342101   | SCA4.5  | R2575520502            | SCX4.3  | 8435801                 | OA11.7  |                     |         |
| 25759175   | SCY7.5   | 70342113   | SCA8.9  | R2575520801            | FRY10.7 | 9043801                 | OB10.9  | <b>WESTERN AUTO</b> |         |
| 25759177   | SCY6.0   | 70342121   | SCA3.5  |                        |         | 0358                    | OB10.9  | MN6410A47           | FRM10.5 |
| 25759178   | SCY4.2   | 70342123   | SCQ3.6  | <b>TOYOMENKA (TMK)</b> |         | D359                    | OB10.9  | MNM6410B47          | FRM11.5 |
| 25759179   | SCY8.6   | 70342124   | SCA6.7  | 850P300005             | SCA4.2  | DA438                   | OB10.9  | MNM641A47           | FRM10.5 |
| 25759183   | SCX5.5   | 70342125   | FRM10.2 | 850P30005              | SCA4.2  | PA1043801               | OB10.9  | MNM6460A47          | FRY10.7 |
| 25759185   | FRW9.6   | 70342127   | FRM11.5 | 850P600022             | FRW9.7  | PA1043802               | OA10.9  | 0011720B34          | SCX10.7 |
| 25759201   | SCY9.2   | 70342128   | SCA14.1 | 850P700005             | SCX5.5  | PA1078702               | OA10.9  | MNM7360A37          | OA10.1  |
| 25759203   | SCX7.0   | 70342129   | SCQ6.5  | 850P700023             | SCX4.9  | PA1078703               | OB10.9  | MTC7870A86          | OA8.2   |
| 25759206   | SCY4.4   | 70342131   | SCQ5.1  |                        |         | PA1078707               | OA10.9  | MTC7950A96          | SCA8.9  |
| 25759213   | SCY10.2  | 70342132   | SCA9.2  | <b>TRUETONE</b>        |         | PA114541                | OB14.0  | NBLTH0058AFZZ       | FRM9.6  |
| 25759224   | SCY4.2   | 70342133   | SCQ5.7  | 11391                  | 007.0   | PA11517                 | OA10.1  | NBLTH0070AFZZ       | FRX9.7  |
| 25759225   | SCX7.4   | 70342134   | SCQ4.3  | 16050                  | SCX10.7 |                         |         | NBLTK0140AFZZ       | SCX8.0  |
| 25759226   | SCX6.2   | 70342135   | SCA8.6  | 16060                  | SCX2.4  |                         |         | NBLTK0152AFZZ       | SCX8.4  |
| 25759227   | SCY6.5   | 70342148   | SCB9.5  | 60440                  | 007.0   |                         |         | NEG5665A77          | FRM12.1 |
| 25759233   | SCY9.2   | 70342159   | SCA11.5 | 60450                  | 007.0   |                         |         |                     |         |
| 25759237   | SCY6.5   | 70353575   | ST1.211 | 60620                  | OAI2.4  |                         |         |                     |         |
| 25759242   | SCY9.0   | 70368350   | SCA5.4  |                        |         | <b>WESTERN ELECTRIC</b> |         |                     |         |
| 25761196   | SCQ6.5   | 70673600   | SCQ4.3  | <b>UHER</b>            |         | 24120481                | OB13.2  |                     |         |
| 257663     | SCQ 10.0 | 70673630   | FRW7.1  | 080370                 | VR11.2  |                         |         |                     |         |
| 257718     | FRY25.0  | 70673816   | FRW7.3  | 080390                 | OA10.9  | <b>WESTINGHOUSE</b>     |         |                     |         |
| 257787     | SCQ6.5   | 70678025   | SCQ4.0  | 11391                  | OB9.0   | 30287000                | OB10.9  |                     |         |
| 40342601   | SCY11.7  | 70692037   | VPR20   | 1154                   | OA8.2   | 690V031H14              | OB12.4  |                     |         |
| 5274602410 | SCA5.6   | 70692102   | VPR23   | 2005                   | VR9.0   | 690V031H16              | OB9.0   |                     |         |
| 5760772200 | SCX5.5   | 70692105   | VPR23   | 2006                   | VR4.6   | 690V031H17              | OA10.9  |                     |         |
| 70011781   | ICP-N10  | 70790025   | VPR27   | 40034                  | OB11.7  | 690V044H40              | FF12.6  |                     |         |
| 70012001   | ICP-N5   | 70790107   | SCB10.0 | 40035                  | 007.0   | 690V044H45              | OC13.2  |                     |         |
| 70031384   | VPR23    | 70790714   | VPR27   | 40036                  | 006.6   | 690V044H46              | OA8.2   |                     |         |
| 70031384   | VPR23    | 70901173   | ST.970  | 6006                   | OB14.0  | 690V059H91              | OA7.0   |                     |         |
| 70031442   | SCA8.9   | 9575115000 | FRM11.7 | 6043                   | OB11.7  | 690V083H48              | OB7.6   |                     |         |
| 70031442   | SCA8.9   | B2780202   | SCQ7.8  | 6045                   | 006.6   | 690V083H49              | OB7.0   |                     |         |
| 70114345   | VCR21    | BZ730066   | ST1.152 | 70023                  | OC16.0  | 690V084H34              | SCX8.6  |                     |         |
| 70114347   | VCR21    | BZ730066   | VA54    | 70024                  | SCQ10.0 | 690V093H77              | OA10.9  |                     |         |
| 70123083   | V757     | BZ730220   | SC 88.4 | 70043                  | SCX10.7 | 690V093H79              | OA10.9  |                     |         |
| 70123087   | V761     | BZ730574   | SCB9.5  | 70046                  | OSC10.2 | 690V098H71              | SCQ6.5  |                     |         |
| 70312132   | SCA9.2   | BZ753533   | VPR31   | 70047                  | OSC10.2 | 690V098H74              | SCX8.6  |                     |         |
| 70315132   | SCA9.2   | BZ780115   | VPR4    |                        |         | 690V098H80              | SCQ4.0  |                     |         |
| 70316057   | ST.970   | BZ780137   | SCQ6.5  | <b>UNIVERSAL</b>       |         | 690V102H17              | SCQ10.0 |                     |         |
| 70316131   | ST.948   | BZ780168   | FRQ11.2 | 26810173               | FRM10.5 |                         |         |                     |         |
| 7032121    | SCA3.5   | BZ780202   | SCA7.5  | 38510183               | SCX7.4  |                         |         |                     |         |
| 70322134   | VPR11    | BZ780239   | SCA7.5  | 38510184               | SCX4.3  |                         |         |                     |         |
| 70322207   | VPR11    | BZ780405   | VPR20   |                        |         | <b>VECTOR RESEARCH</b>  |         |                     |         |
| 70322320   | VPR20    | BZ780442   | SCA8.1  |                        |         | 0002438                 | SCQ6.7  |                     |         |
| 70323310   | VPR20    | BZ780464   | SCA10.5 |                        |         | 0002486                 | SCX4.6  |                     |         |
| 70323321   | VPR20    | BZ780493   | SCQ5.7  |                        |         | 0002590                 | FRY2.9  |                     |         |
| 70326449   | ST.970   | EC755002   | FRW10.1 |                        |         | 0002695                 | SCX4.6  |                     |         |
| 70326538   | ST1.211  | EC755003   | OX5.9   |                        |         | 8311602                 | SCQ6.7  |                     |         |
| 70326538   | VA30     | EC755004   | FR011.2 |                        |         |                         |         |                     |         |
| 70326575   | ST1.211  | EC755007   | SCY4.6  |                        |         | <b>VICTOR (KALART)</b>  |         |                     |         |
| 70326575   | VA30     | EC755008   | FRW10.1 |                        |         | 14319                   | OSD13.4 |                     |         |
| 70326616   | ST1.211  | EC755011   | FRW8.5  |                        |         | 14627                   | WP50    |                     |         |
| 70326616   | VA30     | EC755013   | FRM9.7  |                        |         | 16164                   | WP75    |                     |         |
| 70326706   | VPR20    | EC755014   | FRW8.5  |                        |         | 19513                   | WP76    |                     |         |
| 70328372   | VPR23    | EC755016   | SCX9.5  |                        |         | 23216                   | WP78    |                     |         |
| 70332023   | VP R11   | ED000066   | SCX4.0  |                        |         | 23217                   | WP77    |                     |         |
| 70332062   | VPR4     | ED000864   | SCX15.2 |                        |         | 47609                   | OSC7.3  |                     |         |
| 70342023   | FRY19.6  | ED002843   | SCX4.0  |                        |         | 48246                   | GT27.6  |                     |         |
| 70342024   | SCY13.3  | ED003975   | SCX8.6  |                        |         | 53537                   | OSD11.0 |                     |         |
| 70342025   | FRM13.3  | EE004011   | SCY14.7 |                        |         | CE18                    | OB10.1  |                     |         |
| 70342026   | SCX4.3   | EE004294   | SCY8.6  |                        |         | CE19                    | OB6.1   |                     |         |
| 70342027   | SCA6.1   | GL450V     | VCR33   |                        |         | CE21                    | OC12.1  |                     |         |
| 70342028   | SCC15.7  | MSU911     | V757    |                        |         | CE22                    | OC16.0  |                     |         |
| 70342030   | FRX35.1  | MSU951     | V761    |                        |         |                         |         |                     |         |

= Replacement Belt

= Kit May Not Include Tires

^ = Part of the Assy

# WOLLENSAK WOLLENSAK

| MFG. P/N    | PRB NO. | MFG. P/N      | PRB NO. | MFG. P/N      | PRB NO. | MFG. P/N    | PRB NO. | MFG. P/N  | PRB NO. |
|-------------|---------|---------------|---------|---------------|---------|-------------|---------|-----------|---------|
| 2125511     | 0816.4  | 81483000196   | SCX8.9  | >0(612630     | FRX10.5 | 832216      | SCX3.5  | 83279     | FRM9.7  |
| 2126823     | SCA14.1 | 81483000378   | 0A5.4   | >0(612880     | SCY8.0  | 832218      | SCQ5.6  | 832832293 | SCA6.1  |
| 21670       | 008.5   | 81483000394   | SCA8.9  | XX623380      | FRW9.7  | 832219      | FR8.8   | 83285     | FRM9.7  |
| 21671       | 006.1   | 8148300043    | SCX8.0  | XX628860      | SCY7.0  | 832220      | FRX15.2 | 83287     | FRX10.5 |
| 21672       | ST2.65  | 81483000501   | SCX8.9  | )0(629850     | FRW9.2  | 832221      | SCA10.5 | 83288     | SCY6.0  |
| 21673       | STC.624 | 81483000659   | SCA8.9  | XX636800      | FRW9.1  | 832222      | SCX11.8 | 83289     | SCY4.2  |
| 21674       | STC.703 | 81483000741   | FR12.5  | XX63800       | FRW9.1  | 832223      | SCQ4.0  | 83290     | SCX7.0  |
| 21675       | ST2.65  | 81483000758   | SCY8.6  | XX640790      | FRW9.7  | 832224      | SCB14.6 | 834334    | SCA11.1 |
| 21678       | 0B7.6   | 8148300013    | FRX9.7  | )0(640910     | SCY3.2  | 832225      | FRY11.5 | 834702    | VPR26   |
| 21691       | 007.8   |               |         | XX642080      | FR8.2   | 832226      | SCY11.7 | 861360    | ST1.160 |
| 27520       | 0A8.2   | <b>YAMAHA</b> |         | )0(647930     | SCY13.3 | 832229      | FRQ11.2 | 861451    | IW11    |
| 27521       | 006.1   | CB061860      | FRX35.1 | XX648870      | FRW9.2  | 832231      | FRX11.0 | 861452    | IW11    |
| 27719       | 006.1   | CB073580      | FRX22.4 | XX670540      | FRW8.5  | 832232      | SCQ6.0  | 861519    | ST.925  |
| 27750       | 0A14.0  | CB081820      | SCX8.6  | XX670790      | FR8.2   | 832235      | SCQ4.0  | 861636    | ST.948  |
| 2830531     | SCX2.6  | 06090650      | SCY6.0  | XX674520      | FRW9.1  | 832236      | FRW9.2  | 861639    | ST.948  |
| 2830547     | SCX8.6  | CB1660        | SCX8.0  | XX675740      | SCX4.6  | 832237      | SCY4.4  | 861639    | VA14    |
| 28700       | 0A10.9  | 0B21 30       | FRW7.0  | )0(676050     | SCY6.7  | 832238      | SCY4.0  | 861643    | ST.771  |
| 28719       | 006.1   | 0B2550        | FRW8.5  | XX678490      | FRW9.1  | 832239      | FRW10.1 | 861644    | ST.771  |
| 28770       | 006.1   | 06600370      | FRM7.5  | )0(684580     | FRW8.5  | 832240      | SCY5.2  | 86164601  | ST.948  |
| 28877       | 006.1   | 0B606240      | SCX8.0  |               |         | 832243      | SCQ10.0 | 86164601  | VA756   |
| 30144920    | 0B10.9  | CB6240        | SCX8.0  | <b>YORK</b>   |         | 832244      | SCQ6.0  | 86164604  | ST.948  |
| 30177180    | 0C14.4  | CB638290      | SCX8.0  | 033337        | SCY7.6  | 88332224590 | FR11.6  | 86164604  | VA14    |
| 30216670    | 008.5   | 0B640180      | SCX10.7 | 3931202       |         |             | SCB32   | 861654    | ST.948  |
| 30216710    | 006.1   | CB650400      | SCY6.7  | 5610902       | FRX10.5 |             | SCA3.2  | 861654    | VA14    |
| 30216780    | 087.6   | 06652880      | SCY6.5  |               |         | 8833222552  | SCX7.4  | 86165401  | ST.948  |
| 30227500    | 0614.0  | CB6667        | SCQ5.6  | <b>ZENITH</b> |         |             | FRX9.5  | 86165401  | VA14    |
| 30268230    | 0611.7  | CB7130        | SCY6.7  | 3247          | 0B5.2   | 832253      | SCY2.9  | 861655    | ST.948  |
| 302682307   | SCX14.7 | CB7900        | FR23.6  | 3248          | FRX5.1  | 832257      | SCY6.5  | 861655    | VA15    |
| 30275200    | 0A7.0   | CB8310        | SCX8.4  | 3256          | FR21.5  | 832258      | FRX25.0 | 86165501  | ST.948  |
| 30287000    | 0810.9  | CX601750      | SCX4.6  | 325602        | FR21.5  | 832259      | SCY6.0  | 86165501  | VA15    |
| 30288770    | 0812.4  | 0X601760      | FR8.2   | 8320032901    | SCQ4.0  | 832263      | SCY4.6  | 861670    | ST.771  |
| 30306670    | SCX2.4  | CX603200      | SCX15.2 | 832024        | SCX8.6  | 832264      | SCY3.5  | 861671    | ST.771  |
| 3032077008  | SCX8.0  | CX603600      | FRW8.0  | 832024B       | SCA8.6  | 832265      | FRM14.0 | 861707    | VA502   |
| 30320780    | 0B9.0   | CX604250      | SCQ3.6  | 832029        | SCY3.2  | 832267      | SCX5.1  | 86656     | VPR5    |
| 30322060    | FRM12.1 | CX608730      | FR8.2   | 83203         | 0A4.0   | 832268      | SCY6.7  | 88250     | SCA6.1  |
| 30329733    | SCQ5.6  | CX612750      | FR8.2   | 832030        | 0A8.5   | 832269      | SCY4.0  | 88251     | FRM13.3 |
| 303381206   | SCX8.6  | CX614650      | FRW9.0  | 8320306       | SCX8.6  | 832271      | FRM11.0 | 88253     | SCX4.3  |
| 30400680    | SCX8.6  | CX614720      | SCX2.6  | 832031        | FRY11.5 | 832272      | SCA5.4  | 88254     | FRY19.6 |
| 30402850    | SCX8.6  | CX615750      | FR8.2   | 832036        | FR8.2   | 832273      | SCX4.6  | 88255     | SCC15.7 |
| 30402860    | SCX5.1  | CX672970      | FRW8.0  | 83204B        | SCX4.3  | 832274      | SCY9.2  | 88256     | SCY13.3 |
| 30667808    | SCX2.6  | CX673050      | FRW7.7  | 832052        | FRM11.2 | 832275      | SCQ7.2  | 8851080   | V762    |
| 3207        | SCQ8.2  | QDB0114       | 5C04.0  | 832052B       | FRM11.5 | 832276      | SCQ5.3  | 885970    | V754    |
| 32078       | SCB8.6  | QDB0117       | SCX5.1  | 8320536       | FRX12.5 | 832279      | SCX9.5  | 9031198   | VCR33   |
| 32708       | 088.5   | QDB0118       | SCX8.9  | 832055B       | FRM11.7 | 832280      | FRW7.1  | 90422B    | SCX2.4  |
| 32973       | 0B5.6   | SX700070      | FRM8.0  | 832056        | SCX2.4  | 832283      | SCA4.2  | 90467B    | SCX8.6  |
| 33681       | FRM16.3 | SX700080      | SCY4.2  | 832057        | SCA8.   | 832288      | SCY12.7 | 906109586 | FRZ13.2 |
| 33812       | SCX8.9  | SX700090      | SCQ4.0  | 8320576       | SCX8.9  | 832292      | SCY5.0  | 906110684 | FRM15.2 |
| 33813       | SCX8.0  | SX701158      | FRM9.2  | 832058        | SCX8.0  | 832293      | SCA6.1  | 90735429  |         |
| 40068       | SCX8.6  | SX701160      | SCY5.2  | 8320586       | 0A7.0   | 832294      | SCY2.9  | 90745000  | IWV005  |
| 40285       | SCX8.0  | SX701180      | SCY5.2  | 832060        | SCX8.6  | 832298      | SCX7.0  | 917902    | VPR26   |
| 40286       | SCX4.9  | SX706010      | SCY4.2  | 8320606       | SCA8.9  | 832301      | SCA6.7  | 948520    | ST1.130 |
| 483000048   | SCX4.3  | SX711280      | SCY4.6  | 832065B       | SCX8.6  | 832302      | SCQ3.6  | 948520    | VA150   |
| 483000063   | SCX5.1  | SX711290      | SCY5.2  | 832066        | OX5.9-  | 832305      | SCQ6.5  | 948522    | ST1.130 |
| 483000170   | SCX2.4  | SX982910      | SCY12.7 | 83207         | SCA3.0  | 832306      | SCO2.2  | 948522    | VA150   |
| 4830021     | SCX2.4  | SX982950      | SCX8.4  | 83208         | SCA10.0 | 832307      | SCQ4.3  | 948536    | ST1.130 |
| 81018575308 | ST.815  | SX983540      | SCX8.0  | 83208B        | SC010.0 | 832308      | FRW7.3  | 948536    | VA150   |
| 81303207708 | SCA10.0 | SX985990      | FRX7.5  | 832200        | SCY12.7 | 832319      | SCA2.3  | 94853601  | ST1.130 |
| 81303207807 | 0B9.0   | SX988670      | SCX8.4  | 832201        | FRM11.7 | 832320      | SCB5.7  | 94853601  | VA150   |
| 81303297303 | SCY6.0  | SX988930      | SCY6.7  | 832202        | FR9.7   | 83232001    | SCB5.7  | 96951     | FRM10.5 |
| 81303461206 | SCX5.1  | SX988940      | FRM8.0  | 832204        | FRX9.7  | 832324      | SCQ6.5  | 96952     | 50)(9.5 |
| 8148200038  | SCX4.3  | SX996020      | SCX7.0  | 832205        | SCY6.0  | 832327      | SCA2.3  | 96954     | FRM10.5 |
| 81483000048 | SCX4.3  | SX996040      | FRM14.0 | 832206        | FR18.5  | 832334      | SCA11.1 | 96956     | SCX9.5  |
| 81483000055 | SCX8.9  | X675740       | SCX4.6  | 832207        | FRM10.5 | 832335      | SCQ7.8  | 96957     | SCQ6.0  |
| 81483000063 | SCX5.1  | XX602540.     | FRW8.5  | 83220         | SCY5.7  | 832528      | SCQ7.8  | 96964     | SCQ6.7  |
| 8148300011  | SCA4.5  | XX602550      |         | 832209        | SCX9.5  | 832678      | SCX8.6  | 96965     | SCQ6.7  |
| 81483000113 | 0A4.6   | XX606840      | SCX7.4  |               | SCY6.0  | 83269       | FRW10.7 | 96965     | SC5.5   |
| 81483000139 | FRW9.7  | XX606850      | FRX11.2 | 832211        | SCX8.9  | 83273       | SCX8.6  | A6706479A | ST.517  |
| 81483000162 | SCX8.6  | )0(610400     | SCX4.6  | 832214        | FRX16.8 | 83278       | FRM11.2 | X36460260 | ST1.110 |
| 8148300019  | SCX9.2  |               |         |               |         |             |         |           |         |

## Computers

|                          |          |
|--------------------------|----------|
| <b>CONTROL DATA CORP</b> |          |
| 77611821                 | FRFX13.1 |
| 92314113                 | FRF28.0  |
| <b>DIGITAL EQUIP.</b>    |          |
| 12-11583-01              | GT49.8   |

|            |         |
|------------|---------|
| <b>IBM</b> |         |
| 365579     | GT23.5  |
| 945091     | FRF14.7 |
| 945109     | FRF17.5 |
| 945824     | FRC11.6 |
| 94825      | FRC15.7 |
| 1707015    | 0815.6  |
| 6196949    | 064.4   |

|                           |        |
|---------------------------|--------|
| <b>INTEL SYSTEMS CORP</b> |        |
| SDP-6819-080025           | GT6.2  |
| <b>NEC</b>                |        |
| 808-805049-002-A          | GT11.1 |
| *805049-006-A             | GT6.2  |

|               |          |
|---------------|----------|
| <b>TANDON</b> |          |
| 210334        | FRFX12.5 |
| 914000-001    | FRFX12.5 |

|                    |         |
|--------------------|---------|
| <b>TEXAS INST.</b> |         |
| 0943841-0027       | FRF28.8 |
| 0943842-0025       | FRF22.8 |
| 0943848-0054       | FRF29.5 |
| 2213548-0001       | GT23.5  |
| 2213589-0025       | FRF27.7 |
| 2268156-001        | FRF22.5 |

= Part of the Assy

= Kit May Not Include Tires

= Part of the Assy

Mfg. # to PRB #